INS. CASE OWNER	c c	4, yc 1900	6096,	H Ja3 M LKK	
Surveyor.	Lup	DOI: ASSIGNM	YT9	Date / Time :	91014
Pre-assign / CCU Insured Vehicle N Name of Insured Insured Tel No. Excess Sec II :SS Is driver the owner	Cool Blues African	differing & Medrica	Claim No. Policy No. Make / Model Place of Accide		coolousqq
If NO, Driver Na Driver Tel	me / Age : No. :	(V/L: (ES)/NO)	OI GIA REPOI Insured Liabilit		PORT: YES / NO
Liability : RMKS:	INSRS: WSP: Tel: Liability: RMKS:		INSRS: WSP: Tel: Liability: RMKS:		NSRS: VSP: el: inbility:
Date/Time	SMITOSOF COSTAN	1900 1814 [MQ3	100 100	STAGE Non-Reporting ltr (1st): Non-Reporting ltr (2nd): Non-Reporting ltr (Final): Notification ltr (if non-pickup	DATE/PIC
sal4hala	collided into parked be grown liability clear perdung timetize cor	hiole		Call OI After call lir to OI: Documentation Check List: Notification lir (if non-pickup After call lir to OI:	
PI-PI-17	THE PASS TO TYPIN TO FREPR	s. Reiber .		Authorisation To Act: Release Voucher: Final Repair Bill: Car Rental Invoice:	2 v
				Towing Invoice LTA / GIA Medical Bill: PIR Mandate/Reject Instruction	
PRELIMINARY ADVICE	Date/Time:	Sent By:		LOD Payment Breakdown Form: Post-Repair Photos: Others:	-
FINALIZATION Repair Cost: PP FINAL SETTLEMENT	Date/Time: w.41-19 Confirm	Confirm with: s) Reduction: 32 n with Necks	%	Confirm by: Lsop	-]Call
Final Liability: Repair Cost: wifest Loss of Rental (LOR): Loss of Use (LOU): Loss of Income (LOI): LOR only LOU only	SS - (day SS - (s to x \ b day SS - (S x day	5)		IF NO or B 28, Ass. Lia:	deed vahede
BIA/LTA Search Medical: Dishursement: .egal Cost Total:	S\$ - 50 S\$ - S\$ -	(e.g. Tow/ Independent) Sum SS:		1) Claim status: Nermal/Rej 2) Report Format: TP 3) Survey fee: + 450	
Payce 1: Payce 2: (Strike if N.A.)	Date/Time: u. \\1-19 Confirm \$\$ 31.555.96 Name 1	with: HADIA PREMIUM AUTOMOBIL		Email Call	
Payee 1 (Stribe If N.A.)	\$\$ Name 2 \$\$ Name 3				

ASSIGNMENT

From: Date	9/4/2019	Veh No:	Smo	2030E	- Yr Hogn	2018	June
Estimated Cost			/ M.Cycle /	Bus / Van / Lo	rry / Taxi / P	rime Mover /	
DO (TP)WS/TP RES/OD RES/EVA/INV/M	ıv	Truck	/Trailer or				
To Inspect Vehicle No: 3MC 20:		Make:	Audi	A3 Seden		999	
		Colour	Red		AIC: It	sured / Std / N	H/NA
of Workshop m/s Premium 55 ubi Roac	1	Sp.Reading	12	797.	T/Radio: F	insured / Std / I	NE / NA
insured.	F. 1	Eng/No					
Policy No		C/No:	WAU	1222849	J10676	509.	
Citaims No:		Gen. Cond.	B. C	Poor / Burnt			5.
Sum Insured Excess:		Steering: Inc	otder / Jamn	ned / Leaked /	Burnt or		
(Client's Record)		Brake: Ing	Ger / Jame	ned / Leaked /	Burnt or		
Make of Vehr 1001h	\wedge	Modi: Nil		STD A/Rim or			
	p ^p	Tyre Size:	F:	205/55	216		
(Policy Condition)			R:	205/15	5R16		
Remark: The veh had commenced its	N/S O/S	BSY DUN /		Y/FS/LIZA	MIC / OHTS	U / PIR / SUMI	1
repair at the time of inspection.		TOYOTYC	OKO or				
Bal. or Market Value:		Front	,		Ruar		
IDAC Accident Rport: Consistent? : Y	es or No		26	mm	R/Bal.	06	m
GIA / PR Seen: Consistent?: Y		THE PROPERTY OF	06	mm	L/Bal.	06	m
	es or No	D.O.A.			0.0.1	09/04/1	
	es or No	Survey held	at	Prem	iva,	1	
sam sam.		Carrier Parameter	_	Rear / O/S	(NI) I UIC	/ Rooftop or	
CA / REV / REP. / 24 HRS	Vehicle: IN / OUT	- Sept. 10110	THE PARTY OF THE P				
Date: Person Contacted:		The U/C	/ Chassis	frame / Body	Structure	offected due to	collisio
Date / Time Action / Instruction TP Lon Pac.						8	
Phi 414' 258 (BED)	4 5,396 22%)						
Continue District Co.							
Conte/Time, File Pass In? : Preli. Report		Days Of Re					
Date/Fine, File Return to?		Resurvey N	to, of Trip	7	Survey F	~~	
	Add Fee	e Sile	Insp (\$		Darisporte		
2)	Audited		view (\$		1 Photos		
Report Format	6		a Insis (E) Offices		
Report Format :					7 (3)		
Lump Sum / LB.E (\$	1	yvex	skend (\$		1		_
•					TOTAL	1	

Company Registration No. 199607198R

Date: 10/04/2019

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your ref:

18/19/19/VC00/021599

Our ref:

CC4/LPC19006096/Afa3

The Motor Claims Department M/s LONPAC INSURANCE BHD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SMC 2030E

We refer to the above matter.


Please be informed that we had conducted the inspection of the above mentioned vehicle on 09/04/2019 at the premises of M/s Premium Automobiles Pte Ltd - Ubi and have the following to report:-

Workshop Estimate Amount	: S\$	24,924.00	
Revised Estimate Amount	: S\$	18,029.00	
"Check" Items Amount	: S\$	1,034.00	
Total (Including Check Items)	: S\$	19,063.00	
Market Value	: S\$	- (est	.)
LTA Reimbursement Value	: S\$	- (est	.)
Nett Value	: S\$	- (est	.)

Description of Damage:

The vehicle sustained damages at the

N/S Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs:

13.0 days

Yours faithfully,

ADRIAN LING

Licensed Appraiser

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

 Estimate
 : Accident Repairs

 Workshop
 : Ubi Road 1

 Contact No
 : 6366 2323

 Fax No
 : 6841 1183

Reference : PA/TP/0443/2019/DY

Date : 6-Apr-19

Kindly arrange for survey.

Your insured vehicle no : GR 88 U

Lonpac Insurance Bhd

100 Beach Road #19-00 Shaw Tower Singapore 189702

Attn: Motor Claims Dept

Fax: 6296 2706

Owner's Name : Mr. Liu Linxiang
Address : 11A Woodlands Ave 6

#06-07

Singapore 738993

 Telephone
 : 91012197

 Type of Claim
 : Third Party Claim

 Policy No.
 : 1800072411

Vehicle No : SMC 2030 E

Model Code : A3 Sedan 1..0 TFSI 8V

 Model / Year
 : Jun-18

 Engine No
 : CHZ 463478

Chassis No : WAUZZZ8V9J1067609

Mileage :

Liability : Excess Cost : .

Estimated By : Johnny Boo / Allan Wu

Accident Date : 10-Mar-19

Place of Accident : Woodlands Blk 11A Carpark

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMC 2030 E

S/N	Nature of Jobs		Estimated Charges
1	To install solar film.		430 TBC /
2	To remove and reinstall rear parking aid. Check function.	s/n	\$ 280.00
3	To remove and transfer lhs rear door's multi-lock system and power window devices. Inspect for damages.	s/n	\$ 280.00
4	To renew rear windscreen amd lhs 1/4 glass fo facilitate fender renewal.	s/n	\$ 600.00
5	To dislodge and reinstall rear wire harness for lights, battery manager, fuse and relay trays, electrical and audio equipment.	s/n	\$ 1,400.00
	SUB-TOTAL LABOUR CHARGES		\$ 2,560.00

All charges are not inclusive of GST.

Remarks (OK) = Approved, Remarks (X) = Not approved

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SMC 2030 E

S/N	Nature of Jobs			Estimated Charges
6	To remove and reinstall rear seat, back rest, hat tray, abcd pillar trims, lugagge compartment trims. Dislodge roof liner and disengage curtain airbag etc.	s/n	\$	1,400.00
7	To dismantle rear bumper, lhs rear door and rear lid. Cut out and weld lhs rear fender and lhs rear inner side panel. To renew lhs rear door, Re-organize crash management components. Reinstall removed.		s	7,200.00 4200,
8	To respray lhs rear door, lhs rear fender, lhs sill panel, lhs rear inner side panel, door entrances, roof channel, drain panel and end panelling. To carry out stone chip treatment and joint sealer works.		\$	5,000:00 2400
9	To carry out diagnostic check.	s/n	\$	192.00 /
	TOTAL LABOUR CHARGES	:	\$	16,352.00

All charges are not inclusive of GST.

Remarks (OK) = Approved, Remarks (X) = Not approved

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMC 2030 E

S/N	Parts Description		Damage Parts & Prices S/NETT REMARKS
	6.1		NAME OF THE PERSON OF THE PERS
1	REAR FENDER-LH Dewto		\$ 2,110.00
2	REAR WINDOW		\$ 742.00 - 74/50
3	REAR SIDE WINDOW-LH		\$ 520.00 - 519.50
4	REAR DOOR-LH DENTED		\$ 2,279.00
5	REAR OUTER DOOR SEAL-LH		\$ 146.00
6	BONDING AGENT THE ME		\$ 45.00
7	CLEANING SOLUTION HER NEW		\$ 65.00
8	APPLICATOR NOT NOW		\$ 7.00 🖈
9	REAR DOOR ATTACHMENT PARTS PUT NO.		\$ 117.00 ×
10	REAR DOOR CATCH-LH		\$ 85.00 X
11	REAR REINFORCEMENT FOR C-PILLAR		\$ 176.00 🖈
12	ACRYLIC SEALANT 7	S/N	\$ 180.00 -
13	CAVITY WAX	S/N	\$ 140.00
14	STONE CHIP	S/N	\$ 180.00
15	METAL FILLER POWDER	S/N	\$ 280.00
16	REAR WINDSCREEN SEALANT	S/N	\$ 200.00
17	1/4 GLASS SEALANT	S/N	\$ 100.00
18	SUNDRIES HA NEW		\$ 800.00
	TOTAL SPARE PARTS		\$ 8,172.00
	TOTAL LABOUR CHARGES		\$ 16,352.00
	GRAND TOTAL	3	\$ 24,524.00

All charges are not inclusive of GST.

Legend :

Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Name

Surveyed Date

Authorised Date

Excess Cost

Liability

Remarks

LKK Auto Consultants hence notify the Repairer of the following:

- . To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary term(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle.

we Authorised, 13 Days

Should we require further labour charges and spare parts in the

progress of repair, we shall inform you accordingly.

For inspection of vehicle, please refer to Ms Norah Khai at

Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo

Body Repair Manager

Allan Wu

Claims Consultant

Poh Kin (LKKAuto)

From:

Boo seng yak <boojohnny@gmail.com>

Sent: Thursday, 6 June 2019 4:11 PM

To: Adrian Ling (LKKAuto); CS A Team; Admin A; Carrine Leong;

jiayee.yap@premiumauto.com.sg; Chang Chee Sing

Subject: FINAL REVISION - SMC2030E - TP LONPAC - SURVEYED 9 APR 19

Attachments: WhatsApp Image 2019-06-06 at 15.33.07 (1).jpeg; WhatsApp Image 2019-06-06 at 15.33.06.jpeg; WhatsApp Image 2019-06-06 at 15.33.08 (1).jpeg; WhatsApp Image

2019-06-06 at 15.33.07.jpeg; WhatsApp Image 2019-06-06 at 15.33.07 (2).jpeg; WhatsApp Image 2019-06-06 at 15.33.08.jpeg; PA04432019-SMC 2030 E - A3

SEDAN 1.0 TFSI 8 - REAR - TP (LONPAC).xls

Hi Adrian and all,

Revised estimate and photographs is attached.

Please confirm repair cost of @19,228.00 @ 13 days of repairs exclude 2 Sundays and 1 PH.

Your early closure is well appreciated.

Best regards - jb

55 Ubi Road 1, Singapore 408699 Tel: 6366 2323 Fax: 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SMC 2030 E

				Damage Pa	arts 8	Prices
S/N	Parts Description			S/NETT R	EMA	RKS
1	REAR FENDER-LH		\$	2,110.00	\$	2,110.00
2	REAR WINDOW		\$	742.00	\$	741.50
3	REAR SIDE WINDOW-LH		\$	520.00	s	519.50
4	REAR DOOR-LH		\$	2,279.00	\$	2,279.00
5	REAR OUTER DOOR SEAL-LH		s	146.00	\$	146.00
6	BONDING AGENT		\$	45.00		
7	CLEANING SOLUTION		\$	65.00		
8	APPLICATOR		\$	7.00		
9	REAR DOOR ATTACHMENT PARTS		\$	117.00		
10	REAR DOOR CATCH-LH		\$	85.00		
11	REAR REINFORCEMENT FOR C-PILLAR		\$	176.00		
12	ACRYLIC SEALANT	S/N	\$	180.00	\$	180.00
13	CAVITY WAX	S/N	S	140.00	\$	140.00
14	STONE CHIP	S/N	\$	180.00	\$	180.00
15	METAL FILLER POWDER	S/N	\$	280.00	\$	280.00
16	REAR WINDSCREEN SEALANT	S/N	\$	200.00	\$	200.00
17	1/4 GLASS SEALANT	S/N	\$	100.00	5	100.00
18	SUNDRIES		\$	800.00		
	TOTAL SPARE PARTS	1	\$	8,172.00	\$	6,876.00
	TOTAL LABOUR CHARGES	1	\$	16,352.00	\$	12,352.00
	GRAND TOTAL	:	\$	24,524.00	\$	19,228.00

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Nivitha (LKK Auto)

From:

GERALD POH WEE BIN <geraldpoh@lonpac.com>

Sent:

Friday, 5 April 2019 9:50 AM

To:

Admin-D (LKKAuto); sur@lkkauto.com

Cc:

MT_Claim_SG; Claims Dept

Subject:

FW: ACCIDENT INVOLVING SMC 2030 E AND YOUR INSURED SMC2030E ON

10/03/2019 [External Confidential]

Attachments:

SMC 2030 E - 04042019 GIA.pdf

3.06pm@s/4/11 VNI amage on 9/4/11

Lonpac External - Confidential

Our Ref

: 18/19/19/VC00/021599

Dear Nivtha,


Please proceed to conduct the survey and revert to them on liability.

Best Regards Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: Claims Dept [mailto:claims@premiumauto.com.sq]

Sent: Thursday, 4 April, 2019 7:32 PM

To: MT_Claim_SG Cc: 'Claims'

Subject: ACCIDENT INVOLVING SMC 2030 E AND YOUR INSURED SMC2030E ON 10/03/2019

Dear all,

Kindly assist in the liability clearance for the above mentioned case. We propose for 100% direct settlement in our clients favour.

We herein attached the GIA report and letter request for direct settlement for your reference, we will forward you the estimate once is available.

Kindly arrange the survey on 09/04/2019, Tuesday, 10am.

Video is attached as well.

Thank you and have a good day.

Best Regards,

Diyana

Claims Admin Assistant

Premium Automobiles Pte Ltd (Reg No 199902271W)

55 Ubi Road 1 Road Singapore 408699

p. +65 6388 2323 d. +65 6768 9911 f. +65 6841 1183

e. claims@premiumauto.com.sg w. www.audi.com.sg

Audi Showroom, Audi Centre 281 Alexandra Road Singapore 159938 p. +65 6836 222



Email Disclaimer

This email, including any attachment, is confidential and may also be privileged If you have received it in error, please notify as immediately by reply croad and then delete this message from your system. Please do not copy it in use it for any putpose or disclose its contents or any attachment to any other person. Thank you

Mei Kwan (LKKAuto)

From:

Mei Kwan (LKKAuto)

Sent:

Tuesday, 16 April, 2019 10:46 AM

To:

GERALD POH WEE BIN

Cc:

MT_Claim_SG; Poh Kin (LKKAuto); CS A Team; Admin A

Subject:

RE: ACCIDENT INVOLVING SMC 2030 E AND YOUR INSURED SMC2030E ON

10/03/2019 [External Confidential]

Attachments:

TP ESTIMATE - MARKED.pdf; Preliminary Advice.pdf

Categories:

HMK

'WITHOUT PREJUDICE' SAVE AS TO COSTS

LPC ref: 18/19/19/VC00/021599 LKK REF: CC4/LPC19006096/Afa3

Dear Sir / Madam,

We refer to the above matter.

Enclosed revert of vehicle: SMC 2030E

We have not authorized repairs.

Enclosed for your perusal is:

TP estimated cost of repair

Preliminary advice

Our case handler in-charge is Poh Kin and he can be contacted at DID: 6841 2132.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN <geraldpoh@lonpac.com>

Sent: Monday, 8 April, 2019 9:26 AM

To: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>

Cc: MT_Claim_SG <mt_claim@lonpac.com>

Subject: RE: ACCIDENT INVOLVING SMC 2030 E AND YOUR INSURED SMC2030E ON 10/03/2019 [External

Confidential]

Lonpac External - Confidential

Dear Mei Kwan,

Attached copy of insured's report for your attention.

Please be informed that vehicle is not in the workshop, repairer arrange on 09/04/2019.

Best Regards,

G.Nivithal Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: GERALD POH WEE BIN [mailto:geraldpoh@lonpac.com]

Sent: Friday, 5 April 2019 9:50 AM

To: Admin-D (LKKAuto) <admin-d@lkkauto.com>; sur@lkkauto.com

Cc: MT_Claim_SG <mt_claim@lonpac.com>; Claims Dept <claims@premiumauto.com.sg>

Subject: FW: ACCIDENT INVOLVING SMC 2030 E AND YOUR INSURED SMC2030E ON 10/03/2019 [External

Confidential)

Lonpac External - Confidential

Our Ref

: 18/19/19/VC00/021599


Dear Nivtha,

Please proceed to conduct the survey and revert to them on liability.

Best Regards Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd 300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706



Lonpac External - Confidential data is for use by authorised external parties only.

From: Claims Dept [mailto:claims@premiumauto.com.sg]

Sent: Thursday, 4 April, 2019 7:32 PM

To: MT_Claim_SG

Cc: 'Claims'

Subject: ACCIDENT INVOLVING SMC 2030 E AND YOUR INSURED SMC2030E ON 10/03/2019

Dear all,

Kindly assist in the liability clearance for the above mentioned case. We propose for 100% direct settlement in our clients favour.

We herein attached the GIA report and letter request for direct settlement for your reference.

Poh Kin (LKKAuto)

From:

Poh Kin (LKKAuto)

Sent:

Tuesday, 30 April 2019 8:52 AM

To: Cc: Claims

Admin A

Subject:

RE: ACCIDENT INVOLVING SMC 2030 E AND YOUR INSURED GR 88U ON

10/03/2019 [External Confidential]

WITHOUT PREJUDICE SAVE AS TO COSTS

Our Ref:

CC4/LPC19006096/Afa3

Your Ref:

SMC 2030E

Dear Sir/Madam,

We refer to above matter.

Please be informed that basing on the accident statements submitted by both parties, the liability is clear / under BOLA (subject to BOLA guideline settlement) and shall proceed with direct settlement for the above mentioned case.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle.

The final repair cost is subjected to the consistency of the damages according to the nature of the accident.

And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Poh Kin, Chong (Mr) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2132 | email: pohkin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Save the Earth Print only when necessary

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : LIU LINXIANG

Period of Insurance

: 27 Jun 2018 To 26 Jun 2019

Engine No.

: CHZ 463478

Chassis No.

: WAUZZZ8V9J1067609

Vehicle No.

: SMC2030E : 1800072411

Policy No.

Endorsement No.

Issued Date

: 09 Jul 2018

ABOUT THE COVER

Make/Model

: AUDI A3 Sedan 1.0 TFSI S tronic

Engine Capacity/Tonnage : 999.00 CC Driver Restriction

: NA

Sum Insured : Market Value

First Year of Registration : 2018

Off Peak Car No

Insuring with COE/PARF Yes

Person or Classes of Persons Entitled to Drive*:

a) The Pulsiphulder b) Any after person who is driving on the Policyholders order or with higher permission. This PoScy will induminfy the Pulsipholder or any authorised driver only if heralis meets the specified age condition.

You have in pay an additional sum of £3,000 as "Young another inexperienced Driver Escape" ("YEA") If You are or Your Authorises Driver (named or unnamed) is under the age of 23 and in has less than 2 years' driving experience.

Age Condition

All Age Condition

Limitation as to use*

Use anly for social, disnesses and pleasure purposes and for the Pulicyholder's business.
This Pulicy direct not cover use for him or reward, driving facts, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any surpose in connection with Millor Trade.

Loss of Use 1800cz - 2000cc Optional

* Contations rendered imperative by Section 8 of the Motor Vehicles (Third-Party Niets and Compensation) Act (Cap. 186) and Section 96 of the Road Transport Act, 1967 (Malayeta), are not to be included under these headings.

EXCESS

Section 1 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - 50

Windscreen 1 \$100

Named Driver and Excess (where applicable)

LIU LINKIANG - \$600 (Dwn Demage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1 Autil Customer Service Center Add: 55 Uti-Road 1 Singapore 408699 83662323

Far after Approved Reporting CemestASS Authorised Repaires, please contact our 34-hour accident emergency hardness 4-95 6336 6300. Alternatively, you may refer to AIG website www.aig.com.aig or AIG SG Midnik Acc. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

We havely early that the policy to which this Cartificate of Insurance relates is insurance with the provisions of the Motor Vehicles/Third Party Risks and Compensation) Act (Cap. 189). Part IV of the Risks Transport Act, 1967 (Malayelo) and Motor Vehicles (Third Party Risks) Pulse. 1959 (Malayelo)

0504125263

PREMIUM LEASING INS.

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pts. Ltd.

AIG Asia Pacific Insurance Pte. Ltd. AUTHORISED REPRESENTATIVE

Telefax

to Lonpac Insurance Bhd

100 Beach Road #19-00 Shaw Tower Singapore 189702

Attn: Motor Claims Dept

Yr Ref: CC4/LPC19006096/Afa3

:

:

:

:

:

:

:

Norah Khai 6768 9828

6841 1183

Body Repair

from Telephone +65-

Tele

Telefax +65-

Mobile +65

Our department Your Claim Ref

Premium Automobiles Pte Ltd

Telefax (65) 6471 3733

Service & Parts Centres

Telefax (65) 6841 1183

Our Ref

CK Our F 019 Date

1

PA/TP/0443/2019/KK 27 May 2019

total pages

Showroom 9 Leng Kee Road

Singapore 159090 Telephone (65) 6566 1111

55 Ubi Road 1

Singapore 408699 Telephone (65) 6366 2323

RE: CLAIM - OWNER'S SATISFACTION/DISCHARGE VOUCHER

Make & Model

AUDI A3 SEDAN 1.0 TFSI 8V

Vehicle Chassis No.

WAUZZZ8V9J1067609

Vehicle Regn No.

SMC 2030 E

Vehicle Mileage

14317 KM

Vehicle Owner

Mr. Liu Linxiang

Liability

Direct Settlement by Poh Kin of

LKK Auto Consultants Pte Ltd via email dated on 30 April 2019 with LOR/LOU.

Accident Date

: 10/3/2019

Place

Woodlands Blk 11A Carpark

Repair Cost

: \$ 20,575.96

WIP No.

: 48941

Repairer's Name

Premium Automobiles Pte Ltd

I/We certify that the vehicle has been fully repaired to my entire satisfaction and that payment of the repairer's charges that are claimable under the policy will be deemed in full and final settlement of my claim.

Owner / Insured Signature

Time

.

Date

.

19/5

DISCHARGE VOUCHER-LONPAC - SMC 2030 E



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Internation	onale Des Experts En Autom	nobile
LONPAC INSURANC	E BHD	Ref : CC4/LPC19006	8096/Aea3n2
300 BEACH ROAD #17-04/07 THE CONC	OURSESINGAPORE 199555	Date: 26-12-2019 Code: LPC2	
	Policy Particulars	:- THIRD PARTY CLAI	M
Insured Veh.	GR 88U	Veh. Inspected	SMC 2030E
Policy No.	Z/18/VC00/101536	Coverage (\$)	0.00
Claim No.	18/19/19/VC00/021599	Excess (\$)	0.00
Assign From	GERALD	Assign Date	05/04/2019
2.	Vehicle Parti	culars & Condition	
Make & Model	AUDI A3 SEDAN	c.c	999
Engine No.	HIDDEN	Year of Reg.	2018
Chassis No.	WAUZZZ8V9J1067609	Colour	RED
Odometer	12797	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3.	Condit	ions of Tyres	
	Size	Make	Balance
R/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm
L/H Front Tyre	205/55 R16	BRIDGESTONE	6 mm
R/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm
L/H Rear Tyre	205/55 R16	BRIDGESTONE	6 mm
4.	Descripti	on of Damages	
THE VEHICLE SI	JSTAINED DAMAGES AT THE N/S DETAILS.	S BODY.	
5.	Genera	I Information	
Accident Date	10/03/2019	Inspection Date	09/04/2019
Survey held at	PREMIUM AUTOMOBILES PTE	LTD	
	55 UBI ROAD 1 . SINGAPORE 408699		
5a.	R	emarks	WIT SERVICE AND
	ON WAS CONDUCTED ON A WIT ICE TO YOUR INSTRUCTIONS, V		
5b.	Estimate	Days of Repair	
ESTIMATED NO	RMAL PERIOD FOR REPAIR:	13 Working Da	iys



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 2030E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR FENDER -LH (SN)	DENTED	2,110.00	2,110.00
1	REAR WINDOW (SN)	NECESSARY	742.00	741.50
1	REAR SIDE WINDOW -LH (SN)	NECESSARY	520.00	519.50
1	REAR DOOR -LH (SN)	DENTED	2,279.00	2,279.00
1	REAR OUTER DOOR SEAL -LH (SN)	NECESSARY	146.00	146.00
1	BONDING AGENT (SN)	NOT NECESSARY	45.00	
1	CLEANING SOLUTION (SN)	NOT NECESSARY	65.00	
1	APPLICATOR (SN)	NOT NECESSARY	7.00	
1	REAR DOOR ATTACHMENT PARTS (SN)	NOT NECESSARY	117.00	
1	REAR DOOR CATCH -LH (SN)	NOT NECESSARY	85.00	
1	REAR REINFORCEMENT FOR C-PILLAR (SN)	NOT NECESSARY	176.00	
1	ACRYLIC SEALANT (SN)	NECESSARY	180.00	180.00
1	CAVITY WAX (SN)	NECESSARY	140.00	140.00
1	STONE CHIP (SN)	NECESSARY	180.00	180.00
- 1	METAL FILLER POWDER (SN)	NECESSARY	280.00	280.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	200.00	200.00
1	1/4 GLASS SEALANT (SN)	NECESSARY	100.00	100.00
1	SUNDRIES (SN)	NOT NECESSARY	800.00	
			8,172.00	6,876.00
	LABOUR			
	TO INSTALL SOLAR FILM.		400.00	400.00
	TO REMOVE AND REINSTALL REAR PARKING AID .CHECK FUNCTION.		280.00	280.00
	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI- LOCK SYSTEM AND POWER WINDOW DEVICES .INSPECT FOR DAMAGES.		280.00	280.00
	TO RENEW REAR WINDSCREEN AMD LHS 1/4 GLASS TO FACILITATE FENDER RENEWAL.		600.00	600.00
	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.		1,400.00	1,400.00

Report Ref No. CC4/LPC19006096/Aea3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	TO REMOVE AND REINSTALL REAR SEAT ,BAKC REST ,HAT TRAY,ABCD PILLAR TRIMS ,LUGGAGE COMPARTMENT TRIMS.DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.		1,400.00	1,400.00
	TO DISMANTLE REAR BUMPER ,LHS REAR DOOR AND REAR LID.CUT OUT AND WELD LHS REAR FENDER AND LHS REAR INNER SIDE PANEL TO RENEW LHS REAR DOOR .RE-ORGANIZE CRASH MANAGEMENT COMPONENTS .REINSTALL REMOVED.		7,200.00	4,200.00
	TO RESPRAY LHS REAR DOOR LHS REAR FENDER LHS SILL PANEL, LHS REAR INNER SIDE PANEL, DOOR ENTRANCES , ROOF CHANNEL , DRAIN PANEL AND END PANELLING .TO CARRY OUT STONE CHIP TREATMENT AND JOINT SEALER WORKS.		5,000.00	3,600.00
	TO CARRY OUT DIAGNOSTIC CHECK.		192.00	192.00
			16,752.00	12,352.00
	GRAND TOTAL		24,924.00	19,228.00

19,228.00

Report Ref No. CC4/LPC19006096/Aea3n2



ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whetevers, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, sloes so at his or her own risk.