

27/3/2017

ASS. REC. BY:

REF: CS3/LPC/1802/249/R1803-1 n2  
Special Instruction:

Surveyor:

*Ravi*

ASSIGNMENT (Office)

From (Person):

*Ong Li*

of

*LPC*

Date/Time

*05/04/2019*

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

*SJV 2755H*

Insured:

*GBG1016M*

at Workshop m/s

*Benefit Autocare*

Tel:

*8444 6556 / 9489 4845*

of

*11 Kaki Bkt Rd #01-02 Eunus Tehrolink*

Policy No:

Claim No:

*18/18/18/KCOO/021146*

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

*26/11/18*

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS *up?*

Date/Time:

*Apr 23/11/18*

Person Contacted:

*ERIC*

Vehicle ID:

*(OUT)*

Date/Time	Action/Instruction (X) Estimate
	<i>SJV 2755H - X</i>
	<i>GBG1016M - CS/E/G117017959/Kybe2</i>
	<i>DWA: 14/11/17</i>
<i>12/04/19</i>	<i>Submt L/s \$ 1,600/- @ 4 days</i>
	<i>(C\$ 1,200/- Red - 43%)</i>

RECEIVED 12 APR 2019

*[Signature]*

*12/4/2019*

Signature: *Jane*  
PRS

REF: *lpc*

2227H

ASSIGNMENT

From: Date: *26/11/18*

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: *SJV 2755H*  
at Workshop n/s: *Benefit Autocare*  
of: *11 kaki Bkt Rd 1 # 01-02*  
Insured: *Euros technolink*

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

*ERIC@9489 4845*

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val: Yes or No

CA / REV / REP. / 24 HRS *(up)*

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: *SJV 2755H* or Regn: *2010 / SVH*

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: *Subaru Legacy Sedan 2.0 c.c* *1994*

Colour: *Black* A/C: ☒ Insured / Std / NI / NA

Sp Reading: *096714* T/Radio: ☒ Insured / Std / NI / NA

Eng/No:

C/No: *JF1BM3KC2AG003696*

Gen. Cond: Good / ☒ Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: ☒ Nil / ☒ STD A/Rim or

Tyre Size: F: *205/60R16*

R:

BS / DUN / EXNOVA / GY / FS / LIZA ☒ MIC OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: *6* mm

R/Bal: *6* mm

L/Bal: *6* mm

L/Bal: *6* mm

D.O.A: *08/11/18*

D.O.I: *26/11/18* *1.33*

Survey held at: *BENEFIT AUTOCARE*

Des. of Damages: Frt / ☒ Rcs / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

*Submit PRS report*

RECEIVED 28 NOV 2018

Date/Time: File Pass to?

*28/11/18*

1)

*Typist*

Date/Time: File Return to?

2)

☐

Prefl. Report

☐

Final Report

Days Of Repair: */*

Resurvey No. of Trip: */*

Survey Fee:

Transportation:

*/ S + R5, SI*

*/ Photos*

*/ Others*

*/*

TOTAL

Add Fee: ☐ Site Insp (\$

☐ Interview (\$

☐ Tech. Invs (\$

☐ Weekend (\$

Report Format:

*PRS*

Lump Sum / I.B.I: (\$

*450*

## Nivitha (LKK Auto)

---

**From:** ONG LI LI <llong@lonpac.com>  
**Sent:** Friday, 5 April 2019 4:00 PM  
**To:** Admin-D (LKKAuto)  
**Cc:** MT\_Claim\_SG  
**Subject:** RE: 2nd Notice to Conduct Pre-repair Survey; Our Ref: SJV 2755H/BA/jp/ps - Your Ref: 18/18/18/VC00/021146 [External General]  
**Attachments:** 21146 TP SURVEY.pdf


### Lonpac External - General

Dear Nivitha

Attached is the TP survey report.

Please let us have your surveyor's review/report.

Regards,  
Ong Li Li  
Senior Claims Executive | Lonpac Insurance Bhd  
300 Beach Road #17-04/07 The Concourse Singapore 199555  
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706



*Lonpac External - General data is for internal / external use.*

---

**From:** Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]  
**Sent:** Friday, 23 November, 2018 4:52 PM  
**To:** ONG LI LI  
**Cc:** MT\_Claim\_SG  
**Subject:** RE: 2nd Notice to Conduct Pre-repair Survey; Our Ref: SJV 2755H/BA/jp/ps - Your Ref: 18/18/18/VC00/021146

Dear Li Li,

Noted, with thanks.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** ONG LI LI [mailto:llong@lonpac.com]  
**Sent:** Friday, 23 November 2018 4:49 PM  
**To:** Admin-D (LKKAuto) <[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)>  
**Cc:** MT\_Claim\_SG <[mt\\_claim@lonpac.com](mailto:mt_claim@lonpac.com)>  
**Subject:** RE: 2nd Notice to Conduct Pre-repair Survey; Our Ref: SJV 2755H/BA/jp/ps - Your Ref: 18/18/18/VC00/021146

Dear Nivitha

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	09/11/2018 17:10
Date Of Accident	08/11/2018 18:00
Exact Location Of Accident	ALEXANDRA RD BESIDE ALEXANDRA POINT BUILDING
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJV2755H
<b>Insured/Policyholder</b>	
Name Of Registered Owner	TAN KIM WATT EDWIN
NRIC No	S6832227H
Email Address	EDWINTAN1621@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-98232920
Alternative Phone No	OTHERS-98232920

### Vehicle Particulars

Manufacturer	SUBARU
Model	LEGACY 2.0A
Exact Purpose for which vehicle was being used at time of accident	WORK PURPOSE
Are you claiming under your own Insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5102455895
Cover Note Number	

### Driver

Name of Driver	TAN KIM WATT EDWIN
NRIC No	S6832227H
Date Of Birth	29/08/1968
Occupation	OUTDOOR
Date Of Driving Pass	20/06/1994
Driving Experience	24 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98232920
Fax Number	
Contact Number	OTHERS-98232920
Email Address	EDWINTAN1621@YAHOO.COM.SG



Address BLK 148 SERANGOON NORTH AVE 1  
#03-463  
Postcode 550148  
Was driver an employee of the Insured's Company NO  
If No, Relationship of the Driver with the Insured OWNER  
Vehicle Registration Number of Driver's Own Vehicle -  
Vehicle -  
Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR  
Weather Conditions CLEAR  
Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO  
Number of vehicles involved in the accident 2  
Was any body injured in the Accident? YES  
Was any injured conveyed to hospital by ambulance? NO  
Was any other material or property damaged? YES  
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
Number of Passengers (Including Driver) 3  
Passenger 1  
NAME: : NA  
GENDER: : MALE  
Passenger 2  
NAME: : NA  
GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police? YES  
If Yes, Please state which Police Station  
Police Station Name SERANGOON NORTH NEIGHBOURHOOD POLICE POST  
Police Station Address ROAD: BLK 108 SERANGOON NORTH AVENUE 1 #01-709 , POSTCODE: 550108 , COUNTRY: SINGAPORE  
Police Station Contact TEL NO: 1800-2849099 - FAX NO: 63431742  
Was notice of intended Prosecution given? NO  
If Yes, against whom?

#### Circumstances of Accident

REFER POLICE REPORT

#### Attachment(s)

Are accident photos available for attachment? YES  
Was there any video captured by Car Camera? NO  
Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBG1016M  
Vehicle Make/Model/Colour  
Details Of Properties FRONT  
Vehicle Category COMMERCIAL VEHICLE  
Name of Driver

NRIC/Passport Number

Contact Number

84947387

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name

TAN KIM WATT EDWIN

Approximate Age

Injuries Sustain

REFER REPORT

Injured person in which vehicle?

SJV2755H

Were seat belts worn?

YES

Was this injured conveyed to hospital by ambulance?

NO

Address

Postcode

## Sketch Plan Pg. 1

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the Insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (c) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature

Date & Time: 9/11/2018  
1315pm

(GIA/IVC SketchPlan Form - F)



Driver's Signature  
(If driver is not the policyholder)


Date & Time: 9/11/2018  
1315pm



Reporting Centre Personnel's Signature

Name:  
NRIC/FIN No.:

# Sketch Plan #2 Pg. 1



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

SEE ATTACH.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 9/11/2018

13/5 pm

Driver's Signature

(if driver is not the policyholder)

Date & Time: 9/11/2018

13/5 pm

Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:



**Sketch Plan #3 Pg. 1**

**Date : 8<sup>th</sup> Nov 2018**

**Time : 6pm**

**Location : Alexandra Road(Beside Alexandra Point Building) toward Queensway**

**Subject : Car Accident Involve between SJV2755H and GBG1016M**

On 8<sup>th</sup> Nov 2018 at 6pm along Alexandra Road(Beside Alexandra Point Building) toward Queensway at middle lane when my vehicle SJV2755H was moving slowing due to heavy traffic congestion along the Alexandra Road, suddenly the white van of vehicle number GBG1016M bang into my rear and cause damage to my rear bumper. Before I go and check the accident, I on the hazard light and ask my 2 Grab Riders(Passenger) whether they are okay cause during the accident I'm on Grab booking to ferry my 2 Grab riders to Dempsey Road. The 2 Grab riders replied and acknowledged they are fine hence I proceed to check my car condition. There are damages to my rear bumper, I took some photos and as well exchange phone numbers with the driver of GBG1016M(hp 8494 7387) . As not to cause traffic congestion to other road users, we proceed to embark our way and settle the accident via SMS communication.

Attach are the accident photos involve SJV2755H and GBG1016M and also the SMS corresponds.

Best Regards;

Edwin Tan Kim Watt

Mobile : 98232920

Vehicle : SJV2755H



**SINGAPORE  
POLICE FORCE**



T/20181109/2099

Police Station Of Origin:  
Serangoon North NPP  
108 Serangoon North Ave 1 #01-709  
SINGAPORE 550108  
Tel No: 1800-2849999

1 of 3

Report No. T/20181109/2099

## REPORT OF A TRAFFIC ACCIDENT

Date/Time Report Made: 09/11/2018 15:35		Vide Report No.:	Station Diary No.: 9
<b>Informant's Particulars</b>			
Name of Informant: TAN KIM WATT EDWIN		Address: APT BLK 148 SERANGOON NORTH AVENUE 1 #03-463 SINGAPORE 550148	
ID Type / ID No.: NRIC NO / S6832227H		Contact No.: Home/Office: Mobile: 98232920	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 50	Date of Birth: 29/08/1968	Type of Informant: Driver
Race: Chinese		Language: English	Institution / School Name:
Occupation: GRAB DRIVER		Driving Licence Information: Class: Date of Expiry:	

<b>General Information of the Accident</b>				
Type of Accident:	Injury Others	Drink Drive: No	Date/Time of Accident: 08/11/2018 18:00	Type of Location: Straight Road
Location: Along Road 1 Traveling Toward Road 2 ALEXANDRA ROAD QUEENSWAY Beside Alexandra Point Building				
Weather: Clear		Road Surface: Dry	Road Speed Limit:	
Traffic Flow: Two Way		Traffic Control: Traffic Light - Working	Traffic Volume: Heavy	
Type of Collision: Between Moving Vehicles - Head To Rear			Anyone conveyed by ambulance: No	

<b>Details of Vehicle Involved</b>						
Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GBG1016M	Car					0
SJV2755H	Car	SUBARU	LEGACY SEDAN 2.0i AWD CVT ABS AIRBAGS	Black		2

**SINGAPORE  
POLICE FORCE**

T/20181109/2099

Police Station Of Origin:  
Serangoon North NPP  
108 Serangoon North Ave 1 #01-709  
SINGAPORE 550108  
Tel No: 1800-2849999

2 of 3

Report No. T/20181109/2099

## CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No.	Effective	Expiry Date
SJV2755H	NTUC Income Insurance Co-Operative Limited	5102455895	23/07/2018	22/07/2019

**Brief Details.**

On 08/11/2018 at about 1800hrs, I was driving my car SJV2755H, along Alexandra Road towards Queensway. It was heavy traffic then thus the traffic was slow. I was at the center lane near to Alexandra Point Building and was stationery. Suddenly, one van GBG1016M, came from behind and believed that he did not stop and hit onto the back of my car. I had 2 foreign passenger in my car at that point of time. After the hit, I checked on my passenger and they said they were alright. I then stepped out of my vehicle and checked on my car and there was 2 dent at the back of my bumper. I then exchanged particular with the van driver and as the traffic was heavy, I told him to discussed further through phone and we left to smoothed the traffic.

I thought that I was alright, however when it comes to the night, I felt pain at the back of my neck and I went to see the doctor and I got 4 days of MC. Thus I am making this report for insurance claim.



SINGAPORE  
POLICE FORCE



T/20181109/2099

Police Station Of Origin:  
Serangoon North NPP  
108 Serangoon North Ave 1 #01-709  
SINGAPORE 550108  
Tel No: 1800-2849999

3 of 3


Report No. T/20181109/2099

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report  
F /   
Sgt 2 TEO JING XIAN  
Singapore Police Force

Signature Of Interpreter:  
Not applicable

Officer In Charge Of Case:  
TP / AEIT /  
Sr Staff Sgt MOHAMAD ZULFAZDLI BIN  
ABDULLAH  
Contact No: 65476204

Authentication Stamp  
NP168

Signature Of Informant:



Date/Time:  
09/11/2018 15:35

Classification Of Case:



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

## VEHICLE INSPECTION REPORT

Report No. : PAS/TP/0751118

Date of Report : 08/02/2019

To : Mr Tan Kim Watt, Edwin  
C/o. 11 Kaki Bukit Road 1  
#01-02 Eunos Technolink  
Singapore 415939

Date of Assignment : 26/11/2018  
Report requested by : Mr Tan Kim Watt, Edwin  
Date of Accident : 08/11/2018  
Date of Inspection : 26/11/2018  
Claim No. : Third Party Claim  
Policy No. : -

### PARTICULARS OF DAMAGED VEHICLE

Vehicle Registration No. : SJV2755H  
Make & Model : Subaru Legacy  
Date of Registration : 19/01/2010  
Colour : Met. Black

Engine Capacity (cc) : 1994cc  
Mileage (km) : 96714km  
Chassis / Frame No. : JF1BM5KC2AG003696  
Engine No. : EJ20D914317

### TYRE CONDITION

Front LH : 6 mm  
Make : Michelin

Front RH : 6 mm  
Make : Michelin

Rear LH : 6 mm  
Make : Michelin

Rear RH : 6 mm  
Make : Michelin

Road wheels Type : Alloy

(The above represents the approximate remaining life of tyre treads)

### PRE-ACCIDENT CONDITION OF DAMAGED VEHICLE (Static tests only)

General Bodywork : Good  
Paintwork : Good  
Handbrake : Serviceable  
Footbrake : Serviceable  
Steering : Serviceable  
Apparent Engine Modification : Nil

### PLACE OF REPAIRER OFFICE/WORKSHOP

Location : M/s. Benefits Auto Care Private Limited  
11, Kaki Bukit Road 1, #01-02, Eunos Technolink, Singapore 415939

### ASSESSMENT

Repairer's Estimate : \$ 4,694.72  
Revised Amount : \$ 3,507.60  
Less Excess : \$ -  
Recommended Reserve : \$ 2,800.00 (Lump Sum)

Estimated Normal Period of Repairs : 6 Working Days

*Disclaimer: This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle involved. No liability or responsibility whatsoever shall be held by PROMINENT APPRAISER SERVICES PTE LTD for any reliance on this report by any third party.*





# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No : SJV2755H

Report No. : PAS/TP/0751118

## GENERAL REMARKS

WITHOUT PREJUDICE

### THE ASSIGNMENT

The survey was conducted at M/s. Benefits Auto Care Private Limited, 11, Kaki Bukit Road 1, #01-02, Eunost Technolink, Singapore 415939.

(Subsequent inspections have been conducted)

### POINT OF IMPACT

At the rear portion.

### DAMAGES

The boot lid, rear bumper, rear end panel, rear floor panel, rear chassis members, etc.

*Other parts were also found damaged. (See schedule for details)*

### ADJUSTMENT / RECOMMENDATION

We have inspected thoroughly each and every item on the repairer's estimate against the actual damaged found on the vehicle. We list the breakdown of our findings and our recommendation as per schedule attached.

Our adjusted amount for the cost of repairs is SGD \$3,507.60.

### CONCLUSION


The repairer has agreed to undertake the repairs at a lump sum of SGD \$2,800.00.

This inspection was conducted entirely on a 'Without Prejudice' basis. We have not given an authorization and/or instruction to the repairer to proceed with the repairs.

We hereby reverting the matter to you for your discretion on repairs.

Assuring you of our best services always.

Yours Truly,  
**Prominent Appraiser Services Pte Ltd**

  
**Andrew How**  
Automobile Appraiser  
MSAAA  
Licensed Appraiser



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simei St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvcs@hotmail.com

Business Reg. 201404434D

Vehicle No. : SJV2755H

Report No. : PAS/TP/0751118

## APPRAISEMENT SCHEDULE

S/No.	Qty	Parts Descriptions	Condition	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	1 pc	Rr bumper	Dented	\$ 723.00	\$ 723.00
2	6 pcs	Rr bumper clip	Necessary	\$ 18.00	\$ 18.00
3	2 pcs	Rr bumper retainer	Cracked/Necessary	\$ 54.00	\$ 54.00 XNN
4	2 pcs	Rr bumper side bracket	Cracked/Broken	\$ 94.00	\$ 94.00 47
5	1 pc	Rr bumper reinforcement	Dented	\$ 287.00	\$ 287.00
6	1 pc	Rr end panel	Dented/Distorted	\$ 545.00	\$ 545.00 XR
7	1 pc	Rr end panel garnish	Refit	\$ 184.00	\$ -
8	1 pc	Boot lid	Dented/Repair	\$ 612.40	\$ -
9	1 pc	Boot lid emblem (Logo)	Necessary	\$ 64.00	\$ 64.00
10	1 pc	Boot lid emblem (Subaru)	Necessary	\$ 30.00	\$ 30.00
11	1 pc	Boot lid emblem (Legacy)	Necessary	\$ 33.00	\$ 33.00
12	1 pc	Boot lid emblem (AWD)	Necessary	\$ 24.00	\$ 24.00
				\$ 2,668.40	\$ 1,872.00
Less Discount : 20%				\$ 533.68	20% \$ 374.40
List Parts Sub-Total :				\$ 2,134.72	\$ 1,497.60
1	1 set	Reverse sensor	Dented/Damaged	\$ 250.00	\$ 220.00
2	1 pc	Rr end panel sealant	Necessary	\$ 50.00	\$ 40.00 XNN
Special Nett Sub-Total :				\$ 300.00	\$ 260.00
Parts Total :				\$ 2,434.72	\$ 1,757.60



# PROMINENT APPRAISER SERVICES PTE LTD

Qualified Loss Adjusters And Motor Appraisers

Correspondence Address: 1 Simel St.3 #02-24 S(529890)

Mobile: 9295 2204 Fax: 6722 8508 Email: pasvos@hotmail.com

Business Reg. 201404434D

Vehicle No. : SJV2755H

Report No. : PAS/TP/0751118

S/No.	Labour Descriptions	Repairer's Estimate (S\$)	Our Assessment (S\$)
1	To remove and reinstall rear interior trims, garnishes, etc. for necessary repairs.	\$ 100.00	\$ 80.00 <i>40</i>
2	To check rear electrical wiring system.	\$ 50.00	\$ 20.00 <i>XV</i>
3	To remove, replace and reinstall rear reverse sensors & control unit.	\$ 60.00	\$ 50.00
4	To straighten, repair, realign on affected area and replace damaged parts.	\$ 1,000.00	\$ 770.00 <i>300</i>
5	To spray painting, blending on affected and adjacent area.	\$ 1,000.00	\$ 800.00 <i>400</i>
6	To spray anti-rust coating on new and affected panels.	\$ 50.00	\$ 30.00 <i>X</i>
Labour Total :		\$ 2,260.00	\$ 1,750.00 <i>790</i>
Total (Parts & Labour) :		\$ 4,694.72	\$ 3,507.60

## For Lump Sum Repairs

The final adjusted Lump Sum contract amount is \$ 2,800.00

Under normal circumstances, the repairs should be completed within a reasonable period of **6 Working Days.** (Exclude waiting days of PRI, Sunday, Public Holiday and awaiting of shipment for spare parts)

48 Photographs were taken at the time of inspection.

**N.B:** By accepting to carry out the repairs on a contract Lump Sum basis, the repairer shall have the prerogative and discretion to replace the damaged parts with new, used, OEM or reconditioned parts and/or to repair the vehicle on a roadworthy condition to the entire satisfaction of owner.

*Handwritten calculations:*  
980.80  
220.00  
790.00  
-----  
1990.80  
20%  
1592.64  
4/5 - 1,600  
-----  
4 days

Note: The revised estimate has been adjusted from a visual inspection. Any discrepancies or unseen damages should be notified to the company within 7 days from the date hereof. Otherwise this revised amount shall be deemed as valid.




# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD		Ref : CS3/LPC18021249/R1sd3n2-1		
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Date : 16-04-2019		
		Code : LPC2		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBG 1016M	Veh. Inspected	SVJ 2755H	
Policy No.		Coverage (\$)	0.00	
Claim No.	18/18/18/VC00/021146	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	05/04/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	SUBARU LEGACY SEDAN 2.0	c.c	1994	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	JF1BM5KC2AG003696	Colour	BLACK	
Odometer	96714	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/60 R16	MICHELIN	6 mm	
L/H Front Tyre	205/60 R16	MICHELIN	6 mm	
R/H Rear Tyre	205/60 R16	MICHELIN	6 mm	
L/H Rear Tyre	205/60 R16	MICHELIN	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	08/11/2018	Inspection Date	26/11/2018	
Survey held at	BENEFIT AUTO CARE PTE LTD 11 KAKI BUKIT ROAD 1 #01-02 SINGAPORE 415939			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJV 2755H

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	RR BUMPER	DENTED	723.00	723.00
6	RR BUMPER CLIP @\$3.00	NECESSARY	18.00	18.00
2	RR BUMPER RETAINER @\$27.00	NOT NECESSARY	54.00	-
2	RR BUMPER SIDE BRACKET @\$47.00	CRACKED / BROKEN	94.00	47.00
1	RR BUMPER REINFORCEMENT	DENTED	287.00	287.00
1	RR END PANEL	TO REPAIR SEE LABOUR	545.00	-
1	RR END PANEL GARNISH	REFIT	184.00	-
1	BOOT LID	TO REPAIR SEE LABOUR	612.40	-
1	BOOT LID EMBLEM (LOGO)	NECESSARY	64.00	64.00
1	BOOT LID EMBLEM (SUBARU)	NECESSARY	30.00	30.00
1	BOOT LID EMBLEM (LEGACY)	NECESSARY	33.00	33.00
1	BOOT LID EMBLEM (AWD)	NECESSARY	24.00	24.00
	LESS 20% DISCOUNT		-533.68	-245.20
			2,134.72	980.80
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET REVERSE SENSOR (SN)	DENTED / DAMAGED	250.00	220.00
1	RR END PANEL SEALANT (SN)	NOT NECESSARY	50.00	-
			300.00	220.00
<b><u>LABOUR</u></b>				
	TO REMOVE AND REINSTALL REAR INTERIOR TRIMS,GARNISHES,ETC.FOR NECESSARY REPAIRS.		100.00	40.00
	TO CHECK REAR ELECTRICAL WIRING SYSTEM.		50.00	20.00
	TO REMOVE,REPLACE AND REINSTALL REAR REVERSE SENSORS & CONTROL UNIT.		60.00	50.00
	TO STRAIGHTEN,REPAIR,REALIGN ON AFFECTED AREA AND REPLACE DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF RR END PANEL AND BOOT LID.		1,000.00	300.00
	TO SPRAY PAINTING,BLENDING ON AFFECTED AND ADJACENT AREA.		1,000.00	400.00

Report Ref No. CS3/LPC18021249/R1sd3n2-1





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY ANTI-RUST COATING ON NEW AND AFFECTED PANELS.	NOT NECESSARY	50.00	-
			2,260.00	810.00
	<b>GRAND TOTAL</b>		<b>4,694.72</b>	<b>2,010.80</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>1,600.00</b>

Report Ref No. CS3/LPC18021249/R1sd3n2-1

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.