

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Jowyn Tay Mei Ling

Date: 09 Apr 2019

Preliminary Advice

Insured Vehicle No : GBD4301K

TP Vehicle No : SGJ3215S

Make : NISSAN SUNNY

Date of Inspection : 05/04/2019

Inspection At : Abwin Service Pte Ltd (HQ)

No. 8 Kaki Bukit Avenue 4, #07-48 Premier@Kaki Bukit Gate 2
Singapore 415875

Accident Date : 04/04/2019

Assignment Date : 05/04/2019

Est. Duration of Repair : 6 days

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,224.88
Revised Amount	:S\$	4,106.91
Check Items (Estimated)	:S\$	0.00
Total	:S\$	4,106.91
Lump Sum Repair	:S\$	3,800.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(X) The above survey was conducted on a 'without prejudice' basis.