



3A Automobile Pte Ltd

Office Address No 120 Lower Delta Road #02-15 Singapore 169206 Tel: 6223 1122 Fax: 6738 6666

Estimate Report

To Claims Department
Attn: Claims Officer

Tel: 68804625
Fax: motor_survey@axa.com.sg

Policy Number: 999995433/100742918
Vehicles Number: SJR 8431 Z
Make and Model: Toyota Vios 1.5 J (A)
Date Of Accident: 06.08.2016
Time Accident: 08.30AM

Attn: Motor Claim Department
Estimated Repairs Costs
Unit List Items

1	pc	Rear Bumper	\$	491.95	\$	491.95	06-
1	pc	Spare Tyre Panel	\$	669.70	\$	669.70	X
1	pc	Tail Lamp - RHS	\$	287.90	\$	287.90	CRA -
1	pc	Boot Lid Lock	\$	95.60	\$	95.60	AA -
1	pc	Rear End Panel	\$	513.30	\$	513.30	R
1	pc	Rear End Panel Inner Garnish	\$	210.75	\$	210.75	T x an
1	pc	Rear Bumper Bracket - RHS (Big)	\$	84.90	\$	84.90	na -
1	pc	Rear Bumper Bracket - RHS (Small)	\$	45.70	\$	45.70	na -
10	pc	Bumper Clips	\$	3.50	\$	35.00	na -
1	pc	Weatherstrip	\$	165.95	\$	165.95	na -
1	pc	Exhaust Tail End	\$	65.90	\$	65.90	BT -
1	pc	Rear Boot Emblem - Toyota Logo	\$	20.20	\$	20.20	na -
1	pc	Rear Boot Emblem - J	\$	35.30	\$	35.30	na -
1	pc	Rear Boot Emblem - Vios	\$	20.20	\$	20.20	na -

S/Total
Less 20%
Reverse Sensor

1348.60
25%
1011.45
\$ 2,742.35
\$ 548.47
\$ 200.00
\$ 2,393.88

	Labour Charges To Remove and Renewing of Rear Boot, Rear Bumper, Brackets etc including welding, Dismantling, Fixing, Cutting Out of Necessary Joints	\$	650.00	450
	To Provide Skill Labour & Material to do Surface Treatment / Epoxy Treatment and to Respray with 2K Paint on the Affected Areas & Components with Oven Spray Booth Facilities	\$	800.00	600

Total

\$ 3,843.88

Yours faithfully,

3A Automobile Pte Ltd
Person To Contact: Alwin
Hp: 97868677

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Rasul

Hp 90010068

4 days

4/5

10/08/16 @ 10/10

email: rasul@lkkauto.com

Reply after repair