

22/03/2002

ASS. REC. BY:

REF: CS/CT1/9006123/7d362

Special Instruction:

Surveyor: Hwee Jue

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CT1

Date/Time:

5.4.19 11.42a.m

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SJR 8000J

Insured:

SKD 9543P

at Workshop m/s

William Auto

Tel:

67636811

of

Blk 3 Woodlands Road 391-B Yew Tee

Policy No:

Claim No:

SNM19D201510

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22.3.2019

CA / REV / REP. / REV 24 HRS

"wop"

H.O.D. Endorsement:

Date/Time:

5.4.19 12.00p.m

Person Contacted:

WilliamVehicle: IN/OUT

Date/Time

Action/Instruction

(✓)

Estimate

SJR 8000J - NA/INC 10021232/C2D.O.A - 21/10/2010SKD 9543P - XConfirm lump sum \$3400f (Red: 10155.50; 76%)

Hwee Jie

REF: CTI

## ASSIGNMENT

From \_\_\_\_\_ Date \_\_\_\_\_

Estimated Cost \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SJR 8000 JYr Regn: 28 Jan 2011Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or \_\_\_\_\_

Make: BMW 535i c.c. 2979Colour: White A/C: Insured / Std / NI / NASp. Reading: 127443 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: WBAFR72020C580658Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 275/40R19

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or \_\_\_\_\_

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 22/3/19 D.O.I. 5/4/19Survey held at William AutoDes. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Hwee Jie,  
PLS see my remarks.

Not yet finalized

RECEIVED 10 SEP 2019

Date/Time. File Pass to?

1) 91A Typist

Date/Time. File Return to?

2)

Report Format :

Lump Sum / L.B.I. (\$)

☐ : Preli. Report  
☒ : Final ReportDays Of Repair: 4Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation

) S + PS (\$)

) Photos

) Other:

TOTAL

220220

## Nivitha (LKK Auto)

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Friday, 5 April 2019 11:42 AM  
**To:** William Auto  
**Cc:** assignments  
**Subject:** RE: SJR8000J / skd9543p-cntaiping ACC ON 22-03-19 FW: Message from KMBT\_C364e / OUR REF: SNM19D201510

Dear Sir,

We will pri.

Dear LKK,

Pls pri.

### Chong Boon Sen

Claims Executive  
Department

### China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** William Auto [mailto:[waplsp21@singnet.com.sg](mailto:waplsp21@singnet.com.sg)]  
**Sent:** Thursday, 4 April, 2019 6:34 PM  
**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Subject:** RE: SJR8000J / skd9543p-cntaiping ACC ON 22-03-19 FW: Message from KMBT\_C364e / OUR REF: TBA

We CHOOSE- Kelvin Ang  
PLEASE ARRANGE asap Vehicle is in our workshop< tomorrow is friday  
THANK YOU  
WILLIAM aNG

---

**From:** Chong Boon Sen [mailto:[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)]  
**Sent:** Thursday, 4 April, 2019 5:28 PM  
**To:** William Auto <[waplsp21@singnet.com.sg](mailto:waplsp21@singnet.com.sg)>  
**Cc:** Angie Foo <[angie.foo@sg.cntaiping.com](mailto:angie.foo@sg.cntaiping.com)>  
**Subject:** RE: SJR8000J / skd9543p-cntaiping ACC ON 22-03-19 FW: Message from KMBT\_C364e / OUR REF: TBA

Without Prejudice

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Dear Angie,

For your registration.

Thank you.

### **Chong Boon Sen**

Claims Executive  
Department

#### **China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

---

**From:** William Auto [<mailto:waplsp21@singnet.com.sg>]  
**Sent:** Thursday, 4 April, 2019 5:12 PM  
**To:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>  
**Subject:** SJR8000J / skd9543p-cntaiping ACC ON 22-03-19 FW: Message from KMBT\_C364e

Dear Sir / Mdm  
MOTOR CLAIMS DEPT.

PLEASE REFER TO nima PROTOCOL ARRANGE YOUR APPOINTED 10 LISTED SURVEYOR for us to choose  
Thank you  
WILLIAM Ang

**From:** [waplsp21@singnet.com.sg](mailto:waplsp21@singnet.com.sg) [<mailto:waplsp21@singnet.com.sg>]  
**Sent:** Thursday, 4 April, 2019 4:32 PM  
**To:** [waplsp21@singnet.com.sg](mailto:waplsp21@singnet.com.sg)  
**Subject:** Message from KMBT\_C364e

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

## Denise Tay (LKKAuto)

---

**From:** TG Lim (LKK Auto)  
**Sent:** Friday, 6 September 2019 11:50 AM  
**To:** William Auto  
**Cc:** Denise Tay (LKKAuto)  
**Subject:** RE: BMW 535I

Dear William,

Thank you very much for agreeing to finalise the repair cost for the above-mentioned vehicle at \$3400.00 with 4 days repair duration.

Best Regards,  
**TG Lim | Automotive Assessor**  
**LKK Auto Consultants**  
Phone: 6256 3561 | Email: [TeowGuan@lkkauto.com](mailto:TeowGuan@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** William Auto [<mailto:wapisp21@singnet.com.sg>]  
**Sent:** Thursday, 5 September, 2019 6:18 PM  
**To:** TG Lim (LKK Auto) <[TeowGuan@lkkauto.com](mailto:TeowGuan@lkkauto.com)>  
**Subject:** RE: BMW 535I

\$3,500.0  
Thank you

---

**From:** TG Lim (LKK Auto) [<mailto:TeowGuan@lkkauto.com>]  
**Sent:** Thursday, 5 September, 2019 5:01 PM  
**To:** [wapisp21@singnet.com.sg](mailto:wapisp21@singnet.com.sg)  
**Cc:** Denise Tay (LKKAuto) <[denisetay@lkkauto.com](mailto:denisetay@lkkauto.com)>  
**Subject:** BMW 535I

Dear William,

We spoke earlier regarding the adjusted repair cost for the above-mentioned vehicle.

Hope you can agree to finalise this case at \$3400.00 with 4 days of repair duration.

We have tried our level best to adjust the repair cost to a justifiable amount.

Thank you for your understanding.

Best Regards,  
**TG Lim | Automotive Assessor**  
**LKK Auto Consultants**  
Phone: 6256 3561 | Email: [TeowGuan@lkkauto.com](mailto:TeowGuan@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## TG Lim (LKK Auto)

---

**From:** William Auto <waplsp21@singnet.com.sg>  
**Sent:** Thursday, 5 September, 2019 6:18 PM  
**To:** TG Lim (LKK Auto)  
**Subject:** RE: BMW 535I

\$3,500.0  
Thank you

---

**From:** TG Lim (LKK Auto) [mailto:TeowGuan@lkkauto.com]  
**Sent:** Thursday, 5 September, 2019 5:01 PM  
**To:** waplsp21@singnet.com.sg  
**Cc:** Denise Tay (LKKAuto) <denisetay@lkkauto.com>  
**Subject:** BMW 535I

Dear William,

We spoke earlier regarding the adjusted repair cost for the above-mentioned vehicle.

Hope you can agree to finalise this case at \$3400.00 with 4 days of repair duration.

We have tried our level best to adjust the repair cost to a justifiable amount.

Thank you for your understanding.

Best Regards,  
**TG Lim | Automotive Assessor**  
**LKK Auto Consultants**  
Phone: 6256 3561 | Email: [TeowGuan@lkkauto.com](mailto:TeowGuan@lkkauto.com) | fax: 6256-4315  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## Denise Tay (LKKAuto)

---

**From:** William Auto <waplsp21@singnet.com.sg>  
**Sent:** Wednesday, 21 August 2019 5:25 PM  
**To:** Denise Tay (LKKAuto) *sur@lkkauto.com*  
**Subject:** disagreeSJR8000J : DSCN0340.jpg, DSCN0324.jpg, DSCN0325.jpg, DSCN0326.jpg, DSCN0327.jpg, DSCN0328.jpg, DSCN0329.jpg, DSCN0330.jpg, DSCN0331.jpg, DSCN0332.jpg, DSCN0333.jpg, DSCN0334.jpg, DSCN0335.jpg, DSCN0336.jpg, DSCN0337.jpg, DSCN0338.jpg, DSCN0339.jpg

Denise Tay

We disagree to your offer,

Hwee Jie was marked No 1 rear Boot Lid for given and pay, Why you cancelled away, We looking at \$4,450.00  
Revert to me asap Thank you William Ang

-----Original Message-----

**From:** Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]  
**Sent:** Wednesday, 21 August, 2019 11:14 AM  
**To:** William Auto <waplsp21@singnet.com.sg>; SUR <sur@lkkauto.com>  
**Subject:** RE: SJR8000J : DSCN0340.jpg, DSCN0324.jpg, DSCN0325.jpg, DSCN0326.jpg, DSCN0327.jpg, DSCN0328.jpg, DSCN0329.jpg, DSCN0330.jpg, DSCN0331.jpg, DSCN0332.jpg, DSCN0333.jpg, DSCN0334.jpg, DSCN0335.jpg, DSCN0336.jpg, DSCN0337.jpg, DSCN0338.jpg, DSCN0339.jpg

Dear William,

Lump sum \$3300 offer , 4days

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sur@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

**From:** William Auto <waplsp21@singnet.com.sg>  
**Sent:** Tuesday, 18 June 2019 6:13 PM  
**To:** SUR <sur@lkkauto.com>; Hwee Jie (LKK Auto) <hweejie@lkkauto.com>  
**Subject:** SJR8000J : DSCN0340.jpg, DSCN0324.jpg, DSCN0325.jpg, DSCN0326.jpg, DSCN0327.jpg, DSCN0328.jpg, DSCN0329.jpg, DSCN0330.jpg, DSCN0331.jpg, DSCN0332.jpg, DSCN0333.jpg, DSCN0334.jpg, DSCN0335.jpg, DSCN0336.jpg, DSCN0337.jpg, DSCN0338.jpg, DSCN0339.jpg

SJR8000J after repair photos for your kind perusal Thank you  
William Ang

Your message is ready to be sent with the following file or link  
attachments:

DSCN0340.jpg  
DSCN0324.jpg  
DSCN0325.jpg  
DSCN0326.jpg

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	25/03/2019 10:44
Date Of Accident	22/03/2019 10:35
Exact Location Of Accident	WOODLANDS CUSTOM TOWARDS JB
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJR8000J
<b>Insured/Policyholder</b>	
Name Of Registered Owner	NGAM CHER THONG
NRIC No	S1739730C
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-91264826
Alternative Phone No	OTHERS-98167472

### Vehicle Particulars

Manufacturer	BMW
Model	335i

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

### Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5099956238
Cover Note Number	

### Driver

Name of Driver	YONG SUK CHIN
NRIC No	S8075827H
Date Of Birth	07/09/1980
Occupation	INDOOR
Date Of Driving Pass	24/11/2003
Driving Experience	15 YEARS AND 3 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91264826
Fax Number	
Contact Number	
Email Address	NOEMAIL



Address	10A JALAN HIKAYAT
Postcode	769888
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACHMENT

#### Attachment(s)


Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SKD9543P
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	91879906
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

## Sketch Plan #2

### SKETCH PLAN



A - SJR 8000J

B - SKD 9543P

### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

While I was driving my car at woodland  
cotton towards TB. There is a heavy jam. However  
vehicle B which is behind me suddenly bang my  
rear of vehicle.

### DECLARATION

I/We declare the foregoing particulars are true in every respect.

Police Officer's Signature  
Date & Time

Driver's Signature  
(If Driver is not the police officer)  
Date & Time

Reporting Centre Personnel's Signature &  
Name  
Date & Time

## Sketch Plan

### SKETCH PLAN

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
Designation:

> Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	9730C
<b>Vehicle Details</b>	
Vehicle No.:	SJR8000J
Vehicle to be Exported:	No
Intended Deregistration Date:	08 Apr 2019
Vehicle Make:	B.M.W.
Vehicle Model:	535I A
Primary Colour:	White
Manufacturing Year:	2010
Engine No.:	07827636N55B30A
Chassis No.:	WBAFR72020C580658
Maximum Power Output:	225.0 kW (301 bhp)
Open Market Value:	\$66,807.00
Original Registration Date:	28 Jan 2011
First Registration Date:	28 Jan 2011
Transfer Count:	2
Actual ARF Paid:	\$66,807.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jan 2021
PARF Rebate Amount:	\$36,743.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	27 Jan 2021
COE Category:	B - Car (1601cc & above)
COE Period(Years):	10
QP Paid:	\$47,890.00
COE Rebate Amount:	\$8,625.00
<b>Total Rebate Amount:</b>	<b>\$45,368.00</b>

The information contained herein is correct as at 08 Apr 2019

OK

M/S : CHINA TAIPING INSURANCE (S) PTE LTD  
 3 ANSON ROAD  
 #15-00 SPRINGLEAF TOWER  
 SINGAPORE 079909  
 TEL: 63896174 FAX: 62247175  
 ATTN: Motor Claim Department  
 Your Ref No: SJR8000J  
 Claim Type: Third Party  
 Accident Date: 22/03/2019  
 TP Veh Reg No: SKD9543P

Estimate No: EST1900910  
 Date: 29 Mar 2019  
 Policy No: 5099956238  
 Veh Reg No: SJR8000J  
 Make/Model: B.M.W. 535I A  
 Chassis No: WBAFR72020C580658  
 Engine No: 07827636N55B30A  
 Reg. Date: 28/01/2011

### Estimate Repair Cost to Vehicle No : SJR8000J

Description	U/Price	Quantity	Cost S\$	Amount S\$
<b>Special Net</b>				
1 REAR BOOT LID <del>535</del> <del>REPAIR</del> <del>DEF</del> Repair.		1 PC	1,594.00	1,594.00 X
2 REAR BOOT LID '535' EMBLEM nec		1 PC	75.80	75.80 /
3 REAR BOOT LID COVER 'LOGO' nec		1 PC	75.80	75.80 /
4 REAR BOOT LID INNER LOCK SUC X		1 PC	276.20	276.20 X
5 REAR BOOT LID LOCK CATCH SUC X		1 PC	103.20	103.20 X
6 REAR BUMPER DEF		1 PC	1,442.25	1,442.25 /
7 REAR BUMPER CLIPS nec		1 SET	165.00	165.00 30/
8 REAR BUMPER REFLECTORS - (LH) - RH 3 CRA		12 PC	48.85	97.70 48.85
9 REAR BUMPER TOWING COVER nux		1 PC	28.60	28.60 X
10 REAR BUMPER REVERSE SENSOR - BMW shorted		2 PCS	249.30	200 498.60 /
11 REVERSE SENSORS Original BMW HOUSING nec		2 PCS	39.00	156.00 78/
12 REAR BUMPER REINFORCEMENT BT		1 PC	672.00	672.00 /
13 REAR BUMPER REINFORCEMENT BRACKET/ADAPTER 1 nux		2 PC	157.00	314.00 X
14 REAR BUMPER CENTRE BRACKET 3 CRA		12 PC	289.00	578.00 289/
15 REAR BUMPER BRACKETS (LH) - RH 3 CRA		12 PCS	165.00	330.00 165/
16 REAR BUMPER LOWER CENTRE GUIDE 3 CRA		1 PC	89.00	89.00 /
17 REAR BUMPER UNDER COVER GARNISH 3 nux		1 PC	278.00	278.00 X
18 REAR BUMPER LOWER COVER GARNISH CLIPS 3 nec		1 SET	75.00	30 75.00 /
19 REAR END PANEL 3 Repair X		1 PC	1,398.20	1,398.20 X
20 REAR END PANEL TOP GARNISH 1 nux		1 PC	178.00	178.00 X
21 REAR END PANEL TOP GARNISH CLIPS 3 nux		1 SET	95.00	95.00 X
22 REAR EXHAUST PIPE - LH nux		1 PC	1,891.10	1,891.10 X
23 REAR EXHAUST PIPE CHROME PIPE - LH 3 nux		1 PC	195.45	195.45 X
24 REAR EXHAUST PIPE HEAT COVER 1 nux		1 PC	189.90	189.90 X
25 REAR EXHAUST PIPE MOUNTING nux		2 PC	29.35	58.70 X
				10,855.50 X
<b>Labour</b>				
26 TO REMOVE DAMAGED PARTS PANEL BEAT, STRAIGHTEN & RENEW AND REALIGHT PARTS TO THE SAME.		1 JOB	800.00	450 800.00 500
27 LABOUR TO REMOVE UPHOLSTERY, TRIM BOARD, INNER COVER GARNISH ENABLE NECESSARY REPAIR WORKS.		1 JOB	180.00	180.00 50
28 TO RESPRAY PAINTING ON REPLACEMENT PARTS AND OTHER AFFECTED AREAS		1 JOB	900.00	900.00 50
29 REMOVE EXHAUST PIPE SYSTEM, CHECK, REPLACE DAMAGED PARTS AND REFIT SAME.		1 JOB	250.00	250.00 600 X
30 WIRING JOB AND TO CHECK SENSOR WIRE FOR SAMRT OPENER AND REFIT THE SAME		1 JOB	140.00	140.00 40

3195.70  
 -10%  
 2876.13

M/S: CHINA TAIPING INSURANCE (S) PTE LTD  
3 ANSON ROAD

#15-00 SPRINGLEAF TOWER

SINGAPORE 079909

TEL: 63896174

FAX: 62247175

ATTN: Motor Claim Department

Your Ref No: SJR8000J

Claim Type: Third Party

Accident Date: 22/03/2019

TP Veh Reg No: SKD9543P

Estimate No: EST1900910

Date: 29 Mar 2019

Policy No: 5099956238

Veh Reg No: SJR8000J

Make/Model: B.M.W. 535I A

Chassis No: WBAFR72020C580658

Engine No: 07827636N55B30A

Reg. Date: 28/01/2011

**Estimate Repair Cost to Vehicle No : SJR8000J**

Description	U/Price	Quantity	Cost S\$	Amount S\$
31 LABOUR TO TRANSFER REAR DAMAGED BOOT LID COMPONENT AND MECHANISM TO NEW REAR BOOT LID SHELL		1 JOB	80.00	80.00
32 LABOUR TO APPLY/SPRAY ANTI RUST PROOFING WHERE IS NECESSARY.		1 JOB	150.00	150.00
			1260	2,500.00

Total S\$ 13,355.50

Add GST @ 7% 934.89

Total Amount payable S\$ 14,290.39

TOTAL: SINGAPORE DOLLAR FOURTEEN THOUSAND TWO HUNDRED NINETY AND CENTS THIRTY NINE ONLY

For WILLIAM'S AUTO PTE LTD

AUTHORISED SIGNATURE

P- 2876-13

L- 1260

4136-13

L/S - 3308-90

= 3300

3468/2

L/S 3400/2

Hwee Lian - LKK

25/4/19

L/S 4 days.

08/4/19

10:30

# WILLIAM'S AUTO PTE LTD

BLK c3 WOODLANDS ROAD 391-B YEW TEE INDUSTRIAL ESTATE SINGAPORE 677965

TEL: 67636811 FAX: 67632166 Email: wapls21@singnet.com.sg

GST:M2-0032987-2 RCB NO:A03151/1978Z

M/S : CHINA TAIPING INSURANCE (S) PTE LTD

3 ANSON ROAD

#15-00 SPRINGLEAF TOWER

SINGAPORE 079909

TEL: 63896174

FAX: 62247175

ATTN: Motor Claim Department

Your Ref No: SJR8000J

Claim Type: Third Party

Accident Date: 22/03/2019

TP Veh Reg No: SKD9543P

Estimate No: EST1900910

Date: 29 Mar 2019

Policy No: 5099956238

Veh Reg No: SJR8000J

Make/Model: B.M.W. 535I A

Chassis No: WBAFR72020C580658

Engine No: 07827636N55B30A

Reg. Date: 28/01/2011

## Estimate Repair Cost to Vehicle No : SJR8000J

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
<b>Special Net</b>				
1 REAR BOOT LID <del>REAR BOOT LID</del> OD / XR Δ		1 PC	1,594.00	1,594.00
2 REAR BOOT LID ' 523 1 ' EMBLEM nec /		1 PC	75.80	75.80
3 REAR BOOT LID COVER 'LOGO' nec /		1 PC	75.80	75.80
4 REAR BOOT LID INNER LOCK suc x		1 PC	276.20	276.20
5 REAR BOOT LID LOCK CATCH suc x		1 PC	103.20	103.20
6 REAR BUMPER DEF /		1 PC	1,442.25	1,442.25
7 REAR BUMPER CLIPS nec /		1 SET	165.00	165.00
8 REAR BUMPER REFLECTORS - LH - RH ?		2 PC	48.85	97.70
9 REAR BUMPER TOWING COVER nux		1 PC	28.60	28.60
10 REAR BUMPER REVERSE SENSOR - BMW shorted /		2 PCS	249.30	498.60
11 REVERSE SENSORS Original BMW HOUSING nec /		2 PCS	39.00	156.00
12 REAR BUMPER REINFORCEMENT ?		1 PC	672.00	672.00
13 REAR BUMPER REINFORCEMENT BRACKET/ ADAPTER ?		2 PC	157.00	314.00
14 REAR BUMPER CENTRE BRACKET ?		2 PC	289.00	578.00
15 REAR BUMPER BRACKETS LH - RH ?		2 PCS	165.00	330.00
16 REAR BUMPER LOWER CENTRE GUIDE ?		1 PC	89.00	89.00
17 REAR BUMPER UNDER COVER GARNISH ?		1 PC	278.00	278.00
18 REAR BUMPER LOWER COVER GARNISH CLIPS ?		1 SET	75.00	75.00
19 REAR END PANEL ?		1 PC	1,398.20	1,398.20
20 REAR END PANEL TOP GARNISH ?		1 PC	178.00	178.00
21 REAR END PANEL TOP GARNISH CLIPS ?		1 SET	95.00	95.00
22 REAR EXHAUST PIPE - LH nux		1 PC	1,891.10	1,891.10
23 REAR EXHAUST PIPE CHROME PIPE - LH ?		1 PC	195.45	195.45
24 REAR EXHAUST PIPE HEAT COVER nux		1 PC	189.90	189.90
25 REAR EXHAUST PIPE MOUNTING nux		2 PC	29.35	58.70
				10,855.50

### Labour

26 TO REMOVE DAMAGED PARTS PANEL BEAT, STRAIGHTEN & RENEW AND REALIGHT PARTS TO THE SAME.	1 JOB	800.00	420 800.00
27 LABOUR TO REMOVE UPHOLSTERY, TRIM BOARD, INNER COVER GARNISH ENABLE NECESSARY REPAIR WORKS.	1 JOB	180.00	180.00 50
28 TO RESPRAY PAINTING ON REPLACEMENT PARTS AND OTHER AFFECTED AREAS	1 JOB	900.00	900.00 50
29 REMOVE EXHAUST PIPE SYSTEM, CHECK, REPLACE DAMAGED PARTS AND REFIT SAME.	1 JOB	250.00	250.00 x
30 WIRING JOB AND TO CHECK SENSOR WIRE FOR SAMRT OPENER AND REFIX THE EAME	1 JOB	140.00	140.00 40

# WILLIAM'S AUTO PTE LTD

BLK c3 WOODLANDS ROAD 391-B YEW TEE INDUSTRIAL ESTATE SINGAPORE 677965

TEL: 67636811 FAX: 67632166 Email: wapls21@singnet.com.sg

GST:M2-0032987-2 RCB NO:A03151/1978Z

**M/S :** CHINA TAIPING INSURANCE (S) PTE LTD

3 ANSON ROAD

#15-00 SPRINGLEAF TOWER

SINGAPORE 079909

TEL: 63896174

FAX: 62247175

ATTN: Motor Claim Department

Your Ref No: SJR8000J

Claim Type: Third Party

Accident Date: 22/03/2019

TP Veh Reg No: SKD9543P

**Estimate No: EST1900910**

Date: 29 Mar 2019

Policy No: 5099956238

Veh Reg No: **SJR8000J**

Make/Model: B.M.W. 535I A

Chassis No: WBAFR72020C580658

Engine No: 07827636N55B30A

Reg. Date: 28/01/2011

## Estimate Repair Cost to Vehicle No : SJR8000J

Description	U/Price	Quantity	Cost	Amount
			<b>S\$</b>	<b>S\$</b>
31 LANOUR TO TRANSFER REAR DAMAGED BOOT LID COMPONENT AND MECHANISM TO NEW REAR BOOT LID SHELL		1 JOB	80.00	80.00 50
32 LABOUR TO APPLY/SPRAY ANTI RUST PROOFING WHERE IS NECESSARY.		1 JOB	150.00	150.00 20
				2,500.00

Total S\$ 13,355.50

Add GST @ 7% 934.89

Total Amount payable S\$ 14,290.39

TOTAL: SINGAPORE DOLLAR FOURTEEN THOUSAND TWO HUNDRED NINETY AND CENTS THIRTY NINE ONLY

For WILLIAM'S AUTO PTE LTD

AUTHORISED SIGNATURE

*[Signature]* 9/4/19.  
Hwee Lie - LKK  
5/4/19  
1/s 4 days.  
*[Signature]*

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Sep 2019		10 Sep 2019 14:18 <a href="#">Edit Adj Rpt</a>	<b>\$3,400.00</b> <a href="#">Edit Estimates</a>	<b>\$3,400.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by insurer]</span>									
Insured: -, Co. Reg. No.: -									
Main Claimant: <b>NGAM CHER THONG</b> , ID: S1739730C									
Vehicle Reg. No.: <b>SJR8000J</b>		Date of Loss: 22/03/2019 10:00 - :59 [97 Months and 22 Days From LTA Reg Date (Man Yr)]							
Claim Type: <b>TP / SNM19D201510C02</b>		Policy/Cover Note No.: <b>DMPCSN18010019011</b>							
Vehicle Reg. No. (Insured): <b>SKD9543P</b>		Policy No. (Claimant): <b>5099956238</b>							
		Excess: <b>\$0.00</b>							
Repairer: <b>Williams Auto Pte Ltd (HQ)</b> BLK 3 WOODLANDS ROAD 391-B YEW TEE INDUSTRIAL ESTATE, 677965 Woodlands - Tel: 67636811									
Handling Insurer: <b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Chong Boon Sen</b> ]									
Claimant's Insurer: <b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:									
Adjuster: <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>CHEN TSUE YEE</b> ] ... [Final Rpt due 19/09/2019]									
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									












## Claim Documents

\*SJR8000J (SNM19D201510C02)  
[SKD9543P]  
TP  
NGAM CHER THONG  
Mar 22 2019 10:00AM  
[-]  
Williams Auto Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	View <span>View in Browser</span>	
<b>Assessment Reports</b>				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (HQ)		Thumbnail	Print
1	25/03/19 10:48	Accident Statement		Load HTM	
<b>Photos/Images</b>				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (HQ)		Thumbnail	Print
1	25/03/19 10:47	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
2	25/03/19 10:47	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
3	25/03/19 10:47	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
4	25/03/19 10:47	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
5	25/03/19 10:47	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
6	25/03/19 10:47	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
7	25/03/19 10:47	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
8	25/03/19 10:47	Accident Photo [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	10/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
2	10/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
3	10/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
4	10/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
5	10/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
6	10/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
7	10/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
8	10/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
9	10/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
10	10/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
11	10/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
12	10/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
13	10/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
14	10/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
15	10/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
16	10/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
17	10/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
18	10/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
19	10/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
20	10/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
21	10/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
22	10/09/19 14:28	General View		Load JPG	<input checked="" type="checkbox"/>
23	10/09/19 14:28	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
24	10/09/19 14:28	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
25	10/09/19 14:28	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
26	10/09/19 14:28	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
27	10/09/19 14:28	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>
28	10/09/19 14:28	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (HQ)	Thumbnail	Print
29	10/09/19 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	10/09/19 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
31	10/09/19 14:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	10/09/19 14:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	10/09/19 14:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	10/09/19 14:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	10/09/19 14:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	10/09/19 14:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	10/09/19 14:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	10/09/19 14:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	10/09/19 14:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	10/09/19 14:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	10/09/19 14:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	10/09/19 14:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	10/09/19 14:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	10/09/19 14:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	10/09/19 14:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	10/09/19 14:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	10/09/19 14:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	10/09/19 14:30	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (HQ)	Thumbnail	Print
1	25/03/19 10:47	Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	25/03/19 10:47	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>

## Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (HQ)	Thumbnail	Print
1	25/03/19 10:48	Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (HQ)	Thumbnail	Print
1	25/03/19 10:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	25/03/19 10:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	25/03/19 10:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	25/03/19 10:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	25/03/19 10:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	25/03/19 10:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	25/03/19 10:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	25/03/19 10:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Yew Tee Automobile Tech Pte Ltd (HQ)	Thumbnail	Print
1	25/03/19 10:47	Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	25/03/19 10:47	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

## Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119006123/ETD3E2

Date: 27/09/2019

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN18010019011
Claimant Vehicle No :	SJR8000J	Insured Vehicle No :	SKD9543P
Date of Loss:	22/03/2019	Nature of Claim: TP	Claim No: SNM19D201510C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	<b>SJR8000J</b>	Engine No:	07827636N55B30A
Make & Model:	BMW 535i, 3.0 (A)	Chassis No:	WBAFR72020C580658
Reg. Date:	28/01/2011 (Man. Year: 2010)	Odometer:	177443 km
Colour:	White		
Engine Capacity:	2979 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	275/40 R19	Rear Tyre Size:	275/40 R19
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,855.50	2,876.13	7,979.37	73.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,500.00	1,460.00	1,040.00	41.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>13,355.50</b>	<b>4,336.13</b>	<b>9,019.37</b>	<b>67.53</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>3,400.00</b>		
<b>Nett Amount (S\$)</b>	<b>13,355.50</b>	<b>3,400.00</b>	<b>9,955.50</b>	<b>74.54</b>

## INSPECTION

Date of Assignment: 10/09/2019

Date Inspected: 05/04/2019 Inspected At:

Williams Auto Pte Ltd (HQ)  
BLK 3 WOODLANDS ROAD 391-B  
YEOW TEE INDUSTRIAL ESTATE  
Singapore 677965

Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.



## REPAIR DETAILS

<b>Reference</b>		
<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 27 Sep 2019)
<b>Parts:</b>	143	BMW 535I 3.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SJR8000J)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT LID	Repair	1,594.00 F	*- FN
2	1		*REAR BOOT LID 535 I EMBLEM	Necessary	75.80 F	*75.80 FN
3	1		*REAR BOOT LID COVER LOGO	Necessary	75.80 F	*75.80 FN
4	1		*REAR BOOT LID INNER LOCK	Serviceable	276.20 F	*- FN
5	1		*REAR BOOT LID LOCK CATCH	Serviceable	103.20 F	*- FN
6	1		*REAR BUMPER	Deformed	1,442.25 F	*1,442.25 FN
7	1		*SET REAR BUMPER CLIPS	Necessary	165.00 F	*30.00 FN
8	1		*REAR BUMPER REFLECTORS - LH - RH	N/S Cracked	97.70 F	*48.85 FN
9	1		*REAR BUMPER TOWING COVER	Not Necessary	28.60 F	*- FN
10	2		*REAR BUMPER REVERSE SENSOR - BMW	Shorted	498.60 F	*200.00 FN
11	1		*REAR BUMPER REINFORCEMENT	Bent	672.00 F	*672.00 FN
12	2		*REAR BUMPER REINFORCEMENT BRACKET / ADAPTER	Not Necessary	314.00 F	*- FN
13	1		*REAR BUMPER CENTRE BRACKET (2PCS)	Cracked (1Pcs Only)	578.00 F	*289.00 FN
14	1		*REAR BUMPER BRACKETS - LH - RH	N/S Cracked	330.00 F	*165.00 FN
15	1		*REAR BUMPER LOWER CENTRE GUIDE	Cracked	89.00 F	*89.00 FN
16	1		*REAR BUMPER UNDER COVER GARNISH	Not Necessary	278.00 F	*- FN
17	1		*SET REAR BUMPER LOWER COVER GARNISH CLIPS	Necessary	75.00 F	*30.00 FN
18	1		*REAR END PANEL	Repair	1,398.20 F	*- FN
19	1		*REAR END PANEL TOP GARNISH	Not Necessary	178.00 F	*- FN
20	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	95.00 F	*- FN
21	1		*REAR EXHAUST PIPE - LH	Not Necessary	1,891.10 F	*- FN
22	1		*REAR EXHAUST PIPE CHROME PIPE - LH	Not Necessary	195.45 F	*- FN
23	1		*REAR EXHAUST PIPE HEAT COVER	Not Necessary	189.90 F	*- FN
24	2		*REAR EXHAUST PIPE MOUNTING	Not Necessary	58.70 F	*- FN
25	1		*REVERSE SENSORS ORIGINAL BMW HOUSING (4PCS)	Necessary (2Pcs Only)	156.00 F	*78.00 FN

F=Franchise part. N=NetItemDisc.

Sub Total (\$\$) 10,855.50 3,195.70  
 - Nett Item Discount on N Items 0.00/10.00% (\$\$) 0.00 319.57

Total Parts (\$\$) 10,855.50 2,876.13

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE DAMAGED PARTS PANEL BEAT, STRAIGHTEN & RENEW AND REALIGHT PARTS TO THE SAME	New	800.00	700.00
2	LABOUR TO REMOVE UPHOLSTERY, TRIM BOARD, INNER COVER GARNISH ENABLE NECESSARY REPAIR WORKS	New	180.00	50.00
3	TO RESPRAY PAINTING ON REPLACEMENT PARTS AND OTHER AFFECTED AREAS	New	900.00	600.00
4	REMOVE EXHAUST PIPE SYSTEM, CHECK, REPLACE DAMAGED PARTS AND REFIT SAME	New	250.00	0.00
5	WIRING JOB AND TO CHECK SENSOR WIRE FOR SMART OPENER AND REFIX THE SAME	New	140.00	40.00
6	LABOUR TO TRANSFER REAR DAMAGED BOOT LID COMPONENT AND MECHANISM TO NEW REAR BOOT LID SHELL	New	80.00	50.00
7	LABOUR TO APPLY / SPRAY ANTI RUST PROOFING WHERE IS NECESSARY	New	150.00	20.00
Gross Labour Cost (\$\$)			<b>2,500.00</b>	<b>1,460.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >