

(08/1/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GLA / PR Seen


Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:



Consistent? : Yes or No

Consistent? : Yes or No

Res.: Yes or No

3 Val.: Yes or No

Vehicle: IN / OUT

Veh No:

Yr Regn:

Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

31-3-2022 A 14 14709 with 4291

10/4/19 4/5 4000 car p.m. with Ansys

(Red = 45061.23 / 56%)

* 6 repair days + 1 PRS = 7 days

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS \$

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX1035H

OW CHIH KAN

BLK 21B SIMEI STREET 4

07-47

SINGAPORE 528719

TEL : FAX :

PH : 97713330

ATTN :

ESTIMATE BILL

Number : EB00005125

Date : 08/04/2019

Case No : AD00010326

Vehicle No : SGT7762A

Chassis : MR053HY4204217507

Year of Mfr 2006

Policy No 5089634752-01

Model : TOYOTA VIOS

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	BOOTLID	1.0	580.57	25	435.43
2	BOOTLID EMBLEM	1.0	62.52	25	46.89
3	BOOTLID LOGO - 1.5E	1.0	45.54	25	34.16
4	BOOTLID LOGO - VIOS	1.0	58.10	25	43.58
5	TAIL LAMP LH	1.0	190.97	25	143.23
6	TAIL LAMP RH	1.0	190.97	25	143.23
7	TAIL LAMP CLIP LH	4.0	10.50	25	31.50
8	TAIL LAMP CLIP RH	4.0	10.50	25	31.50
9	BOOTLID WEATHERSTRIP	1.0	59.60	25	44.70
10	BOOTLID LOCK	1.0	78.90	25	59.18
11	REAR FENDER INNER GARNISH LH	1.0	310.84	25	233.13
12	END PANEL	1.0	783.90	25	587.93
13	END PANEL TOP GARNISH	1.0	99.11	25	74.33
14	SPARE TYRE PANEL	1.0	798.90	25	599.18
15	SPARE TYRE PANEL TOP TRIMBOARD	1.0	276.84	25	207.63
16	SPARE TYRE PANEL SIDE TRIMBOARD LH	1.0	188.50	25	141.38
17	SPARE TYRE PANEL SIDE TRIMBOARD RH	1.0	188.50	25	141.38
18	REAR BUMPER	1.0	281.90	25	211.43
19	REAR BUMPER RETAINER LH	2.0	171.45	25	257.18
20	REAR BUMPER RETAINER RH	2.0	171.45	25	257.18
21	REAR BUMPER BRACKET LH	1.0	121.10	25	90.83
22	REAR BUMPER BRACKET RH	1.0	121.10	25	90.83
23	REAR EXHAUST PIPE	1.0	781.45	25	586.09
24	REAR EXHAUST PIPE MOUNTING	1.0	43.70	25	32.78
25	REAR FENDER SHIELD RH	1.0	181.90	25	136.43
26	REAR FENDER SHIELD LH	1.0	181.90	25	136.43
27	REAR EXHAUST PIPE CHROME	1.0	191.58	25	143.69
List Price - Parts Sub Total					4,941.23
28	REAR FENDER LH - REPAIR	1.0			
29	REAR FENDER RH - REPAIR	1.0			
30	BOOTLID HINGE RH - REPAIR	1.0			
31	BOOTLID HINGE LH - REPAIR	1.0			
32	REAR NUMBER PLATE	1.0	30.00	0	30.00

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX1035H
OW CHIH KAN
BLK 21B SIMEI STREET 4
07-47
SINGAPORE 528719
TEL : FAX :
PH : 97713330
ATTN :

ESTIMATE BILL

Number : EB00005125
Date : 08/04/2019
Case No : AD00010326
Vehicle No : SGT7762A
Chassis : MR053HY4204217507
Year of Mfr : 2006
Policy No : 5089634752-01
Model : TOYOTA VIOS

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
33	REAR NUMBER PLATE HOLDER <i>Ref</i>	1.0	30.00	0	30.00
34	REVERSE SENSOR <i>Ref</i>	1.0	280.00	0	280.00
35	SPARE TYRE PANEL TOP CARPET <i>Ref</i>	1.0	250.00	0	250.00
Special Nett Price - Parts Sub Total					590.00
Parts Total					5,531.23
36	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	1,500.00	0	1,500.00
37	SPRAY PAINT ON THE AFFECTED AREAS	1.0	1,500.00	0	1,500.00
38	ANTI-RUST COATING	1.0	300.00	0	300.00
39	WIRING	1.0	80.00	0	80.00
40	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
Labour 1 Sub Total					3,530.00
SINGAPORE DOLLARS : NINE THOUSAND SIX HUNDRED NINETY-FIVE AND CENTS FIFTY-TWO ONLY					
Less Excess					0.00
SUBTOTAL					9,061.23
GST 7.00%					634.29
TOTAL					9,695.52

Date of accident : 06/04/2019 01:10 PM. Place : PIE > TUAS NEAR EXIT 12

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	1035H
Vehicle No.:	5GT7762A
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5E A
Primary Colour:	Black
Manufacturing Year:	2006
Engine No.:	1NZX519450
Chassis No.:	MR053HY4204217507
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,237.00
Original Registration Date:	24 Apr 2007
First Registration Date:	24 Apr 2007
Transfer Count:	0
Actual ARF Paid:	\$11,924.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
COE Expiry Date:	31 Mar 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$24,715.00
COE Rebate Amount:	\$14,709.00
Total Rebate Amount:	\$14,709.00

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 09 Apr 2019

OK

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	1035H

Vehicle Details

Vehicle No.:	SGT7762A
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	VIOS 1.5E A
Primary Colour:	Black
Manufacturing Year:	2006
Engine No.:	1NZX519450
Chassis No.:	MR053HY4204217507
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$12,237.00
Original Registration Date:	24 Apr 2007
First Registration Date:	24 Apr 2007
Transfer Count:	0
Actual ARF Paid:	\$11,924.00

Intended PARF Rebate Details

PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	31 Mar 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$24,715.00
COE Rebate Amount:	\$14,709.00
Total Rebate Amount:	\$14,709.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 09 Apr 2019

OK



DON'T FALL FOR HER ONLINE PURCHASE SCAM

CLICK TO FIND OUT MORE AT www.scamalert.sg



SINGAPORE POLICE FORCE



SafePay



Credit Card

Toyota Vios

Price Range

▼

Depreciation

▼

> 10 year(▼)

Vehicle Type

▼

Submit

Advanced Search

Home » Used Cars » Mandai Motor Trading » Toyota Vios 1.5A E (COE till 01/2022)

Toyota Vios 1.5A E (COE till 01/2022)

Overview Financial Insurance Accessories Similar Research Photos Map

Price	\$17,800		
Depreciation	\$6,410 /yr	Reg Date	18-Jan-2007 (2yrs 9mths 8days COE left)
Mileage	N.A.	Manufactured	2006
Road Tax	\$821 /yr	Transmission	Auto
Dereg Value	\$14,070 as of today (change)	OMV	\$12,237
COE	\$25,323	ARF	\$9,978
Engine Cap	1,497 cc	Power	80.0 kW (107 bhp)
Curb Weight	1,020 kg	No. of Owners	3
Type of Vehicle	Mid-Sized Sedan		

Features
View specs of the Toyota Vios (2003-2007)

Category
COE Car

Status
Available

Resources



Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free
Find out the market value of your existing car for free. Get started



Shortlist Compare Add note
Report Error More Actions


Seller Information

Company	Mandai Motor Trading
	• dealer's pricelist • 38 vehs sold 22 vehs available
Address	31 West Coast Highway #01-08/09 Search cars nearby this location
Location	West Coast Car Mart
Office No	67775585
Contact Person(s)	Darren 82233251 Heng Heng 90058812 Mr Ee 96275585

Posted on: 05-Apr-2019 | Last Updated on: 08-Apr-2019

Upfront Payment		> more Financial info
Transfer Fee	\$25	
Down Payment	\$5,340 (change)	Maximum 70% Loan
1st Instalment	\$417	Based on 3.75% interest rate

Compare



Toyota Vios Price Range Depreciation > 10 year(s) Vehicle Type Submit Advanced Search

Home > Used Cars > FredLink Auto Trading > Toyota Vios 1.5A E (COE till 08/2022)

Toyota Vios 1.5A E (COE till 08/2022)

Overview Financial Insurance Accessories Similar Research Photos Map

Price	\$23,800		
Depreciation	\$7,060 /yr	Reg Date	22-Aug-2007 (3yrs 4mths 12days COE left)
Mileage	145,000 km (12.5k /yr)	Manufactured	2007
Road Tax	\$821 /yr	Transmission	Auto
Dereg Value	\$15,299 as of today (change)	OMV	\$12,607
COE	\$22,700	ARF	\$13,868
Engine Cap	1,497 cc	Power	80.0 kW (107 bhp)
Curb Weight	1,095 kg	No. of Owners	3
Type of Vehicle	Mid-Sized Sedan		



Shortlist Compare Add note
Report Error More Actions

Features

1.5L 4-Cylinders In-Line 16-Valves DOHC VVT-i. 4 Speeds Auto Transmission. Electrical Retractable Side Mirrors With Indicators. SRS Airbags. View specs of the Toyota Vios (2007-2013)

Accessories

Leather Seats, CD/MP3 Player With Steering Control, 3M Solar Film, Reverse Sensor, Fog Lights, Knockdown Rear Seats, 4 Disc Brakes.

Description

Well Taken Care By The Previous Owner. Loan With High Trade In. Price Negotiable. Call Now Or Visit Our Showroom Today!

Category

COE Car

Status

Available

Resources



Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free
Find out the market value of your existing car for free. Get started

Seller Information

Company	FredLink Auto Trading * dealer's pricelist * 19 vehs sold 26 vehs available	
Address	31 West Coast Highway #01-01/02 Search cars nearby this location	
Location	West Coast Car Mart	
Office No	67788997 / 67788995	
Contact Person(s)	Mohammad Daniel Loh Freddy Lee	81121493 83938889 96923373

Posted on: 27-Mar-2019 | Last Updated on: 27-Mar-2019

Upfront Payment
Compare

> more Financial info

Print Received Message

This mail is associated with :

***SGT7762A (MCT19040165)**
[SHB4341J]

TP
OW CHIH KAN
Apr 6 2019 1:00PM

[~]
Hock Wah Motor Workshop Pte Ltd

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 05/08/2019 14:31 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$4980.00) - SGT7762A - Claim Handler: Zuhaidah Bte Samsuri

Approved:4980.00.

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL: 6441 5655 FAX: 6441 5355/6243 8121
R.O.C No: 200104141D GST Reg. No. 20-0104141-D

Ref : SGT7762A

Date : 13/06/2019

Motor Claims Dept
India International Insurance Pte Ltd
NO 64 Cecil Street
#04-05 IOB Building
SINGAPORE 049711
Fax : 62244174 , 62257743

Dear Sir/Mdm

DIRECT SETTLEMENT - Accident Involving vehicle no SGT7762A and SHB4341J On 06/04/2019 Along PIE > TUAS NEAR EXIT 12

We refer to the above matter.

We are instructed by our clients, OW CHIH KAN of vehicle number SGT7762A to claim damages against your insured SHB4341J in connection with a road traffic accident on 06/04/2019 1:10:58PM

We are instructed that the accident was caused by your insured's negligent driving and /or management of this vehicle. As a result, our client's vehicle was damaged and our clients have to put to loss and expenses, particulars of which are as follows:

Cost Of Repair			\$	4,280.00
Loss of Use			\$	0.00
Car Rental Fee	7 Days X \$	120.00	\$	840.00
Survey Fee			\$	0.00
GIA Fees			\$	0.00
Total			\$	5,120.00

Please revert within the next **SEVEN (7) Days** so that we can advise our third party claimant for the next course of action.

We/I support our/my claim with documents enclosed.

Motor Claims Dept
Anysia Foo
motor@hockwah.com



HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK II
BEDOK NORTH AVE 4
#01-2008/10/12 SINGAPORE 480977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No: 200104141D GST Reg. No: 20-0104141-D

Ref : SGT7762A

Date : 13/06/2019

Motor Claims Dept
India International Insurance Pte Ltd
NO 64 Cecil Street
#04-05 IOB Building
SINGAPORE 049711
Fax : 62244174 , 62257743

Dear Sir/Mdm

DIRECT SETTLEMENT - Accident Involving vehicle no SGT7762A and SHB4341J On 06/04/2019 Along PIE > TUAS NEAR EXIT 12

We refer to the above matter.

We are instructed by our clients, OW CHIH KAN of vehicle number SGT7762A to claim damages against your insured SHB4341J in connection with a road traffic accident on 06/04/2019 1:10:58PM

We are instructed that the accident was caused by your insured's negligent driving and /or management of this vehicle. As a result, our client's vehicle was damaged and our clients have to put to loss and expenses, particulars of which are as follows:

Cost Of Repair				\$	4,280.00
Loss of Use				\$	0.00
Car Rental Fee	7	Days X \$	120.00	\$	840.00
Survey Fee				\$	0.00
GIA Fees				\$	0.00
Total				\$	5,120.00

Please revert within the next **SEVEN (7) Days** so that we can advise out third party claimant for the next course of action.

We/I support our/my claim with documents enclosed.


Motor Claims Dept
Anyisia Foo
motor@hockwah.com



cc6/111 19006126/UGA3

cecilia

LETTER OF AUTHORISATION

I/We, OW CHIH KAN (name) S8101035H (NRIC/Company Reg)
the owner of vehicle no SGT776QA hereby authorizes M/s Hock Wah Motor Workshop Pte
Ltd to submit corresponds, negotiate and settle my claim for repair costs and/or rental and/or loss of use
arising from the accident which occurred on 06/04/2019 (date) along PIE TOWARDS THAS
DEAR EXIT 12 involving vehicle no/s SHB 43413 (third party).

I further authorize M/s Hock Wah Motor Workshop to accept and receive any payment due to me in
respect to my claim above. I further permit payment of the settlement sum to be made in the name of
M/s Hock Wah Motor Workshop Pte Ltd.

Dated this 06 day of 04 2019.

CLIENT:Signature: Name : OW CHIH KANNRIC : S8101035HAddress : BLK 213 LIMEL STREET 4#04-43 S (5287A)

Company Chop:

(If applicable) _____

WITNESS:Signature: Name : Anyia Foo

NRIC : _____

HOCK WAH MOTOR WORKSHOP PTE LTDAddress: 5011 Bedok Industrial Park E#01-2008/2010/2012Singapore 489977

Tel: 5441 5551 (3 Lines) Fax: 6441 5355

Email: motor@hockwah.com.sg

Company Chop:

(If applicable) _____

EXPRESS SETTLEMENT

DISCHARGE VOUCHER

III- Direct Settlement (PODS)

India Ref: MCT19040155
Claimant Ref: SGT 7762A

We/I, HOCK WAH MOTOR WORKSHOP PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of Surveyor) with respect to the amount claimed for S\$ 4,280.00 (repair cost), S\$ 700.00 (loss of use/rental), S\$ - (search fee), vehicle no. SGT 7762A that was damaged pursuant to the accident which occurred on 06/04/2019 (date) at PIE (location) involving vehicle no. SHB 4341J (insured vehicle). This is pursuant to the inspection conducted on 06/04/2019 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner OW CHIH KAN ("the third party claimant") of vehicle no. SGT 7762A to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SGT 7762A (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 4,980.00 to HOCK WAH MOTOR WORKSHOP PTE LTD

Dated this 29 day of August 2019

CLAIMANT:

Signature:

Signed by "the workshop" (with chop)

Name:

Anysia Foo

NRIC:

Address: HOCK WAH MOTOR WORKSHOP PTE LTD

Blk 3011 Bedok Industrial Park E,
#01-2008/2010/2012
Singapore 489977

Nationality: Tel: 6441 5655 (3 Lines) Fax: 6441 5355

Occupation: Email: motor@hockwah.com.sg

WITNESS:

Signature:

Signed by appointed Surveyor

Name:

LKK AUTO CONSULTANT PTE LTD

NRIC:

199607198R

Address:

51 UBI AVE 1 #02-25

Nationality:

Occupation:

PAYA UBI INDUSTRIAL PARK S(408933)



CKS

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX1035H

India International Insurance Pte Ltd
NO 64 Cecil Street
#04-05 IOB Building
SINGAPORE 049711
TEL : 62238122 , 63476100 FAX : 62244174 , 62257743
PH :
ATTN :

TAX INVOICE

Number : IV00060118
Date : 12/06/2019
Case No :
Vehicle No : SGT7762A
Chassis: MR053HY4204217507
Year of Mfr 2006
Policy No 5089634752-01
Model : TOYOTA VIOS

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	LUMPSUM REPAIR	1.0	4,000.00	0	4,000.00
	Sub Total				4,000.00
	Parts Total				4,000.00
SINGAPORE DOLLARS : FOUR THOUSAND TWO HUNDRED EIGHTY AND CENTS ZERO ONLY			Less Excess		0.00
			SUBTOTAL		4,000.00
			GST 7.00%		280.00
			TOTAL		4,280.00

Date of accident : 06/04/2019 01:10 PM. Place : PIE > TUAS NEAR EXIT 12

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE



KOH CAR HO PTE.LTD.

Reg No 20142285TD

3011 BEDOK INDUSTRIAL PARK E
#01-2010 SINGAPORE 489977

INVOICE

Refer to Rental Agreement:

CRA 200083

Reference Vehicle:

SET 7762A

Date:

20-03-2019

Customer Information

Name:

OW CHIO KAN

NRIC No.:

S810103541

Address:

218 BRISTOL STREET 4 #07-47

S (528719.)

Contact No:

9771 3330

Rental Car Information

Vehicle No.:

SLR 3867X

Make & Model:

TOYOTA Vios

Start Date:

06, 04, 2019

End Date:

12, 04, 2019

Rent for (No. of Days)

7

Rate at (Per Day)

\$120.00

Total Amount

\$ 840.00

Customer Signature

Authorized Signature



R.Vehicle No. SGT7762A

CRA# -200085

KOH CAR HO PTE.LTD.
Reg No. 201422877J
3011 BEDOK INDUSTRIAL PARK E
#01-2010 SINGAPORE 489977

RENTAL AGREEMENT - CLAIM**Hirer's Particulars**Name: DOO CHIH EAN NRIC No.: S81010354Address: 218 SIMEI STREET 4 #02-42S (558719)Contact No: 9771 3330Licence Date: 08 / 01 / 2004 Birth Date: 07 / 01 / 1981**Additional Driver's Particulars**

Name: _____ NRIC No.: _____

Licence Date: / / Contact No: _____**Rental Vehicle**Vehicle No.: SLR55634 Start Date: 06 / 04 / 2019Rate (Per day): _____ No. of days: _____ End Date: 12 / 04 / 2019PL (Out): _____ PL (In): OK / Time out/in: 14:00hrs 17:00hrs

The Hirer agreed to the Rental Agreement as followed: -

- ☐ Rental vehicle is restricted to SINGAPORE use only, check water and engine oil daily.
- ☐ No refund if vehicle return early.
- ☐ Hirer is liable to pay all fines, summons, claims, excess within rental period.
- ☐ Hirer shall bear the responsibility if any damages found on/in vehicle.
- ☐ Extension: One day in advance notice is required otherwise no extension will be allowed.
- ☐ Car collection and return shall be within the office operating hour.
- ☐ Excess: In the event when accident occurred, the Hirer is liable to bear the excess of at least S\$4,000 / S\$8,000 (Young, Inexperience Driver) in cash plus loss of earnings.

Any problem arises to vehicle within rental period, Hirer must inform 6441 5655 immediately.

Hirer acknowledges all T&C and signifies acceptance upon signing.



Hirer and Driver Signature

Date & Company Stamp (if any)

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	08 Apr 2019 Edit Reg		08 Apr 2019 00:00 Edit Adj Rpt	\$4,000.00 Edit Estimates	\$4,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD. Co. Reg. No.: 199303821R								
Main Claimant:	OW CHIH KAN, ID: S8101035H								
Vehicle Reg. No.:	SGT7762A	Date of Loss:	06/04/2019 13:00 - :59 143 Months and 13 Days From LTA Reg Date (Man Yr)						
Claim Type:	TP / MCT19040165	Policy/Cover Note No.:	MCOM0015						
Vehicle Reg. No. (Insured):	SHB43413	Policy No. (Claimant):	5089634752-01						
	Excess:								
Repairer:	Hock Wah Motor Workshop Pte Ltd (Bedok) Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012, 489977 Bedok - Tel: 6441 5655								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 17/04/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- III_SG (27/08/2019): Alert - Adj Mandate Approved (\$4980.00) - SGT7762A - Claim Handler: Zuhaidah Bt... - III_SG (05/08/2019): Alert - Adj Mandate Approved (\$4980.00) - SGT7762A - Claim Handler: Zuhaidah Bt... - III_SG (05/08/2019): Alert - Adj Mandate Approved (\$4980.00) - SGT7762A - Claim Handler: Zuhaidah Bt... - III_SG (15/04/2019): Alert - Adj Mandate Approved (\$0.00) - SGT7762A - Claim Handler: Zuhaidah Bte S...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SGT7762A (MCT19040165)
 [SHB4341J]
 TP
 OW CHIH KAN
 Apr 6 2019 1:00PM
 [COMFORT TRANSPORTATION PTE LTD]
 Hock Wah Motor Workshop Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	05/08/19 11:41	General View	 Load JPG	☒
2	05/08/19 11:41	General View	 Load JPG	☒
3	05/08/19 11:41	General View	 Load JPG	☒
4	05/08/19 11:41	General View	 Load JPG	☒
5	05/08/19 11:41	General View	 Load JPG	☒
6	05/08/19 11:41	General View	 Load JPG	☒
7	05/08/19 11:41	General View	 Load JPG	☒
8	05/08/19 11:41	General View	 Load JPG	☒
9	05/08/19 11:41	General View	 Load JPG	☒
10	05/08/19 11:41	General View	 Load JPG	☒
11	05/08/19 11:41	General View	 Load JPG	☒
12	05/08/19 11:41	General View	 Load JPG	☒
13	05/08/19 11:41	General View	 Load JPG	☒
14	05/08/19 11:41	General View	 Load JPG	☒
15	05/08/19 11:41	General View	 Load JPG	☒
16	05/08/19 11:41	General View	 Load JPG	☒
17	05/08/19 11:41	General View	 Load JPG	☒
18	05/08/19 11:41	General View	 Load JPG	☒
19	05/08/19 11:41	General View	 Load JPG	☒
20	05/08/19 11:41	General View	 Load JPG	☒
21	05/08/19 11:41	General View	 Load JPG	☒
22	05/08/19 11:41	General View	 Load JPG	☒
23	05/08/19 11:41	General View	 Load JPG	☒
24	05/08/19 11:41	General View	 Load JPG	☒
25	05/08/19 11:41	General View	 Load JPG	☒
26	05/08/19 11:41	General View	 Load JPG	☒
27	05/08/19 11:41	General View	 Load JPG	☒
28	05/08/19 11:41	General View	 Load JPG	☒
29	05/08/19 11:41	General View	 Load JPG	☒
30	05/08/19 11:41	General View	 Load JPG	☒
31	05/08/19 11:41	General View	 Load JPG	☒
32	05/08/19 11:41	General View	 Load JPG	☒
33	05/08/19 11:41	General View	 Load JPG	☒
34	05/08/19 11:41	General View	 Load JPG	☒
35	05/08/19 11:41	General View	 Load JPG	☒
36	05/08/19 11:41	General View	 Load JPG	☒
37	05/08/19 11:41	General View	 Load JPG	☒
38	05/08/19 11:41	General View	 Load JPG	☒
39	05/08/19 11:41	General View	 Load JPG	☒
40	05/08/19 11:41	General View	 Load JPG	☒
41	05/08/19 11:41	General View	 Load JPG	☒
42	05/08/19 11:41	General View	 Load JPG	☒
43	05/08/19 11:41	General View	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
44	05/08/19 11:41	General View	 Load JPG	☒
45	05/08/19 11:41	General View	 Load JPG	☒
46	05/08/19 11:41	General View	 Load JPG	☒
47	05/08/19 11:41	General View	 Load JPG	☒
48	05/08/19 11:41	General View	 Load JPG	☒
49	05/08/19 11:41	General View	 Load JPG	☒
50	05/08/19 11:41	General View	 Load JPG	☒
51	05/08/19 11:41	General View	 Load JPG	☒
52	05/08/19 11:41	General View	 Load JPG	☒
53	05/08/19 11:41	General View	 Load JPG	☒
54	05/08/19 11:41	General View	 Load JPG	☒
55	05/08/19 11:41	General View	 Load JPG	☒
56	05/08/19 11:41	General View	 Load JPG	☒
57	05/08/19 11:41	General View	 Load JPG	☒
58	05/08/19 11:41	General View	 Load JPG	☒
59	05/08/19 11:41	General View	 Load JPG	☒
60	05/08/19 11:41	General View	 Load JPG	☒
61	05/08/19 11:41	General View	 Load JPG	☒
62	05/08/19 11:41	General View	 Load JPG	☒
63	05/08/19 11:41	General View	 Load JPG	☒
64	05/08/19 11:41	General View	 Load JPG	☒
65	05/08/19 11:41	General View	 Load JPG	☒
66	05/08/19 11:41	General View	 Load JPG	☒
67	05/08/19 11:41	General View	 Load JPG	☒
68	05/08/19 11:41	General View	 Load JPG	☒
69	05/08/19 11:41	General View	 Load JPG	☒
70	05/08/19 11:41	General View	 Load JPG	☒
71	05/08/19 11:41	General View	 Load JPG	☒
72	05/08/19 11:41	General View	 Load JPG	☒
73	05/08/19 11:41	General View	 Load JPG	☒
74	27/08/19 09:36	After Repair Photo	 Load JPG	☒
75	27/08/19 09:36	After Repair Photo	 Load JPG	☒
76	27/08/19 09:36	After Repair Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/04/19 12:10	TP GIA REPORT	 Load PDF	
2	13/04/19 13:59	TP ESTIMATE - MARKED	 Load PDF	
3	02/08/19 10:06	RENTAL RECEIPT	 Load PDF	
4	02/08/19 10:06	LOD	 Load PDF	
5	12/09/19 08:01	WORKSHOP INVOICE	 Load PDF	
6	12/09/19 08:01	AUTHORISATION TO ACT FORM	 Load PDF	
7	12/09/19 08:01	DISCHARGE VOUCHER	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	09/04/19 09:21	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg No: 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III19006126/UGA3Q2

Date: 12/09/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant SGT7762A Insured Vehicle No: SHB4341J
 Vehicle No: SGT7762A
 Date of Loss: 06/04/2019 Nature of Claim: TP Claim No: MCT19040165

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGT7762A
 Make & Model: TOYOTA VIOS, 1.5 E (A) Engine No: 1NZX519450
 Reg. Date: 24/04/2007 (Man. Year: 2006) Chassis No: MR053HY4204217507
 Colour: Black Odometer: 311656 km
 Engine Capacity: 1497 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R14 Rear Tyre Size: 185/60 R14
 Front Left Side: West Lake 6 mm Rear Left Side: West Lake 6 mm
 Front Right Side: West Lake 6 mm Rear Right Side: West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,531.15	2,572.14	2,959.01	53.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,530.00	2,440.00	1,090.00	30.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,061.15	5,012.14	4,049.01	44.69
Approved Total (Overridden) (S\$)		4,000.00		
(S\$)	9,061.15	4,000.00	5,061.15	55.86
+ GST 7.00/7.00% (S\$)	634.28	280.00	354.28	55.86
Nett Amount (S\$)	9,695.43	4,280.00	5,415.43	55.86
+ Car Rental (7.0 x S\$100.00/day) (S\$)		700.00		
Nett Liability (S\$)		4,980.00		

INSPECTION

Date of Assignment: 08/04/2019

Date Inspected: 09/04/2019 Inspected At:

Hock Wah Motor Workshop Pte Ltd
 (Bedok)
 Blk 3011, Bedok Industrial Park E.,
 #01-2008/2010/2012
 Singapore 489977

Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 31 Jul 2019)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGT7762A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Dented / Bent	580.57 FL	*580.57 FL
2	1		*BOOTLID EMBLEM	Necessary	62.52 FL	*62.52 FL
3	1		*BOOTLID LOGO - 1.5E	Necessary	45.54 FL	*45.54 FL
4	1		*BOOTLID LOGO - VIOS	Necessary	58.10 FL	*58.10 FL
5	1		*TAIL LAMP LH	Cracked	190.97 FL	*190.97 FL
6	1		*TAIL LAMP RH	Cracked	190.97 FL	*190.97 FL
7	4		*TAIL LAMP CLIP LH	Not Necessary	42.00 FL	*- FL
8	4		*TAIL LAMP CLIP RH	Not Necessary	42.00 FL	*- FL
9	1		*BOOTLID WEATHERSTRIP	Twisted	59.60 FL	*59.60 FL
10	1		*BOOTLID LOCK	Twisted	78.90 FL	*78.90 FL
11	1		*REAR FENDER INNER GARNISH LH	Not Necessary	310.84 FL	*- FL
12	1		*END PANEL	Badly Dented	783.90 FL	*783.90 FL
13	1		*END PANEL TOP GARNISH	Twisted	99.11 FL	*99.11 FL
14	1		*SPARE TYRE PANEL	Repair	798.90 FL	*- FL
15	1		*SPARE TYRE PANEL TOP TRIMBOARD	Torn	276.84 FL	*276.84 FL
16	1		*SPARE TYRE PANEL SIDE TRIMBOARD LH	Not Necessary	188.50 FL	*- FL
17	1		*SPARE TYRE PANEL SIDE TRIMBOARD RH	Not Necessary	188.50 FL	*- FL
18	1		*REAR BUMPER	Distorted	281.90 FL	*281.90 FL
19	2		*REAR BUMPER RETAINER LH	Bent	342.90 FL	*65.50 FL
20	2		*REAR BUMPER RETAINER RH	Bent	342.90 FL	*65.50 FL
21	1		*REAR BUMPER BRACKET LH	Bent	121.10 FL	*121.10 FL
22	1		*REAR BUMPER BRACKET RH	Repair	121.10 FL	*- FL
23	1		*REAR EXHAUST PIPE	Repair	781.45 FL	*- FL
24	1		*REAR EXHAUST PIPE MOUNTING	Not Necessary	43.70 FL	*- FL
25	1		*REAR FENDER SHIELD RH	Torn	181.90 FL	*68.50 FL
26	1		*REAR FENDER SHIELD LH	Not Necessary	181.90 FL	*- FL
27	1		*REAR EXHAUST PIPE CHROME	Missing	143.69 FS	*60.00 FS
28	1		*REAR FENDER LH (NPA)	Repair	0.00 FS	*- FS
29	1		*REAR FENDER RH (NPA)	Repair	0.00 FS	*- FS
30	1		*BOOTLID HINGE RH (NPA)	Repair	0.00 FS	*- FS
31	1		*BOOTLID HINGE LH (NPA)	Repair	0.00 FS	*- FS
32	1		*REAR NUMBER PLATE	Bent	30.00 FS	*20.00 FS
33	1		*REAR NUMBER PLATE HOLDER	Bent	30.00 FS	*20.00 FS
34	1		*SET REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
35	1		*SPARE TYRE PANEL TOP CARPET	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,130.30	3,329.52
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,599.15	757.38
Total Parts (\$\$)	5,531.15	2,572.14

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS.	New	1,500.00	1,200.00
2	SPRAY PAINT ON THE AFFECTED AREAS.	New	1,500.00	1,080.00
3	ANTI-RUST COATING.	New	300.00	80.00
4	WIRING.	New	80.00	30.00
5	TO REMOVE & REFIT REVERSE SENSOR.	New	150.00	50.00
Gross Labour Cost (S\$)			3,530.00	2,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >