

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX1035H
OW CHIH KAN
BLK 21B SIMEI STREET 4
07-47
SINGAPORE 528719
TEL : FAX :
PH : 97713330
ATTN :

ESTIMATE BILL

Number : EB00005125
Date : 08/04/2019
Case No : AD00010326
Vehicle No : SGT7762A
Chassis : MR053HY4204217507
Year of Mfr : 2006
Policy No : 5089634752-01
Model : TOYOTA VIOS

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	BOOTLID	1.0	580.57	25	435.43
2	BOOTLID EMBLEM	1.0	62.52	25	46.89
3	BOOTLID LOGO - 1.5E	1.0	45.54	25	34.16
4	BOOTLID LOGO - VIOS	1.0	58.10	25	43.58
5	TAIL LAMP LH	1.0	190.97	25	143.23
6	TAIL LAMP RH	1.0	190.97	25	143.23
7	TAIL LAMP CLIP LH	4.0	10.50	25	31.50
8	TAIL LAMP CLIP RH	4.0	10.50	25	31.50
9	BOOTLID WEATHERSTRIP	1.0	59.60	25	44.70
10	BOOTLID LOCK	1.0	78.90	25	59.18
11	REAR FENDER INNER GARNISH LH	1.0	310.84	25	233.13
12	END PANEL	1.0	783.90	25	587.93
13	END PANEL TOP GARNISH	1.0	99.11	25	74.33
14	SPARE TYRE PANEL	1.0	798.90	25	599.18
15	SPARE TYRE PANEL TOP TRIMBOARD	1.0	276.84	25	207.63
16	SPARE TYRE PANEL SIDE TRIMBOARD LH	1.0	188.50	25	141.38
17	SPARE TYRE PANEL SIDE TRIMBOARD RH	1.0	188.50	25	141.38
18	REAR BUMPER	1.0	281.90	25	211.43
19	REAR BUMPER RETAINER LH	2.0	171.45	25	257.18
20	REAR BUMPER RETAINER RH	2.0	171.45	25	257.18
21	REAR BUMPER BRACKET LH	1.0	121.10	25	90.83
22	REAR BUMPER BRACKET RH	1.0	121.10	25	90.83
23	REAR EXHAUST PIPE	1.0	781.45	25	586.09
24	REAR EXHAUST PIPE MOUNTING	1.0	43.70	25	32.78
25	REAR FENDER SHIELD RH	1.0	181.90	25	136.43
26	REAR FENDER SHIELD LH	1.0	181.90	25	136.43
27	REAR EXHAUST PIPE CHROME	1.0	191.58	25	143.69
List Price - Parts Sub Total					4,941.23
28	REAR FENDER LH - REPAIR	1.0			
29	REAR FENDER RH - REPAIR	1.0			
30	BOOTLID HINGE RH - REPAIR	1.0			
31	BOOTLID HINGE LH - REPAIR	1.0			
32	REAR NUMBER PLATE	1.0	30.00	0	30.00

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : SXXX1035H
OW CHIH KAN
BLK 21B SIMEI STREET 4
07-47
SINGAPORE 528719
TEL : FAX :
PH : 97713330
ATTN :

ESTIMATE BILL

Number : EB00005125
Date : 08/04/2019
Case No : AD00010326
Vehicle No : SGT7762A
Chassis: MR053HY4204217507
Year of Mfr 2006
Policy No 5089634752-01
Model : TOYOTA VIOS

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
33	REAR NUMBER PLATE HOLDER	1.0	30.00	0	30.00
34	REVERSE SENSOR	1.0	280.00	0	280.00
35	SPARE TYRE PANEL TOP CARPET	1.0	250.00	0	250.00
Special Nett Price - Parts Sub Total					590.00
Parts Total					5,531.23
36	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	1,500.00	0	1,500.00
37	SPRAY PAINT ON THE AFFECTED AREAS	1.0	1,500.00	0	1,500.00
38	ANTI-RUST COATING	1.0	300.00	0	300.00
39	WIRING	1.0	80.00	0	80.00
40	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
Labour 1 Sub Total					3,530.00
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					5012.14
SINGAPORE DOLLARS : NINE THOUSAND SIX HUNDRED NINETY-FIVE AND CENTS FIFTY-TWO ONLY			Less Excess		0.00
			SUBTOTAL		9,061.23
			GST 7.00%		634.29
			TOTAL		9,695.52

Date of accident : 06/04/2019 01:10 PM. Place : PIE > TUAS NEAR EXIT 12

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE