

Address  
 Postcode  
 Was driver an employee of the Insured's Company NO  
 If No, Relationship of the Driver with the Insured OWNER  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident COLLISION - HEAD TO REAR  
 Weather Conditions CLEAR  
 Road Surface DRY

**Other Information**

Was any foreign vehicle involved in this accident? NO  
 Number of vehicles involved in the accident  
 Was any body injured in the Accident? YES  
 Was any injured conveyed to hospital by ambulance? NO  
 Was any other material or property damaged? YES  
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO  
 Number of Passengers (Including Driver) 1

**Details of Police Action**

Was the accident reported to the police? YES  
 If Yes, Please state which Police Station  
 Police Station Name CHOA CHU KANG NPC  
 Police Station Address ROAD: 20 CHOA CHU KANG ST 52 #01-02 , POSTCODE: 689286 , COUNTRY: SINGAPORE  
 Police Station Contact TEL NO: - FAX NO:  
 Was notice of intended Prosecution given? NO  
 If Yes, against whom?

**Circumstances of Accident**

REFER TO SKETCH PLAN

**Attachment(s)**

Are accident photos available for attachment? YES  
 Was there any video captured by Car Camera? NO  
 Was there any audio recorded? NO

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number GW6046A  
 Vehicle Make/Model/Colour  
 Details Of Properties  
 Vehicle Category COMMERCIAL VEHICLE  
 Name of Driver SELVARAJ  
 NRIC/Passport Number  
 Contact Number  
 Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage

No. Of Passenger (Including Driver)

**DETAILS OF INJURED PERSON 1**

Name ABDUL MONIP BIN SUBAHAN

Approximate Age

Injuries Sustain

Injured person in which vehicle? SGF3898S

Were seat belts worn?

Was this injured conveyed to hospital by ambulance?

Address

Postcode

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:





**SINGAPORE  
POLICE FORCE**



T/20180731/2095

Police Station Of Origin:  
Choa Chu Kang N.P.C  
20 Choa Chu Kang Street 52 #01-02  
SINGAPORE 689286  
Tel No: 1800-7659999

1 of 3

Report No. T/20180731/2095

**REPORT OF A TRAFFIC ACCIDENT**

Date/Time Report Made: 31/07/2018 15:41	Vide Report No.:	Station Diary No.: 80
--	------------------	--------------------------

**Informant's Particulars**

Name of Informant: ABDUL MONIP BIN SUBAHAN		Address: APT BLK 663 CHOA CHU KANG CRESCENT #05-261 SINGAPORE 680663	
ID Type / ID No.: NRIC NO / S1187716H		Contact No.: Home/Office:                      Mobile: 91711946	
Nationality: SINGAPORE CITIZEN		Email:	
Sex: Male	Age: 61	Date of Birth: 04/10/1956	Type of Informant: Driver
Race: Boyanese		Language:	Institution / School Name:
Occupation: PERSONAL DRIVER		Driving Licence Information: Class: 2B,2A,2,3,4,5	Date of Expiry:

**General Information of the Accident**

Type of Accident:	Injury Attended by Police	Drink Drive: No	Date/Time of Accident: 31/07/2018 12:00	Type of Location:
Location: Along Road 1 SUNGEI KADUT AVENUE				
Sungei Kadut Avenue heading towards Choa Chu Kang Way, in front of (Thong Huat Bros) 4 Sungei Kadut Avenue, S729641				
Weather: Clear		Road Surface: Dry		Road Speed Limit:
Traffic Flow:		Traffic Control:		Traffic Volume: Moderate
Type of Collision: Between Moving Vehicles - Head To Rear				Anyone conveyed by ambulance: No

**Details of Vehicle Involved**

Vehicle No.	Type	Make	Model	Color	Condition	No of Passenger
GW6046A	Lorry				Slightly Damaged	0
SGF3898S	Car	NISSAN	SYLPHY 1.5 4AT	Red	Seriously Damaged	0

**Details of Vehicle Insurance**

Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
-------------	-------------------	--------------	-----------	-------------



**SINGAPORE  
POLICE FORCE**



T/20180731/2095

Police Station Of Origin:  
Choa Chu Kang N.P.C  
20 Choa Chu Kang Street 52 #01-02  
SINGAPORE 689286  
Tel No: 1800-7659999

2 of 3

Report No. T/20180731/2095

## CONTINUATION OF REPORT

Details of Vehicle Insurance				
Vehicle No.	Insurance Company	Insurance No	Effective	Expiry Date
SGF3898S	SHC INSURANCE PTE. LTD.	DMPC18S002993	10/04/2018	09/04/2019

Details of Person Involved				
Any Pedestrian Involved: No				
No. of Pedestrians Injured: NIL		Use of Pedestrian Crossing: NA		
Driver				
Name	ABDUL MONIP BIN SUBAHAN	ID No.	S1187716H	
Related Vehicle	SGF3898S (Car)	Contact No.	91711946	
Hospital/Clinic	NIL	Class of Driving Licence & Expiry Date	Class: 2B,2A,2,3,4,5 Date of Expiry: NIL	
Date Treatment	NIL	Date Discharge	NIL	
No. of Days granted Medical Leave	NIL	Degree of Injury	NIL	

**Brief Details.**

On 31/07/2018 between 1200-1230hrs along Sungei Kadut Avenue heading towards Choa Chu Kang Way, I was driving my car (SGF3898S) and following behind a lorry (GW6046A). As the Lorry driver did not signal and show his intention that he is going to make a right turn into one of the compound (Thong Huat Bros) 4 Sungei Kadut Avenue, S729641. I am unable to stop in time and knocked onto the lorry rear.

Due to the impact I am injured, suffered swollen right forearm, fingers pain, right shoulder and back feeling painful and aching, giddiness.

My car front bonnet is badly damaged.

Attended by Traffic Police.

I went to CCK Polyclinic and I was being referred to SGH for further medical check-up.

I am making this police report for insurance claims.

The lorry driver details  
G2151527U  
Selvaraj Mohanraj



SINGAPORE  
POLICE FORCE



T/20180731/2095

Police Station Of Origin:  
Choa Chu Kang N.P.C  
20 Choa Chu Kang Street 52 #01-02  
SINGAPORE 689286  
Tel No: 1800-7659999


3 of 3  
Report No. T/20180731/2095

CONTINUATION OF REPORT

Sketch Plan

Informant is not able to provide sketch plan

IMPORTANT: Please attach a copy of your vehicle's Insurance Certificate to this report. If you don't have the certificate with you now, please fax a copy to 65474885 stating the report number as reference.

Signature Of Officer Recording The Report: J Sgt 2 <b>WONG SENG HOCK</b>	
Signature Of Interpreter: Not applicable	Signature:
 Officer In Charge Of Case: TP / GIT / Sr Staff Sgt <b>IRMAN BIN MOHAMAD SAID</b> Contact No.: 65476365	

Signature Of Informant: 
Date/Time: 31/07/2018 15:41
Classification Of Case:

Authentication Stamp  
NP168

Accident Photo




Accident Photo




Accident Photo



Accident Photo



Accident Photo




Accident Photo



Accident Photo



Accident Photo





221 Balestier Road #10-01, Rocca Balestier, Singapore 329928  
 Tel: +65 6707 8932 Fax: +65 6352 6802  
 Mobile: +65 9673 0595 / +65 9788 9809  
 E-mail: ethtan88@singnet.com.sg Email: ethtan88@gmail.com  
 Company Registration No: 40156500M

**PRO  
 PLUS  
 AUTOMOBILE  
 ENGINEERS**

*Consultants to Motor Industry, Automobile  
 Engineers, Claims Investigators, Accident  
 Reconstruction Specialists, Insurance Loss  
 Assessors / Adjusters, Valuers And  
 Licensed Appraisers.*

### VEHICLE INSPECTION REPORT

To: M/s Home Shape Design & Construction  
 c/o 4 Sungei Kadut Avenue  
 Singapore 729641

Insured :  
 Policy Number :  
 Claim Number :  
 Our Reference : PP/ET/CT.6046.TP.8-18  
 Own Damage/Sum Insured :  
 Excess :  
 Third Party/Insce Company :  
 Date : 15 August 2018

Instructed By : Yourself  
 Date of Assignment : 1 August 2018  
 Date of Accident : 31 July 2018  
 Date of Inspection : 21 August 2018  
 Name of Workshop : Kim Motor Service  
 Place of Inspection : 4 Sungei Kadut Avenue  
 Singapore 729641

#### PARTICULARS OF DAMAGED VEHICLE

Registration Number	: GW 6046 A	Odometer Reading	: 432 660 Km
Make/Model	: Toyota Dyna 150D	Radio/Cassette/CD	: Fitted
Year of Manuf/Reg	: 2003	Air Conditioner	: Fitted
Engine Number	: 5L5358379	View Mirrors	: Fitted -C/S & n/s
Chassis Frame Number	: JTFUF34Y403001563	Seat Belts	: Fitted -Front only
Class/Type	: Lorry ( Metal Body )	Other Accessories	: (Specify)
Colour	: Metallic Silver		

#### PRE-ACCIDENT CONDITION OF VEHICLE

General Condition	: Good	Any Apparent Engine	:
Paintwork	: Good	Modification/s	:
Footbrakes	: Serviceable	Market Value	:
Steering	: Serviceable	Scrap Value (PARF/OMV)	:
Undercarriage (Front)	: Serviceable		
Undercarriage (Rear)	: Serviceable		

#### TYRE CONDITIONS ON VEHICLE

		NEAR SIDE	OFF SIDE
Front (Size)	: 185R14	70%	70%
MAKE	: Yokohama		
Rear (Size)	: 155R14 X 2	70% X 70%	70% X 70%
MAKE	: Falken		
SPARE (Size)	: -		
MAKE	: -		
Type of Road Wheels	: Standard		


NOTE: The above percentages represent the estimated remaining life of the tyre threads  
 \* Denotes damaged components

## PRO PLUS AUTOMOBILE ENGINEERS


### IMPACT OF VEHICLE

Direction of Impact (←→)

Damages sustained were consistent with the subject vehicle being involved in a collision with another vehicle and the impact was delivered onto the rear n/s portion of the vehicle.



### SYNOPSIS OF DAMAGES RESULTANT FROM THE ACCIDENT



Damages sustained were the rear carriage assembly- shifted inwards by the impact, tailgate & its inner reinforcement- dented/bent/buckled/warped over an extensive area, tailgate latch ( upper ) n/s- bent/twisted, tailgate latch/lock ( lower ) n/s- bent/twisted, rear body panel- thrusts inwards/buckled, n/s dropside panel and its inner reinforcement- bent/buckled, rear carriage assembly floor panel- buckled etc-----

*Note : Follow-up reinspection of vehicle on 13 August 2018 after spray painting & noted that the listed components as per our recommendations were replaced and repaired accordingly.*

### ESTIMATE

The estimate submitted by **M/s Kim Motor Service** as per schedule attached has been revised and scrutinized, and in our opinion, we consider it to be fair and reasonable. The repairers have/have not agreed to undertake the repairs to the owner's satisfaction at our revision. As instructed, we have/have not authorised the repairs.

	Repairer's Estimate	Our Recommendation	
Spare Parts :	6082.20	3732.32	Estimated number of days for repairs: 5
Labour Charges :	1250.00	800.00	
Paint Work :	1250.00	800.00	Number of photographs taken at time of static inspection: 27
Towing Charges :			
Others :	40.00	20.00	
<b>TOTAL</b>	<b>8622.20</b>	<b>5352.32</b>	

**Remarks:** The repairer has agreed to undertake the repairs on a contract lump sum of \$4,300.00 NETT corresponding to supply of parts, labour and spray painting charges. Invariably, the motor repairer has the prerogative/option for the recommended replacement components to either be repaired or be replaced.

*NOTE: The revised estimate was made from a visual inspection. Any discrepancies or unseen damage/s should be notified with the company within 7 (seven) days from the date thereof. Otherwise, the revised amount should deem to be valid.*

APPRAISEMENT SCHEDULE

Registration No: GW 6046 A

Your Reference:

S/No	Qty	Descriptions	Comments/ Condition	Repairer's Estimate \$ e	Revised Amount \$ e
<u>PARTS REPLACEMENT- LIST ITEMS</u>					
1	1 pc	Tailgate	Dented/buckled	1248.40	1248.40
2	1 pc	Tailgate 'TOYOTA' decal	Essential	196.70	196.70
3	2 pcs	Tailgate latch [ upper ] @\$51.40	O/s intact n/s bent/twisted	102.80	51.40
4	2 pcs	Tailgate latch/lock [ lower ] @\$121.60	O/s intact n/s stiffened/twisted	243.20	121.60
5	4 pcs	Tailgate hinge @\$41.40	Bent/stiffened [ one piece ]	165.60	41.40
6	2 pcs	Taillamp assembly @\$217.80	O/s intact n/s cleft/displaced	435.60	217.80
7	2 pcs	Taillamp holder @\$41.40	O/s intact n/s cracked	82.80	41.40
8	1 pc	Rear body panel/cross-member	Thrusted inwards/buckled	572.40	Rx 572.40
9	2 pcs	Rear body panel/cross-member extension @\$101.40	O/s intact n/s bent	202.80	101.40
10	4 pcs	Rear body panel/cross-member extension gourmet @\$14.50	O/s intact n/s missing	58.00	29.00
11	1 pc	Rear body panel step bar	Bent/buckled	151.40	151.40
12	1 pc	Rear body panel/cross-member 'DYNA' decal	Essential	18.40	18.40
13	1 pc	Dropside panel n/s	Dented/buckled	2011.80	2011.80
14	1 pc	Dropside panel hinge [ outer ] n/s	<del>Bent</del> /serviceable	41.40	Rejected
15	1 pc	Rear spare tyre chain block	Serviceable	174.50	Rejected
16	1 pc	Rear licence plate lamp/holder assembly	Serviceable	41.50	Rejected
17	1 pc	Rear licence plate base panel	Serviceable	117.90	Rejected
				5865.20	4803.10
				4230.70	1200.73
				2173.03	
<u>Less : 25% by Pro Plus Automobile Engineers</u>					
<b>Sub - Total</b>				<b>5865.20</b>	<b>3602.32</b>

APPRAISEMENT SCHEDULE

Registration No: GW 6046 A

Your Reference:

S/No	Qty	Descriptions	Comments/ Condition	Repairer's Estimate		Revised Amount	
				\$	¢	\$	¢
			B/F	5865.20		3602.32	
		<u>PARTS REPLACEMENT- SPECIAL NETT ITEMS</u>					
1	2 pcs	Terostat @\$80.00	Essential	160.00		<del>192.00</del>	60
2	1 pc	Tallgate ' 13 max ' decal	Essential	18.00		15.00	
3	1 pc	Tallgate ' 70 Km/h ' decal	Essential	18.00		15.00	
4	1 pc	Rear licence plate	Serviceable	21.00		Rejected	90
			Sub - Total	6082.20		3732.32	

**APPRAISEMENT SCHEDULE**


Registration No: GW 6046 A.

Your Reference:

S/No	Qty	Descriptions	Comments/ Condition	Repairer's Estimate		Revised Amount	
				\$	¢	\$	¢
			B/F	6082.20		3732.32	
		<u>LABOUR &amp; MISC. CHARGES</u>					
1		To disconnect rear wire harness of electrical components to facilitate repairs, reconnect & check functions.		40.00		20.00	
2		To dismantle/renew the rear accident damaged portion. To heat, cut/weld damaged body panels & components including to heat, knock-out, reshape, straighten, orientate, restore & align repairable constituents to symmetrical dimensions.		1250.00		700 800.00	
3		To putty/primer application and spray painting including touch-up affected areas with polyurethane paint.	) ) ) ) )	1250.00		700 800.00	
4		To rustproofing & cavities preservation to the replaced and repaired panels.	) )			1420	
			Grand - Total	8622.20		5352.32	

Note: The repairer has agreed to undertake the repairs at a contract lump sum of \$4,300.00 NETT, corresponding to supply of parts, labour and spray painting charges. Invariably, the motor repairer has the prerogative/option for the recommended replacement components to either be repaired or be replaced.

Pro Plus Automobile Engineers

  
**ERROL TAN**

B.A.Econ (Hons), UK

Dip. Auto Engr. & Motor Trade Management, UK  
Automobile Engineer & Licensed Appraiser

4683.03  
4583.700  
5 days



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: PCS.CCC.2018.218231.ERGO

Date: 25<sup>th</sup> June 2019

Our Ref: CS1/LAW19006127/T1qd3s2

**M/s ComLaw LLC**

64 Cecil ST #03-02

IOB Building

Singapore 049711

Dear Sir / Madam,

**EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO:  
GW 6046A INSURED VEHICLE: SGF 3898S ACCIDENT DATE: 31/07/2018**

We thank you for your instruction on 03/04/2019.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of GW 6046A from M/s Pro Plus Automobile Engineers.
- b) Survey report by Priority Services with colour photographs.
- c) Final Repair Bill of GW 6046A from M/s Kim Service Station.
- d) Singapore Accident Statement of Vehicles GW 6046A and SGF 3898S.
- e) Colour damaged vehicle photographs of GW 6046A.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number	: GW 6046A
Make & Model	: Toyota Dyna 150D
Year of Registration	: 2003
Chassis Number	: JTFUF34Y403001563
Engine Capacity	: 2986 cc

2. We recommend that the repairs of the entire damage require about 5 (Five) working days to complete.
3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GW 6046A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	TAILGATE	DENTED / BUCKLED	1,248.40	1,248.40
1	TAILGATE "TOYOTA" DECAL	ESSENTIAL	196.70	196.70
2	TAILGATE LATCH (UPPER) @\$51.40	N/S BENT / TWISTED / O/S INTACT	102.80	51.40
2	TAILGATE LATCH/LOCK (LOWER) @\$121.60	N/S STIFFENED / TWISTED / O/S INTACT	243.20	121.60
4	TAILGATE HINGES @\$41.40	BENT / STIFFENED (1 PC ONLY)	165.60	41.40
2	TAILLAMP ASSEMBLY @\$217.80	N/S CLEFT / DISPLACED / O/S INTACT	435.60	217.80
2	TAILLAMP HOLDER @\$41.40	N/S CRACKED / O/S INTACT	82.80	41.40
1	REAR BODY PANEL/CROSS-MEMBER	TO REPAIR SEE LABOUR	572.40	-
2	REAR BODY PANEL/CROSS-MEMBER EXTENSION @\$101.40	N/S BENT / O/S INTACT	202.80	101.40
4	REAR BODY PANEL/CROSS-MEMBER EXYENSION GOURMET @\$14.50	N/S MISSING / O/S INTACT	58.00	29.00
1	REAR BODY PANEL STEP BAR	BENT / BUCKLED	151.40	151.40
1	REAR BODY PANEL/CROSS-MEMBER "DYNA" DECAL	ESSENTIAL	18.40	18.40
1	DROPSIDE PANEL N/S	DENTED / BUCKLED	2,011.80	2,011.80
1	DROPSIDE PANEL HINGE (OUTER) N/S	SERVICEABLE	41.40	-
1	REAR SPARE TYRE CHAIN BLOCK	SERVICEABLE	174.50	-
1	REAR LICENCE PLATE LAMP/HOLDER ASSEMBLT	SERVICEABLE	41.50	-
1	REAR LICENCE PLATE BASE PANEL	SERVICEABLE	117.90	-
	LESS 25% DISCOUNT		-	-1,057.68
			5,865.20	3,173.02
<b>SPECIAL NETT ITEMS</b>				
2	TEROSTAT @\$80.00 (SN)	ESSENTIAL	160.00	60.00
1	TAILGATE "13 PAX" DECAL (SN)	ESSENTIAL	18.00	15.00
1	TAILGATE "70KM/H" DECAL (SN)	ESSENTIAL	18.00	15.00
1	REAR LICENCE PLATE (SN)	SERVICEABLE	21.00	-
			217.00	90.00

Report Ref No. CS1/LAW19006127/T1qd3s2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO DISCONNECT REAR WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS.RECONNECT & CHECK FUNCTIONS.		40.00	20.00
	TO DISMANTLE/RENEW THE REAR ACCIDENT DAMAGED PORTION.TO HEAT,CUT/WELD DAMAGED BODY PANELS & COMPONENTS INCLUDING TO HEAT,KNOCK-OUT,RESHAPE,STRAIGHTEN, ORIENTATE,RESTORE & ALIGN REPAIRABLE CONSTITUENTS TO SYMMETRICAL DIMENSIONS.INCLUSIVE OF THE REPAIR OF REAR BODY PANEL/CROSS-MEMBER.		1,250.00	700.00
	TO PUTTY/PRIMER APPLICATION AND SPRAY PAINTING INCLUDING TOUCH-UP AFFECTED AREAS WITH POLYURETHANE PAINT. }		1,250.00	700.00
	TO RUSTPROOFING & CAVITIES PRESERVATION TO THE REPLACED AND REPAIRED PANELS. }		-	-
			2,540.00	1,420.00
	<b>GRAND TOTAL</b>		<b>8,622.20</b>	<b>4,683.02</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>3,700.00</b>

Report Ref No. CS1/LAW19006127/T1qd3s2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.