




PRO PLUS AUTOMOBILE ENGINEERS (Inspection photographs)



PRO PLUS AU
THE EN



PRO PLUS AU
THE EN



















PRO F-UT
AUTOMOBILE ENG



PRO F-UT
AUTOMOBILE ENG



PRO F-UT
AUTOMOBILE ENG





PRIORITY SERVICES

Insurance Loss Adjusters and Motor Appraisers
Blk 779 #01-1545 Yishun Ave 2 Singapore 760779
Tel: 62934822 Fax: 62963283
E-mail: admin@priorityservices.sg

Your Ref. : SGF38988/Steve
Our Ref. : TP-0009/08/18

Date : 11 August 2018

M/s. ERGO Insurance Pte Ltd
5 Temasek Boulevard #04-01
Suntec Tower Five
Singapore 038985

Attn.: Mr. Steve Lim

Dear Sir

Pre-Repair Survey
Vehicle No.: GW 6046 A
Date Of Accident: 31-Jul-2018

Date and Time of Request : 01-Aug-2018 / 12.19pm
Date and Time of Inspection : 1) 02-Aug-2018 / 1.45pm (PRI by appointment)
3) 06-Aug-2018 / 10.40am (For after repair)
@ M/s. Kim Service Station

Particulars of Vehicle

Registration No. : GW 6046 A
Make / Model : Toyota / Dyna 150 - Lorry With Canopy (M)
Year : 2003
Colour : Silver
Odometer : 432660 km
Engine Capacity : 3986 cc
Carrying Capacity : 3500 kg
Engine No. : -
Chassis / Body Frame : JTFUF34Y403001563
Radio / CD Player : Yes
Air-Con Conditioner : Yes
Other Apparent Accessories : No
Spare Tyre : Intact
Jack / Tools : Intact

(42) Photographs of vehicle taken.

Documents Available At Time Of Inspection

1) Singapore Accident Statement (SAS)

Visual Damages

At the rear LH portion.

Damages subject to consistency.

Remarks

Despite our request, the repairer would not provide.

1) Repairer estimate

Recommendation of repairs attached.

Yours Very Truly
PRIORITY SERVICES




JEFFREY ONG
Motor Appraiser



Registration No. : GW 6046 A
 Make / Model : Toyota / Dyna 150 - Lorry With Canopy (M)
 Year : 2003
 Chassis No. : JTFUF34Y403001563


Estimated repair cost for damages found during first inspection on.

QTY SPARE PARTS ESTIMATED PART PRICE


1	Tailgate	\$	Repaired
1	Tailgate Hinges		130.00
1	Tailgate Side Lock LH		62.10
1	Tailgate Side Lock Bracket LH		183.20
1	Tailgate Side Lower Bracket LH		162.50
1	Tailgate Side Lower Bracket Rubber Stopper LH		112.00
1	Rear End Panel		Repaired
1	Rear Taillamp LH		289.20
1	Rear Taillamp Base LH		132.50
1	Rear Taillamp Bracket LH		128.10
		\$	1199.60
		Less 25%/-	299.90
			=====
	Total For Parts:-	\$	899.70
			=====
LABOUR CHARGES:			
	Labour charges.	\$	500.00
	Spray painting.		600.00
			=====
	Grand Total:	\$	1999.70
			=====
	Proposed Lumpsum		: \$1600.00
	Estimated period of repairs		: 4 working days
	Pre-accident market value		: \$800.00
	PARF/COE rebate		: \$479.00

















TOYOTA
70

