



簡福星摩多工廠

KAN FOOK SING MOTOR WORKSHOP

Headquater: 61 Defu Lane 12 Singapore 539147
Tel: (65) 6747 9560, 6473 5344 Fax: (65) 6748 1006, 6281 8428
E-mail: ryan@kanfs.net/ patricia@kanfs.net
Branch: 1 Kaki Bukit Avenue 6 #01-108 Singapore 417883
Tel: (65) 6481 5150 Fax: (65) 6481 8683

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY #27-01 AXA TOWER SINGAPORE 068811

DATE : 05-04-2019

VEHICLE NO. : SKR5419T
ACCIDENT DATE : 05-04-2019 08:30
THIRD PARTY REF. : GBE3819K

ATTN: MOTOR CLAIMS DEPT.

ESTIMATE COST OF REPAIR TO VEICLE SKR5419T HONDA VEZEL

QTY PARTS DESCRIPTION

1	1	FRONT FENDER RH
2	1	FRONT FENDER WHEEL ARCH GARNISH RH
3	1	FRONT BUMPER
4	10	FRONT BUMPER CLIP@\$1.50
5	1	FRONT HEADLAMP RH

AMOUNT (SG\$)

Bodysm	580.00	—
gand	153.00	—
De	459.80	—
nan	15.00	—
in	1820.00	X
	3,027.80	
LESS 20 %	605.56	
TOTAL (A)	2,422.24	

LABOUR CHARGES

1	1	TO CHECK WIRING SYSTEM
2	1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FI- TTING NEW PARTS
3	1	SPRAYPAINTING CHARGES

30.00 20
520.00 300
620.00 400

TOTAL (D)

1,170.00

ESTIMATE TOTAL

3,592.24

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: