

DING AUTOMOTIVE PTE LTD
 Blk 10 Sin Ming Industrial Estate Sector C
 #01-20

Singapore 575645
 Tel: 6452 1208 Fax: 6452 0614

TO :

FAX NO:

ESTIMATE REPORT 1ST Quotation

06/04/2019 16:02

OWNER'S PARTICULARS

JOB-NO: 50111545

NAME: CityCab PTE LTD (Fleet)
 ADDRESS: 383 SIN MING DRIVE
 SINGAPORE 575717 0

CONTACT: 65533880
 64739522

Page 1 of 2

VEHICLE DETAILS

LICENSE NO: SHA8200L

TRANS: AUTO

CHASSIS: KMHLB41UMGU079804

MAKE / MODEL: HYUNDAI / i40

ENGINE: D4FDEU461381

OWNER'S INSURER: MS First Capital Insurance Limited

JOB-CODE: TP

SA: Ding Auto User 1

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO RUST PROOFING ON ACCIDENT AFFECTED AREAS	1.00	150.00	0.00	150.00		Y	30
2 TO TEST WATER LEAK & CHECK BOOTLID LAMP LIGHTING	1.00	80.00	0.00	80.00		Y	20
3 REMOVE & REFIX REAR BOOTLID CONPNENT	1.00	150.00	0.00	150.00		Y	60
4 REMOVE & REFIX REVERSE SENSOR & CHECK WIRING	1.00	80.00	0.00	80.00		Y	30
5 RESPRAY BOOTLID & REVERSE SENSOR	1.00	400.00	0.00	400.00		Y	200
6 RESPRAY REAR BUMPER & REAR BUMPER DIFFUSER	1.00	500.00	0.00	500.00		Y	300
7 RESPRAY END PANEL & SPARE TYRE PANEL	1.00	500.00	0.00	500.00		Y	200
8 TO REPAIR REAR FENDER LH & REAR FENDER RH. STRAIGHTEN AND PANEL BEAT ACCIDENT AREAS	1.00	2,000.00	0.00	2,000.00		Y	800
TOTAL:		3,860.00	0.00	3,860.00			

MATERIALS

1 BOOTLID	1.00	1,681.40	336.28	1,345.12	L	Y	bt
2 BOOTLID WEATHERSTRIP	1.00	138.55	27.71	110.84	L	Y	int
3 BOOTLID EMBLEM-LOGO	1.00	32.67	6.53	26.14	L	Y	ner
4 BOOTLID EMBLEM-I 40	1.00	38.55	7.71	30.84	L	Y	ner
5 BOOTLID EMBLEM-CRDI	1.00	36.50	7.30	29.20	L	Y	ner
6 BOOTLID INSULATOR	1.00	223.21	44.64	178.57	L	Y	x
7 BOOTLID LAMP LH	1.00	565.60	113.12	452.48	L	Y	crn
8 BOOTLID LAMP RH	1.00	565.60	113.12	452.48	L	Y	x
9 BOOTLID LOCK CATCH	1.00	38.46	7.69	30.77	L	Y	x
10 BOOTLID LOCK	1.00	228.80	45.76	183.04	L	Y	bt
11 BOOTLID HINGE LH	1.00	165.88	33.18	132.70	L	Y	Ry
12 BOOTLID HINGE RH	1.00	165.88	33.18	132.70	L	Y	Ry
13 REAR BUMPER	1.00	599.68	119.94	479.74	L	Y	der
14 REAR BUMPER REINFORCEMENT	1.00	438.40	87.68	350.72	L	Y	crn
15 REAR BUMPER REINFORCEMENT BRACKET LH	1.00	110.33	22.07	88.26	L	Y	bt
16 REAR BUMPER REINFORCEMENT BRACKET RH	1.00	110.33	22.07	88.26	L	Y	bt
17 REAR BUMPER SPONGE	1.00	150.15	30.03	120.12	L	Y	x
18 REAR BUMPER RETAINER LH	1.00	49.14	9.83	39.31	L	Y	ner
19 REAR BUMPER RETAINER RH	1.00	49.14	9.83	39.31	L	Y	x

DING AUTOMOTIVE PTE LTD
 Blk 10 Sin Ming Industrial Estate Sector C
 #01-20

CLAIM DETAILS
 Singapore 575645

Tel: 6452 1208 Fax: 6452 0614

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
20 REAR BUMPER REFLECTOR LH	1.00	42.50	8.50	34.00	L	Y	<u>cut</u>
21 REAR BUMPER REFLECTOR RH	1.00	42.50	8.50	34.00	L	Y	<u>X</u>
22 REAR BUMPER DIFFUSER	1.00	253.40	50.68	202.72	L	Y	<u>cut</u>
23 END PANEL	1.00	629.95	125.99	503.96	L	Y	<u>RP</u>
24 END PANEL TOP GARNISH	1.00	215.45	43.09	172.36	L	Y	<u>X</u>
25 END PANEL INNER	1.00	565.22	113.04	452.18	L	Y	<u>Rv</u>
26 SPARE TYRE PANEL	1.00	852.80	170.56	682.24	L	Y	<u>X</u>
27 BOOTLID REG-GARNISH	1.00	774.50	154.90	619.60	L	Y	<u>de</u>
28 BOOTLID REG-GARNISH CHROME	1.00	184.23	36.85	147.38	L	Y	<u>cut</u>
29 REAR TAIL LAMP LH	1.00	565.50	113.10	452.40	L	Y	<u>ov</u>
30 REAR TAIL LAMP RH	1.00	565.50	113.10	452.40	L	Y	<u>X</u>
31 BOOTLID STICKER-COMFORTDELGRO	1.00	120.00	0.00	120.00	S	Y	<u>ng</u>
BOOKING 65521111							
32 BOOTLID INSULATOR CLIP SET	1.00	35.00	0.00	35.00	S	Y	<u>ne</u> 20
33 REAR BUMPER CLIP SET	1.00	35.00	0.00	35.00	S	Y	<u>ne</u> 30
34 REAR BUMPER RUBBER PROTECTOR PAD	1.00	180.00	0.00	180.00	S	Y	<u>ne</u>
35 REAR BUMPER REVERSE SENSOR SET	1.00	250.00	0.00	250.00	S	Y	<u>200mm</u>
36 REAR END PANEL SEALANT	1.00	80.00	0.00	80.00	S	Y	<u>X</u>
37 REAR FENDER ADS STICKER LH	1.00	125.00	0.00	125.00	S	Y	<u>X</u>
38 REAR FENDER ADS STICKER RH	1.00	125.00	0.00	125.00	S	Y	<u>X</u>
39 REAR FENDER SEALANT LH	1.00	50.00	0.00	50.00	S	Y	<u>X</u>
40 REAR FENDER SEALANT RH	1.00	50.00	0.00	50.00	S	Y	<u>X</u>
TOTAL:		11,129.82	0,015.98	9,113.84			
TOTAL PARTS & LABOUR :		14,989.82	2,015.98	12,973.84			

EXCESS/LOADING:S\$ 0.00

No. Of Day: 6

RE-SURVEY: BEFORE/AFTER PAINTING

PART-BY-PART OR LUMP SUM: S\$

DATE OF SURVEY: 8/4/19

SURVEYED BY: Taufik

CONTACT NO: 92495799 FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto001

Ding Auto User 1

ESTIMATOR

STA AUTOCENTRE

TEL:

FAX:

taufik@lkkauto.com

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

G-STAR-WI-ET-001-02-Rev00