

REPAIR ESTIMATE*

VEHICLE NO : SHB 6688X

DATE 8/4/2019 10:43

MAKE :

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover — <i>conf</i>			\$ 538.80
	Front Bumper Bracket Top (LH) <i>Xm</i>			\$ 22.40
	Front Bumper Protector (LH) <i>Xm</i>			\$ 29.20
	Headlamp (LH) — <i>head</i>			\$ 797.90
	Front Fender (LH) — <i>bumper</i>			\$ 593.00
	Front Fender Shield (LH) <i>X sm</i>			\$ 86.00
	Front Fender Retainer <i>X sm</i>			\$ 9.20
	SUB TOTAL			\$ 2,076.50
	LESS 20%			\$ 415.30
	DISCOUNTED TOTAL			\$ 1,661.20
	Labour Charge			
	Panel Beating			\$ 200
	Spray Painting Charge			\$ 400.00
	Wiring Charge			\$ 600.00
	Tuff Kote			\$ 50.00
	TOTAL LABOUR			\$ 1,100.00
	ESTIMATE TOTAL			\$ 2,761.20

Kalin 16RM

8/4/19 1415hr

3 Days

45

After Repair photo

- Like Auto Centre must notify the Repairer of the following:
- To resurvey before painting
 - To display damaged parts during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.