

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/OD/0440/2019/DY
Date : 5-Apr-19

Vehicle IN workshop. Kindly arrange for survey.

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Au Kok Hua
Address : 103 Cardiff Groves
#03-33
Singapore 558962
Telephone : HP +65 97485439
Type of Claim : Own Damage Claims
Policy No. : 2100407252-04
Vehicle No : **SKT 2218 R**
Model Code : Audi A3 Sedan 1.4 TFSI
Model / Year : Mar-15
Engine No : CZC 224323
Chassis No : WAUZZZ8V3F1069489
Mileage : -
Date In : 3-Apr-19
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 3-Apr-19
Place of Accident : Along PIE towards CTE exit

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKT 2218 R

S/N	Nature of Jobs	Estimated Charges
1	To remove and transfer front wire harness for headlights, horns, outside temperature sensor and headlight washer assy.	s/n \$ 360.00 ✓
2	To remove and renew aircon condenser, radiator, additional radiator, electrical fans and control unit. To carry out vacuum/regas and to pressurise cooling system.	s/n \$ 1,200.00 ✓
3	To dismantle and renew front bumper, both front fender, both headlights and bonnet. Renew front lock carrier and align to position. Reorganise crash management components. Reinstall all parts removed.	\$ 5,600.00 3250. Inclusive of lock carrier.
4	To respray front bumper, bonnet hinges, both front fender and bonnet.	\$ 3,500.00 2200
5	To carry out diagnostic check.	s/n \$ 192.00 ✓
TOTAL LABOUR CHARGES		: \$ <u>10,852.00</u>

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKT 2218 R

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	\$ 1,830.00	—
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 170.00	+
3	FRONT BUMPER COVER TRM-LH/RH <i>new</i>	2 \$ 296.00	✓
4	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	\$ 148.00	+
5	FRONT BUMPER PULL STRAP-LOWER <i>new</i>	4 \$ 187.00	✓
6	FRONT BUMPER GUIDE SECTION-LH/RH <i>new</i>	2 \$ 70.00	+
7	FRONT BUMPER AIR GUDIE GRILLE-LH/RH <i>missing</i>	2 \$ 198.00	✓
8	RADIATOR GRILLE <i>new</i>	\$ 637.00	✓
9	RADIATOR GRILLE COVER <i>new</i>	\$ 89.00	✓
10	FRONT BUMPER REINFORCEMENT BEAM <i>Best</i>	\$ 660.00	✓
11	FOAM FILLER PIECE <i>new</i>	\$ 125.00	✓
12	FRONT BUMPER COVER ?	\$ 51.00	?
13	SIGN 'CAUTION' ?	\$ 13.00	?
14	AIR CONDITIONER STICKER ?	\$ 7.00	?
15	SIGNAL HORN-LH LOW TONE ?	\$ 182.00	?
16	SIGNAL HORN-RH HIGH TONE ?	\$ 182.00	?
17	FRONT FENDER-LH/RH <i>RH Distorted</i>	2 \$ 1,556.00 778	
18	FRONT FENDER ATTACHMENT PARTS ?	2 \$ 130.00	+
19	FRONT FENDER BRACKET-LH/RH <i>new</i>	2 \$ 70.00	+
20	FRONT FENDER BRACE-LH/RH	2 \$ 176.00	+
SUB TOTAL SPARE PARTS		\$ 6,777.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKT 2218 R

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FRONT WHEEL HOUSING LINER-LH/RH <i>new</i>	2 \$	316.00 +
22	FRONT WHEEL HOUSING LINER ATTACHMENT PART <i>new</i>	2 \$	161.00 +
23	BONNET <i>Damaged</i>	\$	2,898.00 ✓
24	BONNET ATTACHMENT PARTS ?	\$	149.00 ?
25	BONNET LID HINGE-LH/RH <i>new</i>	2 \$	112.00 +
26	BONNET GAS FILLED STRUT <i>new</i>	\$	109.00 +
27	BONNET CATCH HOOK ?	2 \$	81.00 ?
28	BONNET LOCK BAR ?	2 \$	200.00 ?
29	BONNET EDGE PROTECTION FRONT <i>new</i>	\$	25.00 ✓
30	BONNET COVER-LH/RH ?	2 \$	74.00 ?
31	BONNET CATCH HOOK ?	\$	58.00 ?
32	BONNET LID LOCK WITH MICRO SWITCH <i>Damaged</i>	2 \$	367.00 ✓
33	FLAT CONNECTOR HOUSING <i>new</i>	\$	12.00 ?
34	BONNET LATCH LOCK COVER ?	2 \$	7.00 ?
35	BONNET BOWDEN CABLE ?	\$	53.00 ?
36	BONNET LID LOCK CABLE ?	\$	67.00 ?
37	BONNET LOCK CABLE COVER ?	\$	9.00 ?
38	HEADLIGHT-LH/RH <i>RH covered, LH ?</i>	2 \$	3,650.00 1825.
39	BONNET LIFT CYLINDER-LH/RH ?	2 \$	362.00 ?
40	HEADLIGHT WASHER HOSE <i>not in</i>	\$	170.00 +
SUB TOTAL SPARE PARTS		\$	15,657.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SKT 2218 R

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
42	WASH WATER RESERVOIR ?	\$ 186.00	?
43	BONNET SOUND ABS ?	\$ 201.00	?
44	FRONT LOCK CARRIER WITH MOUNTING ?	\$ 663.00	?
45	A/C CONDENSER WITH FLUID RESERVOIR ?	\$ 516.00	?
46	REFRIGERANT LINE FOR A/C COMPRESSOR TO CONDESEI	\$ 461.00	+
47	REFRIGERANT LINE FOR A/C CONDENSER CUT OFF POINT	\$ 601.00	+
48	RADIATOR ?	\$ 878.00	?
49	INTERCOOLER ?	\$ 837.00	?
50	COOLANT CONCENTRATE 1.5 LTR ?	4 \$ 137.00	?
51	RADIATOR FAN WITH FAN RING ?	\$ 1,483.00	?
52	FRONT RADIATOR GRILLE SUPPORT AIR DUCT ?	2 \$ 44.00	?
53	RADIATOR SEAL STRIP-RH OUTER ?	\$ 8.00	?
54	RADIATOR AIR DUCT UPPER CENTRE ?	\$ 11.00	?
55	FRONT NO. PLATE <i>Best</i>	S/N \$ 25.00	—
56	SUNDRIES ?	\$ 1,000.00	?
TOTAL SPARE PARTS		\$ 22,708.00	
TOTAL LABOUR CHARGES		\$ 10,852.00	
GRAND TOTAL		\$ 33,560.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Ling
Surveyed Date : 08/04/91
Authorised Date :
Excess Cost :
Liability :
Remarks : not Authorised, 09 Pags

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note

- : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant