

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200616038C
 GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
 18 SIN MING LANE #01-08 MIDVIEW CITY
 SINGAPORE 573960

Contact : 66550005 97257697

TP Lon Pac
 Ashes.

ESTIMATE

Repair Code : CLM15161

Date in : 05/04/2019

Vehicle Num. : SLL8553M

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31220300/LEB5920319

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BONNET <i>Repair</i>	1	892.30	X 892.30
FRONT BONNET HINGES L/R	2	48.50	X 97.00
FRONT BONNET INNER RUBBER GUIDE STOPPER L/R <i>Not Nec</i>	2	23.80	X 47.60
FRONT BONNET INNER SIDE MOULDING L/R	2	37.50	X 75.00
FRONT BUMPER <i>Deformed</i>	1	801.70	✓ 801.70
FRONT BUMPER FOGLAMP BRACKET RH <i>Not Nec</i>	1	48.00	X 48.00
FRONT BUMPER FOGLAMP GARNISH RH	1	45.00	X 45.00
FRONT BUMPER FOGLAMP RH	1	327.70	X 327.70
FRONT BUMPER LOWER GRILLE <i>Not Nec</i>	1	77.50	X 77.50
FRONT BUMPER LOWER LID	1	381.00	X 381.00
FRONT BUMPER SIDE RETAINER L/R <i>RH Damaged</i>	2	20.60	2060 41.20
FRONT BUMPER TOW HOOK COVER <i>Not Nec</i>	1	17.10	X 17.10
FRONT FENDER 'HYBRID' EMBLEM RH <i>Not Nec</i>	1	58.00	✓ 58.00
FRONT FENDER ARCH GARNISH RH <i>Deformed</i>	1	220.00	✓ 220.00
FRONT FENDER INNER SHIELD RH	1	78.00	✓ 78.00
FRONT FENDER RH <i>Distorted</i>	1	580.00	✓ 580.00
FRONT GRILLE	1	351.80	X 351.80
FRONT GRILLE 'LOGO' EMBLEM <i>Not Nec</i>	1	23.40	X 23.40

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005 97257697

ESTIMATE

Repair Code : CLM15161

Date in : 05/04/2019

Vehicle Num. : SLL8553M

Model : HONDA VEZEL HYBRID 1.5X AUTO

Chassis/Eng# : RU31220300/LEB5920319

FRONT GRILLE CENTER BRACKET	1	76.00	x 76.00
FRONT GRILLE CHROME MOULDING	1	98.00	x 98.00
FRONT GRILLE OUTER COVER	1	421.00	x 421.00
FRONT GRILLE TOP GARNISH	1	85.00	x 85.00
FRONT HEADLAMP L/R <i>RH cracked</i>	2	1784.50	<i>3577.80</i> 1784.50 3569.00
FRONT HEADLAMP LOWER BRACKET L/R <i>RH cracked</i>	2	35.00	<i>2862.24</i> 35 70.00
FRONT HEADLAMP SIDE BRACKET L/R <i>Here</i>	2	35.00	x 70.00
FRONT RH SPORT RIM <i>Not on</i>	1	815.00	x 815.00
Subtotal before discount			9,366.30
Percentage discount 20%			1,873.26
Sub-total 1			7,493.04
FRONT BUMPER CLIPS - SET <i>Nec</i>	1	80.00	80 80.00
FRONT FENDER ARCH GARNISH CLIPS RH - SET	1	30.00	✓ 30.00
FRONT FENDER INNER SHIELD CLIPS RH - SET <i>90</i>	1	30.00	✓ 30.00
FRONT GRILLE CLIPS - SET <i>Not on</i>	1	50.00	x 50.00
FRONT TYRE RH 215/60R16	1	400.00	x 400.00

*** This is a computer-generated document which requires no signature.***

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD
18 SIN MING LANE #01-08 MIDVIEW CITY
SINGAPORE 573960

Contact : 66550005 97257697

ESTIMATE

Repair Code : CLM15161
Date in : 05/04/2019
Vehicle Num. : SLL8553M
Model : HONDA VEZEL HYBRID 1.5X AUTO
Chassis/Eng# : RU31220300/LEB5920319

Subtotal before discount	590.00
Percentage discount 0%	0.00
Sub-total 2	590.00
Parts-total	8,083.04

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To road test driving, check and resetting wheel alignments system.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

1290	30 80.00
	X 150.00
	650 900.00
	600 600.00
	X 100.00
Labour Total	1,830.00
Parts & Labour Total	9,913.04

*** This is a computer-generated document which requires no signature.***

page 3

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 4242.24

4/s. 34K

05 Days

34K