

Please arrange to survey vehicle at
8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT
SINGAPORE 415875

ABWIN 諭輝

Date : 08/04/2019
TP Vehicle No. : GZ -4579-B
To : **EQ INSURANCE COMPANY LTD**
Attn : **Motor Claim Department**

LINDA LIAO
ABWIN SERVICE PTE LTD
DID: 67139417
Fax: 67139415
HP: 97519596

Owner : LIM BENG
NTUC INCOME INSURANCE CO-OPERATIVE LTD

Certificate No. : 5095913522

Accident Date: 05/04/2019

Vehicle No. : SJS-1989-Y

Make & Model : CHEVROLET AVEO 1.4MT 5DR T255

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
List Item			
1	FRONT BUMPER	17 \$980.60	X
1	FRONT BUMPER RETAINER RH	17 \$95.60	X
1	FRONT BUMPER RETAINER LH	17 \$95.60	X
10	FRONT BUMPER BUMPER CLIPS	17 \$60.00	X
1	LH WING MIRROR	355.00 one \$550.60	—
1	LH FRONT FENDER	468.00 body \$1,850.60	—
1	LH FRONT FENDER INNER SHIELD	17 \$198.60	X
10	LH FRONT FENDER INNER SHIELD CLIPS	17 \$50.00	X
1	LH FRONT DOOR	820.00 3025.00 \$2,150.60	—
1	LH FRONT DOOR HINGE BOTTOM	17 \$165.60	X
1	LH FRONT DOOR HINGE UPPER	17 \$165.60	X
1	LH FRONT DOOR CHECKER	17 \$185.60	X
1	LH FRONT DOOR INNER MOULDING	17 \$185.60	X
1	LH FRONT DOOR INNER HANDLE	17 \$350.60	X
1	LH FRONT DOOR OUTER HANDLE	155.00 34 \$450.60	—
1	LH FRONT DOOR BLACK TAPE	60.00 22 \$185.60	—
1	LH FRONT DOOR LOCK	17 \$385.60	X
1	LH FRONT DOOR INNER TRIM BOARD	17 \$680.90	X
1	LH REAR DOOR	820 3025.00 \$2,150.60	—
1	LH REAR DOOR LOCK	17 \$385.60	X
1	LH REAR DOOR INNER MOULDING	17 \$185.60	X
1	LH REAR DOOR BLACK TAPE	60.00 22 \$185.60	—
1	LH REAR DOOR CHECKER	17 \$185.60	X
1	LH REAR DOOR HINGE BOTTOM	17 \$165.60	X
1	LH REAR DOOR HINGE UPPER	17 \$165.60	X
1	LH REAR DOOR INNER TRIMBOARD	17 \$680.90	X
1	LH REAR FENDER	2 \$1,850.60	X
1	LH REAR FENDER INNER SHIELD	17 \$198.60	X
10	LH REAR FENDER INNER SHIELD CLIPS	17 \$60.00	X

Date : 08/04/2019
 TP Vehicle No. : GZ -4579-B
 To : EQ INSURANCE COMPANY LTD
 Attn : Motor Claim Department

Owner : LIM BENG
 NTUC INCOME INSURANCE CO-OPERATIVE LTD
 Certificate No. : 5095913522
 Vehicle No. : SJS-1989-Y
 Make & Model : CHEVROLET AVEO 1.4MT 5DR T255

LINDA LIAO
 ABWIN SERVICE PTE LTD
 DID: 67139417
 Fax: 67139415

- To resurvey before/after repair.
- To display damaged parts to surveyor
- Parts prices are subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be approved by the insurance company

Accident Date: 05/04/2019

Acknowledged by Repairer

Signature:

Date:

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
1	REAR BUMPER	1 \$685.60	X
1	REAR BUMPER RETAINER RH	17 \$195.60	X
1	REAR BUMPER RETAINER LH	17 \$195.60	X
10	REAR BUMPER CLIPS	17 \$50.00	X
	Sub Total	\$16,129.00	
	Discount 10% on Parts	(\$1,612.90)	
		\$14,516.10	2268 2471.2

Special Nett

1	LH FRONT TYRE	17 \$350.00	X
1	LH FROTN SPORT RIM	17 \$450.00	X
1	LH REAR TYRE	17 \$350.00	X
1	LH REAR SPORT RIM	17 \$450.00	X
	Sub Total	\$1,600.00	

Labour & Misc

TO STAIGHTEN AND PANEL BEAT ACCIDENT AREAS	\$2,500.00	600
TO SPRAY PAINT ON AFFECTED AREAS	\$2,500.00	1100
TO TRANSFER AND REFIX FRONT LH DOOR FIXTURE	\$250.00	60
TO TRANSFER & REFIX REAR DOOR FIXTURE & FITTING	\$250.00	60
TO APPLY TUFF KOTE ON AFFECTED AREA.	\$150.00	80
TO CHECK LIGHTING AND FOCUS TAILAMP	\$150.00	20
TO REMOVE AND INSTALL SPORE RIM AND CONDUCT ALIGNMENT	\$150.00	60
TO CONDUCT WHEEL ALIGNMENT	\$150.00	
TO REMOVE AND REFIX REVERSE SEMSOR AND CHECK WIRING	17 \$150.00	X
TO REMVOE AND INSTALL TYRE AND BALANCING	17 \$150.00	X
Sub Total	\$6,400.00	

Sub Total

\$22,516.10

Date : 08/04/2019
TP Vehicle No. : GZ -4579-B
To : **EQ INSURANCE COMPANY LTD**
Attn : **Motor Claim Department**

LINDA LIAO
ABWIN SERVICE PTE LTD
DID: 67139417
Fax: 67139415
HP: 97519596

Owner : LIM BENG
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 5095913522
Vehicle No. : SJS-1989-Y
Make & Model : CHEVROLET AVEO 1.4MT 5DR T255

Accident Date: 05/04/2019

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
	GST 7%	\$1,576.13	
	Total	\$24,092.23	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: