

ASSIGNMENT (Office)

From (Person) chong Boon sen

of

CTE

Date/Time: 8/4/19 @ 9.56am

Estimated Cost:

Bill to:

OD (TP) / WS / TP RES / OD RES / EVA / INV / INV / CS

To Inspect Vehicle No.

8KR1273Y

Insured

GBH 6461Y

at Workshop no/

Siong Lee

Tel:

6453 1255

of

160 Sin Ming Drive #02-07

Policy No.

Claim No.

SNM19D201541

Sum Insured

Excess:

Make of Veh:

(Client's Record)

D.O.A.

4/4/2019

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time:

12.25pm @ 8/4/19

Person Contacted:

Ms. Liew

Vehicle IN/

OUT

Date/Time

Action/Instruction

(✓)

Estimate

8KR1273Y - CC3 / AIG15007005 / R/293q.2

DOA: 22/04/2015.

GBH 6461Y - X

23/5

L1 Pmp @ 3800h Summit. (16/10/19 @ 10:17 am Ms. Liew
Confirmed the final figure)

(\$ 4,838.55 Red - 56%)

ASS. REC. BY:

REF:

A1 /
C12

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

3:30pm

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.:

Yes or No

Lum Sum:

1.B.1

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKR 12734

Yr Regn:

01, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Wagon

Make:

M. M. 400

c.c

2 PP8

Colour:

M. Grey

AC:

Insured / Std / NI / NA

Sp. Reading

97521

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WDC 1660562A 373287

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

R:

255/50R19

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal.

6

mm

R/Bal.

3

mm

L/Bal.

6

mm

L/Bal.

3

mm

D.O.A.

4/4/19

D.O.I.

11/4/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

File pass to

11/4

All party have to special order, no stock in market

RECEIVED 13 OCT 2019

Date/Time, File Pass to?

16/10/19

1)

Type

Date/Time, File Return to?

2)



Prell. Report



Final Report

Days Of Repair:

3

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. SI

Fees

Others

TOTAL

220

Add Fee:



Site Insp (\$



Interview (\$



Tech Invs (\$



Weekend (\$

Nivitha (LKK Auto)

From: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Sent: Monday, 8 April 2019 9:56 AM
To: Cheonghoh Law
Cc: assignments
Subject: RE: PRS for SKR 1273 Y accident involving vehicle GBH 6461 Y on 4 April 2019 along Pasir Ris Drive 12 Before TPE Flyover (Oref: LCH.lg/SMSL-90277.19) / our ref: SNM19D201541

Without Prejudice

Dear Sir,

We appoint LKK.

Dear LKK,

Pls pri.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | **FB:** www.facebook.com/chinataipingsg/ | **WeChat:** 太平獅城 Taiping SG 3 Anson
Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Cheonghoh Law [mailto:mail@cheonghoh.sg]

Sent: Monday, 8 April, 2019 9:50 AM

To: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>

Subject: Re: PRS for SKR 1273 Y accident involving vehicle GBH 6461 Y on 4 April 2019 along Pasir Ris Drive 12 Before TPE Flyover (Oref: LCH.lg/SMSL-90277.19) / our ref: SNM19D201541

Dear Sirs,

We refer to the above matter and to your email of even date.

Our client hereby nominate Kenneth Kong of LKK Auto Consultants Pte Ltd named in paragraph 1 of your said email to conduct the pre-repair survey of the damages to our client's vehicle arising out of the above mentioned accident.

Please be contact our client's workshop, Siong Lee Motor, 160 Sing Ming Drive #02-07 AutoCity Singapore 575722 for the survey of SKR 1273 Y.

Contact Person : Mr Tan / Ms Kwee Pin
Telephone : 6453 1255

Kindly proceed to do the needful.

Thanks & regards

Catherine

CHEONGHOH LAW CORPORATION

Blk 53 Chin Swee Road #03-05

Singapore 160053

T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

On 8 Apr 2019, at 9:07 AM, Chong Boon Sen <boonsen.chong@sg.cntaiping.com> wrote:

Without Prejudice

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.
You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Chong Boon Sen

Claims Executive
Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

W: www.sg.cntaiping.com | FB: www.facebook.com/chinataipingsg/ | WeChat: 太平獅

城 Taiping SG 3 Anson Road #16-00 Springleaf Tower Singapore 079909
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

From: Cheonghoh Law [mailto:mail@cheonghoh.sg]
Sent: Friday, 5 April, 2019 6:00 PM
To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>
Cc: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>
Subject: Re: PRS for SKR 1273 Y accident involving vehicle GBH 6461 Y on 4 April 2019 along Pasir Ris Drive 12 Before TPE Flyover (Oref: LCH.lg/SMSL-90277.19)

Dear Sirs,

We enclosed herewith our letter of PRS and await your urgent reply.

Thanks & regards
Catherine
CHEONGHOH LAW CORPORATION
Blk 53 Chin Swee Road #03-05
Singapore 160053
T: 6337 8700 | F: 6337 3700 | E: mail@cheonghoh.sg

Begin forwarded message:

From: roaming26@singtel.com.sg
Subject: Attached Image
Date: 5 April 2019 at 5:45:38 PM SGT
To: "mail@cheonghoh" <mail@cheonghoh.sg>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



松 利 摩 哆 SIONG LEE MOTOR

Company Reg. No.: 100838/00J

Sin Ming AutoCity
160 Sin Ming Drive #02-07 Singapore 575722
Tel: 6457 0410, 6453 1255 Fax: 6552 0692

We specialise in repairing all kinds of vehicles and pre-inspection servicing.
We also undertake accident insurance claims for our customers.

11 April 2019

ATTN: MOTOR CLAIM DEPARTMENT

ATTN: YANG XINPING
H/P: 9109 8532

Dear Sirs / Madam,

Accident Claim for Vehicle No.SKR 1273 Y , Involving Vehicle No.GBH 6461 Y.
Accident on 04 APRIL 2019, AT PASIR RIS DRIVE 12 BEFORE BRIDGE FLYOVER

With reference to the above vehicle. We hereby submit a list of parts required to be changed and append below the charges for changing and repairing ;

NO	PARTS REPLACEMENT	QTY	LIST PRICE
1	REAR BUMPER	1PC	\$ <i>way / car</i> 1,680.00
2	REAR BUMPER TOP CHROME	1PC	\$ <i>nd</i> 277.10
3	REAR BUMPER LOWER CHROME	1PC	\$ <i>nd</i> 1,248.00
4	REAR BUMPER INNER RETIANER	1PC	\$ <i>nd</i> 297.00
5	REAR BUMPER SIDE RETIANER	2PCS	\$ <i>nd</i> 278.00
6	REAR BUMPER LOWER COVER	1PC	\$ <i>nd</i> 266.40
7	REAR BUMPER LOWER GRILLE	1PC	\$ <i>nd</i> 490.00
8	REAR BUMPER REINFORCEMENT	1PC	\$ <i>nd</i> 878.00
9	REAR BUMPER REFLECTOR	2PCS	\$ <i>nd</i> 210.00
10	REAR END PANEL	1PC	\$ <i>nd</i> 1,785.00
TOTAL LIST PRICE			\$ 7,409.50
LESS 10%			\$ (740.95)
TOTAL AMOUNT			\$ 6,668.55

NO	PARTS REPLACEMENT	QTY	SPECIAL NETT PRICE
1	REAR BUMPER REVERSE SENSOR	2PCS	\$ <i>sen</i> 550.00
TOTAL SPECIAL NETT PRICE			\$ 550.00

LABOUR :			
1	LABOUR TO SPRAY PAINT	\$	<i>350l</i> 650.00
2	LABOUR TO PANEL BEATING	\$	<i>300l</i> 650.00
3	LABOUR TO APPLY RUST-PROOFING ON REPAIRED AND REPLACED PARTS	\$	<i>nn</i> 120.00
TOTAL LABOUR		\$	1,420.00
TOTAL AMOUNT		\$	8,638.55

THANK YOU

FROM:

SIONG LEE MOTOR

Mr Tan Leng Huat

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No alteration/retouching is allowed
- Supplies and materials must be resurveyed and is subject to final approval from Insurance Company

Authenticated by Repairer

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI19006149/KSD3N2

Date: 16/10/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN15373518033	
Claimant Vehicle No :	SKR1273Y	Insured Vehicle No :	GBH6461Y	
Date of Loss:	04/04/2019	Nature of Claim:	TP	Claim No: SNM19D201541C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKR1273Y		
Make & Model:	MERCEDES-BENZ ML400, 3.0 4MATIC (W166) (A)	Engine No:	27682130039404
Reg. Date:	19/01/2015 (Man. Year: 2014)	Chassis No:	WDC1660562A373287
Colour:	Metallic Grey	Odometer:	97521 km
Engine Capacity:	2996 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	255/50R19	Rear Tyre Size:	255/50R19
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 3 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,218.55	4,115.35	3,103.20	42.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,420.00	650.00	770.00	54.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,638.55	4,765.35	3,873.20	44.84
Approved Total (Overridden) (S\$)		3,800.00		
(S\$)	8,638.55	3,800.00	4,838.55	56.01
+ GST 7.00/7.00% (S\$)	604.70	266.00	338.70	56.01
Nett Amount (S\$)	9,243.25	4,066.00	5,177.25	56.01

INSPECTION

Date of Assignment:	12/04/2019	
Date Inspected:	11/04/2019 Inspected At:	160 Sin Ming Drive #02-07 Repairer: Siong Lee Motor Sin Ming Industrial Estate, Block 12 Sector B #01-73 Singapore 575656

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 16 Oct 2019)
Parts:	M1-SUV	MERCEDES-BENZ ML400 3.0 4MATIC (W166) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKR1273Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Warped/Cracked	1,680.00 FL	*1,680.00 FL
2	1		*REAR BUMPER TOP CHROME	Dented	277.10 FL	*277.10 FL
3	1		*REAR BUMPER LOWER CHROME	Dented	1,248.00 FL	*1,248.00 FL
4	1		*REAR BUMPER INNER RETAINER	Serviceable	297.00 FL	*- FL
5	2		*REAR BUMPER SIDE RETAINER	Serviceable	278.00 FL	*- FL
6	1		*REAR BUMPER LOWER COVER	Dented	266.40 FL	*266.40 FL
7	1		*REAR BUMPER LOWER GRILLE	Dented	490.00 FL	*490.00 FL
8	1		*REAR BUMPER REINFORCEMENT	Repair	878.00 FL	*- FL
9	2		*REAR BUMPER REFLECTOR	Serviceable	210.00 FL	*- FL
10	1		*REAR END PANEL	Repair	1,785.00 FL	*- FL
11	2		*REAR BUMPER REVERSE SENSOR	Scratched	550.00 FS	*550.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,959.50	4,511.50
- List Item Discount on L Items 10.00/10.00% (\$\$)	740.95	396.15
Total Parts (\$\$)	7,218.55	4,115.35

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR TO SPRAY PAINT	New	650.00	350.00
2	LABOUR TO PANEL BEATING	New	650.00	300.00
3	LABOUR TO APPLY RUST-PROOFING ON REPAIRED AND REPLACED PARTS	New	120.00	0.00
Gross Labour Cost (\$\$)			1,420.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >