



Name: TOH ENG WAH  
 Address: Blk 550 Choa Chu Kang St 52 #10-59  
 Singapore 680550  
 Policy Number: DMCPHQ18-006084  
 Quotation for Reinstste / Repairs for Vehicle

Date: 5/4/19  
 Vehicle No: SJJ9661L

Parts Replacement-Cost Price		Cost Price
1 Pc	Rear R/H Door	\$ 860.00 <i>bt ✓</i>

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

		\$ 860.00
1 job	To remove and replace all the parts mentioned above and knocking and straighten up the necessary affected areas	\$ 500.00 <i>400.</i>
1 job	To spray painting on affected areas	\$ 650.00 <i>550.</i>
<b>Labour's Total :</b>		<b>\$ 1,150.00</b>
<b>Sub-Total :</b>		<b>\$ 2,010.00</b>
<b>GST 7% :</b>		<b>\$ 140.70</b>
<b>Grand Total :</b>		<b>\$ 2,150.70</b>

  
 Michael Tee  
 Wah Hong Motors & Credit Pte Ltd  
 Tel: 67737377  
 Fax: 68966321  
 Email: michael@wahhong.sg



*Tauflin 97495749*  
*wp*  
*8/4/19 @ 3:20pm*  
*Resurvey after repair*  
*tauflin@11kautoburn.*  
*4 days*