



Case Details

Case Reference Number : TAX/04/19/2011
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHC4713P

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-6349-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 03/04/2019 09:45 AM
 Vehicle Age(In Months) : 56

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace ▾	
One Time Key In	Main			BUMPER CLIPS	10	1.61	16.10	25.00	12.08	Replace	10	12.08	Replace ▾	
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	1	154.27	Replace ▾	
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0.00	Check ▾	
One Time Key In	Main			ARM SUB-ASSY, RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	1	104.70	Replace ▾	
One Time Key In	Main			ANTENNA, ELECTRICAL LOWER REAR	1	157.40	157.40	10.00	141.66	Replace	1	141.66	Replace ▾	
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace ▾	
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace ▾	
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	1	54.15	Replace ▾	
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	1	88.57	Replace ▾	
Total Spare Part Cost									21,516.24		Surveyor Total		3,805.51	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)		20.00	
Final Spare Part Cost									21,516.24		Final Sur Total		3,044.41	

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	1	171.68	Replace ▾	
One Time Key In	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	66.68	Replace	1	66.68	Replace ▾	
One Time Key In	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	1	49.28	Replace ▾	
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace ▾	
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	1	71.10	Replace ▾	
One Time Key In	Main			UNDER COVER SUBASSY, RR FLOOR	1	514.50	514.50	25.00	385.88	Replace	0	0.00	Check ▾	
One Time Key In	Main			EXHAUST HEAT SHIELD, REAR	1	107.40	107.40	25.00	80.55	Replace	0	0.00	Check ▾	
One Time Key In	Main			EXHAUST TAIL PIPE	1	656.20	656.20	25.00	492.15	Replace	0	0.00	Check ▾	
One Time Key In	Main			SUPPORT, EXHAUST REAR	2	33.60	67.20	25.00	50.40	Replace	0	0.00	Check ▾	
One Time Key In	Main			TAILGATE ASY	1	1,007.90	1,007.90	25.00	755.92	Replace	1	755.92	Replace ▾	
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, LH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace ▾	
One Time Key In	Main			TAIL GATE DOOR GLASS MOULDING, RH	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace ▾	
One Time Key In	Main			MOULDING BACK WINDOW, LOWER NO.1	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace ▾	
One Time Key In	Main			DAM, BACK DOOR GLASS ADHESIVE, NO.1	1	27.30	27.30	25.00	20.48	Replace	1	20.48	Replace ▾	
One Time Key In	Main			DAM, BACK DOOR GLASS ADHESIVE, NO.2	1	17.40	17.40	25.00	13.05	Replace	1	13.05	Replace ▾	

Total Spare Part Cost		21,516.24		Surveyor Total	3,805.51	
Lump Sum Discount (%)		0.00		Lump Sum Dis (%)	20.00	
Final Spare Part Cost		21,516.24		Final Sur Total	3,044.41	

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			MOULDING, BACK WINDOW, LOWER NO.2	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace ▾	
One Time Key In	Main			MOULDING, BACK WINDOW, OUTSIDE LH NO.2	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace ▾	
One Time Key In	Main			MOULDING, BACK WINDOW, OUTSIDE RH NO.2	1	29.40	29.40	25.00	22.05	Replace	1	22.05	Replace ▾	
One Time Key In	Main			SEALANT W/SCREEN	3	37.00	111.00	25.00	83.25	Replace	3	83.25	Replace ▾	
One Time Key In	Main			TAILGATE DOOR HINGE LH/RH	2	58.30	116.60	25.00	87.45	Replace	0	0.00	Check ▾	
One Time Key In	Main			TAILGATE DOOR LOCK	1	444.10	444.10	25.00	333.08	Replace	0	0.00	Check ▾	
One Time Key In	Main			TAILGATE DOOR STAY LH	1	241.50	241.50	25.00	181.13	Replace	0	0.00	Check ▾	
One Time Key In	Main			TAILGATE DOOR STAY RH	1	241.50	241.50	25.00	181.13	Replace	0	0.00	Check ▾	
One Time Key In	Main			TAILGATE DOOR WEATHER STRIP	1	353.40	353.40	25.00	265.05	Replace	0	0.00	Check ▾	
One Time Key In	Main			TAILGATE LOCK, COVER	1	15.70	15.70	25.00	11.77	Replace	0	0.00	Check ▾	
One Time Key In	Main			TAILGATE OUTSIDE GARNISH	1	504.90	504.90	25.00	378.67	Replace	1	378.67	Replace ▾	
One Time Key In	Main			STRIKER, BACK DOOR	1	48.90	48.90	25.00	36.67	Replace	0	0.00	Check ▾	
One Time Key In	Main			TAILGATE TRIM, LH	1	85.90	85.90	25.00	64.43	Replace	0	0.00	Check ▾	
One Time Key In	Main			TAILGATE TRIM, LOWER	1	180.70	180.70	25.00	135.52	Replace	0	0.00	Check ▾	
One Time Key In	Main			TAILGATE TRIM, RH	1	88.30	88.30	25.00	66.22	Replace	0	0.00	Check ▾	

Total Spare Part Cost		21,516.24	Surveyor Total		3,805.51
Lump Sum Discount (%)		0.00	Lump Sum Dis (%)		20.00
Final Spare Part Cost		21,516.24	Final Sur Total		3,044.41

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			TAILGATE TRIM, UPPER	1	49.60	49.60	25.00	37.20	Replace	0	0.00	Check ▾	
One Time Key In	Main			TAILGATE, BOARD ASSY	1	246.90	246.90	25.00	185.18	Replace	0	0.00	Check ▾	
One Time Key In	Main			WIRE, BACK DOOR, NO.1	1	582.40	582.40	25.00	436.80	Replace	0	0.00	Not Give ▾	
One Time Key In	Main			SWITCH ASSY, BACK DOOR OPENER	1	146.10	146.10	10.00	131.49	Replace	0	0.00	Check ▾	
One Time Key In	Main			EMBLEM REAR	1	60.30	60.30	25.00	45.22	Replace	1	45.22	Replace ▾	
One Time Key In	Main			LICENSE PLATE LAMP	1	35.70	35.70	10.00	32.13	Replace	0	0.00	Check ▾	
One Time Key In	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	0	0.00	Not Give ▾	
One Time Key In	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	0	0.00	Not Give ▾	
One Time Key In	Main			NAME PLATE (HYBRID)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace ▾	
One Time Key In	Main			NAME PLATE (PRIUS)	1	60.80	60.80	25.00	45.60	Replace	1	45.60	Replace ▾	
One Time Key In	Main			NAME PLATE (TOYOTA)	1	51.90	51.90	25.00	38.92	Replace	1	38.92	Replace ▾	
One Time Key In	Main			SPOILER REAR	1	953.70	953.70	25.00	715.28	Replace	0	0.00	Check ▾	
One Time Key In	Main			3RD BRAKE LAMP	1	231.30	231.30	10.00	208.17	Replace	0	0.00	Check ▾	
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace ▾	
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace ▾	

Total Spare Part Cost 21,516.24

Surveyor Total 3,805.51

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 20.00

Final Spare Part Cost 21,516.24

Final Sur Total 3,044.41

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			END PANEL	1	602.10	602.10	25.00	451.58	Replace	1	451.58	Replace ▾	
One Time Key In	Main			END PANEL COVER, DECK TRIM HOLE	1	46.10	46.10	25.00	34.58	Replace	0	0.00	Check ▾	
One Time Key In	Main			END PANEL COVER, DECK TRIM, RR	1	121.10	121.10	25.00	90.82	Replace	0	0.00	Check ▾	
One Time Key In	Main			REINFORCEMENT, RR	2	34.60	69.20	25.00	51.90	Replace	0	0.00	Check ▾	
One Time Key In	Main		4006314	SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	1	37.00	Replace ▾	
One Time Key In	Main			SPARE TYRE PANEL	1	667.70	667.70	25.00	500.78	Replace	0	0.00	Not Give ▾	
One Time Key In	Main			MEMBER SUB-ASSY, RR LH	1	174.10	174.10	25.00	130.57	Replace	0	0.00	Check ▾	
One Time Key In	Main			MEMBER SUB-ASSY, RR RH	1	174.10	174.10	25.00	130.57	Replace	0	0.00	Check ▾	
One Time Key In	Main			FLOOR PANEL RR/LH	1	102.00	102.00	25.00	76.50	Replace	0	0.00	Check ▾	
One Time Key In	Main			FLOOR PANEL RR/RH	1	209.90	209.90	25.00	157.43	Replace	0	0.00	Check ▾	
One Time Key In	Main			BOX, DECK FLOOR, RR	1	649.70	649.70	25.00	487.28	Replace	0	0.00	Not Give ▾	
One Time Key In	Main			BOX, RR FLOOR, BOARD	1	679.60	679.60	25.00	509.70	Replace	0	0.00	Not Give ▾	
One Time Key In	Main			BOARD, RR FLOOR	1	392.30	392.30	25.00	294.23	Replace	0	0.00	Not Give ▾	
One Time Key In	Main			BOARD ASSY, RR RH	1	379.20	379.20	25.00	284.40	Replace	0	0.00	Not Give ▾	
One Time Key In	Main			SPACER, RR FLOOR	1	130.60	130.60	25.00	97.95	Replace	0	0.00	Not Give ▾	
Total Spare Part Cost									21,516.24		Surveyor Total	3,805.51		
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)	20.00		
Final Spare Part Cost									21,516.24		Final Sur Total	3,044.41		

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BOX, DECK FLOOR, COVER LH	1	230.10	230.10	25.00	172.57	Replace	0	0.00	Not Give ▾	
One Time Key In	Main			BOX, DECK FLOOR, LH	1	196.80	196.80	25.00	147.60	Replace	0	0.00	Not Give ▾	
One Time Key In	Main			COVER ASSY, TONNEAU	1	602.10	602.10	25.00	451.58	Replace	0	0.00	Not Give ▾	
One Time Key In	Main			CUSHION, SPARE WHEEL	1	230.80	230.80	25.00	173.10	Replace	0	0.00	Check ▾	
One Time Key In	Main			PROTECTOR, SPARE	1	143.70	143.70	25.00	107.77	Replace	0	0.00	Check ▾	
One Time Key In	Main			CARRIER, SPARE	1	19.70	19.70	25.00	14.77	Replace	0	0.00	Check ▾	
One Time Key In	Main		6503707	TYRE	1	126.74	126.74	25.00	95.05	Replace	0	0.00	Not Give ▾	
One Time Key In	Main			WHEEL, DISC	1	1,490.20	1,490.20	25.00	1,117.65	Replace	0	0.00	Not Give ▾	
One Time Key In	Main			BREAKDOWN SIGN	1	35.00	35.00	0.00	35.00	Replace	0	0.00	Check ▾	
One Time Key In	Main			PANEL ASSY, DECK LH	1	307.00	307.00	25.00	230.25	Replace	0	0.00	Check ▾	
One Time Key In	Main			PANEL ASSY, DECK RH	1	307.00	307.00	25.00	230.25	Replace	0	0.00	Check ▾	
One Time Key In	Main			BATTERY	1	278.00	278.00	10.00	250.20	Replace	0	0.00	Check ▾	
One Time Key In	Main			BATTERY CLAMP	1	16.10	16.10	25.00	12.08	Replace	0	0.00	Check ▾	
One Time Key In	Main			BATTERY TRAY	1	42.80	42.80	25.00	32.10	Replace	0	0.00	Check ▾	
One Time Key In	Main			WIRE, FLOOR	1	1,675.00	1,675.00	10.00	1,507.50	Replace	0	0.00	Not Give ▾	

Total Spare Part Cost	21,516.24		Surveyor Total	3,805.51	
Lump Sum Discount (%)	0.00		Lump Sum Dis (%)	20.00	
Final Spare Part Cost	21,516.24		Final Sur Total	3,044.41	

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			WIRE, FLOOR, NO.2	1	1,305.40	1,305.40	10.00	1,174.86	Replace	0	0.00	Not Give ▾	
One Time Key In	Main			PANEL SUB-ASSY, QTR	1	588.40	588.40	25.00	441.30	Replace	0	0.00	Not Give ▾	
One Time Key In	Main			PANEL SUB-ASSY, QTR WHEEL HOUSE	1	588.40	588.40	25.00	441.30	Replace	0	0.00	Not Give ▾	
One Time Key In	Main			TAIL LAMP BRACKET, LH	1	30.70	30.70	25.00	23.02	Replace	0	0.00	Check ▾	
One Time Key In	Main			TAIL LAMP LH	1	548.40	548.40	10.00	493.56	Replace	0	0.00	Check ▾	
One Time Key In	Main			TROUGH, BACK DOOR LH	1	110.90	110.90	25.00	83.18	Replace	0	0.00	Not Give ▾	
One Time Key In	Main			FENDER RR/LH	1	766.80	766.80	25.00	575.10	Replace	0	0.00	Not Give ▾	
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0.00	Not Give ▾	
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	0	0.00	Not Give ▾	
One Time Key In	Main			FENDER LINER RR/LH	1	141.30	141.30	25.00	105.98	Replace	0	0.00	Not Give ▾	
One Time Key In	Main			QUARTER GLASS RR/LH	1	168.10	168.10	25.00	126.07	Replace	0	0.00	Not Give ▾	
One Time Key In	Main			SEALANT W/SCREEN	1	37.00	37.00	0.00	37.00	Replace	0	0.00	Not Give ▾	
One Time Key In	Main			TAIL LAMP BRACKET, RH	1	30.70	30.70	25.00	23.02	Replace	0	0.00	Check ▾	
One Time Key In	Main			TAIL LAMP RH	1	557.80	557.80	10.00	502.02	Replace	0	0.00	Check ▾	
One Time Key In	Main			TROUGH, BACK DOOR	1	110.90	110.90	25.00	83.18	Replace	0	0.00	Not Give ▾	

Total Spare Part Cost	21,516.24	Surveyor Total	3,805.51
Lump Sum Discount (%)	0.00	Lump Sum Dis (%)	20.00
Final Spare Part Cost	21,516.24	Final Sur Total	3,044.41

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			FENDER RR/RH	1	766.80	766.80	25.00	575.10	Replace	0	0.00	Not Give	
One Time Key In	Main			SMRT LOGO	1	7.80	7.80	0.00	7.80	Replace	0	0.00	Not Give	
One Time Key In	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	0	0.00	Not Give	
One Time Key In	Main			FENDER LINER RR/RH	1	141.30	141.30	25.00	105.98	Replace	1	105.98	Replace	
One Time Key In	Main			BUMPER FRT	1	482.00	482.00	25.00	361.50	Replace	1	0	Repair	
One Time Key In	Main			BUMPER ENERGY ABSORBER FRT	1	78.80	78.80	25.00	59.10	Replace	0	0	Not Give	
One Time Key In	Main			BUMPER REINFORCEMENT FRT	1	498.40	498.40	25.00	373.80	Replace	0	0	Not Give	
One Time Key In	Main			ARM SUB-ASSY, FR BUMPER LH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Give	
One Time Key In	Main			ARM SUB-ASSY, FR BUMPER RH	1	250.40	250.40	25.00	187.80	Replace	0	0	Not Give	
One Time Key In	Main			BRACKET, FR BUMPER	1	110.40	110.40	25.00	82.80	Replace	1	0.00	Replace	
One Time Key In	Main			NUMBER PLATE	1	15.00	15.00	0.00	15.00	Replace	1	0.00	Replace	
One Time Key In	Main			NUMBER PLATE FRAME	1	12.00	12.00	0.00	12.00	Replace	1	0.00	Replace	
One Time Key In	Main			COVER, FR BUMPER HOLE RH	1	18.50	18.50	25.00	13.88	Replace	1	0.00	Replace	
Total Spare Part Cost									21,516.24		Surveyor Total		3,805.51	
Lump Sum Discount (%)									0.00		Lump Sum Dis (%)		20.00	
Final Spare Part Cost									21,516.24		Final Sur Total		3,044.41	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			2,028.00	1,000.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	1,690.00	800.00	
2	Main	TO REPAIR FRONT PORTION	338.00	200	
Total:			2,028.00	1,000.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPSRAY FRONT BUMPER	378.00	200	
2	Main	TO SPRAY FRONT BUMPER LOWER SUB GRILLE	180.00	100	
3	Main	TO RESPRAY REAR BUMPER	378.00	200.00	
4	Main	TO RESPRAY TAIL GATE	378.00	200.00	
5	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	80.00	
6	Main	TO RESPRAY REAR SPOILER	180.00	0.00	
7	Main	TO RESPRAY REAR PANEL	180.00	100.00	
8	Main	TO RESPRAY REAR SPARE TYRE PANEL	180.00	0.00	
9	Main	TO RESPRAY REAR MEMBER,RH	180.00	0.00	
10	Main	TO RESPRAY REAR MEMBER,LH	180.00	0.00	
11	Main	TO RESPRAY RH REAR WHEEL HOUSE	180.00	0.00	
12	Main	TO RESPRAY REAR LH WHEEL HOUSE	180.00	0.00	
13	Main	TO RESPRAY REAR FLOOR SIDE PANEL RH	180.00	0.00	
14	Main	TO RESPRAY REAR FLOOR SIDE PANEL LH	180.00	0.00	
15	Main	TO RESPRAY BATTERY PANEL	180.00	0.00	
16	Main	TO RESPRAY TROUGH BACK DOOR RH	180.00	0.00	
17	Main	TO RESPRAY TROUGH BACK DOOR LH	180.00	0.00	
18	Main	TO RESPRAY REAR FENDER LH	378.00	0.00	
Total:			4,410.00	880.00	

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
19	Main	TO RESPRAY REAR FENDER RH	378.00	0.00	
Total:			4,410.00	880.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE & REFIT EXHAUST	120.00	0.00	
2	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	50.00	
3	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00	
4	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20.00	
5	Main	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	40.00	
6	Main	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	30.00	
7	Main	TO REMOVE AND REFIX REAR WINDSCREEN	240.00	120.00	
8	Main	TO REMOVE AND REFIT WIRE HARDESS	250.00	0.00	
9	Main	TO REPLACE SUNDRY PARTS	100.00	0.00	
10	Main	TO WASH AND VACUUM	60.00	0.00	
11	Main	TOWING CHARGE	56.00	0.00	
12	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	30.00	
13	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0.00	
14	Main	TO REMOVE / REFIT SEAT	120.00	0.00	
15	Main	TO ALIGN CHASSIS	350.00	0.00	
16	Main	TO REMOVE & REFIT FUEL TANK	120.00	0.00	
Total:			2,301.00	290.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	21,516.24	3,044.41

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Labour Cost	2,028.00	1,000.00
Total Spray Painting	4,410.00	880.00
Other	2,301.00	290.00
Overall Total	30,255.24	5,214.41
Lump Sum Repair Option	☒	☒
Lump Sum Total	30,250.00	5,200.00
Surveyor Approved Amount		5,200.00
No of Repair Days*	12	7
Remarks	-	L/S REPAIR, PHOTO AFTER REPAIR.
Surveyor Name		Hwee jie
Signature		
Survey Date	05/04/2019	