

INS. CASE OWNER: CHAN KWAN HONG | CC 4 / AIG1900 6157, K ^{a3} | LKR IDAC

Surveyor: KSC | DOI: ASSIGNMENT 7/4/19 | Date / Time: 8/4/19
 Registered in Merimen: 8/4/19

Pre-assign / CCU / FTE



Insured Vehicle No.: SFU 6314J
 Name of Insured: CHINE LINA SUTING
 Insured Tel No.: _____ HP: _____
 Excess Sec II :\$5 _____ D.O.A.: 7/4/19
 Is driver the owner? (YES / NO) _____ Nature of Accident: _____

Claim No.: 73719995453
 Policy No.: 180022463
 Make / Model: Mitsubishi
 Place of Accident: TAMPINES RD

If NO, Driver Name / Age: _____ OI GIA REPORT: YES / NO : _____ TP GIA REPORT: YES / NO
 Driver Tel No.: _____ (V/L: YES / NO) _____ Insured Liability: % _____ Final ? Yes / No

SUB 7381K



INSRS: _____
 WSP: why
 Tel: hol
 Liability: _____
 RMKS: _____



INSRS: _____
 WSP: _____
 Tel: _____
 Liability: _____
 RMKS: _____



INSRS: _____
 WSP: _____
 Tel: _____
 Liability: _____
 RMKS: _____



INSRS: _____
 WSP: _____
 Tel: _____
 Liability: _____
 RMKS: _____

Date/Time	STAGE	DATE / PIC
	Non-Reporting Itr (1st)	
	Non-Reporting Itr (2nd)	
	Non-Reporting Itr (Final)	
	Notification Itr (if non-pickup)	
	Call OI	
	After call Itr to OI	<u>27/06/19 - VIC</u>
	Documentation Check List: Handler	Typist
	Notification Itr (if non-pickup)	<input type="checkbox"/>
	After call Itr to OI	<input checked="" type="checkbox"/>
	Authorisation To Act	<input checked="" type="checkbox"/>
	Release Voucher	<input checked="" type="checkbox"/>
	Final Repair Bill	<input checked="" type="checkbox"/>
	Car Rental Invoice	<input checked="" type="checkbox"/>
	Towing Invoice	<input checked="" type="checkbox"/>
	LTA/GIA	<input checked="" type="checkbox"/>
	Medical Bill	<input type="checkbox"/>
	PIR	<input type="checkbox"/>
	Mandate/Reject Instruction	<input type="checkbox"/>
	LOD	<input checked="" type="checkbox"/>
	Payment Breakdown Form	<input type="checkbox"/>
	Post-Repair Photos	<input type="checkbox"/>
	Others	<input type="checkbox"/>

PRELIMINARY ADVICE Date/Time: _____ Sent By: _____

FINALIZATION Date/Time: _____ Confirm with: _____ Confirm by: _____

Repair Cost: P/P \$5 3,732.64 (5 days) Reduction: B % Email Call

FINAL SETTLEMENT Date/Time: 11/01/20 Confirm with: JUNE Email Call

Final Liability: % 100 (Assessed / Assessed) BOLA S/N No.: 27 If NO or B 28, Ass. Lia: _____

Repair Cost: (w/acc) \$5 3,993.92 (01 RATE ENDED TP)

Loss of Rental (LOR): \$5 100.00 (4 days) x \$100.00

Loss of Use (LOU): \$5 _____ (5 x days)

Loss of Income (LOI): \$5 _____ (5 x days)

LOR only LOU only LOR + LOU LOR + LOI [Tick only one]

GIA/LTA Search \$5 8.00

Medical \$5 _____

Disbursement \$5 _____ (e.g. Tow/ Independent)

Legal Cost \$5 _____

Total: \$5 4,401.92 Global Sum \$5: _____

FINAL PAYMENT Date/Time: _____ Confirm with: _____ Email Call

Payee 1: \$5 4,401.92 Name 1: CHENG HOE MOTOR PTE LTD

Payee 2: (Strike if N.A.) \$5 _____ Name 2: _____

Payee 3: (Strike if N.A.) \$5 _____ Name 3: _____

COPY SENT
14/1/2020

ASS. REC. BY:

REF: AIG /

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

QD / TP / WS / TP RES / QD RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s Cheng Hoo

of AWK

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 05 days Res.: Yes or No

Lum Sum: 1.31 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SLE 7381K Yr Regn: 07, 16

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Jazz c.c. 1496

Colour: M. Blue A/C: Insured / Std / NI / NA

Sp. Reading: 56572 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JHM GK 5850HX 200065

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Insured / Jammed / Leaked / Burnt or

Brake: Insured / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / RIM or

Tyre Size: F: 185/55R16

R: _____

BS / BUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

R/Bal. 5 mm

L/Bal. 3 mm

D.O.A. 3/14/19

Survey held at _____

Rear

R/Bal. 3 mm

L/Bal. 3 mm

D.O.I. 9/4/19

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 File pass to

8 3732.64 Confirmed Estimate
CRAB: \$ 330.00 (0%)

Panel
(4 x 100 + 60)

Date/Time, File Pass to?

: Prel. Report

: Final Report

1) _____
Date/Time, File Return to?

2) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee:

Transportation: _____
S - RS - SI

Finance

Others

TOTAL

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech Invs (\$ _____)

: Weekend (\$ _____)

Report Format :

Lump Sum / I.B.I. (\$ _____)

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST: 201001158E RCB NO: 201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

WS Ref: TP/AIG/AMK

Claim Type: Third Party

Accident Date: 03/04/2019

TP Veh Reg No: SKV6314J

Estimate No: ES1991370/AMK

Date: 09 Apr 2019

Policy No: 5102298890

Veh Reg No: SLE7381K

Make/Model: HONDA JAZZ 1.5A

Chassis No: JHMGK5850HX200065

Engine No: L15B31190022

Reg. Date: 29/07/2016

Not Adhered
Resurvey B4 paint
5 days

Estimate Repair Cost to Vehicle No :SLE7381K

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	492.50	1PC	492.50	✓
2 REAR BUMPER LH SIDE RETAINER	17.10	1PC	17.10	—
3 REAR BUMPER CLIP	3.90	5PC	19.50	—
4 REAR BUMPER LH SIDE GARNISH	45.00	1PC	45.00	—
5 LH TAILLAMP	237.50	1PC	237.50	—
6 REAR TAILGATE	814.00	1PC	814.00	—
7 TAILGATE INNER LOCK	157.40	1PC	157.40	—
8 TAILGATE INNER RUBBER	92.30	1PC	92.30	—
9 TAILGATE EMBLEM 'JAZZ'	15.50	1PC	15.50	—
10 TAILGATE WINDSCREEN GLASS MOULDING	151.30	1PC	151.30	—
11 REAR END PANEL	314.00	1PC	314.00	—
12 REAR END PANEL INNER TOP GARNISH	60.80	1PC	60.80	—
13 REAR END PANEL BUZZER SENSOR (OUTER)	85.00	1PC	85.00	—
14 REAR END PANEL BUZZER SENSOR (INNER)	58.60	1PC	58.60	—
15 REAR SPARE TYRE TOOL SPONGE	117.80	1PC	117.80	✓
			2,678.30	
		Less 20%	535.66	2,142.64
Special Net				
16 TAILGATE GLASS SEALANT	40.00	1PC	40.00	✓
			40.00	40.00
Labour				
17 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1LA	120.00	✓
18 REMOVE & REFIX REAR BUMPER, TAILGATE, SPOILER & ATTACHMENTS, TAIL LAMPS, TO CUT, WELD & RENEW REAR END PANEL, KNOCKING & REPAIR REAR SPARE TYRE PANEL, FENDERS & REALIGN THE SAME	800.00	1LA	800.00	800
19 PUTTY & RESPRAY REAR BUMPER, TAILGATE, REAR END PANEL, REAR SPARE TYRE PANEL, REAR FENDERS & ALL AFFECTED AREAS	850.00	1LA	850.00	720
20 REMOVE & REFIX REVERSE CAMERA, RESET & REPOSITION	50.00	1PC	50.00	✓
21 RUSTPROOFING	60.00	1LA	60.00	✓
			1,880.00	1,880.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "limited practical" basis
- No illegal modifications allowed
- Supplementary items in _____ and _____
- Is subject to final approval _____

Accepted by Repairer: _____
 Date: _____

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotors@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120
TEL: 64193000 **FAX:** 64153727
ATTN: Motor Claim Department
WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 03/04/2019
TP Veh Reg No: SKV6314J

Estimate No: ES1991370/AMK
Date: 09 Apr 2019
Policy No: 5102298890
Veh Reg No: SLE7381K
Make/Model: HONDA JAZZ 1.5A
Chassis No: JHMGK5850HX200065
Engine No: L15B31190022
Reg. Date: 29/07/2016

Estimate Repair Cost to Vehicle No :SLE7381K

<u>Description</u>	<u>U/Price</u>	<u>Quantity</u>	<u>List Price</u>	<u>Amount</u>
			<u>SS</u>	<u>SS</u>
			Total	SS 4,062.64
			Add GST @ 7%	284.38
			Total Amount Payable	SS 4,347.02

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

DORLYN LI

AUTHORISED SIGNATURE

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC

Owner ID: 9188A

Vehicle Details

Vehicle No.: SLE7381K

Vehicle to be Exported: No

Intended Deregistration Date: 04 Apr 2019

Vehicle Make: HONDA

Vehicle Model: JAZZ 1.5 VTIR CVT ABS D/AIRBAG 2WD

Primary Colour: Blue

Manufacturing Year: 2016

Engine No.: L15B31190022

Chassis No.: JHMGK5850HX200065

Maximum Power Output: 96.0 kW (128 bhp)

Open Market Value: \$17,059.00

Original Registration Date: 29 Jul 2016

First Registration Date: 29 Jul 2016

Transfer Count: 0

Actual ARF Paid: \$12,059.00

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 28 Jul 2026

PARF Rebate Amount: \$9,044.00

Intended COE Rebate Details

COE Expiry Date: 28 Jul 2026

COE Category: A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years): 10

QP Paid: \$52,301.00

COE Rebate Amount: \$38,255.00

Total Rebate Amount: \$47,299.00

The information contained herein is correct as at 04 Apr 2019

OK

PRE-REPAIR INSPECTION REQUEST – SLE7381K vs SKV6314J (OI) on D.O.A.: 03/04/2019

From: Hor, Yinnui
To: 'assignments@kkauto.com', Admin A (admin-a@kkauto.com)
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baijit; Abu Kassim, Noor Marissa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur
Sent: 5/4/2019 9:04:05 AM

Hi,

Please refer to the enclosed request from **Cheng Hoe Motor Pte Ltd (AMK)**.

Claim no : 2329199954SG003
Case Owner : KIAN MENG CHAN

If you have any queries/concerns, please let us know.
Kindly assist to assign Kenneth Kong as Single Joint Expert as requested.

Thanks & Regards,

Yin Rui, Hor (Viviane)
AIG
Claim Adjuster II, Singapore FNOI, Claims Operations – Auto
Shared Services – Malaysia | Global Business Services

Yinnui.Hor@aig.com | www.aig.sg

From: chmamk@singnet.com.sg [mailto:chmamk@singnet.com.sg]
Sent: Thursday, April 04, 2019 2:42 PM
To: Hor, Yinnui
Cc: Fong, Andy-SY; Chin, Lee-Ying; Kaur, Baijit; Abu Kassim, Noor Marissa; Azlan, Syazairdina; Chan, Yoke Shi; Lim, Sheng Yang; Mithoosingh, Aashweenjeetkaur
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKV6314J AND SLE7381K ON 03/04/2019

Hi,

Our Selection as follow :

- Kenneth Kong (LKK Auto Consultants Pte Ltd)

Thank you.

Rgds

Dorlyn Li

Cheng Hoe Motor Pte Ltd (AMK)

Tel : 64812001

9.49am@5/4/19
vml
Dorlyn

From: Hor, Yinrul

Sent: Thu, 4 Apr 2019 05:51:56 +0000

To: chmank@singnet.com.sg

Cc: Fong, Andy-SY, Chin, Lee-Ying, Kaur, Baljit, Abu Kassim, Noor Mariesa, Azlan, Syazairdina, Chan, Yoke Shi, Lim, Sheng Yang, Mithoosingh, Aashweenjeetkaur

Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SKV6314J AND SLE7381K ON 03/04/2019

Without Prejudice

Your Reference SLE7381K

Our Reference 2329199954SG003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
AIG In House Surveyor	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Loi	Automobile Inspection Services Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon HanXin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd
Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Gao Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufik	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thanks & Regards,

Yin Rui, Hor (Viviane)

AIG

Claire Adjuster II, Singapore FNOs, Claims Operations - Auto
Shared Services - Malaysia | Global Business Services

Yinrul.Hor@aig.com | www.aig.sg

From: Cheng Hoe Motor Pte Ltd (AMK) [mailto:chmank@singnet.com.sg]

Sent: Thursday, April 04, 2019 12:58 PM

To: Chan, Yoke Shi; Cheng Hoe Motor Pte Ltd

Cc: Md Ishak, Mohd Imran; Abu Kassim, Noor Mariesa; Lim, Sheng Yang; MohdFitri.Hassim@aig.com; Mithoosingh, Aashweenjeetkaur

Subject: [EXTERNAL] Repair Survey (Single Joint Expert) -SLE7381K doe 03/04/19 (Yr insured SKV6314J)

Caution: External Email

Dear Sir,

OUR CLIENT - SLE7381K

DOA - 03/04/2019 @ 2210HRS

YOUR INSURED : SKV6314J (CLAIRE CHUA YATING)

Kindly provide us of your surveyor listing for the selection on the survey.

Thank you.

Regards
Dorlyn Li
Cheng Hoe Motor Pte Ltd
Tel :64812001
Fax : 64821296

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane






















CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 Apr 2019 Edit Reg		05 Apr 2019 00:00 Edit Adj Rpt	S\$3,732.64 Edit Estimates	S\$3,732.64 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	CLAIRE CHUA YATING , ID: S8312961A								
Main Claimant:	WHYE LAI KUAN , ID: S7019188A								
Vehicle Reg. No.:	SLE7381K	Date of Loss:	03/04/2019 21:00 - :59 [32 Months and 5 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 23291999S4SG	Policy/Cover Note No.:	1800124463 (Comprehensive)						
Vehicle Reg. No. (Insured):	SKV6314J	Policy No. (Claimant):	5102298890						
		Excess:							
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Chan, Kian-Meng] Kianmeng.Chan1@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 17/04/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLE7381K (2329199954SG)
 [SKV6314J]
 TP
 WHYE LAI KUAN
 Apr 3 2019 9:00PM
 [CLAIRE CHUA YATING]
 Cheng Hoe Motor Pte Ltd

Upload Documents		Upload Photos		Compose New Letter		Upload Video		Upload Audio		View <input type="button" value="View in Browser"/>	
Letters/Correspondences										1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	(Draft)	Third Party Express Settlement - Payment Breakdown							Edit		
Photos/Images										3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print		
1	17/10/19 13:27	Odometer Reading							Load JPG	<input checked="" type="checkbox"/>	
2	17/10/19 13:27	Chassis Number							Load JPG	<input checked="" type="checkbox"/>	
3	17/10/19 13:27	General View							Load JPG	<input checked="" type="checkbox"/>	
4	17/10/19 13:27	General View							Load JPG	<input checked="" type="checkbox"/>	
5	17/10/19 13:27	General View							Load JPG	<input checked="" type="checkbox"/>	
6	17/10/19 13:27	General View							Load JPG	<input checked="" type="checkbox"/>	
7	17/10/19 13:27	General View							Load JPG	<input checked="" type="checkbox"/>	
8	17/10/19 13:27	General View							Load JPG	<input checked="" type="checkbox"/>	
9	17/10/19 13:27	General View							Load JPG	<input checked="" type="checkbox"/>	
10	17/10/19 13:27	General View							Load JPG	<input checked="" type="checkbox"/>	
11	17/10/19 13:27	General View							Load JPG	<input checked="" type="checkbox"/>	
12	17/10/19 13:27	General View							Load JPG	<input checked="" type="checkbox"/>	
13	17/10/19 13:27	General View							Load JPG	<input checked="" type="checkbox"/>	
14	17/10/19 13:27	General View							Load JPG	<input checked="" type="checkbox"/>	
15	17/10/19 13:27	General View							Load JPG	<input checked="" type="checkbox"/>	
16	17/10/19 13:27	General View							Load JPG	<input checked="" type="checkbox"/>	
17	17/10/19 13:27	General View							Load JPG	<input checked="" type="checkbox"/>	
18	17/10/19 13:27	General View							Load JPG	<input checked="" type="checkbox"/>	
19	17/10/19 13:27	General View							Load JPG	<input checked="" type="checkbox"/>	
20	17/10/19 13:27	General View							Load JPG	<input checked="" type="checkbox"/>	
21	17/10/19 13:27	General View							Load JPG	<input checked="" type="checkbox"/>	
22	17/10/19 13:27	General View							Load JPG	<input checked="" type="checkbox"/>	
23	17/10/19 13:28	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
24	17/10/19 13:28	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
25	17/10/19 13:28	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
26	17/10/19 13:28	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
27	17/10/19 13:28	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
28	17/10/19 13:28	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
29	17/10/19 13:28	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
30	17/10/19 13:28	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
31	17/10/19 13:28	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
32	17/10/19 13:28	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
33	17/10/19 13:28	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
34	17/10/19 13:28	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
35	17/10/19 13:28	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
36	17/10/19 13:28	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
37	17/10/19 13:28	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
38	17/10/19 13:28	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
39	17/10/19 13:28	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	
40	17/10/19 13:28	Reinspection Photo							Load JPG	<input checked="" type="checkbox"/>	

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
41	17/10/19 13:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	17/10/19 13:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	17/10/19 13:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	17/10/19 13:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	17/10/19 13:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	17/10/19 13:28	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
47	17/10/19 13:28	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
48	17/10/19 13:28	After Repair Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/04/19 15:39	EMAIL FROM AIG DD 05042019	 Load PDF	
2	08/04/19 15:39	TP GIA REPORT	 Load PDF	
3	10/04/19 18:46	TP ESTIMATE- MARKED	 Load PDF	
4	27/06/19 10:43	EMAIL TO OI	 Load PDF	
5	27/06/19 10:43	LETTER TO OI	 Load PDF	
6	13/01/20 15:37	EMAIL FROM TP	 Load PDF	
7	16/01/20 09:31	WORKSHOP INVOICE	 Load PDF	
8	16/01/20 09:31	AUTHORISATION TO ACT FORM	 Load PDF	
9	16/01/20 09:31	Release Voucher	 Load PDF	
10	16/01/20 09:31	RENTAL RECEIPT	 Load PDF	
11	16/01/20 09:31	LTA SEARCH	 Load PDF	
12	16/01/20 09:31	LOD	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	09/04/19 09:42	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**THIRD PARTY EXPRESS SETTLEMENT
(PAYMENT BREAKDOWN)**

Vehicle No:	SKV6314J (Insd veh)	Model:	HONDA JAZZ 1.5 (A)
	SLE7381K (TP veh)		
Date of Accident:	03/04/2019		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No	
Repair Estimate	:	\$	4,347.02	
Final Repair Cost	:	\$	3,993.92	
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$	400.00	4 days
LTA / GIA Search Fee	:	\$	8.00	
Others:	:	\$	0.00	
	:	\$		
Final Settlement Sum	:	\$	4,401.92	
Is Third Party Workshop GIA Registered? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)				
A) For <u>Non GIA Registered Workshop</u> : Agreed Liability _____(%)				
B) For <u>GIA Registered Workshop</u> : BOLA Applicable: Yes/ No BOLA Scenario No: _____				
BOLA Liability: _____100_____(%) Assessed Liability (*): _____(%)				
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	Cheng Hoe Motor Pte Ltd	:	\$ 4,401.92
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

16 Jan
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19006157/KHA3Q2

Date: 16/01/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800124463
 Claimant: SLE7381K Insured Vehicle No: SKV6314J
 Vehicle No: SLE7381K Insured Vehicle No: SKV6314J
 Date of Loss: 03/04/2019 Nature of Claim: TP Claim No: 2329199954SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLE7381K
 Make & Model: HONDA JAZZ, 1.5 (A) Engine No: L15B31190022
 Reg. Date: 29/07/2016 (Man. Year: 2016) Chassis No: JHMGK5850HX200065
 Colour: Metallic Blue Odometer: 56572 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/55 R16 Rear Tyre Size: 185/55 R16
 Front Left Side: Dunlop 5 mm Rear Left Side: Dunlop 3 mm
 Front Right Side: Dunlop 5 mm Rear Right Side: Dunlop 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,182.64	2,182.64	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,880.00	1,550.00	330.00	17.55
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,062.64	3,732.64	330.00	8.12
+ GST 7.00/7.00% (S\$)	284.38	261.28	23.10	8.12
Nett Amount (S\$)	4,347.02	3,993.92	353.10	8.12
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		4,401.92		

INSPECTION

Date of Assignment: 05/04/2019
 Date Inspected: 09/04/2019 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
 Blk 1019 #01-374/382, Yishun
 Industrial Park A
 Singapore 768761
 Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	492.50 FL	*492.50 FL
2	1		*REAR BUMPER LH SIDE RETAINER	Distorted	17.10 FL	*17.10 FL
3	5		*REAR BUMPER CLIP	Necessary	19.50 FL	*19.50 FL
4	1		*REAR BUMPER LH SIDE GARNISH	Dented	45.00 FL	*45.00 FL
5	1		*LH TAILLAMP	Cut	237.50 FL	*237.50 FL
6	1		*REAR TAILGATE	Bent	814.00 FL	*814.00 FL
7	1		*TAILGATE INNER LOCK	Dented	157.40 FL	*157.40 FL
8	1		*TAILGATE INNER RUBBER	Cut	92.30 FL	*92.30 FL
9	1		*TAILGATE EMBLEM JAZZ	Necessary	15.50 FL	*15.50 FL
10	1		*TAILGATE WINDSCREEN GLASS MOULDING	Necessary	151.30 FL	*151.30 FL
11	1		*REAR END PANEL	Bent	314.00 FL	*314.00 FL
12	1		*REAR END PANEL INNER TOP GARNISH	Mtg Cracked	60.80 FL	*60.80 FL
13	1		*REAR END PANEL BUZZER SENSOR (OUTER)	Cracked	85.00 FL	*85.00 FL
14	1		*REAR END PANEL BUZZER SENSOR (INNER)	Cracked	58.60 FL	*58.60 FL
15	1		*REAR SPARE TYRE TOOL SPONGE	Cracked	117.80 FL	*117.80 FL
16	1		*TAILGATE GLASS SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNetf. L=ListItemDisc.

Sub Total (S\$)	2,718.30	2,718.30
- List Item Discount on L Items 20.00/20.00% (S\$)	535.66	535.66
Total Parts (S\$)	2,182.64	2,182.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
2	REMOVE & REFIX REAR BUMPER ,TAILGATE SPOILER & ATTACHMENTS ,TAILLAMPS ,TO CUT ,WELD & RENEW REAR END PANEL ,KNOCKING & REPAIR REAR SPARE TYRE PANEL ,FENDERS & REALIGN THE SAME	New	800.00	800.00
3	PUTTY & RESPRAY REAR BUMPER ,TAILGATE ,REAR END PANEL ,REAR SPARE TYRE PANEL ,REAR FENDERS & ALL AFFECTED AREAS	New	850.00	720.00
4	REMOVE & REFIX REVERSE CAMERA ,RESET & REPOSITION	New	50.00	50.00
5	RUSTPROOFING	New	60.00	60.00
Gross Labour Cost (S\$)			1,880.00	1,550.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >