

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000
ATTN: Motor Claim Department
WS Ref: TP/AIG/AMK
Claim Type: Third Party
Accident Date: 03/04/2019
TP Veh Reg No: SKV6314J

FAX: 64153727

Estimate No: ES1991370/AMK
Date: 09 Apr 2019
Policy No: 5102298890
Veh Reg No: SLE7381K
Make/Model: HONDA JAZZ 1.5A
Chassis No: JHMGK5850HX200065
Engine No: L15B31190022
Reg. Date: 29/07/2016

Not Notched

Resurvey B4 paint

5 days

Estimate Repair Cost to Vehicle No :SLE7381K

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
List Price				
1 REAR BUMPER	492.50	1 PC	<i>B1</i> 492.50	✓
2 REAR BUMPER LH SIDE RETAINER	17.10	1 PC	<i>D1V</i> 17.10	✓
3 REAR BUMPER CLIP	3.90	5 PC	<i>na</i> 19.50	✓
4 REAR BUMPER LH SIDE GARNISH	45.00	1 PC	<i>na</i> 45.00	✓
5 LH TAILLAMP	237.50	1 PC	<i>na</i> 237.50	✓
6 REAR TAILGATE	814.00	1 PC	<i>B1</i> 814.00	✓
7 TAILGATE INNER LOCK	157.40	1 PC	<i>na</i> 157.40	✓
8 TAILGATE INNER RUBBER	92.30	1 PC	<i>na</i> 92.30	✓
9 TAILGATE EMBLEM 'JAZZ'	15.50	1 PC	<i>na</i> 15.50	✓
10 TAILGATE WINDSCREEN GLASS MOULDING	151.30	1 PC	<i>na</i> 151.30	✓
11 REAR END PANEL	314.00	1 PC	<i>B1</i> 314.00	✓
12 REAR END PANEL INNER TOP GARNISH	60.80	1 PC	<i>na</i> 60.80	✓
13 REAR END PANEL BUZZER SENSOR (OUTER)	85.00	1 PC	85.00	?
14 REAR END PANEL BUZZER SENSOR (INNER)	58.60	1 PC	58.60	?
15 REAR SPARE TYRE TOOL SPONGE	117.80	1 PC	<i>CM</i> 117.80	✓
			2,678.30	
		Less 20%	535.66	2,142.64
Special Net				
16 TAILGATE GLASS SEALANT	40.00	1 PC	<i>na</i> 40.00	✓
			40.00	40.00
Labour				
17 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
18 REMOVE & REFIX REAR BUMPER, TAILGATE, SPOILER & ATTACHMENTS, TAILLAMPS, TO CUT, WELD & RENEW REAR END PANEL, KNOCKING & REPAIR REAR SPARE TYRE PANEL, FENDERS & REALIGN THE SAME	800.00	1 LA	800.00	<i>800.00</i>
19 PUTTY & RESPRAY REAR BUMPER, TAILGATE, REAR END PANEL, REAR SPARE TYRE PANEL, REAR FENDERS & ALL AFFECTED AREAS	850.00	1 LA	850.00	<i>720.00</i>
20 REMOVE & REFIX REVERSE CAMERA, RESET & REPOSITION	50.00	1 PC	50.00	✓
21 RUSTPROOFING	60.00	1 LA	60.00	✓
			1,880.00	1,880.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be surveyed and is subject to final approval of the Company

Acknowledged by Repairer

Signature:

Date: