

ASS. REC. BY:

REF: CS/CT119006163/GVD3

Special Instruction:

SURVIVOR: GQ

ASSIGNMENT (Office)

From (Person): Chong Boon Sen of CT2

Date/Time: 8.4.19 3.13p.m

Estimated Cost:

Bill to:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLW 39772

Insured: GBE 9312R

at Workshop m/s Kah motor

Tel: 65145687

of 15 ubi Road 4

Policy No: DMCVSN1626311802

Claim No: SNM19D201549C02

Sum Insured:

Excess:

Make of Veh:  
(Client's Record)

D.O.A. 3.4.19  
1000a.m 10/4/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 8.4.19 3.36p.m

Person Contacted: Mr. Kiew

Vehicle IN (OUT)

Date/Time	Action/Instruction (✓) Estimate
	SLW 39772 - X
	GBE 9312R - X
22/4/19	Final fig \$ 5949.32 (Real 2638.47, 319) confirmed by email



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							Status
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	
Main	08 Apr 2019		10 Apr 2019 17:47 <a href="#">Edit Adj Rpt</a>				<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>					
<b>CLAIM SUBFOLDER DETAILS</b>			[Created by insurer]						
Insured:									
Main Claimant:	<b>CHEW SUAT LENG</b> , ID: S7715079Z								
Vehicle Reg. No.:	<b>SLW3977Z</b>	Date of Loss:	03/04/2019 15:00 - :59						
Claim Type:	<b>TP / SNM19D201549C02</b>	Policy/Cover Note No.:	DMCVSN1626311802						
Vehicle Reg. No. (Insured):	<b>GBE9312R</b>	Policy No. (Claimant):	10-812807						
		Excess:	S\$500.00						
Repairer:	<b>Kah Motor Co Sdn Bhd (Ubi)</b> 15 Ubi Road 4, 408610 Ubi - Tel: 68465671								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Elaine Cheong</b> ]								
Claimant's Insurer:	<b>Aviva Ltd (HQ)</b> - Tel: (65) 6827 9966								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... <b>[Final Rpt due 22/04/2019]</b>								
<b>ASSOCIATED MAIL RECEIVED</b>			<a href="#">View All</a>	<a href="#">Compose Case Mail</a>					
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b>			<a href="#">View All</a>	<a href="#">Search Tasks</a>					
			<a href="#">Create New Task</a>	<a href="#">Complete</a>					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Nivitha (LKK Auto)**

---

**From:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Sent:** Monday, 8 April 2019 3:13 PM  
**To:** Liew Thye Wui  
**Cc:** assignments  
**Subject:** RE: DIRECT SETTLEMENT OF VEHICLE NO. SLW3977Z AGAINST GBE9312R  
ACCIDENT DATE: 03/04/19 / OUR REF: TBA

**Without Prejudice**

Dear Liew,

We pri.

Dear LKK,

Pls pri.

**Chong Boon Sen**

Claims Executive  
Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

P: Mr Liew  
V: Out  
T: 3.35p.m  
E: ✓

---

**From:** Liew Thye Wui [mailto:twliew@honda.com.sg]  
**Sent:** Monday, 8 April, 2019 3:02 PM  
**To:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>  
**Cc:** Angie Foo <angie.foo@sg.cntaiping.com>  
**Subject:** DIRECT SETTLEMENT OF VEHICLE NO. SLW3977Z AGAINST GBE9312R ACCIDENT DATE: 03/04/19 / OUR REF: TBA

Dear Boon Sen,

Kindly help to arrange **XING QUO QIANG** for the survey.

Thank you and have a Nice Day.

Best Regards

TW LIEW  
Kah Motor Co. Sdn. Bhd.  
15 Ubi Road 4  
Singapore 408610  
DID: 6514 5687  
Fax: 6748 0770

**From:** Chong Boon Sen <[boonsen.chong@sg.cntaiping.com](mailto:boonsen.chong@sg.cntaiping.com)>

**Sent:** Monday, 8 April, 2019 2:36 PM

**To:** Liew Thye Wui <[twliew@honda.com.sg](mailto:twliew@honda.com.sg)>

**Cc:** Angie Foo <[angie.foo@sg.cntaiping.com](mailto:angie.foo@sg.cntaiping.com)>

**Subject:** RE: DIRECT SETTLEMENT OF VEHICLE NO. SLW3977Z AGAINST GBE9312R ACCIDENT DATE: 03/04/19 / OUR REF: TBA

Without Prejudice

Dear Sir,

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

ADRIAN LING
Kelvin Ang
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Dear Angie,

Checked system not yet registered.

For your action.

Thank you.

**Chong Boon Sen**

Claims Executive  
Department

**China Taiping Insurance (Singapore) Pte. Ltd.**

3 Anson Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**W:** [www.sg.cntaiping.com](http://www.sg.cntaiping.com) | **FB:** [www.facebook.com/chinataipingsg/](https://www.facebook.com/chinataipingsg/) | **WeChat:** 太平獅城 Taiping SG 3 Anson  
Road #16-00 Springleaf Tower Singapore 079909  
DID: (65) 63896171 | M: (65) XXXX XXXX | F: (65) 6222 1033

**From:** Liew Thye Wui [<mailto:twliew@honda.com.sg>]

**Sent:** Monday, 8 April, 2019 2:02 PM

**To:** Claims Dept of CTI <claimsdept@sg.cntaiping.com>

**Cc:** Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Elaine Cheong <elaine.cheong@sg.cntaiping.com>; Irene Tay <irene.tay@sg.cntaiping.com>; Alfred Toh <alfred.toh@sg.cntaiping.com>; Chee So Chow <sochow.chee@sg.cntaiping.com>

**Subject:** DIRECT SETTLEMENT OF VEHICLE NO. SLW3977Z AGAINST GBE9312R ACCIDENT DATE: 03/04/19

Dear Officer-in-charge, Reminder

Kindly refer to the attachments for third party direct settlement.  
Vehicle is not in our workshop. Please call for the arrangement for the survey.  
Meanwhile, kindly get back to me once liability has establish.

Thank you and have a Nice Day.

Best Regards

TW LIEW  
Kah Motor Co. Sdn. Bhd.  
15 Ubi Road 4  
Singapore 408610  
DID: 6514 5687  
Fax: 6748 0770

**From:** Liew Thye Wui  
**Sent:** Friday, 5 April, 2019 11:53 AM  
**To:** 'Claims Dept of CTI' <claimsdept@sg.cntaiping.com>  
**Subject:** DIRECT SETTLEMENT OF VEHICLE NO. SLW3977Z AGAINST GBE9312R ACCIDENT DATE: 03/04/19

Dear Officer-in-charge,


Kindly refer to the attachments for third party direct settlement.  
Vehicle is not in our workshop. Please call for the arrangement for the survey.  
Meanwhile, kindly get back to me once liability has establish.

Thank you and have a Nice Day.

Best Regards

TW LIEW  
Kah Motor Co. Sdn. Bhd.  
15 Ubi Road 4  
Singapore 408610  
DID: 6514 5687  
Fax: 6748 0770

**From:** Printer Service <printservice@honda.com.sg>  
**Sent:** Friday, 5 April, 2019 11:49 AM  
**To:** Liew Thye Wui <twliew@honda.com.sg>  
**Subject:** Attached Image



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

---

This email has been scanned by the Symantec Email Security.cloud service.  
For more information please visit <http://www.symanteccloud.com>

---

## &gt; Back to OneMotoring

## Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	5079Z
Vehicle Details	
Vehicle No.:	SLW3977Z
Vehicle to be Exported:	No
Intended Deregistration Date:	11 Apr 2019
Vehicle Make:	HONDA
Vehicle Model:	HRV 1.5 LX CVT
Primary Colour:	Silver
Manufacturing Year:	2017
Engine No.:	L15B4533737
Chassis No.:	JHMRU1830GX203737
Maximum Power Output:	96.0 kW (128 bhp)
Open Market Value:	\$21,010.00
Original Registration Date:	09 Feb 2018
First Registration Date:	09 Feb 2018
Transfer Count:	0
Actual ARF Paid:	\$21,414.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	08 Feb 2028
PARF Rebate Amount:	\$16,060.00
Intended COE Rebate Details	
COE Expiry Date:	08 Feb 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$42,339.00
COE Rebate Amount:	\$37,371.00
<b>Total Rebate Amount:</b>	<b>\$53,431.00</b>

The information contained herein is correct as at 11 Apr 2019

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	04/04/2019 14:36
Date Of Accident	03/04/2019 15:15
Exact Location Of Accident	BARTLEY RD EAST TOWARDS TAMPINES
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLW3977Z
Insured/Policyholder	
Name Of Registered Owner	CHEW SUAT LENG
NRIC No	S7715079Z
Email Address	CHEWSL77@YAHOO.COM.SG
Mobile Phone No	(LOCAL) +65-97404125
Alternative Phone No	OTHERS-91205657
Vehicle Particulars	
Manufacturer	HONDA
Model	HR-V-1.5 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USED
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AVIVA LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	10-812807
Cover Note Number	
Driver	
Name of Driver	CHEW KOK HUA
NRIC No	S0060662F
Date Of Birth	25/02/1951
Occupation	INDOOR
Date Of Driving Pass	21/12/1971
Driving Experience	47 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91205657
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address BLK 891, TAMPINES AVE B  
#16-82

Postcode 520891

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured PARENT

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident SIDE SWIPE

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles (including own vehicle) involved in the accident 2

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 4

Passenger 1 NAME: : MILDRED TOMBAGA MACRUSIS  
GENDER: : FEMALE

Passenger 2 NAME: : MIKHAIL BIN MOHD BASROM  
GENDER: : MALE

Passenger 3 NAME: : JAVEN BIN MOHD BASROM  
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER TO ATTACHMENT REPORT.

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBE9312R

Vehicle Make/Model/Colour TOYOTA / LORRY / BLUE

Details Of Properties RIGHT FRONT SIDE

Vehicle Category COMMERCIAL VEHICLE

Name of Driver ISWANDY BIN ISMAIL

NRIC/Passport Number S7725032H

Contact Number	87680960
Address	BLK 986C BUANGKOK CRESCENT #05-70
Postcode	533986
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (including Driver)	1

Vehicle Number

SLW3977Z

**SKETCH PLAN****IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)** I understand, acknowledge, agree and consent that:
  - (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
    - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
    - (ii) investigating the accident and/or my claims;
    - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
    - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
    - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
  - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
  - (e) the information so collected under (d) above may be shared / disclosed:
    - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
    - (ii) for complying with requirements under any regulations, laws or court orders.


\_\_\_\_\_  
 Policyholder's Signature  
 Date & Time:

\_\_\_\_\_  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time: 4/1/19 @ 12:45pm

\_\_\_\_\_  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

Vehicle Number: SLW 3977Z

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Exit from Bentley Viaduct, turning right towards Kaki Bukit and Tampines Ave 10. Accident happened at the junction of Bentley Road East. A lorry from the left cut into the lane when turning.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

\_\_\_\_\_  
Policyholder's Signature  
Date & Time:

  
\_\_\_\_\_  
Driver's Signature  
(if driver is not the policyholder)  
Date & Time: 4/4/98 12:45 pm

  
\_\_\_\_\_  
Reporting Centre Personnel's Signature  
Name:  
NRIC/PRN No.:



**KAH MOTOR CO. SDN. BHD.**  
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

# QUOTATION

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

<b>Customer</b>	: CHINA TAIPING INSURANCE (S'PORE) PTE 3 ANSON ROAD #16-00 SPRINGLEAF TOWER SINGAPORE 079909	<b>Document No.</b>	: SQT19001536	<b>Page</b>	1
<b>Registration No</b>	: SLW3977Z	<b>Date</b>	: 5. Apr 2019	<b>Customer No.</b>	: WZC008
<b>Chassis No</b>	: JHMRU1830GX203737	<b>Svc Advisor</b>	: LIEW THYE WEI	<b>Engine No</b>	: L15B4533737
<b>Model</b>	: HRV LX-SIN CVT YM 2016	<b>Date   Time</b>	: 5. Apr 2019 9:35:24 AM	<b>Surveyor Name</b>	:
<b>Owner's Name</b>	: CHEW SUAT LENG	<b>Survey Date</b>	:	<b>Authorisation Date</b>	:
<b>Ins Policy No.</b>	:				
<b>Date of Accident</b>	: 3/4/2019				

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO.) OWNER: CHEW SUAT LENG OWNER INSURER: AVIVA LTD ACC DATE: 03/04/19 SURVEYED BY: DATE: REF NO: TP INSURER: CHINA TAIPING INSURANCE (S) PTE LTD TP VEH: GBE9312R						
<b>BO-WHEEL ALIGN X4</b>	<b>WHEEL ALIGNMENT X4</b>	1	180.00	✓	180.00	12.60	192.60
			<b>Sum Ext. Service</b>		<b>180.00</b>	<b>12.60</b>	<b>192.60</b>
60260-T7A-J00ZZ	PANEL COMPL.FR.FENDER <i>5 Blue NN</i>	1	394.90	15	335.66	23.50	359.16
74150-T7A-N00	FENDER ASSYL.FR INNER <i>MC. ✓</i>	1	90.00	15	76.50	5.36	81.86
91501-TR0-003	CLIP,INNER FENDER <i>MC. ✓</i>	11	2.80	15	26.18	1.83	28.01
74157-T7A-J01ZQ	PROTECTORL.FR.WHEEL ARCH <i>Cut NN</i>	1	147.60	15	125.46	8.78	134.24
74155-T7A-000	ENCLOSUREL.FR.FENDER <i>? X NN</i>	1	10.00	15	8.50	0.60	9.10
04711-T7A-N00ZZ	FACE.FR.BUMPER <i>Cut NN</i>	1	475.60	15	404.26	28.30	432.56
71103-T7A-000	GRILLEFR.BUMPER <i>X NN</i>	1	79.00	15	67.15	4.70	71.85
04712-T7A-900ZZ	FACEFR.BUMPER LOWER <i>? X NN</i>	1	231.60	15	196.86	13.78	210.64
71198-T7A-J00	SPACER,L.FR.BUMPER SIDE <i>MC. ✓</i>	1	11.00	15	9.35	0.65	10.00
71190-T7A-000	BEAML.FR.BUMPER UPPER <i>? X NN BR.</i>	1	24.60	15	20.91	1.46	22.37
71130-T7A-010ZZ	BEAM COMP.FR.BUMPER <i>? X NN NN</i>	1	222.90	15	189.46	13.26	202.72
71106-T7A-000	GARNISHL.FR.FOG LIGHT <i>X NN NN</i>	1	21.50	15	18.27	1.28	19.55
71166-T7A-000	GARNISHL.FR.BUMPER BEAM <i>? X NN</i>	1	7.70	15	6.54	0.46	7.00
71161-T7A-000	GARNISHR.FR.BUMPER BEAM <i>? X NN</i>	1	7.70	15	6.54	0.46	7.00
91505-TM8-003	CLIP,BUMPER <i>MC. ✓</i>	22	2.30	15	43.01	3.01	46.02
71126-T7B-Z01	SET,FR.GRILLE ASSY <i>? X NN</i>	1	270.90	15	230.26	16.12	246.38

Printed on 5/4/2019 10:54:38 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd. it will be refunded



**KAH MOTOR CO. SDN. BHD.**  
 (A Member of the Oriental Holdings Berhad)  
 Service and Body Repair  
 Tel: +65 6841 3838 Website: www.honda.com.sg  
 For 24-hours Roadside Assistance, Call 98203838

# QUOTATION

GST Reg No.: M200050223  
 Company Ref. No.: S60FC1380G

**Customer** : CHINA TAIPING INSURANCE (S'PORE) PTE  
 3 ANSON ROAD #16-00  
 SPRINGLEAF TOWER  
 SINGAPORE 079909

**Registration No** : SLW3977Z

**Chassis No** : JHMRU1830GX203737

**Model** : HRV LX-SIN CVT YM 2016

**Owner's Name** : CHEW SUAT LENG

**Ins Policy No.** :

**Date of Accident** : 3/4/2019

**Document No.** : SQT19001536 **Page** 2

**Date** : 5. Apr 2019

**Customer No.** : WZC008

**Svc Advisor** : LIEW THYE WEI

**Engine No** : L15B4533737

**Date | Time** : 5. Apr 2019 9:35:24 AM

**Surveyor Name** :

**Survey Date** :

**Authorisation Date** :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
71122-T7A-901	MOLDINGFR.GRILLE UPPER ? x	1	189.80	15	161.33	11.29	172.62
71123-T7A-901	MOLDINGFR.GRILLE ? x } NN	1	43.60	15	37.06	2.59	39.65
75700-TA0-A00	EMBLEMFR. ? x	1	26.70	15	22.69	1.59	24.28
90301-ST0-003	NUTPUSH 3MM ? x	2	2.10	15	3.57	0.25	3.82
72450-T7A-003	MOLDING ASSYL.FR.DOOR - } cut	1	23.70	15	20.14	1.41	21.55
33150-T7S-E11	HEAD LIGHT ASSY,L - } cut	1	1728.70	15	1469.39	102.86	1572.25
33950-SLE-J51	LIGHT ASSYL.FR.FOGLIGHT ? x NN	1	239.70	15	203.74	14.26	218.00
<b>Sum Item</b>					<b>3682.83</b>	<b>257.80</b>	<b>3,940.63</b>
BOSUN	SUNDRIES <i>new</i>	1	30.00	✓ 20	30.00	2.10	32.10
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS <i>560</i>	1	80.00	✓ /	80.00	5.60	85.60
BKBH01S	STRAGHTEN ALIGN BULKHEAD & LEFT FRONT FENDER. <i>560</i>	1	2400.00	✓ 1400	2400.00	168.00	2568.00
BP04R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (4P) <i>11/4/19 450</i>	1	2200.00	✓ 1800	2200.00	154.00	2354.00
<b>Sum Labor</b>					<b>4710.00</b>	<b>329.70</b>	<b>5,039.70</b>

Survey By: Guo Qiang - 8288082

Date & Time: 10/4/19

Excess: \_\_\_\_\_

Status: \_\_\_\_\_

Signature: \_\_\_\_\_

**Total Amount** 8,572.83 600.10 9,172.93

**Total (Inclusive of GST)** **8587.79** **9,172.93**

*before paint photos.*

*5 Days.*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer:

Signature: \_\_\_\_\_

Date: \_\_\_\_\_

Printed on 5/4/2019 10:54:38 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

**HONDA****KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

*5 days -  
Mr. Guo Qiang***SERVICE PRE-INVOICE**GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

Customer: WZC008 / CHINA TAIPING  
 Chassis No: JHMUR1830GX203737  
 License No: SLW3977Z  
 Mileage: 19696  
 Engine No: L15B4533737

Document No: SVO19024208  
 Printed By: TWLIEW  
 Order Date: 16. April 2019  
 Order Time: 9:55:13 AM  
 Service Advisor: LIEW THYE WEI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 72559) OWNER: CHEW SUAT LENG OWNER INSURER: AVIVA LTD ACC DATE: 03/04/19 SURVEYED BY: GUO QIANG DATE: 10/4/19 @ 9.15AM REF NO: SNM19D201549 TP INSURER: CHINA TAIPING INSURANCE (S) PTE LTD TP VEH: GBE9312R						
60260-T7A-G00ZZ	PANEL COMPL.FR.FENDER	1	394.90	15	335.66	23.50	359.16
91501-TR0-003	CLIP,INNER FENDER	11	2.80	15	28.18	1.83	28.01
74157-T7A-J01ZQ	PROTECTORL.FR.WHEEL ARCH	1	147.80	15	125.46	8.78	134.24
04711-T7A-N00ZZ	FACE,FR.BUMPER	1	475.80	15	404.26	28.30	432.56
71198-T7A-J00	SPACER,L.FR.BUMPER SIDE	1	11.00	15	9.35	0.65	10.00
91505-TM8-003	CLIP,BUMPER	22	2.30	15	43.01	3.01	46.02
72450-T7A-003	MOLDING ASSYL.FR.DOOR	1	23.70	15	20.14	1.41	21.55
33150-T7S-E11	HEAD LIGHT ASSY,L.	1	1,728.70	15	1,469.39	102.86	1,572.25
71190-T7A-000	BEAML.FR.BUMPER UPPER	1	24.60	15	20.91	1.46	22.37
71152-T7A-000	BEAML.FR.GRILLE SIDE UPPER	1	17.60	15	14.96	1.05	16.01
	<b>SUM PARTS:</b>				<b>2,469.32</b>	<b>172.85</b>	<b>2,642.17</b>
BOSUN	0760 SUNDRIES		20.00		20.00	1.40	21.40
BML011	EXT-YJ INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS.(N)	1	80.00		80.00	5.60	85.60
BKBH01S	EXT-YJ STRAGHTEN ALIGN BULKHEAD & LEFT FRONT FENDER. RENEW DAMAGE PARTS.	1	1,400.00		1,400.00	98.00	1,498.00
BP04R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(4P)	1	1,800.00		1,800.00	126.00	1,926.00
	<b>SUM LABOUR:</b>				<b>3,300.00</b>	<b>231.00</b>	<b>3,531.00</b>
BO-WHEEL ALIGN X4	WHEEL ALIGNMENT	1	180.00		180.00	12.60	192.60
	<b>SUM EXT SERVICE:</b>				<b>180.00</b>	<b>12.60</b>	<b>192.60</b>
	<b>TOTAL SGD</b>				<b>5,949.32</b>	<b>416.45</b>	<b>6,365.77</b>

**Total Payable (SGD)****6,365.77**

GST Amount is calculated from individual line(s)

**Veron Chen (LKKAuto)**

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Monday, 22 April 2019 11:01 AM  
**To:** Liew Thye Wui; Guo Qiang (LKKAuto)  
**Cc:** Admin A; SUR  
**Subject:** RE: PRE-INVOICE FOR VEHICLE SLW3977Z

Dear Mr Liew,

WITHOUT PREJUDICE

Confirmed finalize amount \$5949.32 before GST @ 5 working days.

**Kindly send Final invoice and all supporting documents directly to CHINA TAIPING**

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Liew Thye Wui <twliew@honda.com.sg>  
**Sent:** Monday, 22 April 2019 10:02 AM  
**To:** Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>  
**Cc:** Admin A <admin-a@lkkauto.com>  
**Subject:** PRE-INVOICE FOR VEHICLE SLW3977Z

Dear Guo Qiang,

We enclosed the total final repair costs of...

<b>Vehicle No.</b>	SLW 3977Z
<b>Final Repair Costs (include GST)</b>	\$6365.77
<b>Repair Period*( Working Day)</b>	05 days

\*Note: Repair period does not include Sunday and Public Holiday.

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

Thanks & best regards,

Best Regards

TW LIEW

Kah Motor Co. Sdn. Bhd.  
15 Ubi Road 4  
Singapore 408610  
DID: 6514 5687  
Fax: 6748 0770



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

### ...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	08 Apr 2019		10 Apr 2019 17:47 <a href="#">Edit Adj Rpt</a>	<b>S\$5,949.32</b> <a href="#">Edit Estimates</a>	<b>S\$5,949.32</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by Insurer]</span>									
Insured:	-, ID: -								
Main Claimant:	<b>CHEW SUAT LENG</b> , ID: S7715079Z								
Vehicle Reg. No.:	<b>SLW3977Z</b>	Date of Loss:	03/04/2019 15:00 - :59 [13 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / SNM19D201549C02</b>	Policy/Cover Note No.:	DMCVSN1626311802						
Vehicle Reg. No. (Insured):	<b>GBE9312R</b>	Policy No. (Claimant):	10-812807						
		Excess:	S\$500.00						
Repairer:	<b>Kah Motor Co Sdn Bhd (Ubi)</b> 15 Ubi Road 4, 408610 Ubi - Tel: 68465671								
Handling Insurer:	<b>China Taiping Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: 6389 6111 ... [Handled by <b>Elaine Cheong</b> ]								
Claimant's Insurer:	<b>Aviva Ltd (HQ)</b> - Tel: (65) 6827 9966								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>XING GUO QIANG</b> ] ... [Final Rpt due 22/04/2019]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
There are no mail for this case.									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SLW3977Z (SNM19D201549C02)  
[GBE9312R]  
TP  
CHEW SUAT LENG  
Apr 3 2019 3:00PM  
[-]  
Kah Motor Co Sdn Bhd

Upload Documents			Upload Photos			Compose New Letter			View <input type="button" value="View in Browser"/>	
<b>Video</b>									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print					
1	04/04/19 14:47	<b>Video - Accident</b> [Linked Accident Report Documents]		Load MP4	<input type="checkbox"/>					
2	04/04/19 14:49	<b>Video - Accident</b> [Linked Accident Report Documents]		Load MP4	<input type="checkbox"/>					
<b>Assessment Reports</b>									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print					
1	04/04/19 14:54	<b>Accident Statement</b>		Load HTM	<input type="checkbox"/>					
<b>Photos/Images</b>									3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)		Thumbnail	Print					
1	04/04/19 14:54	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
2	04/04/19 14:54	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
3	04/04/19 14:54	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
4	04/04/19 14:54	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
5	04/04/19 14:54	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
6	04/04/19 14:54	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
7	04/04/19 14:54	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
8	04/04/19 14:54	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
9	04/04/19 14:54	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
10	04/04/19 14:54	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
11	04/04/19 14:54	<b>Accident Photo</b> [Linked Accident Report Documents]		Load JPG	<input checked="" type="checkbox"/>					
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	22/04/19 10:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
2	22/04/19 10:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
3	22/04/19 10:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
4	22/04/19 10:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
5	22/04/19 10:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
6	22/04/19 10:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
7	22/04/19 10:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
8	22/04/19 10:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
9	22/04/19 10:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
10	22/04/19 10:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
11	22/04/19 10:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
12	22/04/19 10:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					
13	22/04/19 10:43	<b>General View</b>		Load JPG	<input checked="" type="checkbox"/>					

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
14	22/04/19 10:43	General View		<input checked="" type="checkbox"/>
15	22/04/19 10:43	General View		<input checked="" type="checkbox"/>
16	22/04/19 10:43	General View		<input checked="" type="checkbox"/>
17	22/04/19 10:43	General View		<input checked="" type="checkbox"/>
18	22/04/19 10:43	General View		<input checked="" type="checkbox"/>
19	22/04/19 10:43	General View		<input checked="" type="checkbox"/>
20	22/04/19 10:43	General View		<input checked="" type="checkbox"/>
21	22/04/19 10:43	General View		<input checked="" type="checkbox"/>
22	22/04/19 10:43	General View		<input checked="" type="checkbox"/>
23	22/04/19 10:43	General View		<input checked="" type="checkbox"/>
24	22/04/19 10:43	General View		<input checked="" type="checkbox"/>
25	22/04/19 10:43	General View		<input checked="" type="checkbox"/>
26	22/04/19 10:43	General View		<input checked="" type="checkbox"/>
27	22/04/19 10:43	General View		<input checked="" type="checkbox"/>
28	22/04/19 10:43	General View		<input checked="" type="checkbox"/>
29	22/04/19 10:43	General View		<input checked="" type="checkbox"/>
30	22/04/19 10:43	General View		<input checked="" type="checkbox"/>
31	22/04/19 10:43	General View		<input checked="" type="checkbox"/>
32	22/04/19 10:43	General View		<input checked="" type="checkbox"/>
33	22/04/19 10:43	General View		<input checked="" type="checkbox"/>
34	22/04/19 10:43	General View		<input checked="" type="checkbox"/>
35	22/04/19 10:43	General View		<input checked="" type="checkbox"/>
36	22/04/19 10:43	General View		<input checked="" type="checkbox"/>
37	22/04/19 10:43	General View		<input checked="" type="checkbox"/>
38	22/04/19 10:43	Chassis Number		<input checked="" type="checkbox"/>
39	22/04/19 10:43	Odometer Reading		<input checked="" type="checkbox"/>
40	22/04/19 10:44	Dismantled Parts		<input checked="" type="checkbox"/>
41	22/04/19 10:44	Dismantled Parts		<input checked="" type="checkbox"/>
42	22/04/19 10:44	Dismantled Parts		<input checked="" type="checkbox"/>
43	22/04/19 10:44	Dismantled Parts		<input checked="" type="checkbox"/>
44	22/04/19 10:44	Dismantled Parts		<input checked="" type="checkbox"/>
45	22/04/19 10:44	Dismantled Parts		<input checked="" type="checkbox"/>
46	22/04/19 10:44	Dismantled Parts		<input checked="" type="checkbox"/>
47	22/04/19 10:44	Dismantled Parts		<input checked="" type="checkbox"/>
48	22/04/19 10:44	Reinspection Photo		<input checked="" type="checkbox"/>
49	22/04/19 10:44	Reinspection Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	10/04/19 17:49	PRS - SLW3977Z		<input type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	04/04/19 14:46	Sketch Plan <small>[Linked Accident Report Documents]</small>		<input type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/05/19 11:20	SUPPLEMENTARY PART		<input type="checkbox"/>

### Linked Accident Report Documents

View 

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	04/04/19 14:47	Video - Accident		<input type="checkbox"/>

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
2	04/04/19 14:49	Video - Accident	 Load MP4	<input type="checkbox"/>
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	04/04/19 14:54	Accident Statement	 Load HTM	<input type="checkbox"/>
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	04/04/19 14:54	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	04/04/19 14:54	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	04/04/19 14:54	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	04/04/19 14:54	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	04/04/19 14:54	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
6	04/04/19 14:54	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
7	04/04/19 14:54	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
8	04/04/19 14:54	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
9	04/04/19 14:54	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
10	04/04/19 14:54	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
11	04/04/19 14:54	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Kah Motor Co Sdn Bhd (Ubi)	Thumbnail	Print
1	04/04/19 14:46	Sketch Plan	 Load TIF	<input type="checkbox"/>

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

## LKK Auto Consultants Pte Ltd (Co Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS/CT119006163/GVD3Q2

**Date:** 06/05/2019

#### REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd.	Policy No: DMCVSN1626311802	
Claimant Vehicle No: SLW3977Z	Insured Vehicle No: GBE9312R	
Date of Loss: 03/04/2019	Nature of Claim: TP	Claim No: SNM19D201549C02

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLW3977Z	Engine No:	L15B4533737
Make & Model:	HONDA HR-V, 1.5 (A)	Chassis No:	JHMRU1830GX203737
Reg. Date:	09/02/2018 (Man. Year: 2017)	Odometer:	19336 km
Colour:	Silver		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Dunlop 7 mm	Rear Left Side:	Dunlop 7 mm
Front Right Side:	Dunlop 7 mm	Rear Right Side:	Dunlop 7 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,727.79	2,489.32	1,238.47	33.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,860.00	3,460.00	1,400.00	28.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>8,587.79</b>	<b>5,949.32</b>	<b>2,638.47</b>	<b>30.72</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>601.15</b>	<b>416.45</b>	<b>184.70</b>	<b>30.72</b>
<b>Nett Amount (S\$)</b>	<b>9,188.94</b>	<b>6,365.77</b>	<b>2,823.17</b>	<b>30.72</b>

#### INSPECTION

Date of Assignment:	10/04/2019	
Date Inspected:	10/04/2019	Inspected At: Kah Motor Co Sdn Bhd (Ubi) 15 Ubi Road 4 Singapore 408610
Estimated Period of Repair:	5.0 days	

**Adjuster:** XING GUO QIANG

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

Reference	
<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 06 May 2019)
<b>Parts:</b> M1-SUV	HONDA HR-V 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLW3977Z)
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL COMPL.FR.FENDER	Buckled	335.66 FS	*335.66 FS
2	1		*FENDER ASSYL.FR.INNER	Not Necessary	76.50 FS	*- FS
3	11		*CLIP,INNER FENDER	Necessary	26.18 FS	*26.18 FS
4	1		*PROTECTORL.FR.WHEEL ARCH	Cut	125.46 FS	*125.46 FS
5	1		*ENCLOSUREL.FR.FENDER	Not Necessary	8.50 FS	*- FS
6	1		*FACE,FR.BUMPER	Cut	404.26 FS	*404.26 FS
7	1		*GRILLEFR.BUMPER	Not Necessary	67.15 FS	*- FS
8	1		*FACEFR.BUMPER LOWER	Not Necessary	196.86 FS	*- FS
9	1		*SPACER,L.FR.BUMPER SIDE	Necessary	9.35 FS	*9.35 FS
10	1		*BEAML.FR.BUMPER UPPER	Broken	20.91 FS	*20.91 FS
11	1		*BEAM COMP,FR.BUMPER	Not Necessary	189.46 FS	*- FS
12	1		*GARNISHL.FR.FOG LIGHT	Not Necessary	18.27 FS	*- FS
13	1		*GARNISHL.FR.BUMPER BEAM	Not Necessary	6.54 FS	*- FS
14	1		*GARNISHR.FR.BUMPER BEAM	Not Necessary	6.54 FS	*- FS
15	1		*CLIP,BUMPER (22 PCS)	Necessary	43.01 FS	*43.01 FS
16	1		*SET ,FR.GRILLE ASSY	Not Necessary	230.26 FS	*- FS
17	1		*MOLDINGFR.GRILLE UPPER	Not Necessary	161.33 FS	*- FS
18	1		*MOLDINGFR.GRILLE	Not Necessary	37.06 FS	*- FS
19	1		*EMBLEMFR	Not Necessary	22.69 FS	*- FS
20	2		*NUTPUSH 3MM	Not Necessary	3.57 FS	*- FS
21	1		*MOLDING ASSYL.FR.DOOR	Cut	20.14 FS	*20.14 FS
22	1		*HEAD LIGHT ASSY,L	Cut	1,469.39 FS	*1,469.39 FS
23	1		*LIGHT ASSYL.FR.FOGLIGHT	Not Necessary	203.74 FS	*- FS
24	1		*SUNDRIES	Necessary	30.00 FS	*20.00 FS
25	1		*BEAML.FR.GRILLE SIDE UPPER	Cracked	14.96 FS	*14.96 FS
<b>Total Parts (S\$)</b>					<b>3,727.79</b>	<b>2,489.32</b>

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	INSPECT FR LIGHTING MECHANISMS & FOCUS	New	80.00	80.00
2	STRAGHTEN ALIGN BULKHEAD & LEFT FRONT FENDER	New	2,400.00	1,400.00
3	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	2,200.00	1,800.00
4	WHEEL ALIGNMENT	New	180.00	180.00
<b>Gross Labour Cost (S\$)</b>			<b>4,860.00</b>	<b>3,460.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >