

AUTOWORX HOUSE

176 SIN MING DRIVE #02-01 SINGAPORE 575721
TEL: 6452 8211 FAX: 64517420

ESTIMATE

SAM SWEE PENG

c/o 46 Lenton Plain
Singapore 786548

*Not Authorized
Resurvey B4 paint
9 days*

1/2 Day B

Date: 6/04/2019

QUANTITY	PARTICULARS	AMOUNT (\$)
RE: TOYOTA PREVIA / SMH 1197 M		
1 pc	rear boot lid <i>1470.80</i>	<i>Bu</i> 1,940.38 ✓
1 pc	rear boot lock	<i>Su</i> 387.92 X
1 pc	rear boot lock catch	<i>R</i> 132.20 X
2 pcs	rear boot damper	<i>Su</i> 594.20 X
1 pc	rear boot lid side guild	<i>Bu</i> 344.18 X
1 pc	rear boot inner handle	<i>Su</i> 170.65 X
1 pc	rear boot outer handle switch	<i>Su</i> 701.40 X
1 pc	rear boot inner trim	<i>Su</i> 590.65 X
1 pc	rear boot weatherstrip	<i>148.10 Not/In</i> 296.20 <i>306.20</i>
1 pc	rear boot " Logo " emblem	<i>Mu</i> 101.00 ✓
1 pc	rear boot " PREVIA " emblem	<i>Mu</i> 86.30 ✓
1 pc	rear boot " GL " emblem	<i>Mu</i> 77.70 ✓
1 pc	rear boot lid inner tim board cover L/H	<i>Su</i> 198.40 X
1 pc	rear windscreen glass moulding	<i>Mu</i> 182.40 ✓
1 pc	rear bumper <i>785.30</i>	<i>Bu</i> 1,535.10 ✓
2 pcs	rear bumper side retainer	<i>Su</i> 155.00 X
2 pcs	rear bumper corner retainer	<i>Su</i> 144.00 X
2 pcs	rear bumper side reflector	<i>@ 64.60 Not/In</i> 129.20 ✓
2 pcs	rear bumper corner dust cover	<i>@ 116.50</i> <i>Su</i> 233.00 X
2 pcs	rear bumper tow hook cover	<i>@ 67.60</i> <i>Su</i> 135.20 X
2 pcs	rear cabin side lower trim	<i>@ 241.30</i> <i>Bu</i> 482.60 ✓
1 pc	rear cabin lower trim cover R/H	<i>Su</i> 297.60 X
1 pc	rear cabin lower trim cover L/H	<i>Su</i> 297.60 X
2 pcs	rear tail lamp assy	<i>@ 486.80</i> <i>Su</i> 973.60 X
1 pc	rear end panel <i>588.60</i>	<i>Bu</i> 728.10 ✓
1 pc	rear end inner panel	<i>Not/In</i> 467.30 X
1 pc	rear end panel trim	<i>Not/In</i> 356.10 ✓
1 pc	rear end compartment top board	<i>Su</i> 785.60 X
1 pc	rear end compartment panel	<i>Bu</i> 604.30 ✓
1 pc	rear end compartment panel trim	<i>Bu</i> 560.20 ✓
1 pc	rear key lock switch sensor	<i>CM</i> 346.70 ✓
1 pc	rear compartment floor panel	<i>R</i> 922.60 X
		14,957.38

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

Date:

	Balance brought forward.		14,957.38	
1 pc	rear compartment floor panel sub-frame		656.90	Y
1 pc	rear exhaust silencer		884.50	X
1 pc	rear exhaust silencer heat shield		264.10	X
	sub-total		16,762.88	
	less 25%		4,190.72	
	sub-total		12,572.16	
1 pc	rear number plate	s.nett	35.00	X
1 pc	rear number plate casing	s.nett	35.00	X
1 tube	windscreen glass sealant	s.nett	60.00	
3 pcs	exhaust rubber mount	s.nett @ 90.00	270.00	X
1 set	reverse sensor	s.nett	220.00	X
2 pcs	Reverse sensor (original)	@ 367.40	734.80	
			13,192.16	
	To remove and replace the parts mentioned above, panel beat and realign the necessary affected areas.		1,600.00	1100/
	To check wiring system.		20/ 60.00	
	To apply rust proofing on affected areas.		60/ 200.00	
	To apply waterproof sealant on affected areas.		30/ 180.00	
	To apply putty and spray painting on affected areas.		880/ 1,000.00	
	To install reverse sensors.		50/ 80.00	
	To remove fuel tank to enable repair.		20/ 80.00	X
	To remove rear and side windscreen glasses to enable repair.		120/ 140.00	
	To remove carpet, trimming and seats to enable repair.		100/ 300.00	
	To transfer tail door accessories.		60.00	✓
	To carry out exhaust works.		20/ 80.00	X
	TOTAL		16,972.16	
	* supplementary (List items).			
	→ Rear Bumper Park Sensor	@ 367.40	734.80	X Repeated
	→ Rear Bump Closing Mode Buzzer		295.60	✓ Dd.