



Case Details

Case Reference Number : BUS/03/19/5013
 Type of Repair : Accident Repair
 Vehicle Registration Number : SG1745R

Company Type : SMRT Buses Ltd
 Estimation ID : EST-6369-ID
 Assigned By : Audrey Woo Yee Shin

Insurance Company Name : India International Insurance Pte Ltd
 Accident Date and Time : 10/03/2019 09:18 PM
 Vehicle Age(In Months) : 36

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			STCKER SMRT	1	200.00	200.00	0.00	200.00	Replace	1	200.00	Replace	hec
Standard	Main	BODY LH	6009999	PANEL, SIDE:LS, FOR MAN A22 BUS	1	1,776.80	1,776.80	10.00	1,599.12	Replace	1	1,599.12	Replace	BVC
Standard	Main	CONSUMABLE	4006314	ADHESIVE:DIRECT GLAZING	6	37.00	222.00	0.00	222.00	Replace	6	222.00	Replace	hec
Standard	Main	CONSUMABLE	4006315	ACTVATOR	1	80.00	80.00	0.00	80.00	Replace	1	80.00	Replace	hec
Standard	Main	CONSUMABLE	4006313	PRIMER (SIKA 206 G+P)	1	80.00	80.00	0.00	80.00	Replace	1	80.00	Replace	hec
Standard	Main	DOOR	6010498	RUBBER,EXIT DOOR:FOR MAN A22 BUS	1	750.00	750.00	10.00	675.00	Replace	1	675.00	Replace	SCR
Standard	Main	DOOR	6010499	RUBBER,EXIT DOOR:FOR MAN A22 BUS	1	750.00	750.00	10.00	675.00	Replace	1	675.00	Replace	SCR
Standard	Main	VE	6009518	LED LICENCE PLATE LAMP FOR MB OC500 LE	2	172.50	345.00	0.00	345.00	Replace	0	0	Not Given	m
Total Spare Part Cost									3,876.12		Surveyor Total		2,856.12	
Lump Sum Discount (%)									20.00		Lump Sum Dis (%)		20	
Final Spare Part Cost									3,100.90		Final Sur Total		2,284.90	

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REMOVE & INSTALL REPLACE ITEM & REPAIR LEFT SIDE PORTION	1,855.00	1,590	
Total:			1,855.00	1,590.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO PUTTY & RESPRAY	878.00	708	
Total:			878.00	708.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Total:			0.00	0.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	3,100.90	2,284.90
Total Labour Cost	1,855.00	1,590.00
Total Spray Painting	878.00	708.00

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Other	0.00	0.00
Overall Total	5,833.90	4,582.90
Lump Sum Repair Option	☒	☒
Lump Sum Total	5,850.00	4,600.00
Surveyor Approved Amount		4,600.00
No of Repair Days*	5	4
Remarks	-	L/S REPAIR, PHOTO AFTER REPAIR
Surveyor Name		Hwee je
Signature		
Survey Date	08/04/2019	Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: