

INSURANCE

INS. CASE OWNER

CC 3/AIG1900

6167, A 1/13/19

LKK
IDAC

Surveyor:

AORIAN

DOI:

1104/19

Date / Time:

8/4/19

Registered in Merimen:

8/4/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

6167 1227X

Name of Insured:

BOON TECK TEOWING LO

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

5/4/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

CHEN YONG HONG

Driver Tel No.:

(V/L YES / NO)

Claim No.:

84549376854

Policy No.:

15000 E4479

Make / Model:

TOYOTA

Place of Accident:

LP OF BIK LOA 7m BET WPTN

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

5ME WITL



INSRS:
WSP:
Tel:
Liability:
RMKS:

premium



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:



INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time		STAGE	DATE / PIC
11/04/19	5ME WITL	Non-Reporting ltr (1st):	
		Non-Reporting ltr (2nd):	
		Non-Reporting ltr (Final):	
		Notification ltr (if non-pickup):	
11/4/19	Spoke to OIR (rep. Ms. Jim Jim). She confirmed the minor OIR hit parked TP.	Call CR	7/11/4/19 - Khendina
@ 5-15pm	Inform OIR on TP claim, agreed to settle and advise NCD will be affected	After call ltr to OIR	one-one
16/12/19	FILE PND TO TYPE MANDATE	Documentation Check List: Handler Typist	
10/2/2020	FILE PND TO MINA TO CLARE	Notification ltr (if non-pickup):	
		After call ltr to OIR	
		Authorisation To Act:	
		Release Voucher:	
		Final Repair Bill:	
		Car Rental Invoice:	
		Timing Invoice:	
		LTA / GIA:	
		Medical Bill:	
		PIR:	
		Mandate/Reject Instruction:	
		LOD	
		Payment Breakdown Form:	
		Post-Repair Photos:	
		Others:	

PRELIMINARY ADVICE	Date/Time:	Sent By:	Confirm with:	Confirm by:
FINALIZATION	Date/Time:	Repair Cost:	SS	(days) Reduction: %
FINAL SETTLEMENT	Date/Time:	Confirm with:	Final Liability:	%
	7/02/2020	Nadia	SS 10186.91	73
			Repair Cost: (w/61)	
			Loss of Rental (LOR):	
			Loss of Use (LOU):	
			Loss of Income (LOI):	
			LOR only ☐ LOU only ☐ LOR + LOU ☐ LOR + LO ☐ [Tick only one]	
			GIA/LTA Search:	
			Medical:	
			Disbursement:	
			Legal Cost:	
Total:	SS 10438.91	Global Sum SS:		
FINAL PAYMENT	Date/Time:	Confirm with:	Email:	Call:
Payee 1:	SS 10438.91	Name 1:	Premium Automobiles Pte Ltd	
Payee 2: (Strike if N.A.)	SS	Name 2:		
Payee 3: (Strike if N.A.)	SS	Name 3:		

h

Adrian

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 88 days Res.: Yes or No

Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Vehicle: IN / OUT

Person Contacted: _____

Veh No: SME2917L Yr Regn: 2018 18pt

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Audi A3 Sedan c.c. 1395

Colour: White A/C: Insured / Std / Nil / NA

Sp. Reading: 15940 T/Radio: Insured / Std / Nil / NA

Eng/No: _____

C/No: WAUZZZ8V6J1017822

Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16

R: 205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front		Rear	
R/Bal. <u>06</u>	mm	R/Bal. <u>06</u>	mm
L/Bal. <u>06</u>	mm	L/Bal. <u>06</u>	mm
D.O.A. _____		D.O.I. <u>11/04/15</u>	

Survey held at PremiumDes. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

Front O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	TPA LG
	P/P - \$9520.48 (Red \$9661.52 / 50%)
	MV:
	PV:
	Nett:

Date/Time, File Pass to?	Date/Time, File Return to?
1)	2)
3)	4)
5)	6)
Prel. Report:	
Final Report:	

Part Prices Check:

IN OUT

Survey Fee:

Basic & Add.

S + RS, SI

Photos

Others

TOTAL

Date:

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0452/2019/DY/GW
Date : 8-Apr-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your Insured Vehicle : **GBG 1227 X**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Tan Seng Soon
Address : Blk 109 Jalan Bukit Merah
#02-1746
Singapore 160109
Telephone : HP +65 90844993
Type of Claim : Third Party Claim
Policy No. : 1800114612
Vehicle No : **SME 2917 L**
Model Code : Audi A3 SEDAN 1.0 TFSI
Model / Year : Sep-18
Engine No : CZE 693520
Chassis No : WAUZZZBV6J1077322
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Apr-19
Place of Accident : Blk 109 Jalan Bukit Merah

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SME 2917 L

S/N	Nature of Jobs	Estimated Charges
1	To remove, check and reinstall front wire harness for headlight, horns, outside temperature sensor and headlight washer assy.	s/n \$ 360.00 ✓
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Inspect front lock carrier for further damages. Reorganize crash management components. Reinstall all parts removed.	\$ 2,100.00 1250
3	To respray front bumper and rhs front fender.	\$ 1,500.00 1100
4	To carry out diagnostic check.	s/n \$ 280.00 192
TOTAL LABOUR CHARGES		: \$ 4,240.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 2917 L

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	\$ 1,830.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 170.00	✓
3	FRONT BUMPER GUIDE SECTION - RH <i>cracked.</i>	\$ 35.00	✓
4	FRONT BUMPER GRILLE-CENTER <i>new</i>	\$ 146.00	+
5	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE <i>new</i>	\$ 488.00	+
6	FRONT BUMPER CLOSING ELEMENT-RH <i>cracked.</i>	\$ 270.00	+
7	FRONT BUMPER COVER TRIM-RH <i>new</i>	\$ 148.00	+
8	FRONT ADAPTER WHEEL HOUSING LINER-RH <i>new</i>	\$ 34.00	+
9	RADIATOR GRILLE <i>new</i>	\$ 1,301.00	+
10	RADIATOR GRILLE CLOSING ELEMENT <i>new</i>	\$ 174.00	+
11	FRONT BUMPER AIR GUIDE GRILLE-RH <i>cracked.</i>	\$ 171.00	✓
12	FRONT BUMPER REINFORCEMENT BEAM <i>new</i>	\$ 670.00	✓
13	FOAM FILER PIECE <i>Not New</i>	\$ 172.00	✓
14	FRONT BUMPER COVER	\$ 111.00	+
15	AIR CONDITIONER STICKER <i>new</i>	\$ 7.00	+
16	SIGN 'CAUTION'	\$ 13.00	+
17	SIGNAL HORN LOW TONER-RH <i>new</i>	\$ 182.00	+
18	FRONT FENDER-RH <i>Distorted</i>	\$ 778.00	✓
19	FRONT FENDER UPPER BRACKET-RH <i>Best</i>	\$ 25.00	✓
20	FRONT FENDER BRACKET-RH	\$ 35.00	✓
SUB TOTAL SPARE PARTS		\$ 6,760.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 2917 L

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FRONT FENDER BRACE-RH <i>Best</i>	\$ 88.00	✓
22	FRONT WHEEL HOUSING LINER-RH <i>new</i>	\$ 158.00	✓
23	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS-RI	\$ 81.00	✓
24	LED HEADLIGHT-RH <i>cracked</i>	\$ 5,029.00	✓
25	LED HEADLIGHT FOR POWER MODULE-RH	\$ 693.00	✓
26	LED WITH HEAT SINK-RH	\$ 666.00	✓
27	LED HEADLIGHT CONTROL UNIT-RH	\$ 508.00	✓
28	LED HEADLIGHT LIFT CYLINDER FOR WASH SYSTEM-R	\$ 128.00	✓
29	HOSE FOR HEADLIGHT WASHER SYSTEM	\$ 61.00	✓
30	FRONT AIR GUIDE-RH	\$ 22.00	✓
31	FRONT AIR GUIDE SEAL-RH	\$ 8.00	✓
32	FRONT CAR PLATE NO.	S/N \$ 40.00	✓
33	SUNDRIES <i>new</i>	\$ 700.00	✓ 12.00
TOTAL SPARE PARTS		\$ 14,942.00	
TOTAL LABOUR CHARGES		\$ 4,240.00	
GRAND TOTAL		\$ 19,182.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adnan Lim
Surveyed Date : 11/04/19
Authorised Date :
Excess Cost :
Liability :
Remarks : X6L Authorised / OS Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please Note : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly. For inspection of vehicle, please refer to Ms Norah Khai at Tel:6768 9828 for appointment.

Yours faithfully,

Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0452/2019/DY/GW
Date : 8-Apr-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your Insured Vehicle : **GBG 1227 X**

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Hi Adrian

5 days - ok - jb - 3 Jun 19

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Tan Seng Soon
Address : Blk 109 Jalan Bukit Merah
#02-1746
Singapore 160109
Telephone : HP +65 90844993
Type of Claim : Third Party Claim
Policy No. : 1800114612
Vehicle No : **SME 2917 L**
Model Code : Audi A3 SEDAN 1.0 TFSI
Model / Year : Sep-18
Engine No : CZE 693520
Chassis No : WAUZZZBV6J1077322
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Apr-19
Place of Accident : Blk 109 Jalan Bukit Merah

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SME 2917 L

S/N	Nature of Jobs	Estimated Charges			
1	To remove, check and reinstall front wire harness for headlight, horns, outside temperature sensor and headlight washer assy.	s/n	\$ 360.00	\$	360.00
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Inspect front lock carrier for further damages. Reorganize crash management components. Reinstall all parts removed.		\$ 2,100.00	\$	1,250.00
3	To respray front bumper and rhs front fender.		\$ 1,500.00	\$	1,100.00
4	To carry out diagnostic check.	s/n	\$ 280.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 4,240.00	\$	2,902.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 2917 L

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER	\$ 1,830.00	\$ 1,464.00 ✓
2	FRONT BUMPER FIXING PARTS	\$ 170.00	
3	FRONT BUMPER GUIDE SECTION - RH	\$ 35.00	\$ 27.52 ✓
4	FRONT BUMPER GRILLE-CENTER	\$ 146.00	
5	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE	\$ 488.00	
6	FRONT BUMPER CLOSING ELEMENT-RH	\$ 270.00	\$ 216.00 ✓
7	FRONT BUMPER COVER TRIM-RH	\$ 148.00	
8	FRONT ADAPTER WHEEL HOUSING LINER-RH	\$ 34.00	
9	RADIATOR GRILLE	\$ 1,301.00	
10	RADIATOR GRILLE CLOSING ELEMENT	\$ 174.00	
11	FRONT BUMPER AIR GUIDE GRILLE-RH	\$ 171.00	\$ 136.40 ✓
12	FRONT BUMPER REINFORCEMENT BEAM	\$ 670.00	
13	FOAM FILER PIECE	\$ 172.00	
14	FRONT BUMPER COVER	\$ 111.00	
15	AIR CONDITIONER STICKER	\$ 7.00	
16	SIGN ' CAUTION'	\$ 13.00	
17	SIGNAL HORN LOW TONER-RH	\$ 182.00	
18	FRONT FENDER-RH	\$ 778.00	\$ 622.00 ✓
19	FRONT FENDER UPPER BRACKET-RH	\$ 25.00	\$ 19.76 ✓
20	FRONT FENDER BRACKET-RH	\$ 35.00	\$ 27.76 ✓
SUB TOTAL SPARE PARTS		\$ 6,760.00	\$ 2,513.44

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 2917 L

S/N	Parts Description		Damage Parts & Prices	
			S/NETT	REMARKS
		c/f	\$	2,513.44
21	FRONT FENDER BRACE-RH	\$	88.00	\$ 69.84 ✓
22	FRONT WHEEL HOUSING LINER-RH	\$	158.00	
23	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS-RI	\$	81.00	
24	LED HEADLIGHT-RH	\$	5,029.00	\$ 4,023.20 ✓
25	LED HEADLIGHT FOR POWER MODULE-RH	\$	693.00	
26	LED WITH HEAT SINK-RH	\$	666.00	
27	LED HEADLIGHT CONTROL UNIT-RH	\$	508.00	
28	LED HEADLIGHT LIFT CYLINDER FOR WAHER SYSTEM-R	\$	128.00	
29	HOSE FOR HEADLIGHT WASHER SYSTEM	\$	61.00	
30	FRONT AIR GUIDE-RH	\$	22.00	
31	FRONT AIR GUIDE SEAL-RH	\$	8.00	
32	FRONT CAR PLATE NO.	S/N	\$ 40.00	
33	SUNDRIES	\$	700.00	\$ 12.00
TOTAL SPARE PARTS		:	\$ 14,942.00	\$ 6,618.48
TOTAL LABOUR CHARGES		:	\$ 4,240.00	\$ 2,902.00
GRAND TOTAL		:	\$ 19,182.00	\$ 9,520.48

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name :
Surveyed Date :
Authorised Date :
Excess Cost :
Liability :
Remarks :

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the
progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant

View Received Message

This mail is associated with :

***SME2917L (8484793768SG)
[GBG1227X]**

TP
TAN SENG SOON
Apr 5 2019 7:00AM
[BOON TECK TRADING CO]
Premium Automobiles Pte Ltd

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 07/02/2020 15:46 PM
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$10438.91) - SME2917L - Claim Handler: Ler, Bernard-JQ

Approved:10438.91:Cost of Repair : \$10,186.91 Loss of Use : \$250.00 5 days @ S\$ 50/day LTA/ GIA Search Fee : \$2.00 Total : \$10,438.91

DOCUMENTS SUMMARY

There are no documents.

BREAKDOWN OF PAYMENT

Vehicle No: SME 2917 L

Accident on 5/4/2019 at Blk 109 Jalan Bukit Merah Carpark

Involving vehicle/s GBG 1227 X

1) Repair cost \$ 10,186.91 Payable to: Premium Automobiles Pte Ltd

2) GIA/LTA search fee \$ 0 Payable to: Premium Automobiles Pte Ltd

3) Loss of Use or Rental Car \$ 250 Payable to: Tan Seng Soon

4) Medical fees \$ _____ Payable to: _____

5) Others \$ _____ Payable to: _____



CERTIFICATE OF INSURANCE

AUDI AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : TAN SENG SOON
Period of Insurance : 25 Sep 2018 To 24 Sep 2019
Engine No. : CZE693520
Chassis No. : WAUZZZ8V6J1077322

Vehicle No. : SME2917L
Policy No. : 1800114612
Endorsement No. :
Issued Date : 05 Oct 2018

ABOUT THE COVER

Make/Model : AUDI A3 Sedan 1.4 TFSI
Engine Capacity/Tonnage : 1,395.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :
Sum Insured : Market Value
Off Peak Car : No
First Year of Registration : 2018
Insuring with COE/PARF : Yes

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1800cc - 2000cc Optional

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

TAN SENG SOON - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Audi Customer Service Center Add: 55 Ubi Road 1 Singapore 408699 63662323

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: DBS BANK LTD

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504125261

PREMIUM LEASING -CYS

281 ALEXANDRA ROAD AUDI CUSTOMER SERVICE CENTRE

SINGAPORE 159938

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Monik

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

Cheng Cheng Chua

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Apr 2019 Edit Reg		11 Apr 2019 00:00 Edit Adj Rpt	S\$9,520.48 Edit Estimates	S\$9,520.48 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	BOON TECK TRADING CO., Co. Reg. No.: 23961700B								
Main Claimant:	TAN SENG SOON, ID: S1392191A								
Vehicle Reg. No.:	SME2917L	Date of Loss:	05/04/2019 07:00 - :59 [6 Months and 11 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 8484793768SG	Policy/Cover Note No.:	1800044439 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBG1227X	Policy No. (Claimant):	1800114612						
		Excess:							
Repairer:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1, 408699 Ubi - Tel: 67689828/9827/9911								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com								
Claimant's Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (SG) - Tel: 65-6419-3000								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 17/04/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
AIG_SG_EXPRESS (07/02/2020): Alert - Adj Mandate Approved (S\$10438.91) - SME2917L - Claim Handler: Ler, Berna...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SME2917L (8484793768SG)
[GBG1227X]
TP
TAN SENG SOON
Apr 5 2019 7:00AM
[BOON TECK TRADING CO]
Premium Automobiles Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser
------------------	---------------	--------------------	--------------	--------------	--

Letters/Correspondences				1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	(Draft)	Third Party Express Settlement - Payment Breakdown		Edit	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	04/10/19 11:20	General View		Load JPG	☒
2	04/10/19 11:20	General View		Load JPG	☒
3	04/10/19 11:20	General View		Load JPG	☒
4	04/10/19 11:20	General View		Load JPG	☒
5	04/10/19 11:20	General View		Load JPG	☒
6	04/10/19 11:20	General View		Load JPG	☒
7	04/10/19 11:20	General View		Load JPG	☒
8	04/10/19 11:20	General View		Load JPG	☒
9	04/10/19 11:20	General View		Load JPG	☒
10	04/10/19 11:20	General View		Load JPG	☒
11	04/10/19 11:20	General View		Load JPG	☒
12	04/10/19 11:20	General View		Load JPG	☒
13	04/10/19 11:20	General View		Load JPG	☒
14	04/10/19 11:20	General View		Load JPG	☒
15	04/10/19 11:20	General View		Load JPG	☒
16	04/10/19 11:20	General View		Load JPG	☒
17	04/10/19 11:20	Reinspection Photo		Load JPG	☒
18	04/10/19 11:20	Reinspection Photo		Load JPG	☒
19	04/10/19 11:20	Reinspection Photo		Load JPG	☒
20	04/10/19 11:20	Reinspection Photo		Load JPG	☒
21	04/10/19 11:21	Reinspection Photo		Load JPG	☒
22	04/10/19 11:21	Reinspection Photo		Load JPG	☒
23	04/10/19 11:21	Reinspection Photo		Load JPG	☒
24	04/10/19 11:21	Reinspection Photo		Load JPG	☒
25	04/10/19 11:21	Reinspection Photo		Load JPG	☒
26	04/10/19 11:21	Reinspection Photo		Load JPG	☒
27	04/10/19 11:21	Reinspection Photo		Load JPG	☒

Documentation				1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print	
1	08/04/19 16:29	TP GIA REPORT		Load PDF	
2	15/04/19 09:19	TP ESTIMATE- MARKED		Load PDF	
3	10/01/20 15:18	LETTER TO OI		Load PDF	
4	10/01/20 15:29	TP ESTIMATE - MARKED (FINAL)		Load PDF	
5	10/01/20 15:29	LOD		Load PDF	
6	10/01/20 15:29	GIA SEARCH FEE		Load PDF	
7	11/02/20 14:41	WORKSHOP INVOICE		Load PDF	
8	11/02/20 14:41	AUTHORISATION TO ACT FORM		Load PDF	
9	11/02/20 14:41	Release Voucher		Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print	
1	09/04/19 16:28	OI GIA REPORT		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer			
Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBG1227X (Insd veh)	Model:	AUDI A3 1.4 SEDAN TFSI
	SME2917L (TP veh)		COD S-TRONIC (A)
Date of Accident:	05/04/2019		

Global Sum Settlement	: ☐ Yes	: ☒ No	
Repair Estimate	: \$		20,524.74
Final Repair Cost	: \$		10,186.91
Loss of Use	: \$		250.00
Rental (if any)	: \$		0.00
LTA / GIA Search Fee	: \$		2.00
Others:	: \$		0.00
	: \$		
Final Settlement Sum	: \$		10,438.91

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: _____

_____23_____

BOLA Liability: _____100_____ (%) Assessed Liability (*): _____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Premium Automobiles Pte Ltd	: \$	10,438.91
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

11 Feb
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19006167/ADS3Q2

Date: 11/02/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800044439
 Claimant: SME2917L Insured Vehicle No: GBG1227X
 Vehicle No: SME2917L
 Date of Loss: 05/04/2019 Nature of Claim: TP Claim No: 8484793768SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SME2917L
 Make & Model: AUDI A3, 1.4 SEDAN TFSI COD S-TRONIC (A) Engine No: CZE693520
 Reg. Date: 25/09/2018 (Man. Year: 2018) Chassis No: WAUZZZ8V6J1077322
 Colour: White Odometer: 15940 km
 Engine Capacity: 1395 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,942.00	6,618.48	8,323.52	55.71
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,240.00	2,902.00	1,338.00	31.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	19,182.00	9,520.48	9,661.52	50.37
+ GST 7.00/7.00% (S\$)	1,342.74	666.43	676.31	50.37
Nett Amount (S\$)	20,524.74	10,186.91	10,337.83	50.37
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		10,438.91		

INSPECTION

Date of Assignment: 11/04/2019
 Date Inspected: 11/04/2019 Inspected At: Premium Automobiles Pte Ltd (UBI)
 55 Ubi Road 1
 Singapore 408699
 Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,830.00 FS	*1,464.00 FS
2	1		*FRONT BUMPER FIXING PARTS	Not Necessary	170.00 FS	*- FS
3	1		*FRONT BUMPER GUIDE SECTION -RH	Cracked	35.00 FS	*27.52 FS
4	1		*FRONT BUMPER GRILLE -CENTER	Not Necessary	146.00 FS	*- FS
5	1		*FRONT BUMPER CLOSING ELEMENT -LOWER CENTER	Not Necessary	488.00 FS	*- FS
6	1		*FRONT BUMPER CLOSING ELEMENT -RH	Cracked	270.00 FS	*216.00 FS
7	1		*FRONT ADAPTER WHEEL HOUSING LINER -RH	Not Necessary	34.00 FS	*- FS
8	1		*RADIATOR GRILLE	Not Necessary	1,301.00 FS	*- FS
9	1		*RADIATOR GRILLE CLOSING ELEMENT	Not Necessary	174.00 FS	*- FS
10	1		*FRONT BUMPER AIR GUIDE GRILLE -RH	Cracked	171.00 FS	*136.40 FS
11	1		*FRONT BUMPER REINFORCEMENT BEAM	Not Necessary	670.00 FS	*- FS
12	1		*FOAM FILER PIECE	Not Necessary	172.00 FS	*- FS
13	1		*FRONT BUMPER COVER	Not Necessary	111.00 FS	*- FS
14	1		*AIR CONDITIONER STICKER	Not Necessary	7.00 FS	*- FS
15	1		*SIGN CAUTION	Not Necessary	13.00 FS	*- FS
16	1		*SIGNAL HORN LOW TONER -RH	Not Necessary	182.00 FS	*- FS
17	1		*FRONT FENDER -RH	Distorted	778.00 FS	*622.00 FS
18	1		*FRONT FENDER UPPER BRACKET -RH	Bent	25.00 FS	*19.76 FS
19	1		*FRONT FENDER BRACKET -RH	Bent	35.00 FS	*27.76 FS
20	1		*FRONT BUMPER COVER TRIM -RH	Not Necessary	148.00 FS	*- FS
21	1		*FRONT FENDER BRACE -RH	Bent	88.00 FS	*69.84 FS
22	1		*FRONT WHEEL HOUSING LINER -RH	Not Necessary	158.00 FS	*- FS
23	1		*FRONT WHEEL HOUSING LINER ATTACHMENT PARTS -RH	Not Necessary	81.00 FS	*- FS
24	1		*LED HEADLIGHT -RH	Cracked	5,029.00 FS	*4,023.20 FS
25	1		*LED HEADLIGHT FOR POWER MODULE -RH	Not Necessary	693.00 FS	*- FS
26	1		*LED WITH HEAT SINK -RH	Not Necessary	666.00 FS	*- FS
27	1		*LED HEADLIGHT CONTROL UNIT-RH	Not Necessary	508.00 FS	*- FS
28	1		*LED HEADLIGHT LIFT CYLINDER FOR WASHER SYSTEM -RH	Not Necessary	128.00 FS	*- FS
29	1		*HOSE FOR HEADLIGHT WASHER SYSTEM	Not Necessary	61.00 FS	*- FS
30	1		*FRONT AIR GUIDE -RH	Not Necessary	22.00 FS	*- FS
31	1		*FRONT AIR GUIDE SEAL -RH	Not Necessary	8.00 FS	*- FS
32	1		*FRONT CAR PLATE NO	Not Necessary	40.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
33	1		*SUNDRIES	Necessary	700.00 FS	*12.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					14,942.00	6,618.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ,CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHT ,HORNS ,OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER .RHS FRONT FENDER AND RHS HEADLIGHT .INSPECT FRONT LOCK CARRIER FOR FURTHER DAMAGES .REORGANIZE CRASH MANAGEMENT COMPONENTS .REINSTALL ALL PARTS REMOVED	New	2,100.00	1,250.00
3	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER	New	1,500.00	1,100.00
4	TO CARRY OUT DIAGNOSTIC CHECK	New	280.00	192.00
Gross Labour Cost (S\$)			4,240.00	2,902.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >