

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0452/2019/DY/GW
Date : 8-Apr-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your Insured Vehicle : GBG 1227 X

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Tan Seng Soon
Address : Blk 109 Jalan Bukit Merah
#02-1746
Singapore 160109
Telephone : HP +65 90844993
Type of Claim : Third Party Claim
Policy No. : 1800114612
Vehicle No : **SME 2917 L**
Model Code : Audi A3 SEDAN 1.0 TFSI
Model / Year : Sep-18
Engine No : CZE 693520
Chassis No : WAUZZZBV6J1077322
Mileage : -
Date In : -
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 5-Apr-19
Place of Accident : Blk 109 Jalan Bukit Merah-

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SME 2917 L

S/N	Nature of Jobs	Estimated Charges
1	To remove, check and reinstall front wire harness for headlight, horns, outside temperature sensor and headlight washer assy.	s/n \$ 360.00 ✓
2	To dismantle and renew front bumper, rhs front fender and rhs headlight. Inspect front lock carrier for further damages. Reorganize crash management components. Reinstall all parts removed.	\$ 2,100.00 1250
3	To respray front bumper and rhs front fender.	\$ 1,500.00 1100
4	To carry out diagnostic check.	s/n \$ 280.00 192
TOTAL LABOUR CHARGES		: \$ 4,240.00

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 2917 L

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
1	FRONT BUMPER <i>Distorted</i>	\$ 1,830.00	✓
2	FRONT BUMPER FIXING PARTS <i>new</i>	\$ 170.00	✓
3	FRONT BUMPER GUIDE SECTION - RH <i>?</i>	\$ 35.00	?
4	FRONT BUMPER GRILLE-CENTER <i>new</i>	\$ 146.00	+
5	FRONT BUMPER CLOSING ELEMENT-LOWER CENTRE <i>new</i>	\$ 488.00	+
6	FRONT BUMPER CLOSING ELEMENT-RH <i>new</i>	\$ 270.00	+
7	FRONT BUMPER COVER TRIM-RH <i>new</i>	\$ 148.00	✓
8	FRONT ADAPTER WHEEL HOUSING LINER-RH <i>new</i>	\$ 34.00	✓
9	RADIATOR GRILLE <i>new</i>	\$ 1,301.00	+
10	RADIATOR GRILLE CLOSING ELEMENT <i>new</i>	\$ 174.00	✓
11	FRONT BUMPER AIR GUIDE GRILLE-RH <i>?</i>	\$ 171.00	?
12	FRONT BUMPER REINFORCEMENT BEAM <i>?</i>	\$ 670.00	?
13	FOAM FILER PIECE <i>?</i>	\$ 172.00	?
14	FRONT BUMPER COVER	\$ 111.00	+
15	AIR CONDITIONER STICKER <i>new</i>	\$ 7.00	+
16	SIGN ' CAUTION'	\$ 13.00	+
17	SIGNAL HORN LOW TONER-RH <i>new</i>	\$ 182.00	✓
18	FRONT FENDER-RH <i>Distorted</i>	\$ 778.00	✓
19	FRONT FENDER UPPER BRACKET-RH <i>Best</i>	\$ 25.00	✓
20	FRONT FENDER BRACKET-RH	\$ 35.00	✓
SUB TOTAL SPARE PARTS		\$ 6,760.00	

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Material List for Accident Vehicle Regn No. SME 2917 L

S/N	Parts Description	Damage Parts & Prices	
		S/NETT	REMARKS
21	FRONT FENDER BRACE-RH <i>Best</i>	\$ 88.00	✓
22	FRONT WHEEL HOUSING LINER-RH <i>new new</i>	\$ 158.00	+
23	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS-RI	\$ 81.00	+
24	LED HEADLIGHT-RH <i>concluded</i>	\$ 5,029.00	✓
25	LED HEADLIGHT FOR POWER MODULE-RH	\$ 693.00	+
26	LED WITH HEAT SINK-RH	\$ 666.00	+
27	LED HEADLIGHT CONTROL UNIT-RH	\$ 508.00	+
28	LED HEADLIGHT LIFT CYLINDER FOR WAHER SYSTEM-R	\$ 128.00	?
29	HOSE FOR HEADLIGHT WASHER SYSTEM	\$ 61.00	+
30	FRONT AIR GUIDE-RH	\$ 22.00	+
31	FRONT AIR GUIDE SEAL-RH	\$ 8.00	+
32	FRONT CAR PLATE NO. <i>S/N</i>	\$ 40.00	+
33	SUNDRIES ?	\$ 700.00	+
TOTAL SPARE PARTS		\$ 14,942.00	
TOTAL LABOUR CHARGES		\$ 4,240.00	
GRAND TOTAL		\$ 19,182.00	

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian Lim
Surveyed Date : 11/04/19
Authorised Date :
Excess Cost :
Liability :
Remarks : XBL Authorised , 05 Days

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant