

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## FINAL REPORT

Estimate No. : **b1 50772**  
Date Estimated : **08/04/2019**  
Prepared By : **Kevin Leong Wai Kit**

Page No. :

**REPAIR FOR -**  
**Chang Lai Chan Belinda**  
**21 Faber Heights**

**- ACCOUNT - 121**  
**AIG Asia Pacific Insurance Pte. Ltd.**  
**78 Shenton Way**  
**#08-16 Chartis Building**  
**Singapore 079120**

**Singapore 129167**

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
<b>SKP6401Y</b>	<b>NS37834</b>	<b>26/09/2014</b>	<b>316iA/4</b>	<b>0</b>

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

To replace front bumper and attachments include making good the front LH fender and knocking out dents caused by the accident	1275.00		1,275.00
---	---------	--	----------

To spray paint front bumper and front LH fender	1730.00		1,730.00
---	---------	--	----------

To replace LH xenon headlight include programming and conducting tests for proper function	408.00		408.00
--	--------	--	--------

To check electrical wiring systems at the front section for proper function	150.00		150.00
---	--------	--	--------

Sundries	80.00		80.00
----------	-------	--	-------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

FRT BUMPER TRIM PRIMED (SRA)	1,027.25	1.00		1,027.25
------------------------------	----------	------	--	----------

PLAQUE 82MM	71.25	1.00		71.25
-------------	-------	------	--	-------

LH HEADLIGHT (XENON)	2,119.70	1.00		2,119.70
----------------------	----------	------	--	----------

### # SUPPLEMENTARY ITEMS

Total Labour :	3,643.00
Total Parts :	3,218.20
Total Labour & Parts :	6,861.20
Deduction for Excess :	0.00
Total Repair Costs less Excess:	6,861.20
GST @7%:	480.28
<b>Grand Total :</b>	<b>7,341.48</b>