

Performance Motors Limited

A Sime Darby Motors Company
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
 Toll-Free Number (1800-2255269)

303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax. 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax. 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax. 64796601 (AfterSales)
 64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

08 APR 2019

E S T I M A T E

Estimate No. : b1 50772	Page No. : 1 of 5
Date Estimated : 08/04/2019	
Prepared By : Kevin Leong Wai Kit	

<p>- ESTIMATE REPAIR FOR - Chang Lai Chan Belinda 21 Faber Heights Singapore 129167</p>	<p>- ACCOUNT - 121 AIG Asia Pacific Insurance Pte. Ltd. 78 Shenton Way #08-16 Chartis Building Singapore 079120</p>
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKP6401Y	NS37834	26/09/2014	316iA/4	0

DESCRIPTION	VALUE		
To replace frt bumper, frt LH headlamp support @ all attachments cause by accident. To repair on frt LH side panel	1275 2,500.00		
Painting on frt bumper & frt LH side panel	1730 1,923.00		
To replace left headlight.	408? 481.00		
To check electrical wiring systems at the front section for proper function.	150 177.00		
Sundries.	? 80.00		
Total Labour 1:	5,211.00		
DESCRIPTION	QTY	PRIC	VALUE
FRONT SHOCK ABSORBER ?	1	43.00	43.00
INSERT AIR INTAKE CENTER ?	1	97.90	97.90
LH SUPPORT FOGLAMP ?	1	41.85	41.85
FRT BUMPER TRIM PRIMED (SRA) ?	1	1,027.25	1,027.25
LH COVER SPRAY NOZZLE PRIMED ?	1	43.25	43.25
LH SUPPORT ?	1	131.50	131.50
PLAQUE 82MM ?	1	71.25	71.25
LH HEADLIGHT (XENON) ?	1	2,119.70	2,119.70
DECOUPLING RING PDC TORQUE CONVERTE ?	4	5.05	20.20
Total Parts :			3,595.90

Performance Motors Limited

A Sime Darby Motors Company
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
 Toll-Free Number (1800-2255269)

303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax. 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax. 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax. 64796601 (AfterSales)
 64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : **b1 50772**
 Date Estimated : **08/04/2019**
 Prepared By : **Kevin Leong Wai Kit**

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKP6401Y	NS37834	26/09/2014	316iA/4	0

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. _____ Claim No. _____

Date & Time 21/05/19 @ 12:45 Excess S\$ _____

Surveyor's Name Ramu Sign _____

Surveyor's Tel 9232068 Authorised Yes / No _____

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No _____

Surveyor's E-mail _____

No. of Working Days Recommended 5 days

Labour 1	:	5,211.00
Parts	:	3,595.90
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	616.48
Grand Total	:	9,423.38

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **