

Longpal
LKK



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLN 4169 E

Not Authorized
Resurvey B4 print


Parts	(a) Cost / List Price Items	\$	28,997.88
	Plus/Less 25%	\$	7,249.47
	Total of Cost / List	\$	21,748.41
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	340.00
Total Parts Cost		\$	22,088.41
Labour		\$	6,480.00
Total		\$	28,568.41

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor	:	Kenneth	
Company	:	LKK	
Survey conducted on	:	9/4/11	at
<u>Remarks By Surveyor</u>			
(a)	The repair of this vehicle is authorized / is not authorized until further notice.		
(b)	Recommended Days of Repair	:	11 day(s)
(c)	Resurvey	:	Required / Not Required
(d)	Excess	:\$	
(e)	Signature of surveyor	:	 Date: 9/4/11



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLN 4169 E**
Make & Model : **TOYOTA PRIUS**
Chassis No : **JTDKB3FU203556663**

Submit By : **Carmen Lim**
Year Manufacture : **2017**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Front number plate <i>SLN</i>	1	\$45.00	S.N	X
2	Front number plate garnish <i>SLN</i>	1	\$129.00		X
3	Front support panel LH	1	\$213.50		?
4	Headlamp panel LH	1	\$89.20		?
5	Headlamp LH <i>C/M</i>	1	\$2,531.60		✓
6	Front bumper <i>C/M</i>	1	\$450.80		✓
7	Front bumper clip <i>SLN</i>	10	\$40.00		✓
8	Front bumper reinforcement - upper <i>SLN</i>	1	\$711.50		X
9	Front bumper reinforcement - lower <i>SLN</i>	1	\$245.30		X
10	Front bumper side retainer RH <i>SLN</i>	1	\$107.20		X
11	Front bumper side retainer LH <i>C/M</i>	1	\$107.20		✓
12	Front bumper upper grille <i>SLN</i>	1	\$321.90		X
13	Front bumper lower grille <i>SLN</i>	1	\$148.60		X
14	Front bumper emblem <i>SLN</i>	1	\$87.10		✓
15	Front bumper tow cover LH <i>SLN</i>	1	\$25.70		X
16	Front bumper sponge - upper <i>SLN</i>	1	\$89.81		X
17	Front bumper sponge - lower <i>SLN</i>	1	\$135.70		X
18	Fog lamp LH <i>SLN</i>	1	\$910.70		✓
19	LH front fender <i>SLN</i>	1	\$868.70		✓
20	LH front fender undershield <i>Di's</i>	1	\$195.60		✓
21	LH front fender undershield clip <i>SLN</i>	10	\$25.00		✓
22	LHF fender wording "HYBRID" <i>SLN</i>	1	\$44.17		✓
23	LH front fender quarter garnish <i>Di's</i>	1	\$122.70		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SLN 4169 E**

Make & Model : **TOYOTA PRIUS**

Chassis No : **JTDKB3FU203556663**

Submit By : **Carmen Lim**

Year Manufacture : **2017**

Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
24	LH front lower arm	1	\$492.65		?
25	LH front shock absorber	1	\$462.70		?
26	LH front shock absorber top mounting	1	\$195.07		?
27	LH front shock absorber stopper	1	\$37.02		?
28	LH front knuckle arm	1	\$476.75		?
29	LH front knuckle bearing	1	\$573.20		?
30	LH front wheel hub	1			
31	LH front wheel hub lock nut	1	\$28.02		X
32	LH front tie rod	1	\$1,721.85		?
33	LH front tie rod end	1	\$116.40		?
34	LH front hub cap	1	\$195.62		?
35	LH front rim	1	\$1,555.10		✓
36	Rear windscreen moulding	1	\$97.70		✓
37	Rear windscreen sealant	1	\$50.00		4012
38	Rear windscreen top garnish	1	\$655.40		✓
39	Rear windscreen top quarter garnish LH	1	\$189.60		✓
40	Rear windscreen top quarter garnish RH	1	\$189.60		✓
41	Rear number plate	1	\$45.00	S.N	✓
42	Reverse sensor	1	\$200.00	S.N	✓
43	Rear bumper	1	\$497.50		✓
44	Rear bumper clip	10	\$40.00		✓
45	Rear bumper side retainer LH	1	\$112.70		✓
46	Rear bumper side retainer RH	1	\$112.70		X

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. :

SLN 4169 E

Submit By :

Carmen Lim

Make & Model :

TOYOTA PRIUS

Year Manufacture :

2017

Chassis No. :

JTDKB3FU203556663

Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
47	Rear bumper reinforcement	1	\$398.90		✓
48	Rear bumper lower garnish centre	1	\$582.60		✓
49	Rear bumper lower garnish LH	1	\$149.70		?
50	Rear bumper lower garnish RH	1	\$149.70		X
51	Rear bumper tow cover	1	\$31.70		X
52	Rear bumper under cover	1	\$355.20		?
53	Rear bumper under cover LH	1	\$187.60		?
54	Rear bumper under cover RH	1	\$187.60		X
55	Rear bumper under cover clip	4	\$14.00		?
56	Tail door	1	\$1,122.50		✓
57	Tail door lock	1	\$487.70		✓
58	Tail door emblem	1	\$61.70		✓
59	Wording "PRIUS"	1	\$51.90		✓
60	Wording "HYBRID"	1	\$55.47		✓
61	Tail door hinge LH	1	\$87.60		✓
62	Tail door hinge RH	1	\$87.60		✓
63	Taildoor absorber LH	1	\$296.40		?
64	Taildoor absorber RH	1	\$296.40		?
65	Tail door plate garnish	1	\$782.50		✓
66	Tail door inner trim	1	\$278.90		?
67	Tail door inner trim clip	10	\$28.00		?
68	Taildoor spoiler	1	\$1,567.83		✓
69	Tail end panel	1	\$596.60		✓

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

Spare Parts

Vehicle No. : **SLN 4169 E**
 Make & Model : **TOYOTA PRIUS**
 Chassis No : **JTDKB3FU203556663**

Submit By : **Carmen Lim**
 Year Manufacture : **2017**
 Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
47	Tail end panel garnish	1	\$151.60		?
48	Tail end panel garnish clip	10	\$35.00		?
49	Boot weatherstrip	1	\$353.10		?
50	Spare tyre well panel	1	\$793.15		?
51	Spare tyre board	1	\$566.79		?
52	Spare tyre compartment sponge LH	1	\$297.67		?
53	Spare tyre compartment sponge RH	1	\$297.67		X
54	Spare tyre compartment centre	1	\$251.70		?
55	Tail lamp LH - UPPER	1	\$498.75		✓
56	Tail lamp RH - UPPER	1	\$498.75		X
57	Tail lamp LH - LOWER	1	\$511.60		✓
58	Tail lamp RH - LOWER	1	\$511.60		X
59	Taillamp clip	3	\$13.50		✓
60	Taildoor glass	1	\$598.70		✓
61	Taildoor glass sealant	1	\$50.00	S.N	✓
62	Third brake light	1	\$359.64		✓
63					
64					
65					
66					
67					
68					
69					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLN 4169 E** Submit By : **Carmen Lim**
Make & Model : **TOYOTA PRIUS** Year of Manufacture : **2017**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, LHR FENDER, LHR CHASSIC, FRONT BUMPER, LHF FENDER, SUPPORT PANEL, LHF DOOR)	\$2,600.00	1200
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL, SPARE TYRE WELL PANEL, LHR FENDER, LHR CHASSIC, FRONT BUMPER, LHF FENDER, SUPPORT PANEL, LHF DOOR)	\$2,200.00	1600
3	To check wiring & focus headlamp	\$50.00	40
4	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load.	\$150.00	100
5	To remove & refit rear windscreen.	\$120.00	✓
6	To tuff coat.	\$300.00	90
7	To transfer boot mechanism to new boot	\$120.00	60
8	To conduct water leakage tests to ensure proper air and sealing	\$120.00	30
9	Towing	\$60.00	50

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

Labour

Vehicle No. : **SLN 4169 E**

Submit By : **Carmen Lim**

Make & Model : TOYOTA PRIUS

Year of Manufacture : 2017

[illegible]

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.