

AUTOLUTION INDUSTRIAL PTE. LTD.

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/H/0184/19

DATE : 01-APR-2019

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 6846 7483

EQ INSURANCE COMPANY LIMITED
5 MAXWELL ROAD
#17-00 TOWER BLOCK
MND COMPLEX S(069110)
TEL : 62239433
FAX : 62234190
ATTN : MOTOR CLAIM MANAGER

OWNER'S NAME : TAN SIEW CHOON @ CHAN SIEW CHOON
ADDRESS : 22 BAYSHORE ROAD
#06-04 THE BAYSHORE
S(469970)
TELEPHONE NO : 81686276

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : *
VEHICLE NO : SFL67Z
MODEL CODE : FRLARBZJ11UEA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2
ENGINE NO : HRA2307174A
CHASSIS NO : SJNFEAJ11U1718821
MILEAGE : 33982 KM
DATE IN : 01/04/2019
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : HAMZAH - 96450079
ACCIDENT DATE : 31/03/2019

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorized
LKK

take photo before party,
23/4/19
H. Jy.

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SFL67Z

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOUR CHARGES TO REPAIR RH CENTRE PILLAR, RH REAR FENDER AND RENEW BOTH RH DOORS.	900.00	✓
2	ZZ/002	CHARGES TO SPRAY PAINTING SAME.	800.00	750
3	ZZ/003	REMOVE AND INSTALL BOTH RH DOORS MECHANISM.	160.00	✓
4	ZZ/004	APPLY SEALANT TO BOTH RH DOORS.	200.00	✓
5	ZZ/005	RENEW RH REAR WHEEL RIM AND WHEEL BALANCING.	15.00	?
6	ZZ/006	CHECK AND ADJUST WHEEL ALIGNMENT.	95.00	✓
TOTAL LABOUR CHARGES			2170.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SFL67Z

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			REMARKS
			NETT	LIST	S/NETT	
1	SUNDRIES	NPN			70.00	?
2	WHEEL RIM REAR RH	D0300-4EA1A			1231.90	?
3	R/R DOOR ARC MLDG	93828-4EA0A	483.00	—		
4	R/R DOOR LOWER PVC MLDG	82870-4EA0A	264.80	—		
5	R/R DOOR CHECK LINK	82430-4EA0A	39.50	?		
6	R/R DOOR LOWER HINGE	82420-4EA0A	56.10	?		
7	R/R DOOR TAPE	82818-4EA0A	29.90	—		
8	R/R DOOR TAPE	82812-4EA0A	29.90	—		
9	DOOR-REAR RH	H2100-4EAMA	1104.80	—		
10	R/F DOOR LOWER PVC MLDG	80870-4EA0A	323.60	—		
11	R/F DOOR TAPE	80812-4EA0A	29.90	—		
12	RH FRT DOOR SASH	80282-4EA1A	100.70	—		
13	DOOR-FRONT RH	H0100-4EAAA	1104.80	—		
SUB TOTAL			3567.00	0.00	1301.90	
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)			713.40	0.00	0.00	
GRAND TOTAL			2853.60	0.00	1301.90	
OVERALL TOTAL			4155.50			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SFL67Z

TOTAL LABOUR CHARGES	2170.00
TOTAL SPARE PARTS CHARGES	4155.50

GRAND TOTAL	6325.50 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE : 0.00
LIABILITY : 0.00
REMARKS :

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.