

Arabic

INS. CASE OWNER

CC 3/CT11900

6237, F2433/4

LKIC

IDAC

Surveyor

FALAN

DOI

ASSIGNMENT

8/4/19

Date / Time

8/4/19

Registered in Merimen

Pre-assign / CCU / FTE



Insured Vehicle No.

SGU 59860

Name of Insured

CHM HEE KIONG

Insured Tel No.

HP:

Excess Sec II :SS

D.O.A:

2/4/19

Is driver the owner?

(YES / NO)

Nature of Accident :

Claim No.

SWH190201589

Policy No.

OMP/CSN 3006141900

Make / Model

SURBON

Place of Accident

TAN QUEE LAM ST

If NO. Driver Name / Age :

Driver Tel No. :

(V/L: YES / NO)

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability :

%

Final ? Yes / No

SHC 68497



INSRS:

WSP:

Tel :

Liability :

RMKS:

premier



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time

4/16/2019 - 4/16/2019

EMAIL TO REQUEST FOR EVIDENCE FROM TP.

STAGE

DATE / PIC

Non-Reporting Itr (1st)

Non-Reporting Itr (2nd)

Non-Reporting Itr (Final)

Notification Itr (if non-pickup)

Call OE:

8/4/19 03:10:39

After call Itr to OE:

Documentation Check List: Handler Typist

Notification Itr (if non-pickup)

After call Itr to OE:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by: *hdc*

Repair Cost:

PIP \$5380.00

(2 days) Reduction:

TL %

Email ☒ Call ☐

FINAL SETTLEMENT

Date/Time: 06-12-19

Confirm with: *SHAFINORIN*

Email ☒ Call ☐

Final Liability:

100%

%

50

(Agreed / Assessed) BOLA S/N No. : *nil*

If NO or B 28, Ass. Lia :

Repair Cost:

4/16/19

+620.60

\$5310.30

(CONFIRMING, YES/NO)

Loss of Rental (LOR):

200.18

\$5100.39

(2 days) * +100.39

Loss of Use (LOU):

-

\$5 -

(5

3

days)

Loss of Income (LOI):

780.00

\$540.00

(5

10

3

days)

LOR only ☐

LOU only ☐

LOR + LOU ☐

LOR + LO ☒

[Tick only one]

GIA/LTA Search

+2.00

\$52.00

Medical

-

\$5 -

1) Claim status: *Normal/Reject/Private Settle*

Disbursement:

-

\$5 -

(e.g. Tow/Independent)

2) Report Format:

TP

Legal Cost

-

\$5 -

3) Survey fee:

+400

Total:

+903.38

\$5452.69

Global Sum \$5: 450

FINAL PAYMENT

Date/Time: 06-12-19

Confirm with: *SHAFINORIN*

Email ☒ Call ☐

Payee 1:

\$5450.00

Name 1:

PREMIER AUTOMOTIVE SERVICES PTE LTD

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

Surveyor: Kalvin

REF: _____

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Insp'd Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vth: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SH26849T Yr Regt: 20 Aug 2015Type: M. Car / M. Cycle / Bus / Van / Lorry / T₀ / Prime Mover /

Truck / Trailer or

Make: KIA optima cc 1885Colour: Silver A/C: Insu Q / Std / NI / NASp. Reading: 30 62x7 T/Radio: Insu Q / Std / NI / NA

Eng/No: _____

C/No: KNAHAM 414 MF5603451Gen. Cond: Good / F / Poor / BurntSteering: Inord G Jammed / Leaked / Burnt orBrake: Inord T Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A Rim orTyre Size: F: 205/65R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Adidas

Front: _____ Rear: _____

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 7/4/19 D.O.I. 8/4/19Survey held at Premier

Des. of Damages: Frl / Rear / O/S / N/S / U/C / Rooftop or

n/s Frnt

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	PP: +580 (USD: +1,919.30 71%)

Date/Time, File Pass to?

☐ : Prel. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Report Format: _____

Lump Sum / L.B.I. / \$

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

\$ + RS \$

Photos

Others

TOTAL



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

511 BLAKE L #02-25 PAVANTEL INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC3/CTI19006237/K1jb3

Date: 09.04.2019

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SHC6849T

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 08.04.2019 at the premises of M/s Premier Automotive Services Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$	2,554.30
Revised Estimate Amount	: S\$	580.00
"Check" Items Amount	: S\$	-
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
N/S Front Portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 2 days

Yours faithfully,

KALVIN ANG
Licensed Appraiser

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

8-Apr-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6849 T

1 pc	Front bumper	X repair	\$	531.00
1 pc	Front bumper emblem @ \$44.00	X "	\$	44.00
2 pcs	Front bumper n/s & o/s side retainer @ \$16.00	X sm	\$	32.00
1 pc	Front n/s wheel cover @ \$116.00	X repair	\$	116.00
1 pc	Front n/s fender @ \$384.00	X repair	\$	384.00
			\$	1,107.00
		Less 10%	\$	110.70
			\$	996.30

S/NETT

1 set	Front bumper clips	X "	\$	48.00
1 pc	Front n/s fender sticker	X "	\$	30.00

Sundry

To check front n/s wheel alignment

To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.

To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc

To putty and spray painting on front bumper, front n/s fender,

To apply rustproofing on the repaired and replaced panels.

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

By using Premier Automotive Services, I hereby
acknowledge that I have read and understand the
following terms and conditions:
• To reserve damaged parts during recovery
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be surveyed and
is subject to final approval from Insurance Company
Acknowledged by Repairer
Name: _____
Date: _____

Kalin 16/11/18

8/4/19 1705h

2 2 2

4s

Abbe Rep 2 photo

30/4/19

check prep \$580 / 2 1/2

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

8-Apr-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6849 T

1 pc	Front bumper <i>x repair</i>	\$	531.00
1 pc	Front bumper emblem @ \$44.00 <i>x</i>	\$	44.00
2 pcs	Front bumper n/s & o/s side retainer @ \$16.00 <i>x</i>	\$	32.00
1 pc	Front n/s wheel cover @ \$116.00 <i>x repair</i>	\$	116.00
1 pc	Front n/s fender @ \$384.00 <i>x repair</i>	\$	384.00
		\$	1,107.00
		Less 10%	\$ 110.70
		\$	996.30

S/NETT

1 set	Front bumper clips <i>x</i>	\$	48.00
1 pc	Front n/s fender sticker <i>x</i>	\$	30.00
Sundry		\$	50.00 <i>2.</i>
To check front n/s wheel alignment		\$	80.00 <i>x</i>
To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.		\$	180.00 <i>x</i>
To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc		\$	650.00 <i>200</i>
To putty and spray painting on front bumper, front n/s fender,		\$	400.00 <i>36</i>
To apply rustproofing on the repaired and replaced panels.		\$	120.00 <i>x</i>
		\$	2,554.30

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE ANY UNFORESEEN DAMAGES.


Ka/ia UUK

8/4/19 1705h

2 hrs

4s

After Repair photo



Text size + -

Enquire Transaction History**Transaction History Details**

Log Date/Time:	20 Aug 2015 / 07:34:48	Receipt No.:	AACCK001-AX239-150820-000012
Asset Type:	Vehicle	Transaction Amount:	\$72,061.00
Asset ID:	SHC6849T	Channel:	AA Counterless - CYCLE & CARRIAGE KIA PTE LTD
Transaction Type:	01 02 Register New Vehicle (AA)		
Business Transaction Reference No.:	20150820073448394339		
Vehicle No.:	SHC6849T		
Vehicle Type:	H10 - Public Transport Taxi (Motor Car)		
Vehicle Attachment 1:	Air-Con (Taxi)		
Vehicle Attachment 2:	-		
Vehicle Attachment 3:	-		
Vehicle Scheme:	Taxi (Company)		
First Registration Date:	20 Aug 2015		
Original Registration Date:	20 Aug 2015		
Vehicle Make:	KIA		
Vehicle Model:	OPTIMA 1.7(A) DIESEL		
Chassis No.:	KNAGM414MF5603451		
Engine No.:	D4FDEH313361		
Motor No.:	-		
Trailer Chassis No.:	-		
Propellant:	Diesel		
Passenger Capacity:	4		
Engine Capacity:	1685		
Power Rating:	-		
Unladen Weight:	1584		
Maximum Laden Weight:	2050		
Primary Color:	Silver		
Secondary Color:	-		
Manufacturing Year:	2015		
Open Market Value:	\$21,203.00		
Minimum PARF Benefit:	\$13,011.00		
PARF Eligibility:	Y		
No. of Transfer:	0		
Effective Ownership Date/Time:	20 Aug 2015 07:34:48		
COE No.:	2015082001003028G		
COE Expiry Date:	19 Aug 2023		
COE Bid Category:	-		
Actual QP/PQP Paid Amount:	\$50,236.00		
Lifespan Expiry Date:	19 Aug 2023		

Certificate of Insurance

MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) ACT (CHAPTER 189)
MOTOR VEHICLES (THIRD PARTY RISKS AND COMPENSATION) RULES, 1960
ROAD TRANSPORT ACT, 1987 (MALAYSIA)
MOTOR VEHICLES (THIRD PARTY RISKS) RULES, 1969 (MALAYSIA)

Certificate Number : 5107202885-001095

Cover : Third Party

1. Index mark and Registration Number of Vehicle : **5HC6849T**
Chassis Number : **KNAGM414MF5603451**
2. Name of Policyholder : **PREMIER TAXIS PTE. LTD.**
3. Effective Date of Insurance : **01 Feb 2019**
4. Expiry Date of Insurance : **31 Jan 2020**
5. Persons or Classes of Persons entitled to drive*
(a) The Policyholder.
(b) Any licensed taxi driver driving on the Policyholder's order or with his/her permission.
Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.
6. Limitations as to Use*
(a) Use as a Taxi.
(b) Use for social domestic and pleasure purposes.

This Policy does not cover

- (a) Use for racing, pace-making, reliability trial or speed-testing.
- (b) Use whilst drawing a trailer except the towing (Other than for reward) of any one disabled mechanically propelled vehicle.

* Limitations rendered inoperative by Section 8 of the Motor Vehicle (Third- Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS (SECTION I)	: N/A
EXCESS (SECTION II)	: S\$3,500
INSURE WITH COE	: N/A
HIRE PURCHASE COMPANY	: N/A
SUM INSURED	: N/A

I/We hereby Certify that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia)

Agency : **HL SUNTEK INSURANCE BROKERS PTE LTD (00000690672)**

Date of Issue : **01 Feb 2019 09:37 hrs**

For NTUC INCOME INSURANCE CO-OPERATIVE LIMITED

Countersigned By:



Authorised Officer



Chief Executive



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC3/CTI19006237/K1eb3q2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 02-01-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGU 5986D	Veh. Inspected	SHC 6849T
Policy No.	DMPCSN3006141900	Coverage (\$)	0.00
Claim No.	SNM19D201589	Excess (\$)	0.00
Assign From		Assign Date	08/04/2019

2. Vehicle Particulars & Condition

Make & Model	KIA OPTIMA	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	KNAGM414MF5603451	Colour	SILVER
Odometer	306247	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/65 R16	ACHILLES	6 mm
L/H Front Tyre	205/65 R16	ACHILLES	6 mm
R/H Rear Tyre	205/65 R16	ACHILLES	6 mm
L/H Rear Tyre	205/65 R16	ACHILLES	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	07/04/2019	Inspection Date	08/04/2019
Survey held at	PREMIER AUTOMOTIVE SERVICES PTE LTD 23 CHANGI SOUTH AVENUE 2 #01-02 SINGAPORE 486443		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	2 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 6849T

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT BUMPER	TO REPAIR SEE LABOUR	531.00	-
1	FRONT BUMPER EMBLEM	NOT NECESSARY	44.00	-
2	FRONT BUMPER N/S & O/S SIDE RETAINER @\$16.00	SERVICEABLE	32.00	-
1	FRONT N/S WHEEL COVER	TO REPAIR SEE LABOUR	116.00	-
1	FRONT N/S FENDER	TO REPAIR SEE LABOUR	384.00	-
	LESS 10% DISCOUNT		-110.70	-
			996.30	-
SPECIAL NETT ITEMS				
1	SET FRONT BUMPER CLIPS (SN)	NOT NECESSARY	48.00	-
1	FRONT N/S FENDER STICKER (SN)	NOT NECESSARY	30.00	-
1	SUNDRY (SN)	NECESSARY	50.00	20.00
			128.00	20.00
LABOUR				
	TO CHECK FRONT N/S WHEEL ALIGNMENT.	NOT NECESSARY	80.00	-
	TO DISMANTLE /REFIT THE INNER GARNISHES ,INNER LININGS ,INNER TRIMS ,CUSHION SEAT, CARPET ,ETC TO FACILITATE REPAIRS.	NOT NECESSARY	180.00	-
	TO LABOUR CHARGE FOR DISMANTLE AND RENEW THE ACCIDENT DAMAGED PARTS.INCLUDING KNOCK - OUT ,STRAIGHTEN ,REPAIR,RESHAPE AND ADJUST OF THE SAME ,ETC.INCLUSIVE OF THE REPAIR OF FRONT N/S WHEEL COVER ,FRONT BUMPER AND FRONT N/S FENDER .		650.00	200.00
	TO PUTTY AND SPRAY PAINTING ON FRONT BUMPER ,FRONT N/S FENDER .		400.00	360.00
	TO APPLY RUSTPROOFING ON THE REPAIRED AND REPLACED PANELS.	NOT NECESSARY	120.00	-
			1,430.00	560.00
GRAND TOTAL			2,554.30	580.00
RECOMMENDED COST OF REPAIRS				580.00

Report Ref No. CC3/CTI19006237/K1eb3q2



Report Ref No. CC3/CTI19006237/K1eb3q2

A handwritten signature in black ink, appearing to be 'Calvin'.

KALVIN ANG WEI KUN

Automotive Assessor / Investigator

A handwritten signature in black ink, appearing to be 'Ho Leong Chuan'.

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.