

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 CHANGI SOUTH AVENUE 2 #01-02
SINGAPORE 486443

TEL: 65446676 / 65446689 FAX: 62141511
CO. REG:200707743D GST REG:200707743D

8-Apr-19

ESTIMATE REPAIR BILL FOR KIA OPTIMA REGN NO: SHC 6849 T

1 pc	Front bumper <i>X repair</i>	\$	531.00
1 pc	Front bumper emblem @ \$44.00 <i>X</i>	\$	44.00
2 pcs	Front bumper n/s & o/s side retainer @ \$16.00 <i>X</i>	\$	32.00
1 pc	Front n/s wheel cover @ \$116.00 <i>X repair</i>	\$	116.00
1 pc	Front n/s fender @ \$384.00 <i>X repair</i>	\$	384.00
		\$	1,107.00
	Less 10%	\$	110.70
		\$	996.30

S/NETT

1 set	Front bumper clips <i>X</i>	\$	48.00
1 pc	Front n/s fender sticker <i>X</i>	\$	30.00
	Sundry	\$	50.00 <i>2</i>
	To check front n/s wheel alignment	\$	80.00 <i>X</i>
	To dismantle / refit the inner garnishes, inner linings, inner trims, cushion seat, carpet, etc to facilitate repairs.	\$	180.00 <i>X</i>
	To labour charge for dismantle and renew the accident damaged parts. Including knock-out, straighten, repair, reshape and adjust of the same, etc	\$	650.00 <i>200</i>
	To putty and spray painting on front bumper, front n/s fender,	\$	400.00 <i>36</i>
	To apply rustproofing on the repaired and replaced panels.	\$	120.00 <i>X</i>
		\$	2,554.30

(ALL THE REPAIR COSTS ARE SUBJECTED TO GST)

THE ABOVE ESTIMATED COST OF REPAIR DO NOT INCLUDE
ANY UNFORESEEN DAMAGES.

Ka/ua UUA

✓

8/4/19 1705h

2 Rys

4s

Alle Repz photo

KYK Auto Consultants have notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____