

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 8487R

MAKE :

MODEL : HYUNDAI i40

DATE 8/4/2019 10:49

CHINA

LICK / Ju

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover ✓			\$ 544.50
	Front Bumper Bracket Top (LH) ?			\$ 22.40
	Front Bumper Bracket (LH) ?			\$ 24.60
	Headlamp (LH) ✓			\$ 1,388.00
	Front Fender (LH) ✓			\$ 566.30
	Front Fender Shield (LH) ?			\$ 175.90
	Front Fender Retainer ?			\$ 24.60
	Frt Wheel Hub Cap, LH ✓			\$ 107.10
	SUB TOTAL			\$ 2,853.40
	LESS 20%			\$ 570.68
	DISCOUNTED TOTAL			\$ 2,282.72
	Labour Charge			300
	Panel Beating			\$ 400.00
	Spray Painting Charge			\$ 600.00 400
	Wiring			\$ 50.00 20
	Tuff Kote			\$ 50.00 20
	Frt Wheel Alignment			\$ 80.00 X
	TOTAL LABOUR			\$ 1,180.00
	ESTIMATE TOTAL			\$ 3,462.72

Kalin 11/11/19

N 8/4/19 1320 hr

3075

4/5

After Repair photo

Insurance notify
 • To notify insurance company
 • Parts must be replaced with original or equivalent parts
 • This is a survey report only, it is not a "Prejudice" basis
 • No illegal modifications are allowed
 • Supplementary items must be surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.