

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

071/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

SLK 69167

Yr Regn:

1, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

CA

Make:

Nissan Qashqai

c.c 1197

Colour:

Brown

A/C:

Insured / Std / NI / NA

Sp. Reading:

245-35-

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

SJNFEAJ1141720846

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

215/60 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

9/4/19

D.O.I.

9/4/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

24/4/19 have G.A
L/S 4900 confirmed work after.

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair:

1)

☐

Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time, File Return to?

Transportation:

FASTECH AUTO PTE LTD
1 KAKI BUKIT AVENUE 6
#01-46/48/50
SINGAPORE 417883

VEHICLE NO: SLK 6916T

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts price is subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary work(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Not Authorized
dla
2/5 \$ 4900
4/2
9/4/19

QTY	PARTICULAR
1 PCS	REAR WINDSCREEN W/MOULDING
2 PCS	REAR WINDSCREEN INNER SIDE GARNISH @\$165.00
1 PCS	TAILGATE
1 PCS	TAILGATE OUTER GARNISH
1 PCS	TAILGATE REAR LOGO
1 PCS	TAILGATE 'ASHWA' EMBLEM
2 PCS	TAILGATE REFLECTORS @\$650.00
1 PCS	TAILGATE REAR WIPER ARM
1 PCS	TAILGATE REAR WIPER MOTOR
1 PCS	TAILGATE INNER LOCK
1 PCS	TAILGATE INNER TRIM BOARD
1 SET	TAILGATE INNER TRIM BOARD CLIPS
1 PCS	TAILGATE WEATHERSTRIP
1 PCS	TAILGATE REVERSE CAMERA
2 PCS	TAILGATE LICENCE PLATE LAMPS @\$53.00
1 PCS	REAR BUMPER 717.00
1 PCS	REAR BUMPER TOW COVER
2 PCS	REAR BUMPER REFLECTORS @\$68.00
2 PCS	REAR BUMPER SIDE RETAINERS @\$35.00
1 SET	REAR BUMPER CLIPS
1 PCS	REAR BUMPER SPONGE 126.40
1 PCS	REAR BUMPER REINFORCEMENT 619.20
2 PCS	REAR BUMPER REINFORCEMENT BRACKETS @\$150.00
1 PCS	REAR END PANEL 482.60
1 PCS	REAR SUPPORT PANEL TOP GARNISH 315.30
1 PCS	REAR FLOOR PANEL
1 PCS	REAR FLOOR PANEL TOP BOARD
2 PCS	REAR FLOOR PANEL TOOLS SPONGES @\$305.00
1 PCS	REAR END PANEL LOCK SENSOR
1 PCS	REAR FLOOR PANEL TOP BOARD SPONGE
1 PCS	REAR EXHAUST
2 PCS	REAR EXHAUST MOUNTINGS @\$60.00
2 PCS	TAILLAMPS @\$580.00 323.70x2=647.40
2 PCS	REAR FENDERS @\$1150.00 10%
2 PCS	REAR FENDER OUTER PROTECTORS @\$541.00 541x2=1082

11	\$1,855.30	X
11	\$330.00	X
11	\$3,066.20	X
11	\$450.00	X
11	\$38.50	X
11	\$78.50	X
11	\$1,300.00	X
11	\$166.00	X
11	\$966.00	X
11	\$292.00	X
11	\$595.30	X
11	\$30.00	X
11	\$166.20	X
11	\$485.00	X
11	\$106.00	X
11	\$891.00	X
11	\$22.00	X
11	\$136.00	X
11	\$70.00	X
11	\$35.00	X
11	\$185.00	X
11	\$721.00	X
11	\$300.00	X
11	\$720.00	X
11	\$408.00	X
11	\$1,288.00	X
11	\$622.00	X
11	\$610.00	X
11	\$265.00	X
11	\$495.00	X
11	\$1,122.30	X
11	\$120.00	X
11	\$1,160.00	X
11	\$2,300.00	X
11	\$1,082.00	X
	\$22,477.30	

	S.NETT
1 PCS	REAR LICENCE PLATE W/HOLDER
1 PCS	REAR WINDSCREEN SEALANT

11	\$50.00	X
11	\$50.00	X

1 SET
1 PCS
1 SET

REAR BUMPER REVERSE SENSOR
REAR END PANEL SEALANT
REAR FLOOR PANEL INSULATOR

should
21
17

\$280.00 203
\$50.00 ✓
\$50.00 X

LABOUR CHARGES:

TO CHECK WIRING

\$80.00 30

TO DISMANTLE & REPLACING REVERSE SENSOR

\$80.00 50

TO DISMANTLE & REPLACING REAR WINDSCREEN

17 \$150.00 X

TO DISMANTLE & REFIX REAR EXHAUST

\$150.00 80

TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTREY

\$100.00 80

TO SPRAY RUSF PROOFING

\$120.00 50

TO MOUNT VEHICLE ON CAR O-LINER

17 \$380.00 X

LABOUR FOR PANEL BEATING & REPLACING PARTS

\$1,500.00 80

TO PUTTY & SPRAY PAINTING

\$1,500.00 95

TOTAL

\$27,017.30

613264