

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 1359J

CHINA

DATE 8/4/2019 11:04

MAKE :

LKK

F2

MODEL : HYUNDAI IONIQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid — But			\$ 2,489.40
	Boot Lid Lock Upper x su			\$ 224.00
	Boot Lid 'H' Emblem x su			\$ 28.00
	Emblem -Hybrid — su			\$ 24.30
	Emblem -Ioniq — su			\$ 31.30
	Emblem -Blue Drive (LH/RH) x su		\$ 26.60	\$ 53.20
	Boot Lid Glass, Upper x su			\$ 543.30
	Boot Lid Glass, Lower x su			\$ 384.90
	Rear Spoiler x repair			\$ 665.40
	Boot Lid Lamp (LH) — su			\$ 794.40
	Bootlid Garnish x su			\$ 36.10
	Bootlid Lower Garnish x su			\$ 25.40
	Rear Bumper — But			\$ 459.40
	Rear Bumper Reinforcement — But			\$ 294.80
	Rear Bumper Reinforcement Bracket (LH/RH) x su		\$ 138.10	\$ 276.20
	Rear Bumper Centre Moulding Assy — su			\$ 451.25
	Rear Bumper Lower Centre Moulding Assy x su			\$ 47.50
	Rear Bumper Cover Clips — su			\$ 22.00
	Tail Lamp (LH) x su			\$ 870.40
	Rear Panel x repair			\$ 532.00
	Rear Panel Garnish x su			\$ 155.00
	Rear Panel Lower Panel x repair		\$ 39.40	\$ 78.80
	SUB TOTAL			\$ 8,478.05
	LESS 20%			\$ 1,695.61
	DISCOUNTED TOTAL			\$ 6,782.44
	Boot Lid Comfort Logo Sticker — su			\$ 30.00
	Rear No.Plates — su			\$ 25.00
				\$ 55.00
	Labour Charge			\$ 800.00
	Panel Beating			\$ 900.00
	Spray Painting Charge			\$ 50.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 120.00
	Remove/Refix Reverse Sensor			
	TOTAL LABOUR			\$ 1,920.00
	ESTIMATE TOTAL			\$ 8,757.44

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Auto Com- parts hence notify
the Repairer of the following:
• To resurvey before spray painting
• To display damaged part(s) during resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: [Signature]
Date: 8/4/19

Ka lon 16/11/19
8/4/19
3 Bay
P/P
Buton Paint p/h

Nett -
Nett -

600
20
20
30

VEHICLE NO. : SHA1359J

JOB CARD NO. 305285103

ACC.DATE 06/04/19

SURVEY BY : KALVIN

DATE : _____

SUPPLEMENTARY OF PARTS AND LABOUR COSTS			
DESCRIPTION	QTY	ESTIMATE	REMARKS
ANTENNA ASSY-SMARTK	1	\$40.50	LIST ✓ ne
UNIT ASSY – BSD LH	1	\$1,487.00	LIST ✓ slhl
GLASS SEALANT	2	\$46.00	NET ✓ ne
REAR BUNMPER MAT	1	\$50.00	NET ✓ ne
REVERSE SENSOR	1	\$135.70	NET ✓ slhl
REAR FOG LAMP ASSY	1	\$201.50	LIST ✓ ne
CHECK ITEMS			
BOOTLID GLASS – LOWER	1	\$384.90	LIST
TOTAL:		\$2,345.60	JUMANI

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

Our Job Ref No 305285103
Date : 17/04/2019

FINALIZATION FORM

To : LKK
Attn : KALVIN
: SHA1359J

Fax :

Date of Accident : 06/04/19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: CHINA -- XD3414P
###
2. The finalized amount shall be:

(a) Spare Parts after List discount		\$5,631.30
(b) Labour Charges	###	\$1,270.00
Total for Part-By-Part Repair Cost		\$6,901.30
- (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost

3. Estimated normal period for repairs: 3 working days

4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature :
Name : JUMANI
Tel : 6214 8315
Fax : 65468156

Signature :
Name : Kalvin
Date : 18/4/19

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	\$7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks: