

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 1359J

DATE 8/4/2019 11:04

MAKE :

MODEL : HYUNDAI IONIQ

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid			\$ 2,480.40
	Boot Lid Lock Upper X			\$ 224.00
	Boot Lid 'H' Emblem			\$ 28.00
	Emblem -Hybrid			\$ 24.30
	Emblem -Ioniq			\$ 31.30
	Emblem -Blue Drive (LH/RH) X		\$ 26.60	\$ 53.20
	Boot Lid Glass, Upper X			\$ 543.30
	Boot Lid Glass, Lower X			\$ 384.90
	Rear Spoiler X rpr			\$ 665.40
	Boot Lid Lamp (LH)			\$ 794.40
	Bootlid Garnish X			\$ 36.10
	Bootlid Lower Garnish X			\$ 25.40
	Rear Bumper			\$ 459.40
	Rear Bumper Reinforcement			\$ 294.80
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 138.10	\$ 276.20
	Rear Bumper Centre Moulding Assy			\$ 451.25
	Rear Bumper Lower Centre Moulding Assy ?			\$ 47.50
	Rear Bumper Cover Clips			\$ 22.00
	Tail Lamp (LH) X			\$ 870.40
	Rear Panel X rpr			\$ 532.00
	Rear Panel Garnish ?			\$ 155.00
	Rear Panel Lower Panel X rpr		\$ 39.40	\$ 78.80
	SUB TOTAL			\$ 8,478.05
	LESS 20%			\$ 1,695.61
	DISCOUNTED TOTAL			\$ 6,782.44
	Boot Lid Comfort Logo Sticker			\$ 30.00
	Rear No.Plake			\$ 25.00
				Nett
				Nett
				\$ 55.00
	Labour Charge			600
	Panel Beating			\$ 800.00
	Spray Painting Charge			\$ 900.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Remove/Refix Reverse Sensor			\$ 120.00
	TOTAL LABOUR			\$ 1,920.00
	ESTIMATE TOTAL			\$ 8,757.44

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.