

INS. CASE OWNER:

PH

CC 4, Asm 1900

6242, Ugas

LAA:

IDAC:

109416

Surveyor:

C/S

DOI:

ASSIGNMENT

9/4/2019

Date / Time:

9/4/2019

Registered in Merimen:

Pre-assign / CCU / FTE

SEA 8998H



Insured Vehicle No.:

Claim No.:

S9M01JGX

Name of Insured:

THAM BOON HEE Jimmy

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A:

6/4/2019

Place of Accident:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SKH1802Z



INSRS:

WSP:

Tel:

Liability:

RMKS:

Les Bo.



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

18/4

Joy

SKH1802Z - C/L 6/6/1 (30/4/2019) / 10/4/2019: 007: 6/10/19

SEA 8998H - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List:

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

TO verify claim

Rejection email send to both on App.

TP disagree rejection. seek AXA instruction.

Hale on App, both parties has the intention

to change of lane. Thus, 50/50 settlement

under BOLA 19. Email TP to notify.

Email LOI (50/50).

TP reject 50/50. seek AXA instruct.

AXA approve 100% settlement.

Rel work to TP (pending LOD)

TO seek mandate.

Pending mandate approval (approved).

offer \$8126.45 (pending acceptance)

offer \$8126.45, file pass su to send DV.

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS 7800.00

(4 days) Reduction: \$892.29 % 55

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email:

Call:

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

Repair Cost:

SS 7400.00

Loss of Rental (LOR):

SS 600.00

(6 days) x \$100

Loss of Use (LOU):

SS

-

(\$ x days)

Loss of Income (LOI):

SS

-

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

SS

Medical:

SS

Disbursement:

SS

Legal Cost

SS

Total:

SS 8126.45

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email:

Call:

Payee 1:

SS 8126.45

Name 1:

LEE BROTHERS AUTOMOTIVE PTE LTD

Payee 2 (Strike if N.A.)

SS

Name 2:

Payee 3 (Strike if N.A.)

SS

Name 3:

COPY SENT

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP

3) Survey fee: \$350

X GIA

LEE BROTHERS AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47
 AUTOBAY SINGAPORE 417883
 Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

AXA INSURANCE SINGAPORE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811
SFQ8998H

ESTIMATE

DATE : 08.04.2019
 VEHICLE NO : SKH1802Z
 MAKE/MODEL : TOYOTA ALTIS
 ACC DATE : 06.04.2019

PARTICULAR

QTY	UNIT PRICE	AMOUNT
	SS	SS
NETT ITEMS		
1 1 FRONT HEADLAMP LH <i>Scr</i>	1,790.40	1,790.40 ✓
2 1 FRONT BUMPER <i>Dis</i>	528.34	528.34 ✓
3 1 FRONT BUMPER FOG LAMP LH <i>11 X</i>	329.10	329.10 X
4 1 FRONT BUMPER FOG LAMP COVER LH <i>gnd</i>	124.10	124.10 ✓
5 1 FRONT BUMPER REINFORCEMENT <i>11 X</i>	399.45	399.45 X
6 2 FRONT BUMPER BRACKET RH/LH <i>11 X</i>	124.10	248.20 X
7 1 FRONT BUMPER TOP RUBBER <i>ren</i>	125.60	125.60 ✓
8 1 FRONT BUMPER EMBLEM LOGO <i>ren</i>	65.30	65.30 ✓
9 2 FRONT BUMPER SIDE RETAINER RH/LH <i>abs 1/2 c</i>	112.35	224.70 1/2 c
10 1 FRONT FENDER LH <i>5-100</i>	617.30	617.30 ✓
11 1 FRONT FENDER COWLING LH <i>Torn</i>	169.30	169.30 ✓
12 2 FRONT SHOCK ABSORBER RH/LH <i>Ren/ren</i>	490.15	980.30 ✓
13 2 FRONT SHOCK ABSORBER MOULDING RH/LH <i>TDI X</i>	210.15	420.30 X
14 2 FRONT LOWER ARM RH/LH <i>Ren/crc</i>	602.10	1,204.20 ✓
15 2 FRONT LOWER ARM BALL JOINT RH/LH <i>TDI X</i>	203.10	406.20 X
16 2 FRONT KNUCKLE ARM RH/LH <i>Ren</i>	478.10	956.20 ✓
17 2 FRONT KNUCKLE BEARING <i>ren</i>	210.10	420.20 ✓
18 2 FRONT STABILIZER BAR LINK RH/LH <i>Ren</i>	195.00	390.00 ✓
19 2 FRONT DRIVE SHAFT RH/LH <i>11 X</i>	1,716.70	3,433.40
		12,832.59
	LESS 25% <i>502?</i>	3,208.15
	<i>2-10294.06</i>	9,624.44

SPECIAL NETT ITEMS

1 1 (SET) FRONT BUMPER CLIP <i>ren</i>	45.00	45.00 ✓
2 1 (SET) FRONT FENDER COWLING CLIP <i>ren</i>	35.00	35.00 ✓
3 2 FRONT SPORT RIM <i>enr/24 6005.0</i>	580.00	1,160.00 600
4 2 FRONT TYRE <i>Scr X</i>	280.00	560.00 X
		1,800.00

Q15, 552-29

LEE BROTHERS AUTOMOTIVE PTE. LTD.

PARTICULAR		UNIT PRICE	AMOUNT
QTY		SS	SS
LABOUR CHARGES :			
1	TO KNOCK OUT DENT AND REPLACE ACCIDENT PARTS	400	600.00
2	TO SPRAY PAINTING ON ACCIDENT PORTION	400	600.00
3	TO CHECK WIRING	20	30.00
4	TO REMOVE AND REPLACE UNDERCARRIAGE PARTS	300	580.00
5	TO 4 WHEEL ALIGNMENT	✓	120.00
6	TO TUFF KOTE	30	90.00
			2,020.00

1270

ESTIMATE PARTS AND LABOUR GRAND TOTAL : \$ 13,444.44

P - 5147.03
S.N - 680
labour 1270

7097



LEE BROTHERS AUTOMOTIVE PTE. LTD.

NO 1 KAKI BUKIT AVE 6 #02-47
AUTOBAY SINGAPORE 417883
Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

AXA INSURANCE SINGAPORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
SFQ8998H

ESTIMATE

DATE : 9.4.2019
VEHICLE NO : SKH1802Z
MAKE/MODEL : TOYOTA ALTIS
ACC DATE : 06.04.2019

PARTICULAR		UNIT PRICE	AMOUNT
QTY		SS	SS
SUPPLEMENTARY			
1	1 FRONT CROSS MEMBER	1,207.23	1,207.23
2	1 FRONT STEERING RACK	1,603.24	1,603.24
			2,810.47
		LESS 25% (V)	702.62
			2,107.85

Lee Brothers Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Singapore NRIC
Owner ID:	4444E

Vehicle Details

Vehicle No.:	SKH1802Z
Vehicle to be Exported:	No
Intended Deregistration Date:	09 Apr 2019
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Silver
Manufacturing Year:	2012
Engine No.:	1ZRX234641
Chassis No.:	MR053REE104151378
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$14,944.00
Original Registration Date:	12 Nov 2012
First Registration Date:	12 Nov 2012
Transfer Count:	0
Actual ARF Paid:	\$14,944.00 7472

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Nov 2022
PARF Rebate Amount:	\$9,713.00

Intended COE Rebate Details

COE Expiry Date:	11 Nov 2022
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$71,001.00
COE Rebate Amount:	\$25,481.00
Total Rebate Amount:	\$35,194.00

The information contained herein is correct as at 09 Apr 2019

OK

sgCARMART.COM

Login

Sign up

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Articles

Forum

Resources

IS YOUR CAR DUE FOR SCRAP OR EXPORT?

Use Our **FREE** Service To Get The Best Selling Price!



sgCARMART

QUOTZ

Helping You Sell Your Car

toyota corolla altis

Price Range

Depreciation

2012

Vehicle Type

Submit

Advanced Search

Home > Used Cars > 007 > Toyota Corolla Altis 1.6A

Toyota Corolla Altis 1.6A

- Overview
- Financial
- Insurance
- Accessories
- Similar
- Research
- Photos
- Map

Price	\$39,998		
Depreciation	\$9,450 /yr View models with similar depre	Reg Date	19-Sep-2012 (3yrs 5mths 9days COE left)
Mileage	125,000 km (19.1k /yr)	Manufactured	2012
Road Tax	\$742 /yr	Transmission	Auto
Dereg Value	\$32,729 as of today (change)	OMV	\$14,885
COE	\$66,889	ARF	\$14,885
Engine Cap	1,598 cc	Power	90.0 kW (120 bhp)
Curb Weight	1,195 kg	No. of Owners	4
Type of Vehicle	Mid-Sized Sedan		

Features

Powered By Toyota's 1.6L 4 Cylinders Inline 16 Valves DOHC VVT-I Engine Producing 120BHP Coupled With A 4 Speed Automatic Transmission. View specs of the Toyota Corolla Altis (2008-2013)

Accessories

Leather Seats, Built In Audio System, Steering Control, Retractable Side Mirrors With Light Indicators, Reverse Sensors, Eco Mode.

Description

Be Our Next Happy Client To Owned This Quality Pre-Owned Vehicle At Most Reasonable And Affordable Price! Very Well Kept Interior & Exterior! No Knocking Sounds From Undercarriage! Low Fuel Consumption! Flexible Bank/In House Loan Up To 100%! Call Our Professional And Friendly Staffs For A No Obligations Discussion. Reasonable Offer Will Be Considered.

Category

P&RF Car

Status

Available

Resources



Vehicle Evaluation
Afraid of lemons? Request to have this car evaluated professionally. Find out more



Car Valuation - Free
Find out the market value of your existing car for free. Get started



Price Chart

Click on the point to view the vehicle

- Shortlist
- Compare
- Add note
- Report Error
- More Actions

Seller Information

Company	007 • dealer's pricelist • 18 vels sold 27 vels available
Address	421 Tagore Industrial Avenue #02-09

Nivitha (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Tuesday, 9 April 2019 10:15 AM
To: assignments
Subject: FW: Accident involving SKH1802Z and SFQ8998H along Tampines Ave 10 towards Pasir Ris on 06.04.2019

Hi team

TP smart. Kindly assist.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

10-ASAM@9/4/19
person@Jason
vehicle In

From: Jason <karen@leebrothers.com.sg>
Sent: Monday, 8 April, 2019 5:44 PM
To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>
Subject: Accident involving SKH1802Z and SFQ8998H along Tampines Ave 10 towards Pasir Ris on 06.04.2019

Dear Sirs / Ma'am,

Kindly arrange PRI for our vehicle SKH1802Z.

Thanks & Best Regards

Adeine Seng
Lee Brothers Automotive Pte Ltd
1 Kaki Bukit Ave 6
#02-47 Autobay
Singapore 417883
Tel: 6509 5521
Fax: 6509 5523



TP's claim.

Type

🔔 Question

Message

Pls reject TP's claim & upload your tax invoice for the services rendered. TY.

Reply

Cecilia Chong (LKK Auto)

From: Cecilia Chong (LKK Auto)
Sent: Tuesday, 3 September 2019 11:28 AM
To: karen@leebrothers.com.sg
Subject: RE: Accident involving SKH1802Z and SFQ8998H along Tampines Ave 10 towards Pasir Ris on 06.04.2019 *** LKK REF: CC4/ASM19006242/Uga3
Attachments: ACCIDENT SCENE.jpg

Your Ref: **SKH 1802Z** Without Prejudice
Our Ref: CC4/ASM19006242/Uga3

Dear Sirs/Madam,

ACCIDENT INVOLVING SKH1802Z and SFQ8998H ON 06.04.2019

We refer to the above matter.

Attached is a copy of the accident scene photo submitted. We have reviewed the matter and we are of the view that our driver is not liable for the accident. Base on the photo, it can be seen that your client has the intention to change into Our Insured's lane thus leads to the collision.

In view of the above, we have our principal instruction to deny liability and unable to look into your client's matter.

Thank you.

"Please note that our proposal and correspondence with you is strictly on a without prejudice basis and should not be construed as an admission of liability on our part and/or that of our policyholder and/or the authorised driver. The terms of our without prejudice engagement should not be disclosed in any other related matter(s) in respect of this accident nor should it be binding in any other related claims."

Best Regards,

Cecilia Chong | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6749-4274 | email: CeciliaChong@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Mei Kwan (LKKAuto)
Sent: Tuesday, 9 April 2019 3:57 PM
To: Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>
Cc: CS A Team <cs-a@lkkauto.com>
Subject: FW: Accident involving SKH1802Z and SFQ8998H along Tampines Ave 10 towards Pasir Ris on 06.04.2019 ***
LKK REF: CC4/ASM19006242/Uja3

Hi

Fyip.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jason <karen@leebrothers.com.sg>

Sent: Tuesday, 9 April, 2019 3:42 PM

To: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>

Subject: RE: Accident involving SKH1802Z and SFQ8998H along Tampines Ave 10 towards Pasir Ris on 06.04.2019 ***

LKK REF: CC4/ASM19006242/Uja3

Dear Mei Kwan,

The photo as attached for you to look into the matter. What happen was your Insured had cut into our lane and my client hit onto the side of the kerb which case the undercarriage damage and lost control of his vehicle as such his vehicle is facing to change lane. Base on the photo, my client also in his lane and your insured vehicle was behind. I believe your insured also mention that he had a video of the accident to my client. You may want to check with them regarding the video too.

Thanks & Best Regards

Jason Lee

Lee Brothers Automotive Pte Ltd

1 Kaki Bukit Ave 6

#02-47 Autobay

Singapore 417883

Tel: 6509 5521

Fax: 6509 5523

From: Mei Kwan (LKKAuto) [<mailto:Meikwan@lkkauto.com>]

Sent: Tuesday, 9 April, 2019 3:00 PM

To: Jason <karen@leebrothers.com.sg>

Cc: Joy Irene (LKKAuto) <JoyIrene@lkkauto.com>; CS A Team <cs-a@lkkauto.com>; Admin A <admin-a@lkkauto.com>

Subject: RE: Accident involving SKH1802Z and SFQ8998H along Tampines Ave 10 towards Pasir Ris on 06.04.2019 ***

LKK REF: CC4/ASM19006242/Uja3

'WITHOUT PREJUDICE'

SAVE AS TO COSTS


Dear Sir / Madam,

We refer to the above matter.

Please be informed that we are currently **pending verification for direct settlement.**

Fyi, OI has reported. Please refer to the below OI's sketch plan and statement.

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Was travelling along Tampines Avenue 10 Towards TPE in the middle lane, a Toyota want to swerve to my lane resulting in head to head collision, my front tender and door was hit.

Meanwhile, please provide us :-

- evidence i.e. video and scene photo.
- estimated cost of repair

Please note that for liability, claim negotiation and settlement, please contact **Joy at 6841 2409**

Our respective case handler will look into the matter and revert to you in due course.

To check availability of the case handler, you may contact the undersigned.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Jason <karen@leebrothers.com.sg>

Sent: Monday, 8 April, 2019 5:44 PM

To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>

Subject: Accident involving SKH1802Z and SFQ8998H along Tampines Ave 10 towards Pasir Ris on 06.04.2019

Dear Sirs / Ma'am,

Kindly arrange PRI for our vehicle SKH1802Z.

Thanks & Best Regards

Adeine Seng

Lee Brothers Automotive Pte Ltd

1 Kaki Bukit Ave 6

#02-47 Autobay
Singapore 417883
Tel: 6509 5521
Fax: 6509 5523



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 1/11/2019

Survey Details:

Date of loss	6-Apr-19
Date of appointment	9-Apr-19
Date of survey	9-Apr-19
Location of survey	LEE BROTHERS AUTOMOTIVE PTE LTD

Vehicle Details:

Claim Type:	THIRD PARTY CLAIM
Vehicle number	SKH 1802Z
Make and Model	TOYOTA COROLLA ALTIS 1.6 (A)
Date of registration	12-Nov-12
Parf Rebate	
Market Value	\$ 42,500.00
Parf Rebate	\$ 35,194.00
Nett Loss	\$ 7,306.00

Repair details:

Initial Estimate	\$ 15,552.29
------------------	--------------

Proposed/Revised repair cost:

Parts	\$ 5,827.03
Check items (estimate)	\$ -
Labour	\$ 1,270.00
Total	\$ 7,097.03
Lump Sum(if applicable)	\$ 7,000.00

Number of days for repair	4
---------------------------	---



Auto
Consultants
Pte Ltd

Company Registration No: 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

04 RECOMMENDED REPAIR DAYS + 1PRS + 1SUNDAY = 6DAYS

Mandate:

Liability(TP)	100%	
Proposed repair cost	\$ 7,490.00	W/GST
Loss of use	\$ -	
Loss of rental	\$ 600.00	6days x \$100
Loss of income	\$ -	
LTA search fees	\$ 36.45	
Others	-	
Proposed Total	8126.45	



<MANDATE IA> - S9M01JGX {ACCIDENT INVOLVING SFQ 8998H (OI) & SKH 1802Z ON 06/04/2019}

Type

🔔 Question

Message

LIABILITY: 100% BOLA S15 - INFORMED OI ABOUT TP CLAIM AND NCD ISSUE. AGREED TO SETTLE AT BEST. WE SEEK YOUR MANDATE AT \$8,126.45 (CLAIMING LOR). MANDATE IA HAS BEEN UPLOADED IN SMARTCLAIM. KINDLY LET US HAVE YOUR APPROVAL/INSTRUCTION. THANKS - CCL

Reply

LEE BROTHERS AUTOMOTIVE PTE.LTD

NO. 1 KAKI BUKIT AVE 6 #02-47 AUTOBAY

SINGAPORE 417883

TEL: 6509 5521 FAX: 6509 5523 GST Reg. No. : 201101880C

ATTN:THE MOTOR CLAIMS DEPARTMENT

AXA INSURANCE SINGAPORE PTE LTD

8 SHENTON WAY

#27-01 AXA TOWER

SINGAPORE 068811

Yrs Ref. : SFQ8998H

Our Ref. : LB0419-2610

Date: : 04.06.2019

Accident involving SKH1802Z and SFQ8998H on 06.04.2019 at 1705hrs along Tampines Ave 10 towards Pasir Ris

We refer to the above matter. We are instructed that above accident was caused solely and completely by the negligence of your insured, as a result of which, our client have suffered loss and expenses.

We are instructed by our client to make a property damages claims as:-

	<u>Amount</u>
1. Cost of repair (Inc GST)	S\$ 7,490.00
2. Loss of Rental (6Days @ S\$120 PerDay)	S\$ 720.00
3. Towing	S\$ -
5. LTA Search fee	S\$ 7.45
4. E-File Search fee	S\$ 29.00
Claim Amount	<u>S\$ 8,246.45</u>

Enclosed are the following documents for your perusal.

☒ Original Final repair Bill	☒ Letter of Authority
☐ Original Survey Report & Invoice	☒ Rental Agreement /Receipt
☐ Original Photographs of [SKH1802Z]	☒ E-File Search Fee/LTA Receipt
☒ GIAS Reports of [SKH1802Z]	☒ Vehicle Registration Card
☒ Certificate of Insurance	☒ Driver's Driving License / Identity Card
☐ Report Of A Traffic Accident	

Your prompt action will be greatly appreciated.

Kindly acknowledge receipt of the above said documents and your favourable reply is greatly appreciated.

Yours faithfully,

Lee Brothers Automotive Pte.Ltd



sales@leebrothers.com.sg

LEE BROTHERS AUTOMOTIVE PTE LTD

1 Kaki Bukit Avenue 6, #02-47 Autobay, Singapore 417883

Tel : (65) 6509 5521 Fax : (65) 6509 5523

Email : sales@leebrothers.com.sg

Co. Reg. : 201101880C

GST Reg. No. : 201101880C

TAX INVOICE

9922

Messrs : **AXA INSURANCE PTE LTD**
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Claim No. : LB0419-2610
Acc. Date : 06/04/2019

Veh. No./Model : SKH 1802Z TOYOTA ALTIS

Date : 31/05/2019

QTY	DESCRIPTIONS	AMOUNT
	Repair Cost : Inclusive of supply parts, panel beating, spray painting and labour.	7,000.00
	Sub-total	7,000.00
	Add GST 7%	490.00
	Total Amount	7,490.00

E. & O.E.

* Please make all payments to " Lee Brothers Automotive Pte Ltd "

* All service and repairing are in good order & conditions.



Customer Sign & Chop

Lee Brothers Automotive Pte Ltd



**Re:<MANDATE IA> - S9M01JGX {ACCIDENT INVOLVING
SFQ 8998H (OI) & SKH 1802Z ON 06/04/2019}**

Type

 Question

Message

Hi, pls proceed as per mandate. TY.

Reply

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM19006242/Uga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:RICHARD ANG

Date : 26-11-2019



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SFQ 8998H	Veh. Inspected	SKH 1802Z
Policy No.	VPA/P1262823	Coverage (\$)	0.00
Claim No.	S9M01JGX	Excess (\$)	0.00
Assign From		Assign Date	09/04/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA COROLLA ALTIS (A)	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	MR053REE104151378	Colour	GREY
Odometer	205763	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT AND O/S FRONT PORTION.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/04/2019	Inspection Date	09/04/2019
Survey held at	LEE BROTHERS AUTOMOTIVE PTE LTD 1 KAKI BUKIT AVENUE 6 #02-47 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.

B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	-----------------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKH 1802Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT HEADLAMP LH (N) (CONSISTENT)	SCRATCHED	1,790.40	1,790.40
1	FRONT BUMPER (N) (CONSISTENT)	DISTORTED	528.34	528.34
1	FRONT BUMPER FOG LAMP LH (N) (CONSISTENT)	NOT NECESSARY	329.10	-
1	FRONT BUMPER FOG LAMP COVER LH (N) (CONSISTENT)	GRAZED	124.10	124.10
1	FRONT BUMPER REINFORCEMENT (N) (CONSISTENT)	NOT NECESSARY	399.45	-
2	FRONT BUMPER BRACKET RH/LH @\$124.10 (N) (CONSISTENT)	NOT NECESSARY	248.20	-
1	FRONT BUMPER TOP RUBBER (N) (CONSISTENT)	NECESSARY	125.60	125.60
1	FRONT BUMPER EMBLEM LOGO (N) (CONSISTENT)	NECESSARY	65.30	65.30
2	FRONT BUMPER SIDE RETAINER RH/LH @\$112.35 (N) (CONSISTENT)	N/S BENT	224.70	112.35
1	FRONT FENDER LH (N) (CONSISTENT)	BADLY DENTED	617.30	617.30
1	FRONT FENDER COWLING LH (N) (CONSISTENT)	TORN	169.30	169.30
2	FRONT SHOCK ABSORBER RH/LH @\$490.15 (N) (CONSISTENT)	BENT / TWISTED	980.30	980.30
2	FRONT SHOCK ABSORBER MOULDING RH /LH @\$210.15 (N) (CONSISTENT)	NOT NECESSARY	420.30	-
2	FRONT LOWER ARM RH/LH @\$602.10 (N) (CONSISTENT)	CRACKED	1,204.20	1,204.20
2	FRONT LOWER ARM BALL JOINT RH/LH @\$203.10 (N) (CONSISTENT)	NOT NECESSARY	406.20	-
2	FRONT KNUCKLE ARM RH/LH @\$478.10 (N) (CONSISTENT)	BENT	956.20	956.20
2	FRONT KNUCKLE BEARING @\$210.10 (N) (CONSISTENT)	NECESSARY	420.20	420.20
2	FRONT STABILIZER BAR LINK RH/LH @\$195.00 (N) (CONSISTENT)	BENT	390.00	390.00
2	FRONT DRIVE SHAFT RH/LH @\$1716.70 (N) (CONSISTENT)	NOT NECESSARY	3,433.40	-
1	FRONT CROSS MEMBER (N) (CONSISTENT) (ADDITIONAL)	BENT / TWISTED	1,207.23	1,207.23
1	FRONT STEERING RACK (N) (CONSISTENT) (ADDITIONAL)	BENT / JAMMED	1,603.24	1,603.24
	LESS 25% DISCOUNT		-3,910.77	-

Report Ref No. CC4/ASM19006242/Uga3q2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 50% DISCOUNT		-	-5,147.03
			11,732.29	5,147.03
	<u>SPECIAL NETT ITEMS</u>			
1	SET FRONT BUMPER CLIP (SN) (CONSISTENT)	NECESSARY	45.00	45.00
1	SET FRONT FENDER COWLING CLIP (SN) (CONSISTENT)	NECESSARY	35.00	35.00
2	FRONT SPORT RIM @\$580.00 (SN) (CONSISTENT)	CUT / BENT	1,160.00	600.00
2	FRONT TYRE @\$280.00 (SN) (CONSISTENT)	SERVICEABLE	560.00	-
			1,800.00	680.00
	<u>LABOUR</u>			
	TO KNOCK OUT DENT AND REPLACE ACCIDENT PARTS.		600.00	400.00
	TO SPRAY PAINTING ON ACCIDENT PORTION .		600.00	400.00
	TO CHECK WIRING .		30.00	20.00
	TO REMOVE AND REPLACE UNDERCARRIAGE PARTS.		580.00	300.00
	TO 4 WHEEL ALIGNMENT.		120.00	120.00
	TO TUFF KOTE.		90.00	30.00
			2,020.00	1,270.00
	GRAND TOTAL		15,552.29	7,097.03
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			7,000.00

Report Ref No. CC4/ASM19006242/Uga3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

Service Request Details

Claim

59M01JGX

Reference

CC4/GSM19006242/Uga2u2

Loss Date

6 April 2019

Report Date

9 Apr 2019 9:29:00 AM

Request Date

9 April 2019

Due Date

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Vehicle Information

Incident Vehicle Registration #

SKH1802Z

Make

TPVD TOYOTA

Model

ALTIS

Service Address

...

Primary Contact/Insured

THAM BOON WEE
BLK 496B TAMPINES STREET 45, #06-380, 521498, Singapore
96759505

Claim Handler

ANG Richard
richard.angbo@axa.com.sg

Actions

Next Step

Wait for Approve Invoice

Approve Invoice

Additional Instructions

Document Type

Document SubType

+ Upload Documents

NAME

TYPE

SUB-TYPE

AUTHOR

DATE UPLOADED

Accident Statement

Reports & Statement

Members

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 LKXInvoice1 (1).pdf	Invoice	Surveyor/ Assessor expense	LKX AUTO CONSULTANTS PTE LTD (TP)	4 December 2019
 RENTAL RECEIPT.pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	4 December 2019
 LTA SEARCH.pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	4 December 2019
 LKXInspection.pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	4 December 2019
 LKXAdjustment1.a.pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	4 December 2019
 GIA SEARCH.pdf	Forms / Claim Documents	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	4 December 2019
 PAYMENT BREAKDOWN_EXPRESS SETTLEMENT FORM.pdf	Forms / Claim Documents	Satisfaction / Discharge Voucher	LKX AUTO CONSULTANTS PTE LTD (TP)	4 December 2019
 AUTHORISATION TO ACT FORM.pdf	Forms / Claim Documents	POA / Authority Letter	LKX AUTO CONSULTANTS PTE LTD (TP)	4 December 2019
 LETTER TO OI.pdf	Letters and Correspondence	Policy Holders / Insured	LKX AUTO CONSULTANTS PTE LTD (TP)	4 December 2019
 LKX RESURVEY PHOTO.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	1 November 2019
 MANDATE IA DO 01112019 .pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	1 November 2019
 LKX SURVEY PHOTO.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	1 November 2019
 LOD AND OTHER DOCUMENTS.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	1 November 2019
 TP FINAL EST LIST.pdf	Reports & Statement	Others	LKX AUTO CONSULTANTS PTE LTD (TP)	1 November 2019

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 PAIR COE REBATE.pdf	Reports & Statement	Others	LXX AUTO CONSULTANTS PTE LTD (TP)	1 November 2019
 TP ASP 2.jpg	Evidence	Photos	LXX AUTO CONSULTANTS PTE LTD (TP)	4 September 2019
 TP ASP 1.jpg	Evidence	Photos	LXX AUTO CONSULTANTS PTE LTD (TP)	4 September 2019
 TP LOO.png	Letters and Correspondence	Workshop	KUMAR Shaleendra	17 June 2019
 TP ESTIMATE - MARKED.pdf	Reports & Statement	Estimate / Quotation	LXX AUTO CONSULTANTS PTE LTD (TP)	13 April 2019
 EMAIL FROM WORKSHOP (THIRD PARTY PRQ).img	Letters and Correspondence	Workshop	KADRI Maseen	9 April 2019
 GIA SKH180ZZ TP.PDF	Reports & Statement	GIA Report	VISHNU BATHAM Shekhar	9 April 2019
 ACCIDENT SCENE.jpg	Evidence	Photos	LXX AUTO CONSULTANTS PTE LTD (TP)	9 April 2019