

INS. CASE OWNER:

CC 4, Hsm 1900

6746, Uja34

LNA:

109433

IDAC:

Surveyor:

OKS

DOI:

17/4/19

Date / Time:

9/4/2019

Registered in Merimen.

Pre-assign / CCU / FTE

SLA 2888 U



Insured Vehicle No.:

Dr. Ong Hoe Boon

Claim No.:

59m01jms

Name of Insured:

Policy No.:

Insured Tel No.:

HP:

Make / Model:

Excess Sec II :SS

D.O.A:

06/04/19

Place of Accident:

Is driver the owner?

(YES) NO

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SLX 6952 U



INSRS:

WSP:

Tel:

Liability:

RMKS:

Am.



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

16/4
3/4

SLX 6952 U X SLA 2888 U X

HEAD TO REAR
OI BEHIND BOLA 27.

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

17/4/19 JMY

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorization To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(days) Reduction:

%

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

24-5-19

Confirm with:

JALYNE

Email:

Call:

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No. : 27

If NO or B 28, Ass. Lia:

Repair Cost:

SS

6,700

Loss of Rental (LOR):

SS

x

(days)

Loss of Use (LOU):

SS

480

(\$

60

x

8

days)

Loss of Income (LOI):

SS

x

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

x

Medical:

SS

x

Disbursement:

SS

x

Legal Cost:

SS

x

Total:

SS

7,180

x

x

x

x

Global Sum SS:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

FINAL PAYMENT

Date/Time:

Confirm with:

Email:

Call:

Payee 1:

SS

7,180

x

x

x

x

Name 1:

AUTOMOBILE INTEGRATED MANAGEMENT

Payee 2: (Strike if N.A.)

SS

x

x

x

x

x

Name 2:

ITE LTD

Payee 3: (Strike if N.A.)

SS

x

x

x

x

x

Name 3:

not added 4/5 \$6700/2

7.11-6283581

12/4/19

8 day

Three plus After up



Automobile Integrated Management Pte Ltd
(Business Reg no. 201605297G)
Office: 28 Ser Ming Lane #07-147
Midview City Singapore 573972
Email: automm.claim@gmail.com

ESTIMATE

Our Ref: AC2019006/TP/SLX6952U-06.04.2019

Vehicle number: SLX6952U

Vehicle Make & Model: HONDA HRV

| Items | Qty | List Items | Amount \$ |
|------------|-------|-------------------------------------------------|------------|
| 1 | 1 | Tailgate | 1,209.10 ✓ |
| 2 | 1 | Tailgate outer garnish | 341.20 X |
| 3 | 1 | Tailgate emblem 'H' | 32.20 X |
| 4 | 1 | Tailgate emblem 'HRV' | 45.90 ✓ |
| 5 | 1 | Tailgate emblem 'i-VTEC' | 42.20 ✓ |
| 6 | 2 | Tailgate lamps - L/R @ 311.80 | 623.60 X |
| 7 | 1 set | Tailgate glass moulding | 112.20 ✓ |
| 8 | 1 | Tailgate inner lock | 204.10 ✓ |
| 9 | 1 | Tailgate inner trim | 310.60 ✓ |
| 10 | 1 | Tailgate inner pull pocket | 86.60 X |
| 11 | 1 | Tailgate lock striker | 28.60 X |
| 12 | 1 | Tailgate w/strip | 114.10 ✓ |
| 13 | 2 | Tailgate dampers - L/R @ 108.50 | 217.00 X |
| 14 | 2 | Tailgate hinges @ 74.10 | 148.20 X |
| 15 | 2 | Tailgate stoppers @ 12.20 | 24.40 X |
| 16 | 2 | Taillamps - L/R @ 381.90 | 763.80 ✓ |
| 17 | 1 | Rear bumper | 761.60 ✓ |
| 18 | 2 | Rear bumper reflectors - L/R @ 89.60 | 179.20 X |
| 19 | 2 | Rear bumper sides - L/R @ 241.60 | 483.20 ✓ |
| 20 | 2 | Rear bumper side retainers - L/R @ 48.60 | 97.20 X |
| 21 | 10 | Rear bumper clips @ 4.50 | 45.00 ✓ |
| 22 | 1 | Rear end panel | 560.90 ✓ |
| 23 | 1 | Rear end panel inner trim | 182.90 ✓ |
| 24 | 1 | Rear exhaust silencer | 688.10 X |
| 25 | 1 | Rear exhaust insulator | 70.80 X |
| 26 | 2 | Rear exhaust mountings @ 18.60 | 37.20 X |
| 27 | 1 | Rear floor board | 380.60 ✓ |
| 28 | 1 | Rear floor tray | 391.20 ✓ |
| 29 | 1 | Rear floor panel | 911.40 ✓ |
| 30 | 1 | Rear floor panel undercover | 241.20 ✓ |
| 31 | 2 | Rear fender inner trims - L/R @ 290.80 | 581.60 X |
| 32 | 1 | Rear smart keyless antenna | 180.90 X |
| 33 | 1 | Rear smart keyless buzzer | 192.90 ✓ |
| 34 | 2 | Rear fender wheel arch garnishes - L/R @ 241.20 | 482.40 ✓ |
| Sub-total | | | 10,772.10 |
| Less 20% | | | 2,154.42 |
| Total List | | | 8,617.68 |

P-6472.90

Vehicle number: SLX6952U

Vehicle Make & Model: HONDA HRV

Special Nett Items

- | | | |
|----|-------|-----------------------------|
| 35 | 1 set | Rear reverse sensor - 4 Pcs |
| 36 | 1 | Rear reverse camera |
| 37 | 1 set | Tailgate glass sealant |
| 38 | 1 set | Tailgate glass foam tape |

| | | |
|-------|--------|-----|
| shell | 480.00 | 200 |
| shell | 450.00 | 380 |
| ser | 80.00 | 40 |
| ser | 65.00 | 30 |

Total Special Nett 1,075.00

Labour charges

- | | |
|----|------------------------------------------------------------|
| 39 | To check rear electrical wiring |
| 40 | To remove, refix tailgate glass |
| 41 | To remove, refix rear reverse camera / sensor |
| 42 | To remove, refix rear exhaust systems |
| 43 | To respray undercoating |
| 44 | To remove, refix rear interior trims to assist repair |
| 45 | Reinstall tailgate electrical & mechanical to new tailgate |
| 46 | To respray painting and etc |
| 47 | Panel beating, cut, weld remove & replacing above parts |

| | |
|----------|------|
| 50.00 | 30 |
| 180.00 | 120 |
| 80.00 | 50 |
| 100.00 | 60 |
| 120.00 | 60 |
| 120.00 | 80 |
| 180.00 | 60 |
| 1,400.00 | 1100 |
| 1,500.00 | 1200 |

Total Labour 3,730.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

13,422.68

1. This is a quote for the repair of the vehicle described above.

2. The quote is based on the information provided by the customer.

3. The quote is valid for 30 days from the date of issue.

4. The quote is based on the assumption that the vehicle is in good condition.

5. The quote is based on the assumption that the vehicle is not under a recall.

6. The quote is based on the assumption that the vehicle is not under a warranty.

7. The quote is based on the assumption that the vehicle is not under a lease.

8. The quote is based on the assumption that the vehicle is not under a finance agreement.

9. The quote is based on the assumption that the vehicle is not under a hire purchase agreement.

10. The quote is based on the assumption that the vehicle is not under a conditional sale agreement.

P- 6572.90

50%

P- 3286.45

SN- 660.00

down - 2760.00

6706.45

not pulled
note
necus
Tel: 62633561
12/4/19
8 day.
Thupha Atheru



Automobile Integrated Management Pte Ltd
(Business Reg no. 201605297G)
Office: 28 Sin Ming Lane #07-147
Midview City Singapore 573972
Email: automim.claim@gmail.com

ESTIMATE

Our Ref: AC2019006/TP/SLX6952U-06.04.2019

Vehicle number: SLX6952U

Vehicle Made & Model: HONDA HRV

| Items | Qty | List Items | Amount \$ |
|------------|-------|-------------------------------------------------|------------|
| 1 | 1 | Tailgate | 1,209.10 ✓ |
| 2 | 1 | Tailgate outer garnish | 341.20 X |
| 3 | 1 | Tailgate emblem 'H' | 32.20 X |
| 4 | 1 | Tailgate emblem "HRV" | 45.90 ✓ |
| 5 | 1 | Tailgate emblem "i-VTEC" | 42.20 ✓ |
| 6 | 2 | Tailgate lamps - L/R @ 311.80 | 623.60 X |
| 7 | 1 set | Tailgate glass moulding | 112.20 ✓ |
| 8 | 1 | Tailgate inner lock | 204.10 ✓ |
| 9 | 1 | Tailgate inner trim | 310.60 |
| 10 | 1 | Tailgate inner pull pocket | 86.60 X |
| 11 | 1 | Tailgate lock striker | 28.60 X |
| 12 | 1 | Tailgate w/strip | 114.10 ✓ |
| 13 | 2 | Tailgate dampers - L/R @ 108.50 | 217.00 X |
| 14 | 2 | Tailgate hinges @ 74.10 | 148.20 X |
| 15 | 2 | Tailgate stoppers @ 12.20 | 24.40 X |
| 16 | 2 | Taillamps - L/R @ 381.90 | 763.80 |
| 17 | 1 | Rear bumper | 761.60 ✓ |
| 18 | 2 | Rear bumper reflectors - L/R @ 89.60 | 179.20 X |
| 19 | 2 | Rear bumper sides - L/R @ 241.60 | 483.20 |
| 20 | 2 | Rear bumper side retainers - L/R @ 48.60 | 97.20 X |
| 21 | 10 | Rear bumper clips @ 4.50 | 45.00 ✓ |
| 22 | 1 | Rear end panel | 560.90 ✓ |
| 23 | 1 | Rear end panel inner trim | 182.90 ✓ |
| 24 | 1 | Rear exhaust silencer | 688.10 X |
| 25 | 1 | Rear exhaust insulator | 70.80 X |
| 26 | 2 | Rear exhaust mountings @ 18.60 | 37.20 X |
| 27 | 1 | Rear floor board | 380.60 ✓ |
| 28 | 1 | Rear floor tray | 391.20 ✓ |
| 29 | 1 | Rear floor panel | 911.40 |
| 30 | 1 | Rear floor panel undercover | 241.20 ✓ |
| 31 | 2 | Rear fender inner trims - L/R @ 290.80 | 581.60 |
| 32 | 1 | Rear smart keyless antenna | 180.90 X |
| 33 | 1 | Rear smart keyless buzzer | 192.90 ✓ |
| 34 | 2 | Rear fender wheel arch garnishes - L/R @ 241.20 | 482.40 ✓ |
| Sub-total | | | 10,772.10 |
| Less 20% | | | 2,154.42 |
| Total List | | | 8,617.68 |

KKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Knownledged by Repairer
Signature:
Date:

Vehicle number: SLX6952U

Vehicle Made & Model: HONDA HRV

Special Nett Items

- | | | |
|----|-------|-----------------------------|
| 35 | 1 set | Rear reverse sensor - 4 Pcs |
| 36 | 1 | Rear reverse camera |
| 37 | 1 set | Tailgate glass sealant |
| 38 | 1 set | Tailgate glass foam tape |

| | | |
|------|--------|-----|
| shub | 480.00 | 200 |
| shub | 450.00 | 380 |
| rer | 80.00 | 40 |
| rer | 65.00 | 30 |

| | |
|---------------------------|-----------------|
| Total Special Nett | 1,075.00 |
|---------------------------|-----------------|

Labour charges

- | | |
|----|------------------------------------------------------------|
| 39 | To check rear electrical wiring |
| 40 | To remove, refix tailgate glass |
| 41 | To remove, refix rear reverse camera / sensor |
| 42 | To remove, refix rear exhaust systems |
| 43 | To respray undercoating |
| 44 | To remove, refix rear interior trims to assist repair |
| 45 | Reinstall tailgate electrical & mechanical to new tailgate |
| 46 | To respray painting and etc |
| 47 | Panel beating, cut, weld remove & replacing above parts |

| | |
|----------|------|
| 50.00 | 30 |
| 180.00 | 120 |
| 80.00 | 50 |
| 100.00 | 60 |
| 120.00 | 60 |
| 120.00 | 80 |
| 180.00 | 60 |
| 1,400.00 | 1100 |
| 1,500.00 | 1200 |

| | |
|---------------------|-----------------|
| Total Labour | 3,730.00 |
|---------------------|-----------------|

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

13,422.68

Let's Agree to the Terms and Conditions of the Insurance Policy:

- To respray before and after painting
- To inspect damaged parts during respray
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Signature of the Insured

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

| | |
|-------------------------------------|--------------------------------------|
| Vehicle Owner Particulars | |
| Owner ID Type: | Company |
| Owner ID: | 5995E |
| Vehicle Details | |
| Vehicle No.: | SLX6952U |
| Vehicle to be Exported: | No |
| Intended Deregistration Date: | 15 Apr 2019 |
| Vehicle Make: | HONDA |
| Vehicle Model: | HRV 1.5 LX CVT |
| Primary Colour: | Silver |
| Manufacturing Year: | 2017 |
| Engine No.: | L15B4533857 |
| Chassis No.: | JHMRU1830GX203854 |
| Maximum Power Output: | 96.0 kW (128 bhp) |
| Open Market Value: | \$21,077.00 |
| Original Registration Date: | 05 Apr 2018 |
| First Registration Date: | 05 Apr 2018 |
| Transfer Count: | 0 |
| Actual ARF Paid: | \$21,508.00 |
| Intended PARF Rebate Details | |
| PARF Eligibility: | Yes |
| PARF Eligibility Expiry Date: | 04 Apr 2028 |
| PARF Rebate Amount: | \$16,131.00 |
| Intended COE Rebate Details | |
| COE Expiry Date: | 04 Apr 2028 |
| COE Category: | A - Car up to 1600cc & 97kW (130bhp) |
| COE Period(Years): | 10 |
| QP Paid: | \$38,830.00 |
| COE Rebate Amount: | \$34,833.00 |
| Total Rebate Amount: | \$50,964.00 |

The information contained herein is correct as at 15 Apr 2019

OK

Mei Kwan (LKK Auto)

From: Mei Kwan (LKKAuto) <Meikwan@lkkauto.com>
Sent: Tuesday, 9 April 2019 11:06 AM
To: assignments
Subject: FW: NOA- SLX6952U // Claim TP 06.04.19
Attachments: Notice of acct SLX6952U.pdf

2.28pm @ 10/4/19
shyl
MI
average on 12/4/19

Hi team

TP smart. Kindly assist.

Thank you.

Best Regards,

Mei Kwan | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366 0055 | email: MeiKwan@lkkauto.com | fax: 67414108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: AIM PTE LTD <automim.claim@gmail.com>
Sent: Tuesday, 9 April, 2019 9:28 AM
To: SG AXA Insurance SM AXA SGP - Motor Survey <motor.survey@axa.com.sg>
Subject: NOA- SLX6952U // Claim TP 06.04.19

Hi,

Please find attached to advise.

Thank you.

Regards,
Jacyne

--

AIM
tel: 91198371



Automobile Integrated Management Pte Ltd
(Business Reg no. 201605297G)
Office: 28 Sin Ming Lane #02-147 Midview City
Singapore 573972
Workshop: 23 Kaki Bukit Ave 4 Kaki Bukit Vcom
#04-01 Singapore 415933
automim.claim@gmail.com

By Email

Our ref: AC2019006/TP/SLX6952U-06.04.19/NOA

09 April 2019

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811
Attention: Claim Officer in charge

Dear Sir / Madam,

NOTIFICATION OF ACCIDENT

**ACCIDENT INVOLVING SLX6952U AND SLA2888U ALONG COMMONWEALTH AVE TO
ALEXANDRA ON 06 APRIL 2019**

We are appointed by Excel Marine & Engineering Pte Ltd to repair their vehicle SLX6952U and assist to make a claim against from your insured SLA2888U, please let us know within 2 workings days from the date of this notice if you wish to carry out a pre-repair inspection.

The vehicle is available for inspection on Friday (12/4/19) at 1030am onwards at the below location:

23 Kaki Bukit Ave 4 #04-01 (South Wing) Singapore 415933

Kindly email or contact Sheryl at 97451591 to arrange for inspection.

Thank you.

Yours faithfully,

Automobile Integrated Management Pte Ltd

<<

Re:MANDATE IA - AIM - SLX6952U

Type

🔔 Question

Message

Hi Pls proceed as per IA-VO

Reply



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 409035 TEL : (065) 62563561 FAX : (065) 62564333

Immediate Advice

To : AXA Insurance Pte Ltd

Date: 15/4/2019

Survey Details:

| | |
|---------------------|-------------------------------------|
| Date of loss | 6-Apr-19 |
| Date of appointment | 9-Apr-19 |
| Date of survey | 12-Apr-19 |
| Location of survey | AUTOMOBILE INTEGRATED MANAGEMENT PL |

Vehicle Details:

| | |
|----------------------|----------------------|
| Claim Type: | THIRD PARTY CLAIM |
| Vehicle number | SLX6952U |
| Make and Model | HONDA HRV 1.5 LX CVT |
| Date of registration | 5-Apr-18 |
| Part Rebate | |
| Market Value | \$ 75,000.00 |
| Part Rebate | \$ 46,088.00 |
| Nett Loss | \$ 28,912.00 |

Repair details:

| | |
|------------------|--------------|
| Initial Estimate | \$ 13,422.68 |
|------------------|--------------|

Proposed/Revised repair cost:

| | |
|-------------------------|-------------|
| Parts | \$ 3,946.45 |
| Check items (estimate) | |
| Labour | \$ 2,760.00 |
| Total | \$ 6,706.45 |
| Lump Sum(if applicable) | \$ 6,700.00 |

| | |
|---------------------------|---|
| Number of days for repair | 8 |
|---------------------------|---|



Auto
Consultants
Pte Ltd

Company Registration No. 199607188R

21 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Remarks:

BOLA 27 - HEAD TO REAR

Mandate:

| Liability(TP) | 100% | |
|----------------------|------|----------|
| Proposed repair cost | \$ | 6,700.00 |
| Loss of use | \$ | 480.00 |
| Proposed Total | \$ | 7,180.00 |

\$60 X 8 DAYS



By Email

Automobile Integrated Management Pte Ltd
(Business Reg no. 201605297G)
Office: 28 Sin Ming Lane #07-147 Midview City
Singapore 573972
Workshop: 23 Kaki Bukit Ave 4, Kaki Bukit Vicom
#04-01 Singapore 415933
automim.claim@gmail.com

Our ref. AC2019006/TP/SLX6952U – 06.04.19/LOD

14th May 2019

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811
Attention: Claim Officer in charge

Dear Sir / Madam,

**CLAIMANT – EXCEL MARINE & ENGINEERING PTE LTD
ACCIDENT INVOLVING SLX6952U AND SLA2888U ALONG COMMONWEALTH AVE TO ALEXANDRA
ON 6 APRIL 2019**

We are appointed by Excel Marine & Engineering Pte Ltd, to repair their vehicle SLX6952U. The claimant has requested and authorized us to assist them in presenting their claims in connection with the above-said accident.

We are submitting these claim for your consideration:

| | |
|----------------------------------------|---------------------------|
| 1. Cost of Repair | S\$ 6700.00 |
| 2. Loss of use (8 days x \$100per day) | S\$ 800.00 |
| Total Claims: | <u>S\$ 7500.00</u> |

We enclosed herewith the following document:

- (a) Original Final Repair Bill
- (b) Letter of Authorization

We look forward to the settlement of the said claim.

Please note that it is a condition of any settlement reached that it shall be without prejudice to and shall not affect any other claims arising from this accident.

Thank you.

Yours faithfully,
Automobile Integrated Management Pte Ltd



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

17 APRIL 2019

DR ONG HOE BOON
1F SHELFORD ROAD
#05-43 THE SHELFORD
SINGAPORE 286891

Dear Sir/Madam,

OUR REF : CC4/ASM19006246/Uja3
YOUR REF : SLA 2888U

ACCIDENT INVOLVING SLA 2888U AND SLX 6952U ALONG COMMONWEALTH AVE ON 06.04.2019

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Singapore Pte Ltd to deal with the third party claim against your policy.

We have received a claim from M/s AUTOMOBILE INTERGRATED MANAGEMENT PTE LTD acting on behalf of the owner of SLX 6952U against your motor insurance policy.

Based on the accident report and accident scenario, it was reported that your vehicle had hit Third Party vehicle from the rear. As such, liability is down against us.

Please be informed that your No Claim Discount (NCD) may be affected as a result of the claim against your policy.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 10 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to joyirene@lkkauto.com within 10 days from the date of this letter **if not provided at our reporting centre**. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

- Statement and/or police report from independent witness(es) (if any)
- If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent.

This letter should **not** be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6256 3561 or email us at joyirene@lkkauto.com.

Please quote the claim reference when you contact us that we can assist you more effectively.

Yours sincerely,



Joy Irene
Case Handler
DID: 6841 2409
FAX: 6741 4108
Email: joyirene@lkkauto.com

c.c. AXA Insurance Singapore Pte Ltd (AXA)
(Motor Claims Dept)

AUTHORIZATION TO ACT

I, Excel Marine & Engineering Pte Ltd (the third party claimant) of 2 Penjuru Close
#01-03 & 04 Singapore 608611 (address), owner of SLX6952U (vehicle no.)
hereby authorize Automobile Integrated Management Pte Ltd ("the workshop") to act for me
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle
no. SLX6952U that was damaged pursuant to the accident which occurred on 6/4/19
(date) along Commonwealth Ave to Alexandra (location) involving vehicle no/s
SLA2888U ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 14th (day) of May (month) 20 19 (year)

X  

Signed by "the third party claimant"
(with chop if applicable)

Signed by "the workshop"
(with chop)



AXA THIRD PARTY DIRECT SETTLEMENT

| | | | |
|-------------------------|-----------|------------|------------------|
| Vehicle No: | SLA 2888U | (Insd veh) | Model: HONDA HRV |
| | SLX 6952U | (TP veh) | |
| Date of Accident/ Time: | 06/04/19 | | |

| | | | |
|----------------------|------|-------------|----------------------------|
| Repair Estimate | : \$ | (5,43) . 68 | |
| Final Repair Cost | : \$ | 6,700.00 | |
| Loss of Use | : \$ | 480.00 | 8 days at \$ 60.00 per day |
| Rental (if any) | : \$ | | days at \$ per day |
| LTA / GIA Search Fee | : \$ | | |
| Others: | : \$ | | |
| | : \$ | | |
| Final Settlement Sum | : \$ | 7,180.00 | |

Payee Name: AUTOMOBILE INTEGRATED MANAGEMENT PTE LTD

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

| | | |
|------------------------------------------------------------------------------------------------------|----------------------------------|--------------------------------------------------|
| A) | For Non GIA Registered Workshop: | Agreed Liability 100 (%) |
| B) | For GIA Registered Workshop: | BOLA Applicable: Yes/ No BOLA Scenario No: _____ |
| | BOLA Liability: _____ (%) | Assessed Liability (*): _____ (%) |
| * Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply. | | |
| Remarks: | | |

NOTE:

- PLEASE EXPRESSLY RESERVE YOUR CLIENT'S RIGHTS IF SO REQUIRED IN THIS SETTLEMENT DOCUMENT.
- THIS SETTLEMENT IS ON A WITHOUT PREJUDICE BASIS AND SHOULD NOT CONSTRUED AS AN ADMISSION OF LIABILITY ON AXA AND THEIR CLIENT/TORTFEASOR IN ANY MANNER WHATSOEVER.
- AXA RESERVES THEIR RIGHTS UNDER THE POLICY TERMS & CONDITIONS AS WELL AS THEIR RIGHTS IN LAW.

Only applicable to rental claim - All document are to be submitted with this settlement confirmation. In the event, rental agreement / invoices are *not received within 7 days* of this signed confirmation, we will automatically revert to loss of use claim per the NIMA rates.

We/I confirmed that this is a full and final settlement that we and or our client have/had/has against you (AXA and their policyholder/authorised driver/tortfeasor) for any and all losses (past/present/future) arising from this accident.

We confirmed that we have the authority of Automobile Integrated Management Pte Ltd act for and on their behalf in this accident.

| | |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
|   Signature of workshop representative / Workshop stamp Name of Representative: <u>Ang Beck Hoon</u> Date: <u>25/6/19</u>  Signature of AXA's surveyor/representative: Name of AXA's surveyor /Representative: Date: <u>25/6/2019</u> |  Signature of Witness / Workshop stamp (if applicable) Name of Witness: <u>Lee Chia Seng</u> Date: <u>25/6/19</u> |
|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|



Automobile Integrated Management Pte Ltd
(Business Reg no. 201605297G)
28 Sin Ming Lane #07-147
Midview City Singapore 573972
automim.claim@gmail.com

FINAL REPAIR BILL

AXA Insurance Pte Ltd
8 Shenton Way
#24-01 AXA Tower
Singapore 068811

Date: 14-May-19
Our Ref. no.: AC2019006/TP

| Make/Model | Vehicle no. | DOA |
|------------|-------------|----------|
| HONDA HRV | SLX6952U | 06-04-19 |

| DESCRIPTION | AMOUNT S\$ |
|----------------------|------------|
| Lump Sum Repair Cost | 6,700.00 |
| Total: | 6,700.00 |

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|----------------------------------------------------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------|-----------------|------------------------------|-------------------------------------------------------------------------------------|
| AXA INSURANCE PTE LTD | | | Ref : CC4/ASM19006246/Uja3q2 | |
| 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:VALE OH | | | Date : 11-07-2019 |  |
| | | | Code : ASM | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| Insured Veh. | SLA 2888U | Veh. Inspected | SLX 6952U | |
| Policy No. | VA1/GA429000 | Coverage (\$) | 0.00 | |
| Claim No. | S9M01JM5 | Excess (\$) | 0.00 | |
| Assign From | | Assign Date | 09/04/2019 | |
| 2. Vehicle Particulars & Condition | | | | |
| Make & Model | HONDA HRV (A) | c.c | 1496 | |
| Engine No. | HIDDEN | Year of Reg. | 2018 | |
| Chassis No. | JHMRU1830GX203854 | Colour | SILVER | |
| Odometer | 25368 | Steering | IN ORDER | |
| Brakes | IN ORDER | Modification | SPORTS RIM | |
| General | GOOD | | | |
| 3. Conditions of Tyres | | | | |
| | Size | Make | Balance | |
| R/H Front Tyre | 215/60 R16 | DUNLOP | 7 mm | |
| L/H Front Tyre | 215/60 R16 | DUELER | 7 mm | |
| R/H Rear Tyre | 215/60 R16 | DUNLOP | 7 mm | |
| L/H Rear Tyre | 215/60 R16 | DUNLOP | 7 mm | |
| 4. Description of Damages | | | | |
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. | | | | |
| 5. General Information | | | | |
| Accident Date | 06/04/2019 | Inspection Date | 12/04/2019 | |
| Survey held at | AUTOMOBILE INTEGRATED MANAGEMENT PL 28 SIN MING LANE #07-147 MIDVIEW CITY SINGAPORE 573972 | | | |
| 5a. Remarks | | | | |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | |
| 5b. Estimate Days of Repair | | | | |
| ESTIMATED NORMAL PERIOD FOR REPAIR: | | 8 Working Days | | |



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLX 6952U

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----------------------------|-------------------------------------------------------|----------------------|---------------------------|-------------------|
| REPLACEMENT OF PARTS | | | | |
| 1 | TAILGATE (CONSISTENT) | BADLY DENTED | 1,209.10 | 812.80 |
| 1 | TAILGATE OUTER GARNISH (CONSISTENT) | NOT NECESSARY | 341.20 | - |
| 1 | TAILGATE EMBLEM 'H' (CONSISTENT) | NOT NECESSARY | 32.20 | - |
| 1 | TAILGATE EMBLEM 'HRV' (CONSISTENT) | NECESSARY | 45.90 | 32.70 |
| 1 | TAILGATE EMBLEM 'I-VTEC' (CONSISTENT) | NECESSARY | 42.20 | 35.00 |
| 2 | TAILGATE LAMPS -L/R @\$311.80 (CONSISTENT) | NOT NECESSARY | 623.60 | - |
| ✓ 1 | SET TAILGATE GLASS MOULDING (CONSISTENT) | NECESSARY | 112.20 | 112.20 |
| 1 | TAILGATE INNER LOCK (CONSISTENT) | TWISTED | 204.10 | 204.10 |
| 1 | TAILGATE INNER TRIM (CONSISTENT) | DEFORMED | 310.60 | 310.60 |
| 1 | TAILGATE INNER PULL POCKET (CONSISTENT) | NOT NECESSARY | 86.60 | - |
| 1 | TAILGATE LOCK STRIKER (CONSISTENT) | NOT NECESSARY | 28.60 | - |
| 1 | TAILGATE W/STRIP (CONSISTENT) | TWISTED | 114.10 | 114.10 |
| 2 | TAILGATE DAMPERS -L/R @\$108.50 (CONSISTENT) | NOT NECESSARY | 217.00 | - |
| ✓ 2 | TAILGATE HINGES @\$74.10 (CONSISTENT) | NOT NECESSARY | 148.20 | - |
| ✓ 2 | TAILGATE STOPPERS @\$12.20 (CONSISTENT) | NOT NECESSARY | 24.40 | - |
| ✓ 2 | TAILLAMPS -L/R @\$381.90 (CONSISTENT) | DAMAGED / CRACKED | 763.80 | 763.80 |
| ✓ 1 | REAR BUMPER (CONSISTENT) | DENTED / DEFORMED | 761.60 | 517.10 |
| 2 | REAR BUMPER REFLECTORS -L/R @\$89.60 (CONSISTENT) | NOT NECESSARY | 179.20 | - |
| 2 | REAR BUMPER SIDES -L/R @\$241.60 (CONSISTENT) | DEFORMED / TWISTED | 483.20 | 483.20 |
| 2 | REAR BUMPER SIDE RETAINERS -L/R @\$48.60 (CONSISTENT) | NOT NECESSARY | 97.20 | - |
| 10 | REAR BUMPER CLIPS @\$4.50 (CONSISTENT) | NECESSARY | 45.00 | 45.00 |
| 1 | REAR END PANEL (CONSISTENT) | BADLY DENTED | 560.90 | 425.90 |
| 1 | REAR END PANEL INNER TRIM (CONSISTENT) | TWISTED | 182.90 | 182.90 |
| 1 | REAR EXHAUST SILENCER (CONSISTENT) | TO REPAIR SEE LABOUR | 688.10 | - |
| 1 | REAR EXHAUST INSULATOR (CONSISTENT) | NOT NECESSARY | 70.80 | - |
| 2 | REAR EXHAUST MOUNTINGS @\$18.60 (CONSISTENT) | NOT NECESSARY | 37.20 | - |
| 1 | REAR FLOOR PANEL (CONSISTENT) | WARPED | 380.60 | 380.60 |

Report Ref No. CC4/ASM19006246/Uja3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|------------------------------------------------------------------------------------------------------------|--------------------|---------------------------|-------------------|
| 1 | REAR FLOOR TRAY (CONSISTENT) | TORN | 391.20 | 391.20 |
| 1 | REAR FLOOR PANEL (CONSISTENT) | CRUMPLED / BUCKLED | 911.40 | 845.20 |
| 1 | REAR FLOOR PANEL UNDERCOVER (CONSISTENT) | DISTORTED | 241.20 | 241.20 |
| 2 | REAR FENDER INNER TRIMS -L/R @\$290.80 (CONSISTENT) | NOT NECESSARY | 581.60 | - |
| 1 | REAR SMART KEYLESS ANTENNA (CONSISTENT) | NOT NECESSARY | 180.90 | - |
| 1 | REAR SMART KEYLESS BUZZEL (CONSISTENT) | CRACKED | 192.90 | 192.90 |
| 2 | REAR FENDER WHEEL ARCH GARNISHES -L/R @\$241.20 (CONSISTENT) | TORN | 482.40 | 482.40 |
| | LESS 20% DISCOUNT | | -2,154.42 | - |
| | LESS 50% DISCOUNT | | - | -3,286.45 |
| | | | 8,617.68 | 3,286.45 |
| | <u>SPECIAL NETT ITEMS</u> | | | |
| 1 | SET REAR REVERSE SENSOR -4 PCS (SN) (CONSISTENT) | SHORTED | 480.00 | 200.00 |
| 1 | REAR REVERSE CAMERA (SN) (CONSISTENT) | SHORTED | 450.00 | 380.00 |
| 1 | SET TAILGATE GLASS SEALANT (SN) (CONSISTENT) | NECESSARY | 80.00 | 40.00 |
| 1 | SET TAILGATE GLASS INNER TAPE (SN) (CONSISTENT) | NECESSARY | 65.00 | 30.00 |
| | | | 1,075.00 | 650.00 |
| | <u>LABOUR</u> | | | |
| | TO CHECK REAR ELECTRICAL WIRING. | | 50.00 | 30.00 |
| | TO REMOVE,REFIX TAILGATE GLASS. | | 180.00 | 120.00 |
| | TO REMOVE,REFIX REAR REVERSE CAMERA /SENSOR . | | 80.00 | 50.00 |
| | TO REMOVE,REFIX REAR EXHAUST SYSTEMS. | | 100.00 | 60.00 |
| | TO RESPRAY UNDERCOATING. | | 120.00 | 60.00 |
| | TO REMOVE,REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR. | | 120.00 | 80.00 |
| | REINSTALL TAILGATE ELECTRICAL & MECHANICAL TO NEW TAILGATE. | | 180.00 | 60.00 |
| | TO RESPRAY PAINTING AND ETC. | | 1,400.00 | 1,100.00 |
| | PANEL BEATING ,CUT ,WELD REMOVE & REPLACING ABOVE PARTS.INCLUSIVE OF THE REPAIR OF REAR EXHAUST SILENCER . | | 1,500.00 | 1,200.00 |
| | | | 3,730.00 | 2,760.00 |

Report Ref No. CC4/ASM19006246/Uja3q2



| | | | |
|-------------------------------------------------------------------------|--|-----------|----------|
| GRAND TOTAL | | 13,422.68 | 6,696.45 |
| RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) | | | 6,700.00 |

Report Ref No. CC4/ASM19006246/Uja3q2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

<< Service Request Details

Claim

S9H03JMS

Reference

CC4/ASM1906246/Up342

Loss Date

6 April 2019

Report Date

9 Apr 2019 10:24:09 AM

Received Date

9 April 2019

Due Date

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Vehicle Information

Incident Vehicle Registration #

SLX6952U

Make

TPVD HONDA

Model

HRV

Service Address

...

Primary Contact/Insured

DR ONG HOE BOON

1F SHELFORD ROAD, #05-43 THE SHELFORD,

286891, Singapore

ONGHOEB00N@YAHOO.COM.SG

Claim Handler

OH Vale

656804897

vale.oh@axa.com.sg

Actions















Next Step

Wait for Approve Invoice

Send Invoice

Additional Instructions

| Messages | Invoices | History | Documents | Assessment | Metrics | Notes |
|-----------------------------------------------------------------------------------------------------------|----------|----------------------------|-----------------------------------|---------------|---------|-------|
| Document Type | | | | | | |
| Document SubType | | | | | | |
| <div>Upload Documents</div> | | | | | | |
| NAME | TYPE | SUB-TYPE | AUTHOR | DATE UPLOADED | | |
|  LKKInvoice1 (3).pdf | Invoice | Surveyor/ Assessor expense | LKK AUTO CONSULTANTS PTE LTD (TP) | 12 JULY 2019 | | |

| NAME | TYPE | SUB-TYPE | AUTHOR | DATE UPLOADED |
|-----------------------------------------------------------------------------------------------------------------------------------|-------------------------|----------------------------------|--------------------------------------|------------------|
|  LKK Inspection.pdf | Forms / Claim Documents | Others | LKK AUTO CONSULTANTS PTE LTD (TP) | 12 July 2019 |
|  LKK Adjustment 1a.pdf | Forms / Claim Documents | Others | LKK AUTO CONSULTANTS PTE LTD (TP) | 12 July 2019 |
|  LKK PHOTO-3.pdf | Forms / Claim Documents | Others | LKK AUTO CONSULTANTS PTE LTD (TP) | 12 July 2019 |
|  LKK PHOTO-2.pdf | Forms / Claim Documents | Others | LKK AUTO CONSULTANTS PTE LTD (TP) | 12 July 2019 |
|  PAYMENT BREAKDOWN EXPRESS SETTLEMENT FORM.pdf | Forms / Claim Documents | Satisfaction / Discharge Voucher | LKK AUTO CONSULTANTS PTE LTD (TP) | 12 July 2019 |
|  AUTHORISATION TO ACT FORM.pdf | Forms / Claim Documents | POA / Authority Letter | LKK AUTO CONSULTANTS PTE LTD (TP) | 12 July 2019 |
|  WORKSHOP INVOICE.pdf | Invoice | Requaire | LKK AUTO CONSULTANTS PTE LTD (TP) | 12 July 2019 |
|  TP ESTIMATE_MARKED IF FINAL.pdf | Reports & Statement | Others | LKK AUTO CONSULTANTS PTE LTD (TP) | 20 June 2019 |
|  LETTER TO INQUIRED-.pdf | Reports & Statement | Others | LKK AUTO CONSULTANTS PTE LTD (TP) | 20 June 2019 |
|  MANDATE 1A - AIM - SLX 6952U.pdf | Reports & Statement | Others | LKK AUTO CONSULTANTS PTE LTD (TP) | 20 June 2019 |
|  1A.pdf | Forms / Claim Documents | Assessment | LKK AUTO CONSULTANTS PTE LTD (TP) | 16 April 2019 |
|  LKK SURVEY PHOTO.pdf | Forms / Claim Documents | Assessment | LKK AUTO CONSULTANTS PTE LTD (TP) | 16 April 2019 |
|  TP ESTIMATE - MARKED.pdf | Reports & Statement | Estimate / Quotation | LKK AUTO CONSULTANTS PTE LTD (TP) | 16 April 2019 |
|  VIDEO-2019-04-08-10-44-35.mp4 | Evidence | Videos | LKK AUTO CONSULTANTS PTE LTD (TP) | 10 April 2019 |

| NAME | TYPE | SUB-TYPE | AUTHOR | DATE UPLOADED |
|---------------------------------------------------------------------------------------------------------------------------|----------------------------|--------------------------------------------------------|-------------------------|------------------|
|  GUA29000-Certificate of Insurance.pdf | Forms / Claim Documents | Policy Schedule / Covernote / Certificate of Insurance | Oh Vale | 9 April 2019 |
|  GUA29000-Policy Schedule.pdf | Forms / Claim Documents | Policy Schedule / Covernote / Certificate of Insurance | Oh Vale | 9 April 2019 |
|  SLA2888U-INSO GUA.PDF | Reports & Statement | GIA Report | NIKAM Santosh Pandurang | 9 April 2019 |
|  EMAIL FROM WORKSHOP FOR TP REG.msi | Letters and Correspondence | Others | NIKAM Santosh Pandurang | 9 April 2019 |
|  SLA6952U-TP GUA.PDF | Reports & Statement | GIA Report | NIKAM Santosh Pandurang | 9 April 2019 |