

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SME5452R

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST GBA4910T - EQ INSURANCE INSURED		
2	ZZ/001	CONDUCT TP CLAIM EQ INSURANCE LOCATION:BCP CHANGI BFR TANJONG KATONG EXIT DATE:26/03/2019 TIME:1525		
3	ZZ/002	REPAIR/REPLACE RR BUMPER,RR TAILGATE,RR FLOORPAN & PANEL	3360.00	16800
4	ZZ/003	RESPRAY RR BUMPER,RR TAILGATE,RR FLOORPAN & PANEL	2520.00	12600
5	ZZ/004	DISMANTLE & REFIX UNDERCARRIAGE TO FACILITATE REPAIRS	nn 900.00	X
6	ZZ/005	REMOVE & REFIX EXHAUST	NN 150.00	X
7	ZZ/006	TO CONDUCT WATER SEEPAGE TEST	100.00	200
8	ZZ/007	TRANSFER TAILGATE MECHANISM	150.00	1200
9	ZZ/008	TO CONDUCT 4 WHEEL ALIGNMENT	nn 200.00	X
10	ZZ/009	REMOVE & REFIX CARPET,SEATS TO FACILITATE REPAIRS	400.00	2500
11	ZZ/011	FAULT DIAGNOSTIC AND RESET SYSTEMS	NN 280.00	X
12	ZZ/012	REMOVE & INSTALL REAR WINDSCREEN	300.00	✓
13	ZZ/013	TO REMOVE & REFIX FUEL TANK	nn 200.00	X
14	ZZ/014	TO CONDUCT REAR LIGHTING TEST	50.00	300
15	ZZ/015	TO CONDUCT PROTECTANT COATING	500.00	2500
16	ZZ/016	TO CONDUCT ANTI-RUST COATING	580.00	2900
17	ZZ/017	TO SUPPLY & INSTALL REVERSE SENSOR - 2 EYES	nn 300.00	✓
18	ZZ/018	TO SUPPLY & INSTALL REAR TINTED FILM	nn 145.00	✓
19	ZZ/019	SUNDRIES	100.00	300
20	ZZ/10	REMOVE & REFIX REAR BOOT GARNISH & TRIM TO FACILITATE REPAIRS	150.00	1200
TOTAL LABOUR CHARGES			10385.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SME5452R

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			
			NETT	LIST	S/NETT	S/LIST REMARKS
1	EXH PIPE ASSY R	44200FL120	SVC	540.00	X	
2	MUFFLER ASSY W20	44300FL000	11	576.00	X	
3	FLOOR PAN R R CP 5D	52129FL0209P	11	432.00	X	
4	SKIRT COMPL R 5D	52401FL0209P	11	432.00	✓	
5	BUMPER FACE R XV	57704FL250	11	401.00	✓	
6	BRKT SD R XV RH	57707FL400	R	12.10	X	
7	BRKT SD R XV LH	57707FL410	R	12.10	X	
8	BRKT CORNER R 5D RH	57707FL460	R	21.60	X	
9	BRKT CORNER R 5D LH	57707FL470	R	21.60	X	
10	BRKT LWR R	57707FL510	BU	50.40	✓	
11	BEAM COMPL R EU	57711FL0419P	11	203.00	✓	
12	COVER HOOK R XV	57731FL570NN	11	6.50	✓	
13	MIDGUARD RRH	59122FL020	11	64.80	X	
14	MIDGUARD RLH	59122FL030	11	64.80	X	
15	PANEL COMPL R GAT	60809FL0009P	11	940.00	✓	
16	GLASS ASSY R G	63019FL030	11	1062.00	✓	
17	LATCHACT ASSY RG	63032PG102	R	144.00	X	
18	STRIKER R/G	63264AG100	11	21.60	X	
19	WSTR DR R G	63516FL000	R	108.00	X	
20	DAM RUBBER	65245FL000	11	18.00	✓	
21	LENS & BODY COMPL LH	84912FL050	R	378.00	X	
22	LENS & BODY COMPL RH	84913AL120	R	129.60	X	
23	LENS & BODY COMPL LH	84913AL140	SVC	64.80	X	
24	GARNISH SC	91111FL030NN	11	173.90	X	
25	ORNAMENT ASSY F SIX	91174SA181	11	68.40	✓	

		DAMAGED PARTS & PRICES				
S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
26	PROTECTOR UP FHI	91713FL000	NN	7.20	X	
27	PROTECTOR SD RH FHI	91713FL010	NN	3.60	X	
28	PROTECTOR SD LH FHI	91713FL020	NN	3.60	X	
29	PROTECTOR LMR A FHI	91713FL030	NN	3.60	X	
30	PROTECTOR LMR B FHI	91713FL040	NN	3.60	X	
31	LETTER MK R	93079FL100	<i>u</i>	90.00	<i>—</i>	
32	LETTER MK R XV	93079FL140	<i>u</i>	36.00	<i>—</i>	
33	TRIM PNL AY SKIRT	94026FL010VH	R	108.00	X	
34	REAR NUMBER PLATE	WM002		<i>u</i>	45.00	X
SUB TOTAL			6201.80	0.00	45.00	0.00
LESS DISCOUNT (NETT-20 %)			1240.36	0.00	0.00	0.00
GRAND TOTAL			4961.44	0.00	45.00	0.00
OVERALL TOTAL			5006.44			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

SUPP (-20%)

1. EYE SIGHT EMBLEM \$43.20 ✓ NEC

MOTORIMAGE ENTERPRISES PTE. LTD.
19 LORONG 8, TOA PAYOH
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SME545ZR

TOTAL LABOUR CHARGES	10385.00
TOTAL SPARE PARTS CHARGES	5006.44

GRAND TOTAL	15391.44 *

* All charges do not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

Not Notchick
Penny B4 paint
6 days