



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road
#08-1339 Singapore 470130
Tel: 9450 7920
* zoomautowerks@gmail.com

15 April 2019

REG NO.: SGK 393 A
MAKE/MODEL: LEXUS GS 250

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	LIST ITEMS	
1	Front headlamp -L/H 3225.15	\$ CME 3,669.60 ✓
1	Front headlamp lower bracket	\$ 17 48.70 X
1	Front headlamp spray nozzle pen	\$ 17 254.90 X
1	Front headlamp spray nozzle pen cover	\$ 17 52.00 X
1	Front grille base	\$ 17 291.00 X
1	Front grille chrome moulding	\$ 17 407.90 X
1	Front grille logo	\$ 17 69.80 X
1	Front grille top rubber seal	\$ 17 87.00 X
1	Front bumper	\$ De/warped 847.30 ✓
1	Front bumper clip (1 set)	\$ ME 61.00 ✓
1	Front bumper fog lamp	\$ CME 348.30 ✓
1	Front bumper fog lamp cover	\$ 17 130.90 X
1	Front bumper inner sponge	\$ To. 1 142.50 ✓
1	Front bumper reinforcement	\$ SN 681.70 X
2	Front bumper PDC sensors	\$ SN 507.80 X
1	Front fender -L/H	\$ 1,032.30 X
1	Front fender inner shield	\$ 17 347.10 X
1	Front fender inner shield clip (1 set)	\$ 10 50.00 X
		\$ 9,029.80
	Less 10%	\$ 902.98 4624.25
		\$ 8,126.82 4161.82

S/N	LABOUR CHARGES
1	To check wiring and reset headlamps focussing.
2	To apply undercoating.
3	Panel beating.
4	To re-spray painting on the affected areas.
5	To diagnose erase fault memory after repair.

\$	80.00 20
\$	17 100.00 X
\$	1,400.00 300
\$	1,200.00 400
\$	300.00 50
\$	3,080.00

Zoom Autowerks hereby notify the Repairer of the following:

- To resurvey before/after spray
- To inspect damaged part(s) during resurvey
- Price quoted is subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

PAGE 1 OF 1

\$ 11,206.82