

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SHA 7398G

MAKE :

MODEL : HYUNDAI i40

DATE 8/4/2019 11:54

Left Rear Door

(Su)

| Qty                                                                                                                                                                                                                   | Parts Description/ Labour                                | Type | Unit Price | Amount                          |      |
|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----------------------------------------------------------|------|------------|---------------------------------|------|
|                                                                                                                                                                                                                       | Rear Fender (LH) — <i>Bent</i>                           |      |            | \$ 2,171.40                     |      |
|                                                                                                                                                                                                                       | Rear Fender Inner Lining (LH) <i>X su</i>                |      |            | \$ 169.30                       |      |
|                                                                                                                                                                                                                       | Rear Windscreen Moulding — <i>nee</i>                    |      |            | \$ 28.30                        |      |
|                                                                                                                                                                                                                       | Rear Door (LH) <i>X repair</i>                           |      |            | \$ 2,201.10                     |      |
|                                                                                                                                                                                                                       | Rocker Panel Outer Garnish (LH) — <i>cm</i>              |      |            | \$ 341.40                       |      |
|                                                                                                                                                                                                                       | <b>SUB TOTAL</b>                                         |      |            | <b>\$ 4,911.50</b>              |      |
|                                                                                                                                                                                                                       | <b>LESS 20%</b>                                          |      |            | <b>\$ 982.30</b>                |      |
|                                                                                                                                                                                                                       | <b>DISCOUNTED TOTAL</b>                                  |      |            | <b>\$ 3,929.20</b>              |      |
|                                                                                                                                                                                                                       | Rear Windscreen Sealant — <i>nee</i>                     |      |            | \$ 46.00                        | Nett |
|                                                                                                                                                                                                                       | Rear Door Comfortdelgro & Apps Sticker (LH) — <i>nee</i> |      |            | \$ 80.00                        | Nett |
|                                                                                                                                                                                                                       |                                                          |      |            | <b>\$ 126.00</b>                |      |
|                                                                                                                                                                                                                       | <b>Labour Charge</b>                                     |      |            |                                 |      |
|                                                                                                                                                                                                                       | Panel Beating                                            |      |            | \$ <del>800.00</del> <i>600</i> |      |
|                                                                                                                                                                                                                       | Spray Painting Charge                                    |      |            | \$ <del>900.00</del> <i>600</i> |      |
|                                                                                                                                                                                                                       | Wiring Charge                                            |      |            | \$ <del>50.00</del> <i>X 77</i> |      |
|                                                                                                                                                                                                                       | Tuff Kote                                                |      |            | \$ <del>50.00</del> <i>20</i>   |      |
|                                                                                                                                                                                                                       | Remove/Refix Cushion & Upholstery Rear                   |      |            | \$ <del>150.00</del> <i>50</i>  |      |
|                                                                                                                                                                                                                       | Remove/Refix Rear Windscreen Glass                       |      |            | \$ <del>120.00</del> <i>100</i> |      |
|                                                                                                                                                                                                                       | Remove/Refix Reverse Sensor                              |      |            | \$ <del>80.00</del> <i>X 77</i> |      |
|                                                                                                                                                                                                                       | Transfer of Door                                         |      |            | \$ <del>80.00</del> <i>X 77</i> |      |
|                                                                                                                                                                                                                       | <b>TOTAL LABOUR</b>                                      |      |            | <b>\$ 2,230.00</b>              |      |
|                                                                                                                                                                                                                       | <b>ESTIMATE TOTAL</b>                                    |      |            | <b>\$ 6,285.20</b>              |      |
| <p><i>Ka hui LKK</i></p> <p><i>8/4/19 1340 hr.</i></p> <p><i>4 Days</i></p> <p><i>L/S</i></p> <p><i>After Repair photo</i></p>                                                                                        |                                                          |      |            |                                 |      |
| <p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p> |                                                          |      |            |                                 |      |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- This survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
- is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date: