

REPAIR ESTIMATE*

VEHICLE NO : SHB 4078U

DATE 8/4/2019 10:53

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Bumper Cover — <i>Painted</i>			\$ 544.50	
	Front Bumper Bracket Top (RH) <i>X 54</i>			\$ 22.40	
	Front Bumper Bracket (RH) <i>2 cm</i>			\$ 24.60	
	Front RH Head lamp — <i>cm</i>		<i>\$1388</i>	\$ 591.50	
	Front RH Fender — <i>Painted</i>		<i>\$566.30</i>	\$ 118.30	
	SUB TOTAL			\$ 473.20	
	LESS 20% DISCOUNTED TOTAL				
	Front Fender Advertisement Logo (RH) — <i>all</i>			\$ 100.00	Nett
				\$ 100.00	
	Labour Charge			<i>300</i>	
	Panel Beating-Repair Fender			\$ 400.00	
	Spray Painting Charge			\$ 600.00	<i>400</i>
	Tuff Kote			\$ 50.00	<i>20</i>
	TOTAL LABOUR			\$ 1,050.00	
	ESTIMATE TOTAL			\$ 1,623.20	

Kalam 1/1/14

8/4/19 1400

3 days

4/5

After Repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.