

趙 源 摩 哆 **Chew Goon Motor**

新加坡宏茂桥第 2A 工业园第五道大牌十号门牌十五,十六,十七(一楼)及门牌五(三楼)

Blk 10, Ang Mo Kio Industrial Park 2A, Ave. 5, #01-15, 16, 17 & #03-05, AMK Autopoint

Singapore 568047

Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

TEL: 6484 1626 (24Hrs) FAX: 6484 0465

◀◀ 修理各种汽车敲焊打吗咭喷漆等 ▶▶

MSIG Insurance (S) Pte Ltd

Accident Date : 05.04.2019

12.04.2019

Estimate Cost of Repair "BMW 528I" Reg. No. SKK8318T
Claiming Against Your Insured Veh. No. SGR1894C

	Supplementary	
1pc	Front Headlamp LH (LED)	2210.
1pc	Front Bumper Air Lower Duct	
	Less 10%	

Grand Total :

CM	2,790.00	✓
RM	62.00	✓
	2,852.00	
	285.20	
	2,566.80	
	<u>2,566.80</u>	