

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No.: 6287 6666 Fax No.: 6257 1330

CO./GST Reg. No. 201019626G

SHC 5183L

AAD1904-058

*Not Authored
L1 Pay @ 4500/*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

SHC 5183L

VF1ABL15AUC276748

RENAULT

LATITUDE

5.4.2019

III

14/1/2014

PART**LIST**

1	DOOR PANEL REAR RH	\$	<i>R</i> 2,844.66
1	DOOR GUIDE REAR RH	\$	<i>Sm</i> 176.82
1	DOOR HINGE UPPER RH	\$	<i>R</i> 274.50
1	DOOR HINGE LOWER RH	\$	<i>R</i> 300.55
1	DOOR CHECK REAR LH/RH L70Y	\$	<i>Sm</i> 203.06
1	DOOR LOCK REAR RH	\$	<i>R</i> 908.75
1	DOOR HANDLE OUTER REAR RH	\$	<i>Sm</i> 126.49
1	DOOR HANDLE CAP REAR RH	\$	<i>Sm</i> 35.52
1	DOOR HANDLE SEAL REAR RH	\$	<i>Sm</i> 7.89
1	DOOR HANDLE COVER REAR RH	\$	<i>Sm</i> 13.22
1	DOOR HANDLE MODULE REAR RH	\$	<i>Sm</i> 133.60
1	DOOR REGULATOR REAR RH	\$	<i>R</i> 1,135.10
1	DOOR REGULATOR MOTOR REAR RH	\$	<i>Sm</i> 893.75
1	DOOR REGULATOR NUT REAR L70Y	\$	<i>Sm</i> 12.43
1	DOOR REGULATOR MOTOR SCREW REAR L70Y	\$	<i>Sm</i> 6.31
1	DOOR FINISHER REAR RH	\$	<i>Sm</i> 423.10
1	DOOR MOULDING REAR RH	\$	<i>Sm</i> 176.82
1	DOOR MOULDING CLIP L70Y	\$	<i>nn</i> 5.92
1	DOOR MOULDING SCREW L70Y	\$	<i>nn</i> 6.91
1	DOOR CASING REAR RH	\$	<i>Sm</i> 1,509.06
1	DOOR WATER SHIELD REAR RH	\$	<i>Sm</i> 30.39
1	DOOR CASING CLIP	\$	<i>nn</i> 12.63
1	DOOR CASING LIGHT L70Y	\$	<i>Sm</i> 48.74
1	DOOR FINISHER INNER REAR RH	\$	<i>Sm</i> 323.44
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>R</i> 46.97
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>R</i> 20.33
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>R</i> 20.33
1	DOOR FINISHER BRACKET INNER REAR RH	\$	<i>R</i> 20.33
1	DOOR GRAB HANDLE REAR RH	\$	<i>Sm</i> 210.96

X

Trans-cab Auto Services Pte Ltd

AAD1904-058

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5183L

1	DOOR BLIND REAR RH	\$	<i>Sm</i>	741.80	X
1	DOOR WHEATHESTRIP REAR RH	\$	<i>Sm</i>	410.66	X
1	DOOR SEAL REAR RH	\$	<i>Sm</i>	162.02	X
1	DOOR GLASS RUNNER SEAL REAR RH	\$	<i>Sm</i>	229.31	X
1	DOOR WAIST SEAL OUTER REAR RH	\$	<i>Sm</i>	334.69	X
1	DOOR WAIST SEAL INNER REAR RH	\$	<i>Sm</i>	115.64	X
1	FENDER PANEL REAR RH	\$	<i>Bu</i>	3,299.13	✓
1	FENDER PANEL INNER TRIM REAR	\$	<i>Sm</i>	671.45	X
1	WHEELARCH REAR RH	\$	<i>Sm</i>	543.47	X
1	BUMPER COVER REAR	\$	<i>Bu</i>	1,108.46	✓
		\$		17,545.20	
		10% \$		1,754.52	
		\$		15,790.68	

Special Nett

1	REAR DOOR STICKER '6555-3333"	\$	<i>nu</i>	80.00	<i>base</i>
1	DOOR CHECK BOLT	\$	<i>nu</i>	22.69	} X
1	DOOR GUIDE SCREW	\$	<i>nu</i>	10.85	
1	DOOR HINGE BOLT	\$	<i>nu</i>	10.85	
1	DOOR HINGE NUT RH	\$	<i>nu</i>	14.60	
1	DOOR CHECK BOLT	\$	<i>Sm</i>	22.69	
1	DOOR CHECK NUT	\$	<i>Sm</i>	3.75	
1	DOOR LOCK SCREW L70Y	\$	<i>Sm</i>	6.12	
1	DOOR CATCH SCREW L70Y	\$	<i>Sm</i>	10.06	
	TOTAL	\$		181.63	
	TOTAL PARTS	\$		15,972.31	

LABOUR

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	3,000.00	<i>8001</i>
Putty and spray painting of the affected portion.	\$	3,000.00	<i>8601</i>

Trans-cab Auto Services Pte Ltd

AAD1904-058

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC 5183L

To rust-proofing of the affected areas.	\$	170.00	30%
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	100%
To check steering geometry and computer wheel alignment	\$	na 220.00	X
To transfer of tire, rim and on wheel balancing.	\$	na 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	20%
To transfer of front fender fittings, attachment and perform water seepage test.	\$	na 380.00	X
To transfer of front door fittings, attachment and perform water seepage test.	\$	na 380.00	X
To transfer of Rear door fittings, attachment and perform water seepage test.	\$	na 380.00	X
To transfer of Rear fender fittings, attachment and perform water seepage test.	\$	na 380.00	X

TOTAL \$ 8,630.00

Over All Total \$ 24,602.31

LUMP SUM (REPAIR DAY)

10 DAYS

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: