



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKK8423Y

Tan Hwee Leng (chen Huiling)

37A Surin Avenue
Singapore 535628

Mobile: 90610093

Vehicle & Document Information

WIP No 32382
Reg No/Reg Date SKK8423Y / 29/03/2012
Date In/Mileage 1 / 0
Chassis No WDD2120472A578180
Engine No 27186030419067
Make/Model MB/E 250 CGI SEDAN (W212)
Colour/Trim 027 755 Tenorite Gr/ 042 Leather Black/C

| Account No | Terms | Date/Time Printed | CSE | Operator |
|------------|-------|-------------------|-----|--------------------|
| CS100001 | Cash | 08/04/2019/ 16:33 | | 356 / Vincent Seah |

| Description of Goods / Services | Qty | Unit Price | Disc% | Amount |
|---|------|------------|-------|-------------|
| M BPNSUN POLICY NO/ACC DATE : 29009811QMY // 07.04.19 DRIVE IN/EXCESS : 08.04.19 // TP CAR NO YP6526H=AXA INS DATE IN/DATE SURVEY: 08.04.19 // BY/AUTHORIZED ON : | | | | |
| A BPILAB "USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT" | | | 0.10 | 380.00 |
| A BPILAB REMOVE & REPLACE ON REAR BUMPER | | | | 960 1200.00 |
| A BPIRES RESPRAY ON REAR BUMPER | | | | 600 1200.00 |
| M REAR BUMPER | 1.00 | 1634.76 | 00.00 | 1634.76 |
| M LEFT REAR BUMPER CHROME MOULDING | 1.00 | 132.65 | 00.00 | 132.65 |
| M RIGHT REAR BUMPER CHROME MOULDING | 1.00 | 132.65 | 00.00 | 132.65 |
| M REAR LOWER BUMPER | 1.00 | 531.91 | 00.00 | 531.91 |
| M RIGHT REAR TAIL PIPE SUPPORT | 1.00 | 72.83 | 00.00 | 72.83 |
| M RIGHT BOTTOM BRACKET | 1.00 | 16.75 | 00.00 | 16.75 |
| M TOW CAP | 1.00 | 81.09 | 00.00 | 81.09 |
| M RIGHT REAR BUMPER SUPPORT | 1.00 | 70.54 | 00.00 | 70.54 |
| M REAR BUMPER CENTRE CHROME MOULDING | 1.00 | 178.58 | 00.00 | 178.58 |
| M REAR CROSS MEMBER | 1.00 | 817.08 | 00.00 | 817.08 |

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Confirmed & accepted by

Acknowledged by Repairer

Signature:

Date:

Authorized signatory and company stamp

7% GST on Net 6,448.84
451.42

Total Payable 6,900.26

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SKK8423Y

Tan Hwee Leng (chen Hailing)

37A Surin Avenue
Singapore 535628

Vehicle & Document Information

WIP No 32382
Reg No/Reg Date SKK8423Y / 29/03/2012
Date In/Mileage 15/04/2019/ 90041
Chassis No WDD2120472A578180
Engine No 27186030419067
Make/Model MB/E 250 CGI SEDAN (W212)
Colour/Trim 027 755 Tenorite Gr/ 042 Leather Black/C

| Account No | Terms | Date/Time Printed | CSE | Operator |
|------------|-------|-------------------|-----|--------------------|
| CSI00001 | Cash | 23/04/2019/ 11:39 | VS | 356 / Vincent Seah |

| Description of Goods / Services | Qty | Unit Price | Disc% | Amount |
|---------------------------------|-----|------------|-------|--------|
|---------------------------------|-----|------------|-------|--------|

M. BPNSUN

POLICY NO/ACC DATE : 29009811QMY // 07.04.19
DRIVE IN/EXCESS : 08.04.19 // TP CAR NO YP6526H-AXA INS
DATE IN/DATE SURVEY: 08.04.19 // 15.04.19 15:45PM RASUL-LKK
DIRECT SETTLEMENT: ASHER SNG-LKK

A BPILAB

"USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO
STANDARD SETTINGS.NETT"

A BPILAB

REMOVE & REPLACE ON REAR BUMPER

A BPIRES

RESPRAY ON REAR BUMPER

X REAR BUMPER

X LEFT REAR BUMPER CHROME MOULDING

X RIGHT REAR BUMPER CHROME MOULDING

X REAR LOWER BUMPER

X REAR BUMPER CENTRE CHROME MOULDING

0.10 380.00✓

960.00✓

600.00✓

1.00 1634.76 00.00 1634.76✓

1.00 132.65 00.00 132.65✓

1.00 132.65 00.00 132.65✓

1.00 531.91 00.00 531.91✓

1.00 178.58 00.00 178.58✓

Finalization

3 days

Confirmed & accepted by

7% GST on 4550.55
Total Payable 4,869.09

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg