

BMW Dealer

Performance Motors Limited

A Sime Darby Motors Company
 Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
 Toll-Free Number (1800-2255269)

303, Alexandra Road
 Sime Darby Performance Centre
 Singapore 159941
 Fax. 64747770

280, Kampong Arang Road
 East Coast Centre
 Singapore 438180
 Fax. 63449773

315, Alexandra Road
 Sime Darby Business Centre
 Singapore 159944
 Fax. 64796601 (AfterSales)
 64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

09 APR 2019

Estimate No. : b1 50786
 Date Estimated : 08/04/2019
 Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -

Saw Toong Yau
 32 Segar Road
 #01-24 Blossom Residence
 Singapore 677722

- ACCOUNT - 121

AIG Asia Pacific Insurance Pte. Ltd.
 78 Shenton Way
 #08-16 Chartis Building
 Singapore 079120

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLR4428L	0S48082	27/12/2017	X4 xDrive 28i	0

DESCRIPTION

To replace rear bumper, reinforcement & all attachment
 cause by accident.

VALUE
~~850~~ 1,700.00

Painting on rear bumper panel

~~938~~ 1,038.00

To check electrical wiring systems at the rear section
 for proper function.

~~150~~ 177.00

Sundries.

~~?~~ 80.00

Total Labour 1: 2,995.00

DESCRIPTION

RR BUMPER CARRIER ECE ?
 RR BUMPER LH MOUNTING MIDDLE ?
 RR BUMPER RH MOUNTING MIDDLE ? } Xnn
 RR BUMPER LH MOUNT ?
 RR BUMPER RH MOUNT ?
 COVER MIDDLE BOTTOM (M) sur-
 REAR BUMPER PANEL PRIMED (M) DE-
 REAR BUMPER PANEL BOTTOM PRIMED (M) sur-
 RR BUMPER TOWING EYE FLAP PRIMED (M) mcs-
 ULTRASONIC TRANSDUCER DARK SHADOW ? Xnn
 DECOUPING RING PDC TORQUE CONVERTER DE-

QTY	PRIC	VALUE
1	797.80	797.80
1	137.75	137.75
1	137.75	137.75
1	192.15	192.15
1	198.30	198.30
1	92.30	92.30
1	1,805.65	1,805.65
1	379.20	379.20
1	51.95	51.95
1	368.80	368.80
4	5.05	20.20

Total Parts : 4,181.85

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax: 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax: 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax: 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 50786
Date Estimated : 08/04/2019
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLR4428L	0S48082	27/12/2017	X4 xDrive 28i	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement	
Regn No. _____	Claim No. _____
Date&Time <u>29/04/19 @ 1530</u>	Excess S\$ _____
Surveyor's Name <u>RASUL</u>	Sign _____
Surveyor's Tel <u>90010068</u>	Authorised Yes / No _____
Authorised Date _____	Time _____
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No _____ PML Yes / No _____	
Surveyor's E-mail _____	
No. of Working Days Recommend <u>3 days</u>	

Labour 1	:	2,995.00
Parts	:	4,181.85
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	502.38
Grand Total	:	<u>7,679.23</u>

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 50786
Date Estimated : 08/04/2019
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Saw Toong Yau
32 Segar Road
#01-24 Blossom Residence

Singapore 677722

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN.NO.	CHASSIS NO.	REGN.DATE	MODEL	MILEAGE
SLR4428L	0S48082	27/12/2017	X4 xDrive 28i	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments include knocking out dents caused by accident	850.00		850.00
To spray paint rear bumper	934.00		934.00
To check electrical wiring systems at the rear section for proper function	150.00		150.00
Sundries	80.00		80.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
COVER MIDDLE BOTTOM (M)	92.30	1.00		92.30
REAR BUMPER PANEL PRIMED (M)	1,805.65	1.00		1,805.65
REAR BUMPER PANEL BOTTOM PRIMED (M)	379.20	1.00		379.20
RR BUMPER TOWING EYE FLAP PRIMED (M)	51.95	1.00		51.95
# EXPANDING RIVET *	1.35	10.00		13.50
DECOUPING RING PDC TORQUE CONVERTER	5.05	4.00		20.20

SUPPLEMENTARY ITEMS

Total Labour :	2,014.00
Total Parts :	2,362.80
Total Labour & Parts :	4,376.80
Deduction for Excess :	
Total Repair Costs less Excess:	4,376.80
GST @7%:	306.38
Grand Total :	4,683.18

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 50786
Date Estimated : 08/04/2019
Prepared By : Kevin Leong Wai Kit

Page No.:

REPAIR FOR -
Saw Toong Yau
32 Segar Road
#01-24 Blossom Residence

Singapore 677722

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

REGN.NO.	CHASSIS NO.	REGN.DATE	MODEL	MLEAGE
SLR4428L	0S48082	27/12/2017	X4 xDrive 28i	0
DESCRIPTION				
ORIGINAL PRICE				
DISC. %				
NETT				
DESCRIPTION				
UNIT PRICE				
QTY				
DISC. %				
NETT				
# EXPANDING RIVET * <i>rec</i> ✓				
1.35				
10.00				
13.50				

Total Labour :
Total Parts : 13.50
Total Labour & Parts : 13.50