

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

Telefax

Estimate : Accident Repairs
Workshop : Ubi Road 1
Contact No : 6366 2323
Fax No : 6841 1183
Reference : PA/TP/0457/2019/DY
Date : 9-Apr-19

Vehicle NOT IN workshop. Kindly arrange for survey.

Your insured vehicle no : SKP 8215 E

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Owner's Name : Mr. Wong Kar Kean
Address : 20A Sea Avenue
Singapore 424241
Telephone : 90690132
Type of Claim : Third Party Claim
Policy No. :
Vehicle No : **SKX 9556 Y**
Model Code : Q3 1.4 TFSI S tronic
Model / Year : 31/12/2015
Engine No : CZD 217575
Chassis No : WAUZZZ8U7GR041155
Mileage :
Date In :
Liability : -
Excess Cost : -
Estimated By : Johnny Boo / Allan Wu
Accident Date : 8-Apr-19
Place of Accident : Central Boulevard Road

Premium Automobiles

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Telefax

Estimated Labour Charges for Accident Vehicle SKX 9556 Y

| S/n | Nature of Jobs | Estimated Charges | Surveyor's Recommendation |
|----------------------|---|----------------------------|---------------------------|
| 1 | To remove and reinstall rear parking aid. Check function and renew according to damage. | s/n \$ 280.00 ✓ | |
| 2 | To dismantle and renew rear bumper. Re-organise crash management components. Reinstall all parts removed. ✓ ✕ | \$ 1,050.00 500 | |
| 3 | To respray rear bumper, rear bumper spoiler and both rear wheel arch trims. ✕ | \$ 2,500.00 550 | |
| 4 | To carry out diagnostic check. | s/n \$ 192.00 ✓ | |
| TOTAL LABOUR CHARGES | | : \$ 4,022.00 | |

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax**Material List for Accident Vehicle Regn No. SKX 9556 Y**

| S/N | Parts Description | Damaged Parts & Prices | |
|-----|--|------------------------|--------|
| | | S/Nett | Remark |
| 1 | REAR BUMPER COVER <i>RW</i> | \$ 1,238.00 | + |
| 2 | REAR BUMPER FIXING PARTS <i>Ren</i> | \$ 104.00 | + |
| 3 | REAR BUMPER SPOILER <i>at</i> | \$ 716.00 | ✓ |
| 4 | REAR DIFFUSER - LH <i>at</i> | \$ 572.00 | ✓ |
| 5 | COVER FOR TOWING EYE - LH <i>3 new</i> | \$ 21.00 | + |
| 6 | COVER FOR TOWING EYE - RH | \$ 21.00 | + |
| 7 | TAIL LIGHT - RH <i>new</i> | \$ 387.00 | + |
| 8 | REAR BUMPER CARRIER <i>2</i> | \$ 525.00 | + |
| 9 | REAR PARKING SENSOR <i>3 new</i> | 2 \$ 415.00 | + |
| 10 | SEAL RING | 4 \$ 5.00 | + |
| 11 | REAR WHEEL COVER - LH <i>3 new</i> | \$ 453.00 | ✓ |
| 12 | REAR WHEEL COVER - RH | \$ 453.00 | ✓ |
| 13 | SUNDRIES ? | \$ 500.00 | ? |
| 14 | | | |
| 15 | | | |
| 16 | | | |
| 17 | | | |
| 18 | | | |
| 19 | | | |
| 20 | | | |

| | | |
|----------------------|---|--------------|
| TOTAL SPARE PARTS | : | \$ 17,431.00 |
| TOTAL LABOUR CHARGES | : | \$ 4,152.00 |
| GRAND TOTAL | : | \$ 21,583.00 |

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved
Spare parts are Special Nett.

Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Telefax

Name : Adrian King
Surveyed Date : 17/04/19.
Authorised Date :
Excess Cost :
Liability :
Remarks : Not Authorised, 03 Days.

Please Note : This estimate is based on visual inspection of the affected vehicle.
Should we require further labour charges and spare parts in the progress of repair, we shall inform you accordingly.
For inspection of vehicle, please refer to Ms Norah Khai at
Tel:6768 9828 for appointment.

Yours faithfully,
Premium Automobiles Pte Ltd

Johnny Boo
Body Repair Manager

Allan Wu
Claims Consultant