

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg

## Telefax

**Estimate** : Accident Repairs  
**Workshop** : Ubi Road 1  
**Contact No** : 6366 2323  
**Fax No** : 6841 1183  
**Reference** : PA/TP/0457/2019/DY  
**Date** : 9-Apr-19

**Vehicle NOT IN workshop. Kindly arrange for survey.**

**Your insured vehicle no : SKP 8215 E**

## AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

**Attn: Mr. Adrian Ling - Motor Claims Dept**

**Tel: 6841 0055 - Fax: 6256 4315**

**Owner's Name** : Mr. Wong Kar Kean  
**Address** : 20A Sea Avenue  
Singapore 424241  
**Telephone** : 90690132  
**Type of Claim** : Third Party Claim  
**Policy No.** :  
**Vehicle No** : **SKX 9556 Y**  
**Model Code** : Q3 1.4 TFSI S tronic  
**Model / Year** : 31/12/2015  
**Engine No** : CZD 217575  
**Chassis No** : WAUZZZ8U7GR041155  
**Mileage** :  
**Date In** :  
**Liability** : -  
**Excess Cost** : -  
**Estimated By** : Johnny Boo / Allan Wu  
**Accident Date** : 8-Apr-19  
**Place of Accident** : Central Boulevard Road

# Premium Automobiles

55 Ubi Road 1, Singapore 408699  
Tel : 6366 2323 Fax : 6841 1183

## Telefax

### Estimated Labour Charges for Accident Vehicle SKX 9556 Y

S/n	Nature of Jobs		Estimated Charges	Surveyor's Recommendation
1	To remove and reinstall rear parking aid. Check function and renew according to damage.	s/n	\$ 280.00	
2	To dismantle and renew rear bumper. Re-organise crash management components. Reinstall all parts removed.		\$ 1,050.00	
3	To respray rear bumper, rear bumper spoiler and both rear wheel arch trims.		\$ 2,500.00	
4	To carry out diagnostic check.	s/n	\$ 192.00	
TOTAL LABOUR CHARGES		:	<u>\$ 4,022.00</u>	

**Premium Automobiles**

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

**Telefax****Material List for Accident Vehicle Regn No. SKX 9556 Y**

S/N	Parts Description	<b><u>Damaged Parts &amp; Prices</u></b>	
		<b>S/Nett</b>	<b>Remark</b>
1	REAR BUMPER COVER	\$ 1,238.00	
2	REAR BUMPER FIXING PARTS	\$ 104.00	
3	REAR BUMPER SPOILER	\$ 716.00	
4	REAR DIFFUSER - LH	\$ 572.00	
5	COVER FOR TOWING EYE - LH	\$ 21.00	
6	COVER FOR TOWING EYE - RH	\$ 21.00	
7	TAIL LIGHT - RH	\$ 387.00	
8	REAR BUMPER CARRIER	\$ 525.00	
9	REAR PARKING SENSOR	2 \$ 415.00	
10	SEAL RING	4 \$ 5.00	
11	REAR WHEEL COVER - LH	\$ 453.00	
12	REAR WHEEL COVER - RH	\$ 453.00	
13	SUNDRIES	\$ 500.00	
14			
15			
16			
17			
18			
19			
20			

<b>TOTAL SPARE PARTS</b>	:	<b>\$ 17,431.00</b>
<b>TOTAL LABOUR CHARGES</b>	:	<b>\$ 4,152.00</b>
<b>GRAND TOTAL</b>	:	<b>\$ 21,583.00</b>

All charges are not inclusive of GST.

Legend : Remarks (OK) = Approved, Remarks (X) = Not approved

Spare parts are Special Nett.

# Premium Automobiles

55 Ubi Road 1, Singapore 408699

Tel : 6366 2323 Fax : 6841 1183

## Telefax

**Name** :  
**Surveyed Date** :  
**Authorised Date** :  
**Excess Cost** :  
**Liability** :  
**Remarks** :

**Please Note** : This estimate is based on visual inspection of the affected vehicle.  
Should we require further labour charges and spare parts in the  
progress of repair, we shall inform you accordingly.  
For inspection of vehicle, please refer to Ms Norah Khai at  
Tel:6768 9828 for appointment.

Yours faithfully,  
Premium Automobiles Pte Ltd

Johnny Boo  
Body Repair Manager

Allan Wu  
Claims Consultant