



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTOMOTIVE ENGINEERING & MGT DIVISION		Ref : CS/SPF19006284/Ksd3s2		
ACCIDENT CLAIM SECTION (SPORE POLICE FORCE) 1 MOUNT PLEASANT ROAD BLK 8 OLD POLICE ACADEMYSINGAPORE 298333 ATTN: ABDUL RAHMAN		Date : 27-06-2019		
		Code : SPF		
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	GBC 1104M	Veh. Inspected	SKU 1045Z	
Policy No.		Coverage (\$)	0.00	
Claim No.	AEMD/105/009/2019/024	Excess (\$)	0.00	
Assign From	ABDUL RAHMAN	Assign Date	09/04/2019	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	MAZDA 3 (A)	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	JM6BM42A8G0311095	Colour	METALLIC DARK BLUE	
Odometer	30312	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	205/60R16	BRIDGESTONE	4 mm	
L/H Front Tyre	205/60R16	BRIDGESTONE	4 mm	
R/H Rear Tyre	205/60R16	BRIDGESTONE	8 mm	
L/H Rear Tyre	205/60R16	BRIDGESTONE	8 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	29/03/2019	Inspection Date	09/04/2019	
Survey held at	160 SIN MING DRIVE #02-04			
Repairer	CAR TIMES AUTOLUTION PTE LTD			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:		<b>3 Working Days</b>		