

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

Registration No : SFL484C

Chassis No : MRHFC5650HT000139

Model : CIVIC 1.6 VTI YM2017

Owner's Name : TAN KIEN WAH

Ins Policy No. :

Date of Accident : 7/4/2019

Document No. : SQT19001577 **Page** 2

Date : 8. Apr 2019

Customer No. : WZC008

Svc Advisor : ANIKKA LAI SWEE KAM

Engine No : R16B22000237

Date | Time : 8. Apr 2019 3:48:05 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
72430-TEA-T01	GARNISH ASSYR.FR.DOOR SASH <i>hec ✓</i>	1	13.70	15	11.64	0.81	12.45
76208-TEA-T02	MIRROR ASSY,R. <i>mis ✓</i>	1	254.30	15	216.15	15.13	231.28
72235-TEA-T02	RUNCHANNEL,R.FR.DOOR <i>? X nn ✓</i>	1	79.90	15	67.91	4.75	72.66
72210-TEA-T01	REGULATOR ASSYR.FR.DOOR <i>? ✓ BT</i>	1	90.30	15	76.75	5.37	82.12
72142-TBA-A71	BASE COMPR.FR. <i>hec ✓</i>	1	20.70	15	17.59	1.23	18.82
94050-06080	NUT FLANGE <i>hec X nn ✓</i>	1	0.50	15	0.42	0.03	0.45
72133-TBA-A01	CABLEFR.DOOR LOCK <i>? X nn ✓</i>	1	4.20	15	3.57	0.25	3.82
72147-TEA-T01ZP	COVERR.FR.BASE <i>? X nn ✓</i>	1	2.40	15	2.04	0.14	2.18
73300-TS4-Q01	GLASS ASSYR.FR.DOOR <i>CRA ✓</i>	1	349.30	15	296.90	20.78	317.68
67510-TEA-T00ZZ	PANELR.RR.DOOR <i>BVC ✓</i>	1	717.50	15	609.87	42.69	652.56
72810-TEA-T01	WEATHERSTRIP,R.RR.DOOR <i>hec ✓</i>	1	96.40	15	81.94	5.74	87.68
72828-TEA-T01	SEALRR.DOOR LOWER <i>hec X nn ✓</i>	1	6.20	15	5.27	0.37	5.64
72910-TEA-T01	MOLDING ASSYR.RR.DOOR <i>hec ✓</i>	1	25.20	15	21.42	1.50	22.92
72925-TEA-T01	MOLDING ASSY,R.RR.DRINNER <i>hec ✓</i>	1	29.20	15	24.82	1.74	26.56
72930-TEA-T01	GARNISH ASSYR.RR.DOOR SASH <i>hec ✓</i>	1	28.30	15	24.05	1.68	25.73
04635-TEA-T00ZZ	PANELR.FR.OUTSIDE <i>BVC X nn ✓</i>	1	711.60	15	604.86	42.34	647.20
04636-TEA-T00ZZ	PANEL SETR.RR.OUTSIDE <i>BVC ✓</i>	1	711.60	15	604.86	42.34	647.20
71800-TEA-T01ZB	GARNISH ASSYR.SIDE SILL <i>Repa X ✓</i>	1	117.80	15	100.13	7.01	107.14
42700-TEA-T61	DISKALUMINIUM WHEEL <i>SCR ✓</i>	2	297.80	15	506.26	35.44	541.70
44305-TEA-T01	DRIVESHAFT ASSY,R. <i>? X ✓</i>	1	927.90	15	788.71	55.21	843.92
51211-TEA-T10	KNUCKLER.FR. <i>? X } nn ✓</i>	1	141.10	15	119.93	8.40	128.33
51300-TEA-T01	STABILIZER COMPFR. <i>? X } nn ✓</i>	1	141.10	15	119.93	8.40	128.33
51350-TEA-T00	ARM COMPR.FR.LOWER <i>? X } nn ✓</i>	1	215.40	15	183.09	12.82	195.91
51320-TBA-A02	LINK COMP,FR.STABILIZER <i>? X } nn ✓</i>	1	21.70	15	18.44	1.29	19.73
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER <i>DEF ✓</i>	1	617.20	15	524.62	36.72	561.34
71593-TEA-T01	SPACERR.RR.BUMPER SIDE <i>hec ✓</i>	1	10.50	15	9.77	0.68	10.45
71598-TEA-T01	SPACERL.RR.BUMPER SIDE <i>hec ✓</i>	1	11.50	15	9.77	0.68	10.45
91505-TM8-003	CLIP,BUMPER <i>hec ✓</i>	22	2.30	15	43.01	3.01	46.02
71505-TBA-A00	BRACKETR.RR.BUMPER SIDE <i>hec ✓</i>	1	2.30	15	1.95	0.14	2.09

Printed on 8/4/2019 7:32:21 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.