

ASSIGNMENT

REF: CS/MC 19006301 / T19d32

Special Instruction:

Surveyor

Taukiah

ASSIGNMENT (Office)

From (Person)

Annie Koh

of

INC

Date/Time:

9/4/19 @ 9-24am

Estimated Cost:

Bill to:

OD / IT

WS / TR

RES /

OD

RES /

EVA /

INV /

MV

7CS

To Inspect Vehicle No:

8MC 166K

Insured:

SLQ 4302X

at Workshop no:

BP Auto

Tel:

6266 0555

of

48 Joh Gwan Rd East #01-121

Policy No:

Claim No:

M7/1039006-002

Sum Insured:

Process:

Make of Vch:

(Client's Record)

D.O.A

4/4/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement

Date/Time:

1017am @ 9/4/19

Person Contacted:

Yunne

Vehicle:

IT / OTR

Date/Time

Action/Instruction

(✓)

Estimate

SMC 166K - MBA / FWD 1900609414

D.O.A - 4/4/2019

SLQ 4302X - MBA. / FWD 1900609414

D.O.A - 4/4/2019

534

2008: Feb

Rebate \$19,911

Learn More 

78

1570

240

290

RECEIVED 30 JUL 2019

Circumstance of Accident

ON 5.4.08 AT 7.10PM, I WAS DRIVING ALONG ANG MO KIO AVE 6 TOWARDS YISHUN, ON REACHING ANG MO KIO AVE 5 TRAFFIC JUNCTION, MY FRONT VEHICLE STOPPED DUE TO RED LIGHT I LIKEWISE STOPPED MY VEHICLE AND AT THIS JUNCTION. I FELT A GREAT IMPACT FROM MY REAR AND LATER NOTICED THAT GY 6236H HAD COLLIDED ONTO MY REAR PORTION.

STATEMENT RECORDED BY CHONGMENG

(IDAC PAYA UBI TEL NO: 6841 0055)

DETAILS OF OTHER VEHICLE(S) / PROPERTIES

Vehicle Registration Number	GY6236H
Details of Properties	
Vehicle Make / Model / Colour	RENAULT KANGOO
Name of Driver	LIM TOW YONG, KEVIN
NRIC/Passport Number	S7230506Z
Contact Number	
Address	
Insurance Company Name	

Details Of Witness

Name
Phone Number

Nivitha (LKK Auto)

From: Annie Koh <annie.koh@income.com.sg>
Sent: Tuesday, 9 April 2019 1:48 PM
To: 'assignments@lkkauto.com'
Subject: RE: TP CASES FARMED OUT TO LKK ON 09/04/2019

Hi LKK,

Please take note of the OIC and claim number for GBE6149R and SLK9014B.

1	FIONA SHEN	MT/0954065-002	GBE6149R	SIN SHENG ENGINEERING SERVICES	3 TECH PARK CRESCENT TUAS TECH PARK SINGAPORE 638129	Susan / 6863 9595		FBB4174X	15/7/17
5	JARED LIU	MT/1033601-002	SLK9014B	WORLD AUTO PTE LTD	1 KRANJI LOOP SINGAPORE 739535	Daniel / 63621776		SLC4150R	25/2/19

Warmest Regards

Annie Koh
Senior Admin,
Motor Insurance
T +65 64307899
www.income.com.sg



From: Annie Koh
Sent: Tuesday, 9 April 2019 10:44 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Subject: RE: TP CASES FARMED OUT TO LKK ON 09/04/2019

Re-send

Warmest Regards

Annie Koh
Senior Admin,
Motor Insurance
T +65 64307899
www.income.com.sg



Nivitha (LKK Auto)

From: Annie Koh <annie.koh@income.com.sg>
Sent: Tuesday, 9 April 2019 2:20 PM
To: Admin-D (LKKAuto); assignments
Cc: SUR
Subject: RE: TP CASES FARMED OUT TO LKK ON 09/04/2019

Hi LKK,

Please take note of the OIC and claim number for PA8482U**

4	SERENE LIM	MT/1039440-001	PA8482U	CONNECT 3	566 WOODLANDS ROAD (MANDAI ESTATE)	Winnie Chai / 9850-9666	14:00- 16:00
---	---------------	----------------	---------	-----------	--	----------------------------	-----------------

Warmest Regards

Annie Koh
Senior Admin,
Motor Insurance
T+65 64307899
www.income.com.sg



From: Admin-D (LKKAuto) [mailto:admin-d@lkkauto.com]
Sent: Tuesday, 9 April 2019 2:01 PM
To: Annie Koh <annie.koh@income.com.sg>; assignments <assignments@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; SUR <sur@lkkauto.com>; Teng Ken Leong <kenleong.teng@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 09/04/2019

Dear Annie,

Thank you for the assignment.

Please be informed that PA8482U (Connect 3) is not in the workshop, repairer arrange on 10/04/2019.

Best Regards,

G.Nivitha Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Annie Koh
Sent: Tuesday, 9 April 2019 9:24 AM
To: 'assignments@lkkauto.com' <assignments@lkkauto.com>
Cc: Thio Tse Kiat <tsekiat.thio@income.com.sg>; Teng Ken Leong <kenleong.teng@income.com.sg>
Subject: RE: TP CASES FARMED OUT TO LKK ON 09/04/2019

Dear LKK,

Please assist to survey the following vehicles as per Mr Teng's instruction :-

SN	OIC	Claim No.	Vehicle	WorkShop Name	WorkShop Address	WorkShop Contact	Survey Time	DI VEH	DOA
1		PENDING ADVISE	GBE6149R	SIN SHENG ENGINEERING SERVICES	3 TECH PARK CRESCENT TUAS TECH PARK SINGAPORE 638129	Susan / 6863 9595		FBB4174X	15/7/17
2	AZHARI	MT/1039198-002	SLC6230E	VERMOGEN ACE PTE LTD	6 BENOI ROAD, SINGAPORE 629904	Pila / 6358 3031		SGY3323J	5/4/19
3	DAVID PHUA	MT/1039006-002	SMC166K	BP AUTO	48 TOH GUAN ROAD EAST #01-121 ENTERPRISE HUB SINGAPORE 608586	/ 6266 0555		SLQ4302X	4/4/19
4		PENDING ADVISE	PA8482U	CONNECT 3	566 WOODLANDS ROAD (MANDAI ESTATE)	Winnie Chai / 9850-9666	14:00-16:00	FBN5354Z	22/3/19
5		PENDING ADVISE	SLK9014B	WORLD AUTO PTE LTD	1 KRANJI LOOP SINGAPORE 739535	Daniel / 63621776		SLC4150R	25/2/19

Please contact workshops.

Please revert to officer-in-charge after survey.

Thank you.

Annie Koh
 Senior Admin Assistant, Motor Insurance
 T+65 6430 7899
www.income.com.sg



Disclaimer

This e-mail contains privileged or confidential information which is intended only for the use of the recipient(s) named above. If you have received this message in error, please notify the sender immediately and delete all copies of it. Thank you.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 05/04/2019 17:46
 Date Of Accident 04/04/2019 20:25
 Exact Location Of Accident AYE (TUAS) AFTER BUONA VISTA EXIT
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMC166K
Insured/Policyholder
 Name Of Registered Owner TAN JI PUNG, GILBERT (CHEN JIPENG)
 NRIC No S8711714F
 Email Address BERT.87@GMAIL.COM
 Mobile Phone No (LOCAL) +65-88580698
 Alternative Phone No OTHERS-88580698

Vehicle Particulars

Manufacturer TOYOTA
 Model CAMRY
 Exact Purpose for which vehicle was being used at time of accident PRIVATE USE
 Are you claiming under your own insurance policy for repair to your vehicle? NO
 If No, Please state action to be taken THIRD PARTY
 Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company FWD SINGAPORE PTE. LTD.
 Type Of Coverage COMPREHENSIVE
 Fleet Policy NO
 Policy Number PNPV2019-00001768
 Cover Note Number

Driver

Name of Driver TAN JI PUNG, GILBERT (CHEN JIPENG)
 NRIC No S8711714F
 Date Of Birth 02/05/1987
 Occupation OUTDOOR
 Date Of Driving Pass 06/04/2009
 Driving Experience 9 YEARS AND 11 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-88580698
 Fax Number
 Contact Number OTHERS-88580698
 EMail Address BERT.87@GMAIL.COM

Address	BLK 690 JURONG WEST CENTRAL #07-205
Postcode	640690
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	9
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : LEONG JIA SIN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	CLEMENTI POLICE DIVISIONAL HQ (D DIVISION)
Police Station Address	ROAD: 20 CLEMENTI AVENUE 5 , POSTCODE: 129858 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-7740000 - FAX NO: 67741705
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER TO SKETCH AND POLICE REPORT D/2019405/7009

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLQ4302X
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	

Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SKW3206C
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number SLV2263L
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number SJQ2412Z
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 5

Vehicle Registration Number SLV3721A
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR

Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 6

Vehicle Registration Number SLX4924P
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 7

Vehicle Registration Number SLD4035K
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 8

Vehicle Registration Number SJJ3363L
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Accident Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to regulate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/tan be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be used outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (c) above may be shared / disclosed:
 - (i) to all Insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
Date & Time:

Driver's Signature
(If Driver is not the policyholder)
Date & Time:

Reporting Centre Person's Signature
Name: Rep. [Signature]
NRIC/PIN No: [Signature]

Accident Sketch Plan

A: SMC 166K D: SLV 2263L G: SX 404P
 B: SLQ 4302X E: SJQ 2412Z H: SLQ 4031K
 SKETCH PLAN (1: SKW 3206C F: SLV 3721A I: SJJ 3363L



AYE (TUN3) APT BUENA VISTA

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON THE STATED TIME AND DATE, I (SMC 166K) WAS TRAVELLING ALONG THE STATED VENUE ON THE RIGHT MOST LANE. SUDDENLY, THERE WAS A HUGE IMPACT FROM MY REAR AND PUSHED MY VEHICLE FORWARD TO COLLIDE ONTO (SLV 2263L). I ALIGHTED AND REALISED THAT IT WAS A CHAIN COLLISION INVOLVING 9 CARS. (SLQ 4302X) HAD COLLIDED ONTO MY REAR, PROPELLING MY VEHICLE TO COLLIDE ONTO (SLV 2263L).

POLICE REPORT 01/06/2005/7009

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
 Date & Time

Driver's Signature
 (If driver is not the policyholder)
 Date & Time

Reporting Centre Personnel's Signature
 Name:
 NRIC/PPN No:

POLICE REPORT



**SINGAPORE
POLICE FORCE**



D/20190405/7009

1 of 2

POLICE REPORT (NP299)

Report No. D/20190405/7009

Police Station Of Origin
Clementi Division HQ
20 Clementi Avenue 5 SINGAPORE 129858
Tel No: 1800-7740000

Date/Time Report Made 05/04/2019 12:02	Vide Report No.	Station Diary No.
Name Of Informant TAN JI PUNG, GILBERT	Address APT BLK 690 JURONG WEST CENTRAL 1 #07-205 SINGAPORE 640690	
ID Type / ID No. NRIC NO / S8711714F	Contact No. Home/Office: Mobile 88580598	
Nationality SINGAPORE CITIZEN	Email Address bert.87@gmail.com	
Occupation Interior designer	Sex Male	Age 31
Institution/School Name	Date of Birth 02/05/1987	Race Chinese
Date/Time Of Incident 04/04/2019 20:25 - 04/04/2019 21:25	Location Of Incident AYE (TUAS) AFTER BUONA VISTA EXIT	

Brief details.

On the stated time and date, I (SMC186K) was travelling along the stated venue on the right most lane. As the front vehicle applied brakes, I followed suit. Suddenly there was a huge impact from my rear and pushed my vehicle forward and collided onto (SLV2263L). After alighting, I checked on my wife (Leong Jia Sin S8270572B) and realised that (SLU4332X) had collided onto me and resulting in a chain collision involving 9 cars.

1st SJJ3363L

2ND SLD4035K

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required
Signature Of Interpreter: Not applicable	Date/Time: 05/04/2019 12:02
Officer In-Charge Of Case:	Classification Of Case:

Authentication Stamp

POLICE REPORT



**SINGAPORE
POLICE FORCE**



D/20190405/7009

2 of 2

POLICE REPORT (NP299)

CONTINUATION OF REPORT

Report No. D/20190405/7009

3RD SLX4924P
4TH SLV3721A
5TH SJQ2412Z
6TH SLV2263L
7TH SMC166K
8TH SKW3206C
9TH SLQ4302X

Subjects Involved			
Victim			
Person Name	TAN JI PUNG, GILBERT		
ID Type	NRIC NO	ID No	S8711714F
Gender	Male	Age	31
Race	Chinese	Language	English
Occupation	Interior designer	Address Type	
Address	APT BLK 690 JURONG WEST CENTRAL 1 #07-205 SINGAPORE 640690	Mobile No	88580598
Is Informant A Victim?	Yes		
Person Name TAN JI PUNG, GILBERT (Informant)			

Signature Of Officer Recording The Report: Not applicable	Signature Of Informant: The identity of the person making this report has been authenticated by SingPass. No signature is required.
Signature Of Interpreter: Not applicable	Date/Time: 05/04/2019 12:02
Officer in-Charge Of Case:	Classification Of Case:
Authentication Stamp	

BP Auto
(UEN No. 53378133K)
48 Toh Guan Road Esat #01-121
Enterprise Hub S(608586)
Tel: 6266 0555 Fax : 6266 3155

TO : NTUC ATTENTION : MOTOR CLAIMS DEPARTMENT ESTIMATE REPORT : OWNER PARTICULAR NAME : ADDRESS : TEL. NO. : OWNER INSURANCE : FWD POLICY NO. : PNPV2019-00001768 PERSON INCHARGE :	DATE : 7-Apr-19 JOB TYPE : T/P CLAIMS VEHICLE DETAILS VEHICLE NO. : SMC166K MODEL / MAKE : TOYOTA CAMRY CHASSIS NO. : MR053BK4107017515 ACCIDENT DETAIL DATE : 4-Apr-19 TIME : 20:25hrs
--	--

QUOTATION SUMMARY **PAGE 01**
CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BOOT LID	1	\$ 950.90	\$ 950.90
2	REAR BOOT LID LOGO EMBLEM	1	\$ 69.20	\$ 69.20
3	REAR BOOT LID CAMRY EMBLEM	1	\$ 78.30	\$ 78.30
4	REAR BOOT LID SPOILER	1	\$ 989.30	\$ 989.30
5	REAR BOOT LID OUTER GARNISH	1	\$ 325.10	\$ 325.10
6	REAR BOOT LID REFLECTOR LAMP LH/RH	2	\$ 290.40	\$ 580.80
7	REAR BOOT LID REFLECTOR LAMP BACK RUBBER GASKET LH/RH	2	\$ 59.40	\$ 118.80
8	REAR BOOT LID HINGE LH/RH	2	\$ 109.40	\$ 218.80
9	REAR BOOT LID INNER UPHOLSTERY TRIM	1	\$ 246.80	\$ 246.80
10	REAR BOOT LID RUBBER GUIDE STOPPER LH/RH	2	\$ 39.40	\$ 78.80
11	REAR BOOT LID MECHANISM LOCK	1	\$ 269.40	\$ 269.40
12	REAR BOOT LID WEATHER STRIP	1	\$ 196.40	\$ 196.40
13	REAR TAILLAMP LH/RH	2	\$ 320.10	\$ 640.20
14	REAR TAILLAMP LOWER BRACKET LH/RH	2	\$ 57.80	\$ 115.60
15	REAR TAILLAMP INNER PANEL LH/RH	2	\$ 207.90	\$ 415.80
16	REAR TAILLAMP BACK RUBBER GASKET LH/RH	2	\$ 67.90	\$ 135.80
17	REAR BUMPER	1	\$ 480.40	\$ 480.40
18	REAR BUMPER REFLECTOR LH/RH	2	\$ 85.40	\$ 170.80
19	REAR BUMPER INNER SIDE SHIELD LH/RH	2	\$ 57.90	\$ 115.80
20	REAR BUMPER SCREW COVER LH/RH	2	\$ 39.60	\$ 79.20
21	REAR BUMPER REINFORCEMENT	1	\$ 310.40	\$ 310.40
22	REAR BUMPER REINFORCEMENT BRACKET LH/RH	2	\$ 146.50	\$ 293.00
23	REAR BUMPER SIDE RETAINER LH/RH	2	\$ 101.90	\$ 203.80
24	REAR BUMPER CORNER RETAINER LH/RH	2	\$ 92.60	\$ 185.20
25	REAR BUMPER LOWER LIP	1	\$ 1,292.60	\$ 1,292.60
26	REAR END PANEL <i>- photo</i>	1	\$ 400.40	\$ 400.40
27	REAR END PANEL INNER TOP GARNISH	1	\$ 350.40	\$ 350.40

5686.4

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
28	REAR END PANEL BOOT LID ANTENNA SENSOR	1	\$ 369.70	\$ 369.70
29	REAR FENDER LH/RH	2	\$ 2,569.10	\$ 5,138.20
30	REAR FENDER INNER UPHOLSTERY TRIM LH/RH	2	\$ 346.70	\$ 693.40
31	REAR WINDSCREEN MOULDING	1	\$ 173.80	\$ 173.80
32	SPARE TYRE PANEL	1	\$ 710.50	\$ 710.50
33	SPARE TYRE PANEL INNER TOP UPHOLSTERY BOARD	1	\$ 207.50	\$ 207.50
34	SPARE TYRE PANEL INNER TOP SPONGE	1	\$ 223.90	\$ 223.90
35	SPARE TYRE SIDE PANEL LH/RH	2	\$ 289.70	\$ 579.40
36	SPARE TYRE SIDE PANEL INNER TOP SPONGE LH/RH	2	\$ 269.40	\$ 538.80
37	SPARE TYRE	1	\$ 329.80	\$ 329.80
38	SPARE TYRE RETAINER LOCK	1	\$ 79.80	\$ 79.80
39	REAR EXHAUST SILENCER BOX	1	\$ 701.40	\$ 701.40
40	REAR EXHAUST END CHROME PIPE	1	\$ 113.90	\$ 113.90
41	REAR EXHAUST RUBBER MOUNTING	3	\$ 69.40	\$ 208.20
42	REAR EXHAUST ALUMINIUM HEAT SHIELD	1	\$ 123.90	\$ 123.90
43	EXHAUST MID PIPE	1	\$ 759.40	\$ 759.40
44	FRONT BONNET	1	\$ 889.40	\$ 889.40
45	FRONT BONNET RUBBER SEAL	1	\$ 86.30	\$ 86.30
46	FRONT BONNET WEATHER STRIP	1	\$ 101.50	\$ 101.50
47	FRONT BONNET HINGE LH/RH	2	\$ 139.80	\$ 279.60
48	FRONT BONNET DAMPER LH/RH	2	\$ 226.70	\$ 453.40
49	FRONT BONNET INSULATOR MAT	1	\$ 249.50	\$ 249.50
50	FRONT BONNET MECHANISM LOCK	1	\$ 316.50	\$ 316.50
51	FRONT BONNET CABLE	1	\$ 109.70	\$ 109.70
52	FRONT BONNET RUBBER GUIDE STOPPER LH/RH	2	\$ 39.60	\$ 79.20
53	FRONT GRILLE	1	\$ 289.40	\$ 289.40
54	FRONT GRILLE LOGO EMBLEM	1	\$ 82.10	\$ 82.10
55	FRONT GRILLE LOGO EMBLEM BASE	1	\$ 99.10	\$ 99.10
56	FRONT HEADLAMP LH/RH	2	\$ 701.40	\$ 1,402.80
57	FRONT HEADLAMP TOP PANEL LH/RH	2	\$ 181.20	\$ 362.40
58	FRONT BUMPER	1	\$ 560.50	\$ 560.50
59	FRONT BUMPER LOWER CENTER GRILLE	1	\$ 196.20	\$ 196.20
60	FRONT BUMPER CHROME MOULDING LH/RH	2	\$ 111.60	\$ 223.20
61	FRONT BUMPER FOG LAMP LH/RH	2	\$ 240.40	\$ 480.80
62	FRONT BUMPER FOG LAMP GARNISH LH/RH	2	\$ 60.80	\$ 121.60
63	FRONT BUMPER SIDE RETAINER LH/RH	2	\$ 97.40	\$ 194.80
64	FRONT BUMPER INNER SPONGE	1	\$ 109.40	\$ 109.40
65	FRONT BUMPER REINFORCEMENT	1	\$ 290.40	\$ 290.40
66	FRONT BUMPER REINFORCEMENT BRACKET LH/RH	2	\$ 137.60	\$ 275.20
67	FRONT BUMPER TOW HOOK COVER	1	\$ 91.40	\$ 91.40
68	FRONT BUMPER LOWER LIP	1	\$ 1,356.80	\$ 1,356.80
69	FRONT FENDER LH/RH	2	\$ 656.80	\$ 1,313.60
70	FRONT FENDER TOP GARNISH LH/RH	2	\$ 126.80	\$ 253.60
71	FRONT FENDER INNER SHIELD LH/RH	2	\$ 197.40	\$ 394.80
72	FRONT FENDER VVT-I EMBLEM LH/RH	2	\$ 76.30	\$ 152.60
73	FRONT SUPPORT PANEL	1	\$ 810.40	\$ 810.40
74	FRONT BRACE PANEL	1	\$ 246.50	\$ 246.50

7014.60

h

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
75	AIRCON CONDENSER	1	\$ 950.40	\$ 750 950.40
76	AIRCON CONDENSER AIR GUIDE LH/RH	2	\$ 135.90	\$ de 271.80
77	AIRCON FAN MOTOR	1	\$ 335.90	\$? 335.90
78	AIRCON FAN BLADE	1	\$ 115.90	\$? 115.90
79	RADIATOR	1	\$ 1,050.40	\$ 850 1,050.40
80	RADIATOR FAN COWLING	1	\$ 250.10	\$? 250.10
81	RADIATOR FAN MOTOR	1	\$ 335.40	\$? 335.40
82	RADIATOR FAN BLADE	1	\$ 115.90	\$? 115.90
83	HORN	2	\$ 103.40	\$ del 206.80
TOTAL PRICE				\$ 35,768.90
LESS -25%				\$ (8,942.23)
SUB TOTAL PRICE				\$ 26,826.68

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR BOOT LID OUTER GARNISH CLIPS SET	1	\$ 40.00	\$ x 40.00
2	REAR BOOT LID REFLECTOR LAMP CLIPS SET LH/RH	2	\$ 30.00	\$ x 60.00
3	REAR BOOT LID INNER UPOHOLSTERY TRIM CLIPS SET	1	\$ 50.00	\$ x 50.00
4	REAR BOOT LID 3D ALOY WORDING NUMBER PLATE WITH CASING SET	1	\$ 120.00	\$ x 120.00
4	REAR TAILLAMP CLIPS SET LH/RH	2	\$ 30.00	\$ x 60.00
5	REAR TAILLAMP INNER PANEL SEALANT LH/RH	2	\$ 40.00	\$ x 80.00
6	REAR BUMPER REVERSE SENSOR SET	1	\$ 280.00	\$ 200/m 280.00
7	REAR BUMPER CLIPS SET	1	\$ 60.00	\$ 30/m 60.00
8	REAR BUMPER INNER SIDE SHIELD CLIPS SET LH/RH	2	\$ 20.00	\$ x 40.00
9	REAR END PANEL SEALANT	1	\$ 80.00	\$ 40/m 80.00
10	REAR END PANEL INNER TOP GARNISH CLIPS SET	1	\$ 40.00	\$ 10/m 40.00
11	REAR FENDER SEALANT LH/RH	2	\$ 100.00	\$ 200.00
12	REAR FENDER INSULATOR MAT LH/RH	2	\$ 180.00	\$ x 360.00
13	REAR FENDER INNER UPHOLSTERY TRIM CLIPS SET LH/RH	2	\$ 60.00	\$ x 120.00
14	REAR WINDSCREEN SEALANT WITH PRIMER SET	1	\$ 100.00	\$ x 100.00
15	SPARE TYRE PANEL SEALANT	1	\$ 120.00	\$ x 120.00
18	SPARE TYRE SIDE PANEL SEALANT LH/RH	2	\$ 30.00	\$ x 60.00
19	REAR EXHAUST GASKET	1	\$ 25.00	\$ 2 25.00
20	FRONT BONNET INSULATOR MAT CLIPS SET	1	\$ 60.00	\$ 20/m 60.00
21	FRONT GRILLE CLIPS SET	1	\$ 40.00	\$ 10/m 40.00
22	FRONT HEADLAMP CLIP SET LH/RH	2	\$ 20.00	\$ 20/m 40.00
23	FRONT BUMPER 3D ALOY WORDING NUMBER PLATE WITH CASING SE	1	\$ 120.00	\$ mir 60 120.00
24	FRONT BUMPER CLIPS SET	1	\$ 60.00	\$ mir 30 60.00
25	FRONT BUMPER LOWER UNDER COVER CLIPS SET	1	\$ 40.00	\$ x 40.00
27	FRONT BUMPER RUBBER LOWER LIP	1	\$ 335.00	\$ de 335.00
26	FRONT FENDER INNER SHIELD CLIPS SET LH/RH	2	\$ 50.00	\$ x 100.00
27	FRONT SUPPORT PANEL TOP GARNISH CLIP SET	1	\$ 40.00	\$ x 40.00
28	AIRCON CONDENSER AIR GUIDE CLIPS SET LH/RH	2	\$ 20.00	\$ x 40.00
29	RADIATOR COOLANT	1	\$ 80.00	\$ de 80.00

TOTAL

\$ 2,850.00

835

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING REAR PORTION

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 2,400.00		1000 -
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 1,800.00		1200 -
TO APPLY ANTI-RUST & TUFF KOTE	\$ 200.00		40 -
TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00		30 -
TO CALIBRATE CHASSIS & CAR BODY BACK TO MANUFACTURING SPECIFICATION	\$ 240.00		X 44
TO DISMANTLE & REINSTALL REAR PETROL TANK FOR FACILITATE REPAIR	\$ 250.00		X 44
TO DISMANTLE & REINSTALL REAR WINDSCREEN PERFORM WITH WATER LEAK TEST	\$ 150.00		X 44
TO PERFORM TRANSFER REAR BOOT LID MECHANISM & REALIGN BACK TO MANUFACTURING SPECIFICATION	\$ 150.00		60 -
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	\$ 80.00		30 -
TO DISMANTLE & REPLACED REAR EXHAUST SILENCER BOX WITH REALIGN EXHAUST MID PIPE & RUBBER MOUNTING	\$ 180.00		X 44
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 280.00		60 -
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 80.00		20 -

TOTAL

\$ 5,890.00

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 1,600.00	800
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 1,400.00	900
TO APPLY ANTI-RUST & TUFF KOTE	\$ 140.00	30
TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00	30
TO DISMANTLE & REINSTALL AIRCON CONDENSOR WITH REFILL AIRCON GAS	\$ 120.00	120
TO DISMANTLE & REINSTALL RADIATOR WITH REFILL RADIATOR COOLANT & HIGH PRESSURE TEST	\$ 120.00	4320

TOTAL \$ 3,460.00

11271.98

835

4320

16426.98

1/13/20

Repair limit \$10,000

ESTIMATE REPORT

TOTAL PARTS COST : \$ 29,676.68
TOTAL LABOUR COST : \$ 9,350.00
TOTAL REPAIR COST : \$ 39,026.68

APPROVED DETAILS

EXCESS :
NO. OF REPAIR DAYS :
RE-SURVEY :
P / P OR L / S :

DATE / TIME OF SURVEY :
SURVEYED BY / FROM :
CONTACT NUMBER :
FAX NUMBER :
EMAIL ADDRESS :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

10/4/19.
Tuffin 97495749
WP
9/4/19 @ 4:15pm
Resurvey after repair.
Give 11 hours
To check repair limit
12 days

Taufikh (LKK)

TGBPI9-0404

BP Auto
(UEN No. 53378133K)
48 Toh Guan Road Esat #01-121
Enterprise Hub S(608586)
Tel: 6266 0555 Fax : 6266 3155

TO	: NTUC	DATE	: 7-Apr-19
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
ESTIMATE REPORT	:		
<u>OWNER PARTICULAR</u>		<u>VEHICLE DETAILS</u>	
NAME	:	VEHICLE NO.	: SMC166K
ADDRESS	:	MODEL / MAKE	: TOYOTA CAMRY
TEL. NO.	:	CHASSIS NO.	: MR053BK4107017515
OWNER INSURANCE	: FWD	<u>ACCIDENT DETAIL</u>	
POLICY NO.	: PNPV2019-00001768	DATE	: 4-Apr-19
		TIME	: 20:25hrs
PERSON INCHARGE	:		

QUOTATION SUMMARY PAGE 01
CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BOOT LID	1	\$ 950.90	\$ 950.90 950.90 ✓
2	REAR BOOT LID LOGO EMBLEM	1	\$ 69.20	\$ 69.20 69.20 ✓
3	REAR BOOT LID CAMRY EMBLEM	1	\$ 78.30	\$ 78.30 78.30 ✓
4	REAR BOOT LID SPOILER	1	\$ 989.30	\$ 989.30 989.30 ✓
5	REAR BOOT LID OUTER GARNISH	1	\$ 325.10	\$ 325.10 325.10 ✓
6	REAR BOOT LID REFLECTOR LAMP LH/RH	2	\$ 290.40	\$ 580.80 580.80 ✓
7	REAR BOOT LID REFLECTOR LAMP BACK RUBBER GASKET LH/RH	2	\$ 59.40	\$ 118.80 118.80 ✓
8	REAR BOOT LID HINGE LH/RH	2	\$ 109.40	\$ 218.80 218.80 ✓
9	REAR BOOT LID INNER UPHOLSTERY TRIM	1	\$ 246.80	\$ 246.80 246.80 ✓
10	REAR BOOT LID RUBBER GUIDE STOPPER LH/RH	2	\$ 39.40	\$ 78.80 78.80 ✓
11	REAR BOOT LID MECHANISM LOCK	1	\$ 269.40	\$ 269.40 269.40 ✓
12	REAR BOOT LID WEATHER STRIP	1	\$ 196.40	\$ 196.40 196.40 ✓
13	REAR TAILLAMP LH/RH	2	\$ 320.10	\$ 640.20 640.20 ✓
14	REAR TAILLAMP LOWER BRACKET LH/RH	2	\$ 57.80	\$ 115.60 115.60 ✓
15	REAR TAILLAMP INNER PANEL LH/RH	2	\$ 207.90	\$ 415.80 415.80 ✓
16	REAR TAILLAMP BACK RUBBER GASKET LH/RH	2	\$ 67.90	\$ 135.80 135.80 ✓
17	REAR BUMPER	1	\$ 480.40	\$ 480.40 480.40 ✓
18	REAR BUMPER REFLECTOR LH/RH	2	\$ 85.40	\$ 170.80 170.80 ✓
19	REAR BUMPER INNER SIDE SHIELD LH/RH	2	\$ 57.90	\$ 115.80 115.80 ✓
20	REAR BUMPER SCREW COVER LH/RH	2	\$ 39.60	\$ 79.20 79.20 ✓
21	REAR BUMPER REINFORCEMENT	1	\$ 310.40	\$ 310.40 310.40 ✓
22	REAR BUMPER REINFORCEMENT BRACKET LH/RH	2	\$ 146.50	\$ 293.00 293.00 ✓
23	REAR BUMPER SIDE RETAINER LH/RH	2	\$ 101.90	\$ 203.80 203.80 ✓
24	REAR BUMPER CORNER RETAINER LH/RH	2	\$ 92.60	\$ 185.20 185.20 ✓
25	REAR BUMPER LOWER LIP	1	\$ 1,292.60	\$ 1,292.60 1,292.60 ✓
26	REAR END PANEL - photo	1	\$ 400.40	\$ 400.40 400.40 ✓
27	REAR END PANEL INNER TOP GARNISH	1	\$ 350.40	\$ 350.40 350.40 ✓

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
28	REAR END PANEL BOOT LID ANTENNA SENSOR	1	\$ 369.70	\$ 369.70
29	REAR FENDER LH/RH	2	\$ 2,569.10	\$ 5,138.20
30	REAR FENDER INNER UPHOLSTERY TRIM LH/RH	2	\$ 346.70	\$ 693.40
31	REAR WINDSCREEN MOULDING	1	\$ 175.80	\$ 175.80
32	SPARE TYRE PANEL	1	\$ 710.50	\$ 710.50
33	SPARE TYRE PANEL INNER TOP UPHOLSTERY BOARD	1	\$ 207.50	\$ 207.50
34	SPARE TYRE PANEL INNER TOP SPONGE	1	\$ 225.90	\$ 225.90
35	SPARE TYRE SIDE PANEL LH/RH	2	\$ 289.70	\$ 579.40
36	SPARE TYRE SIDE PANEL INNER TOP SPONGE LH/RH	2	\$ 269.40	\$ 538.80
37	SPARE TYRE	1	\$ 329.80	\$ 329.80
38	SPARE TYRE RETAINER LOCK	1	\$ 79.80	\$ 79.80
39	REAR EXHAUST SILENCER BOX	1	\$ 701.40	\$ 701.40
40	REAR EXHAUST END CHROME PIPE	1	\$ 113.90	\$ 113.90
41	REAR EXHAUST RUBBER MOUNTING	3	\$ 69.40	\$ 208.20
42	REAR EXHAUST ALUMINIUM HEAT SHIELD	1	\$ 123.90	\$ 123.90
43	EXHAUST MID PIPE	1	\$ 759.40	\$ 759.40
44	FRONT BONNET	1	\$ 889.40	\$ 889.40
45	FRONT BONNET RUBBER SEAL	1	\$ 86.30	\$ 86.30
46	FRONT BONNET WEATHER STRIP	1	\$ 101.50	\$ 101.50
47	FRONT BONNET HINGE LH/RH	2	\$ 139.80	\$ 279.60
48	FRONT BONNET DAMPER LH/RH	2	\$ 226.70	\$ 453.40
49	FRONT BONNET INSULATOR MAT	1	\$ 249.50	\$ 249.50
50	FRONT BONNET MECHANISM LOCK	1	\$ 316.50	\$ 316.50
51	FRONT BONNET CABLE	1	\$ 109.70	\$ 109.70
52	FRONT BONNET RUBBER GUIDE STOPPER LH/RH	2	\$ 39.60	\$ 79.20
53	FRONT GRILLE	1	\$ 289.40	\$ 289.40
54	FRONT GRILLE LOGO EMBLEM	1	\$ 82.10	\$ 82.10
55	FRONT GRILLE LOGO EMBLEM BASE	1	\$ 99.10	\$ 99.10
56	FRONT HEADLAMP LH/RH	2	\$ 701.40	\$ 1,402.80
57	FRONT HEADLAMP TOP PANEL LH/RH	2	\$ 181.20	\$ 362.40
58	FRONT BUMPER	1	\$ 560.50	\$ 560.50
59	FRONT BUMPER LOWER CENTER GRILLE	1	\$ 196.20	\$ 196.20
60	FRONT BUMPER CHROME MOULDING LH/RH	2	\$ 111.60	\$ 223.20
61	FRONT BUMPER FOG LAMP LH/RH	2	\$ 240.40	\$ 480.80
62	FRONT BUMPER FOG LAMP GARNISH LH/RH	2	\$ 60.80	\$ 121.60
63	FRONT BUMPER SIDE RETAINER LH/RH	2	\$ 97.40	\$ 194.80
64	FRONT BUMPER INNER SPONGE	1	\$ 109.40	\$ 109.40
65	FRONT BUMPER REINFORCEMENT	1	\$ 290.40	\$ 290.40
66	FRONT BUMPER REINFORCEMENT BRACKET LH/RH	2	\$ 137.60	\$ 275.20
67	FRONT BUMPER TOW HOOK COVER	1	\$ 91.40	\$ 91.40
68	FRONT BUMPER LOWER LIP	1	\$ 1,356.80	\$ 1,356.80
69	FRONT FENDER LH/RH	2	\$ 656.80	\$ 1,313.60
70	FRONT FENDER TOP GARNISH LH/RH	2	\$ 126.80	\$ 253.60
71	FRONT FENDER INNER SHIELD LH/RH	2	\$ 197.40	\$ 394.80
72	FRONT FENDER VVT-1 EMBLEM LH/RH	2	\$ 76.30	\$ 152.60
73	FRONT SUPPORT PANEL	1	\$ 810.40	\$ 810.40
74	FRONT BRACE PANEL	1	\$ 246.50	\$ 246.50

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE	
75	AIRCON CONDENSER	1	\$ 950.40	\$? 950.40	PHOTO
76	AIRCON CONDENSER AIR GUIDE LH/RH	2	\$ 135.90	\$ 271.80	
77	AIRCON FAN MOTOR	1	\$ 335.90	\$? 335.90	
78	AIRCON FAN BLADE	1	\$ 115.90	\$? 115.90	
79	RADIATOR	1	\$ 1,050.40	\$? 1,050.40	PHOTO
80	RADIATOR FAN COWLING	1	\$ 250.10	\$? 250.10	PHOTO
81	RADIATOR FAN MOTOR	1	\$ 335.40	\$? 335.40	
82	RADIATOR FAN BLADE	1	\$ 115.90	\$? 115.90	
83	HORN	2	\$ 103.40	\$ 206.80	
TOTAL PRICE				\$ 35,768.90	16,879.50
LESS -25%				\$ (8,942.23)	8,219.87
SUB TOTAL PRICE				\$ 26,826.68	12,659.63

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	REAR BOOT LID OUTER GARNISH CLIPS SET	1	\$ 40.00	\$ X 40.00	
2	REAR BOOT LID REFLECTOR LAMP CLIPS SET LH/RH	2	\$ 30.00	\$ X 60.00	
3	REAR BOOT LID INNER UPOHOLSTERY TRIM CLIPS SET	1	\$ 50.00	\$ X 50.00	
4	REAR BOOT LID 3D ALOY WORDING NUMBER PLATE WITH CASING SET	1	\$ 120.00	\$ X 120.00	
4	REAR TAILLAMP CLIPS SET LH/RH	2	\$ 30.00	\$ X 60.00	
5	REAR TAILLAMP INNER PANEL SEALANT LH/RH	2	\$ 40.00	\$ X 80.00	
6	REAR BUMPER REVERSE SENSOR SET	1	\$ 280.00	\$ 200.00 280.00	
7	REAR BUMPER CLIPS SET	1	\$ 60.00	\$ 30.00 60.00	
8	REAR BUMPER INNER SIDE SHIELD CLIPS SET LH/RH	2	\$ 20.00	\$ X 40.00	
9	REAR END PANEL SEALANT	1	\$ 80.00	\$ 40.00 80.00	
10	REAR END PANEL INNER TOP GARNISH CLIPS SET	1	\$ 40.00	\$ 10.00 40.00	
11	REAR FENDER SEALANT LH/RH	2	\$ 100.00	\$ 200.00	
12	REAR FENDER INSULATOR MAT LH/RH	2	\$ 180.00	\$ X 360.00	
13	REAR FENDER INNER UPHOLSTERY TRIM CLIPS SET LH/RH	2	\$ 60.00	\$ X 120.00	
14	REAR WINDSCREEN SEALANT WITH PRIMER SET	1	\$ 100.00	\$ X 100.00	
15	SPARE TYRE PANEL SEALANT	1	\$ 120.00	\$ X 120.00	
18	SPARE TYRE SIDE PANEL SEALANT LH/RH	2	\$ 30.00	\$ X 60.00	
19	REAR EXHAUST GASKET	1	\$ 25.00	\$ A 25.00	
20	FRONT BONNET INSULATOR MAT CLIPS SET	1	\$ 60.00	\$ 20.00 60.00	
21	FRONT GRILLE CLIPS SET	1	\$ 40.00	\$ 10.00 40.00	
22	FRONT HEADLAMP CLIP SET LH/RH	2	\$ 20.00	\$ 20.00 40.00	
23	FRONT BUMPER 3D ALOY WORDING NUMBER PLATE WITH CASING SET	1	\$ 120.00	\$ 60.00 120.00	
24	FRONT BUMPER CLIPS SET	1	\$ 60.00	\$ 30.00 60.00	
25	FRONT BUMPER LOWER UNDER COVER CLIPS SET	1	\$ 40.00	\$ X 40.00	
27	FRONT BUMPER RUBBER LOWER LIP	1	\$ 335.00	\$ 335.00	
26	FRONT FENDER INNER SHIELD CLIPS SET LH/RH	2	\$ 50.00	\$ X 100.00	
27	FRONT SUPPORT PANEL TOP GARNISH CLIP SET	1	\$ 40.00	\$ X 40.00	
28	AIRCON CONDENSER AIR GUIDE CLIPS SET LH/RH	2	\$ 20.00	\$ X 40.00	
29	RADIATOR COOLANT	1	\$ 80.00	\$ 80.00	
TOTAL				\$ 2,850.00	835.00

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING REAR PORTION

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 2,400.00		1000
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 1,800.00		1200
TO APPLY ANTI-RUST & TUFF KOTE	\$ 200.00		40
TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00		30
TO CALIBRATE CHASSIS & CAR BODY BACK TO MANUFACTURING SPECIFICATION	\$ 240.00		R
TO DISMANTLE & REINSTALL REAR PETROL TANK FOR FACILITATE REPAIR	\$ 250.00		X
TO DISMANTLE & REINSTALL REAR WINDSCREEN PERFORM WITH WATER LEAK TEST	\$ 150.00		X
TO PERFORM TRANSFER REAR BOOT LID MECHANISM & REALIGN BACK TO MANUFACTURING SPECIFICATION	\$ 150.00		60
TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING	\$ 80.00		30
TO DISMANTLE & REPLACED REAR EXHAUST SILENCER BOX WITH REALIGN EXHAUST MID PIPE & RUBBER MOUNTING	\$ 180.00		X
TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR	\$ 280.00		60
TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION	\$ 80.00		20

TOTAL \$ 5,890.00 2,440.00

QUOTATION SUMMARY

PAGE 05

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION	\$ 1,600.00	800
TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA	\$ 1,400.00	900
TO APPLY ANTI-RUST & TUFF KOTE	\$ 140.00	30
TO PERFORM LIGHTING & WIRING CHECK	\$ 80.00	30
TO DISMANTLE & REINSTALL AIRCON CONDENSOR WITH REFILL AIRCON GAS	\$ 120.00	7120 ✓
TO DISMANTLE & REINSTALL RADIATOR WITH REFILL RADIATOR COOLANT & HIGH PRESSURE TEST	\$ 120.00	71

TOTAL \$ 3,460.00 1.880.00

Tuplin 22495749
 WP
 9/4/19 Repair
 Resing after repair
 Give Wharftown
 To check repair limit
 12 days

ESTIMATE REPORT

TOTAL PARTS COST : \$ 29,676.68
 TOTAL LABOUR COST : \$ 9,350.00
 TOTAL REPAIR COST : \$ 39,026.68

APPROVED DETAILS

EXCESS :
 NO. OF REPAIR DAYS :
 RE-SURVEY :
 P / P OR L / S :

DATE / TIME OF SURVEY :
 SURVEYED BY / FROM :
 CONTACT NUMBER :
 FAX NUMBER :
 EMAIL ADDRESS :

Parts: 12,659.63
 SN : 835.00
 Labour: 13,494.63
 4,370.00
 L/S Less 20%: 3,562.93
 14,251.70

Lumpsum \$ 14,250.00 (12 days)

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: CS/INC19006301/T1qd3e2

73 BRAS BASAH ROAD

Date: 01-08-2019

#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556

ATTN: DAVID PHUA

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLQ 4302X	Veh. Inspected	SMC 166K
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1039006-002	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	09/04/2019

2. Vehicle Particulars & Condition

Make & Model	TOYOTA CAMRY	c.c	1998
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	MR053BK4107017515	Colour	WHITE
Odometer	206354 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/55 R17	PIRELLI	6 mm
L/H Front Tyre	215/55 R17	PIRELLI	6 mm
R/H Rear Tyre	215/55 R17	PIRELLI	6 mm
L/H Rear Tyre	215/55 R17	PIRELLI	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/04/2019	Inspect Date / Time	09/04/2019 (04:15 PM)
Survey held at	BP AUTO - 48 TOH GUAN RD EAST #01-121		
Repairer	-		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	12 Working Days
-------------------------------------	-----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 6

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 166K

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BOOT LID	BENT	950.90	950.90
1	REAR BOOT LID LOGO EMBLEM	NECESSARY	69.20	69.20
1	REAR BOOT LID CAMRY EMBLEM	NECESSARY	78.30	78.30
1	REAR BOOT LID SPOILER	TO REPAIR SEE LABOUR	989.30	-
1	REAR BOOT LID OUTER GARNISH	TO REPAIR SEE LABOUR	325.10	-
2	REAR BOOT LID REFLECTOR LAMP LH / RH @\$290.40	CUT	580.80	580.80
2	REAR BOOT LID REFLECTOR LAMP BACK RUBBER GASKET LH / RH @\$59.40	NECESSARY	118.80	118.80
2	REAR BOOT LID HINGE LH / RH @\$109.40	TO REPAIR SEE LABOUR	218.80	-
1	REAR BOOT LID INNER UPHOLSTERY TRIM	NOT NECESSARY	246.80	-
2	REAR BOOT LID RUBBER GUIDE STOPPER LH / RH @\$39.40	NOT NECESSARY	78.80	-
1	REAR BOOT LID MECHANISM LOCK	BENT	269.40	269.40
1	REAR BOOT LID WEATHER STRIP	TWISTED	196.40	196.40
2	REAR TAILLAMP LH / RH @\$320.10	CRACKED	640.20	640.20
2	REAR TAILLAMP LOWER BRACKET LH / RH @\$57.80	NECESSARY	115.60	115.60
2	REAR TAILLAMP INNER PANEL LH / RH @\$207.90	TO REPAIR SEE LABOUR	415.80	-
2	REAR TAILLAMP BACK RUBBER GASKET LH / RH @\$67.90	NECESSARY	135.80	135.80
1	REAR BUMPER	DEFORMED	480.40	480.40
2	REAR BUMPER REFLECTOR LH / RH @\$85.40	NOT NECESSARY	170.80	-
2	REAR BUMPER INNER SIDE SHIELD LH / RH @\$57.90	NOT NECESSARY	115.80	-
2	REAR BUMPER SCREW COVER LH / RH @\$39.60	NOT NECESSARY	79.20	-
1	REAR BUMPER REINFORCEMENT	BENT	310.40	310.40
2	REAR BUMPER REINFORCEMENT BRACKET LH / RH @\$146.50	NOT NECESSARY	293.00	-
2	REAR BUMPER SIDE RETAINER LH / RH @\$101.90	NECESSARY	203.80	203.80
2	REAR BUMPER CORNER RETAINER LH / RH @\$92.60	NECESSARY	185.20	185.20
1	REAR BUMPER LOWER LIP	CRACKED	1,292.60	600.00

Report Ref No. CS/INC19006301/T1qd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END PANEL	BENT	400.40	400.40
1	REAR END PANEL INNER TOP GARNISH	DEFORMED	350.40	350.40
1	REAR END PANEL BOOT LID ANTENNA SENSOR	NOT NECESSARY	369.70	-
2	REAR FENDER LH / RH @\$2569.10	TO REPAIR SEE LABOUR	5,138.20	-
2	REAR FENDER INNER UPHOLSTERY TRIM LH / RH @\$346.70	NOT NECESSARY	693.40	-
1	REAR WINDSCREEN MOULDING	NOT NECESSARY	173.80	-
1	SPARE TYRE PANEL	TO REPAIR SEE LABOUR	710.50	-
1	SPARE TYRE PANEL INNER TOP UPHOLSTERY BOARD	NOT NECESSARY	207.50	-
1	SPARE TYRE PANEL INNER TOP SPONGE	NOT NECESSARY	223.90	-
2	SPARE TYRE SIDE PANEL LH / RH @\$289.70	TO REPAIR SEE LABOUR	579.40	-
2	SPARE TYRE SIDE PANEL INNER TOP SPONGE LH / RH @\$269.40	NOT NECESSARY	538.80	-
1	SPARE TYRE	NOT NECESSARY	329.80	-
1	SPARE TYRE RETAINER LOCK	NOT NECESSARY	79.80	-
1	REAR EXHAUST SILENCER BOX	NOT NECESSARY	701.40	-
1	REAR EXHAUST END CHROME PIPE	NOT NECESSARY	113.90	-
3	REAR EXHAUST RUBBER MOUNTING @\$69.40	NOT NECESSARY	208.20	-
1	REAR EXHAUST ALUMINIUM HEAT SHIELD	NOT NECESSARY	123.90	-
1	EXHAUST MID PIPE	NOT NECESSARY	759.40	-
1	FRONT BONNET	BENT	889.40	889.40
1	FRONT BONNET RUBBER SEAL	NOT NECESSARY	86.30	-
1	FRONT BONNET WEATHER STRIP	NOT NECESSARY	101.50	-
2	FRONT BONNET HINGE LH / RH @\$139.80	BENT	279.60	279.60
2	FRONT BONNET DAMPER LH / RH @\$226.70	NOT NECESSARY	453.40	-
1	FRONT BONNET INSULATOR MAT	DEFORMED	249.50	249.50
1	FRONT BONNET MECHANISM LOCK	BENT	316.50	316.50
1	FRONT BONNET CABLE	NOT NECESSARY	109.70	-
2	FRONT BONNET RUBBER GUIDE STOPPER LH / RH @\$39.60	NECESSARY	79.20	79.20
1	FRONT GRILLE	CRACKED	289.40	289.40
1	FRONT GRILLE LOGO EMBLEM	NECESSARY	82.10	82.10

Report Ref No. CS/INC19006301/T1qd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT GRILLE LOGO EMBLEM BASE	CRACKED	99.10	99.10
2	FRONT HEADLAMP LH / RH @\$701.40	CRACKED	1,402.80	1,402.80
2	FRONT HEADLAMP TOP PANEL LH / RH @\$181.20	BENT	362.40	362.40
1	FRONT BUMPER	DEFORMED	560.50	560.50
1	FRONT BUMPER LOWER CENTER GRILLE	NOT NECESSARY	196.20	-
2	FRONT BUMPER CHROME MOULDING LH / RH @\$111.60	NOT NECESSARY	223.20	-
2	FRONT BUMPER FOG LAMP LH / RH @\$240.40	NOT NECESSARY	480.80	-
2	FRONT BUMPER FOG LAMP GARNISH LH / RH @\$60.80	NOT NECESSARY	121.60	-
2	FRONT BUMPER SIDE RETAINER LH / RH @\$97.40	NECESSARY	194.80	194.80
1	FRONT BUMPER INNER SPONGE	DEFORMED	109.40	109.40
1	FRONT BUMPER REINFORCEMENT	BENT	290.40	290.40
2	FRONT BUMPER REINFORCEMENT BRACKET LH / RH @\$137.60	NOT NECESSARY	275.20	-
1	FRONT BUMPER TOW HOOK COVER	NOT NECESSARY	91.40	-
1	FRONT BUMPER LOWER LIP	DEFORMED	1,356.80	600.00
2	FRONT FENDER LH / RH @\$656.80	TO REPAIR SEE LABOUR	1,313.60	-
2	FRONT FENDER TOP GARNISH LH / RH @\$126.80	NOT NECESSARY	253.60	-
2	FRONT FENDER INNER SHIELD LH / RH @\$197.40	NOT NECESSARY	394.80	-
2	FRONT FENDER VVT-I EMBLEM LH / RH @\$76.30	NECESSARY	152.60	152.60
1	FRONT SUPPORT PANEL	BENT	810.40	810.40
1	FRONT BRACE PANEL	BENT	246.50	246.50
1	AIRCON CONDENSER	BENT	950.40	750.00
2	AIRCON CONDENSER AIR GUIDE LH / RH @\$135.90	DEFORMED	271.80	271.80
1	AIRCON FAN MOTOR	NOT NECESSARY	335.90	-
1	AIRCON FAN BLADE	NOT NECESSARY	115.90	-
1	RADIATOR	BENT	1,050.40	850.00
1	RADIATOR FAN COWLING	CRACKED	250.10	250.10
1	RADIATOR FAN MOTOR	NOT NECESSARY	335.40	-
1	RADIATOR FAN BLADE	NOT NECESSARY	115.90	-
2	HORN @\$103.40	DENTED	206.80	206.80
	LESS 25% DISCOUNT		-8,942.23	-3,757.33
			26,826.67	11,271.97

Report Ref No. CS/INC19006301/T1qd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	SPECIAL NETT ITEMS			
1	SET REAR BOOT LID OUTER GARNISH CLIPS (SN)	NOT NECESSARY	40.00	-
2	SET REAR BOOT LID REFLECTOR LAMP CLIPS LH / RH @\$30.00 (SN)	NOT NECESSARY	60.00	-
1	SET REAR BOOT LID INNER UPHOLSTERY TRIM CLIPS (SN)	NOT NECESSARY	50.00	-
1	SET REAR BOOT LID 3D ALOY WORDING NUMBER PLATE WITH CASING (SN)	NOT NECESSARY	120.00	-
2	SET REAR TAILLAMP CLIPS LH / RH @\$30.00 (SN)	NOT NECESSARY	60.00	-
2	REAR TAILLAMP INNER PANEL SEALANT LH / RH @\$40.00 (SN)	NOT NECESSARY	80.00	-
1	SET REAR BUMPER REVERSE SENSOR (SN)	NOT WORKING	280.00	200.00
1	SET REAR BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
2	SET REAR BUMPER INNER SIDE SHIELD CLIPS LH / RH @\$20.00 (SN)	NOT NECESSARY	40.00	-
1	REAR END PANEL SEALANT (SN)	NECESSARY	80.00	40.00
1	SET REAR END PANEL INNER TOP GARNISH CLIPS (SN)	NECESSARY	40.00	10.00
2	REAR FENDER SEALANT LH / RH @\$100.00 (SN)	NOT NECESSARY	200.00	-
2	REAR FENDER INSULATOR MAT LH / RH @\$180.00 (SN)	NOT NECESSARY	360.00	-
2	SET REAR FENDER INNER UPHOLSTERY TRIM CLIPS LH / RH @\$60.00 (SN)	NOT NECESSARY	120.00	-
1	SET REAR WINDSCREEN SEALANT WITH PRIMER (SN)	NOT NECESSARY	100.00	-
1	SPARE TYRE PANEL SEALANT (SN)	NOT NECESSARY	120.00	-
2	SPARE TYRE SIDE PANEL SEALANT LH / RH @\$30.00 (SN)	NOT NECESSARY	60.00	-
1	REAR EXHAUST GASKET (SN)	NOT NECESSARY	25.00	-
1	SET FRONT BONNET INSULATOR MAT CLIPS (SN)	NECESSARY	60.00	20.00
1	SET FRONT GRILLE CLIPS (SN)	NECESSARY	40.00	10.00
2	SET FRONT HEADLAMP CLIP LH / RH @\$20.00 (SN)	NECESSARY	40.00	20.00
1	SET FRONT BUMPER 3D ALOY WORDING NUMBER PLATE WITH CASING (SN)	MISSING	120.00	60.00
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	60.00	30.00
1	SET FRONT BUMPER LOWER UNDER COVER CLIPS (SN)	NOT NECESSARY	40.00	-
1	FRONT BUMPER RUBBER LOWER LIP (SN)	DEFORMED	335.00	335.00
2	SET FRONT FENDER INNER SHIELD CLIPS LH / RH @\$50.00 (SN)	NOT NECESSARY	100.00	-

Report Ref No. CS/INC19006301/T1qd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:5 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET FRONT SUPPORT PANEL TOP GARNISH CLIPS (SN)	NOT NECESSARY	40.00	-
2	SET AIRCON CONDENSER AIR GUIDE CLIPS LH / RH @\$20.00 (SN)	NOT NECESSARY	40.00	-
1	RADIATOR COOLANT (SN)	NECESSARY	80.00	80.00
			2,850.00	835.00
	LABOUR			
	DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION. INCLUSIVE OF THE REPAIR OF REAR BOOT LID SPOILER, REAR BOOT LID OUTER GARNISH, REAR BOOT LID HINGE LH / RH, REAR TAILLAMP INNER PANEL LH / RH, REAR FENDER LH / RH, SPARE TYRE PANEL, SPARE TYRE SIDE PANEL LH / RH AND FRONT FENDER LH / RH.		2,400.00	1,000.00
	TO SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA.		1,800.00	1,200.00
	TO APPLY ANTI-RUST & TUFF KOTE.		200.00	40.00
	TO PERFORM LIGHTING & WIRING CHECK.		80.00	30.00
	TO CALIBRATE CHASSIS & CAR BODY BACK TO MANUFACTURING SPECIFICATION.	NOT NECESSARY	240.00	-
	TO DISMANTLE & REINSTALL REAR PETROL TANK FOR FACILITATE REPAIR.	NOT NECESSARY	250.00	-
	TO DISMANTLE & REINSTALL REAR WINDSCREEN PERFORM WITH WATER LEAK TEST.	NOT NECESSARY	150.00	-
	TO PERFORM TRANSFER REAR BOOT LID MECHANISM & REALIGN BACK TO MANUFACTURING SPECIFICATION.		150.00	60.00
	TO DISMANTLE & REPLACED REAR BUMPER REVERSE SENSOR WITH DISTANCE SETTING.		80.00	30.00
	TO DISMANTLE & REPLACED REAR EXHAUST SILENCER BOX WITH REALIGN EXHAUST MID PIPE & RUBBER MOUNTING.	NOT NECESSARY	180.00	-
	TO DISMANTLE & REINSTALL INTERIOR CARPET WITH OTHER ATTACHMENT PARTS COMPONENT TO FACILITATE REPAIR.		280.00	60.00
	TO PERFORM CONDUCT WATER LEAKAGE TEST OF ACCIDENT PORTION.		80.00	20.00
	TO DISMANTLE & REPLACED WITH PANEL BEATING ALL THE ACCIDENT PORTION.		1,600.00	800.00
	SPRAY PAINTING ALL THE ACCIDENT PORTION & POLISHING AFFECTED AREA.		1,400.00	900.00
	TO APPLY ANTI-RUST & TUFF KOTE.		140.00	30.00

Report Ref No. CS/INC19006301/T1qd3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3581 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 6 of 6

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PERFORM LIGHTING & WIRING CHECK.		80.00	30.00
	TO DISMANTLE & REINSTALL AIRCON CONDENSOR WITH REFILL AIRCON GAS. }		120.00	120.00
	TO DISMANTLE & REINSTALL RADIATOR WITH REFILL RADIATOR COOLANT & HIGH PRESSURE TEST. }		120.00	-
			9,350.00	4,320.00
GRAND TOTAL			39,026.67	16,426.97

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)				10,000.00
--	--	--	--	-----------

Report Ref No. CS/INC19006301/T1qd3e2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,
MinstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.